

RECEIVED  
JUN 11 1996  
DEPT. OF ECOLOGY

---

**REPORT  
INDEPENDENT REMEDIAL ACTION  
GE CAPITAL, TRANSPORT INTERNATIONAL POOL, INC.  
9801 MARTIN LUTHER KING JUNIOR WAY SOUTH  
SEATTLE, WASHINGTON**

For

**GE CAPITAL, TRANSPORT INTERNATIONAL POOL, INC.  
D&M JOB NO. 28171-391-122  
June 10, 1996**



**DAMES & MOORE**



500 MARKET PLACE TOWER, 2025 FIRST AVENUE, SEATTLE, WASHINGTON 98121  
(206) 728-0744 FAX: (206) 727-3350

June 10, 1996

Ms. Elaine P. Atkinson  
Environmental Scientist  
Washington Department of Ecology  
3190 160th Avenue SE  
Bellevue, Washington 98008-5452

Report Submittal  
Independent Remedial Action  
GE Transport International Pool Facility  
9801 Martin Luther King Jr. Way South  
Seattle, Washington  
D&M Job No. 28171-391-122

Dear Ms. Atkinson:

On behalf of GE Transport International Pool (TIP), Dames & Moore is submitting two copies of the above referenced report for review under the Independent Remedial Action Program (IRAP). This report documents the results of an Independent Remedial Action of soil that were impacted by diesel fuel when a refrigeration unit tank was found to be leaking. This report is prepared in accordance with Washington Department of Ecology's (Ecology) "Guidance on Preparing Independent Remedial Action Cleanup Reports under MTCA" dated March 1, 1994.

The remedial action consisted of the excavation of soil with diesel concentrations exceeding the Model Toxics Control Act (MTCA) Method A cleanup level of 200 mg/kg and the treatment of affected soil at the permitted thermal desorption facility in Tacoma operated by TPS Technologies, Inc. Based on the results presented in this report, soil impacted by the diesel fuel release identified at the site have been removed and the MTCA Method A soil cleanup levels for TPH as diesel have been met.

The remedial action implemented is consistent with the Ecology document "Guidance for Remediation of Petroleum Contaminated Soils" (Document 91-30, revised April 1994) and is intended to allow GE TIP to obtain a determination of "No Further Action" from Ecology's Independent Remedial Action Program (IRAP). Consequently, we respectfully request on the behalf of GE Capital that Ecology issue a letter stating no further action is required at the facility.



Washington Dept. of Ecology  
GE TIP Facility  
June 10, 1996  
Page 2

Please contact me at (206) 728-0744 or Ms. Karen Kern, Manager of Environmental Programs with GE TIP at (610) 648-6764 if you require additional information or wish to discuss our report.

Sincerely,

**Dames & Moore, Inc.**

A handwritten signature in blue ink that reads "Julie K. Harvey".

Julie K. Harvey  
Project Manager

cc: Ms. Karen Kern (w/ report)  
Ms. Cloe Hutto (w/ report)

**TABLE OF CONTENTS**

	<b>Page</b>
EXECUTIVE SUMMARY .....	ES-1
1.0 INTRODUCTION AND SITE DESCRIPTION .....	1
1.1 SITE DESCRIPTION AND OPERATIONS .....	1
1.2 SITE TOPOGRAPHY AND SLOPE .....	1
1.3 GEOLOGY AND HYDROGEOLOGY .....	1
2.0 RELEASE INFORMATION .....	2
3.0 SOIL CHARACTERIZATION AND INDEPENDENT REMEDIAL ACTION .....	2
3.1 SELECTION OF CLEANUP STANDARDS .....	2
3.2 SOIL ASSESSMENT .....	3
3.3 REMEDIATION, CONFIRMATORY SAMPLING AND DISPOSAL/TREATMENT OF SOILS .....	3
4.0 CONCLUSIONS .....	4
5.0 REFERENCES .....	4

**LIST OF TABLES AND FIGURES**

**TABLES**

TABLE 1 - Soil Sample Analytical Results

**FIGURES**

Figure 1 - Site Location Map  
Figure 2 - Photographs  
Figure 3 - Site Plan and Soil Sample Locations

**APPENDICES**

Appendix A - Laboratory Analytical Reports and Chain-of-Custody Forms  
Appendix B - Soil Treatment Bills of Lading and Manifests  
Appendix C - IRAP Form

**INDEPENDENT REMEDIAL ACTION  
GE CAPITAL COMPANY, TRANSPORT INTERNATIONAL POOL, INC.  
9801 MARTIN LUTHER KING WAY SOUTH  
SEATTLE, WASHINGTON**

**EXECUTIVE SUMMARY**

This report documents the results of an Independent Remedial Action of soil containing petroleum hydrocarbons at the GE Capital Company, Transport International Pool, Inc. (TIP) facility located at 9801 Martin Luther King Junior Way South in Seattle, Washington. The property is owned by GE Capital Company, TIP. Approximately 80 feet by 45 feet surface area of soils were impacted by diesel fuel when a refrigeration unit tank was found to be leaking.

The remedial action consisted of the excavation of soil with diesel concentrations exceeding the MTCA Method A cleanup level of 200 mg/kg and the treatment of affected soil at the permitted thermal desorption facility in Tacoma operated by TPS Technologies, Inc. The remedial action implemented is consistent with the Washington Department of Ecology document "Guidance for Remediation of Petroleum Contaminated Soils" (Document 91-30, revised April 1994). Based on the results presented in this report, soil impacted by the diesel fuel release identified at the site have been removed and the remaining soils met the MTCA Method A soil cleanup levels for TPH as diesel.

## 1.0 INTRODUCTION AND SITE DESCRIPTION

Presented in this report are the results of the Independent Remedial Action of petroleum hydrocarbons in soil at the GE Capital Company, TIP facility located at 9801 Martin Luther King Way South in Seattle, Washington (Figure 1). The Independent Remedial Action was conducted at this facility to remove petroleum-affected soil that contained petroleum hydrocarbons concentrations above the appropriate Washington Model Toxics Control Act (MTCA) Method A cleanup levels (WAC 173-340). This remedial action consisted of the excavation and removal of soils containing petroleum hydrocarbons released during refueling of a parked refrigerated truck trailer. The petroleum hydrocarbon impacted soils were removed and treated off site at a permitted facility.

The scope of the Independent Remedial Action implemented at the facility was intended to be consistent with the MTCA and the Washington Department of Ecology (Ecology) guidance, including "Guidance for Remediation of Petroleum Contaminated Soils," (Ecology, 1994). This report was prepared in accordance with the Ecology draft guidance on "Preparing Independent Remedial Action Reports Under the Model Toxics Control Act, Chapter 70.105D RCW" (Publication No. 94-18, March 1, 1994). This report documents the remedial action, areas in which a remedial action occurred, affected media, laboratory results, and soil treatment.

### 1.1 SITE DESCRIPTION AND OPERATIONS

The subject property is located at 9801 Martin Luther King Way South in Seattle, Washington. A site map is presented in Figure 2. The property is currently used for staging truck trailers. The surrounding land use is predominately commercial and/or light industrial.

### 1.2 SITE TOPOGRAPHY AND SLOPE

The subject property is located in SE $\frac{1}{4}$ , NW $\frac{1}{4}$  Section 3, Township 23 North, Range 4 East with a latitude of approximately 47°31' and a longitude of approximately 122°17'. Topographic coverage of the site vicinity is provided by the U.S. Geological Survey, Seattle South, Washington, 7.5 minute quadrangle, dated 1983 (Figure 1). There is little topographic relief across the site. The elevation at the site is approximately 15 feet above Mean Sea Level.

### 1.3 GEOLOGY AND HYDROGEOLOGY

Geologic maps indicate the site vicinity is located in an area that has where extensive excavation, filling or construction has modified or obscured the original geology. The thickness of fill materials in the Duwamish River valley is typically 50 feet or greater and consists of sand, silt, clay and some gravel (Leisch, Price & Walters, 1963). Ground water in the Duwamish River valley is usually encountered at depths of 7 to 10 feet below ground surface. Based on topographic relief of the area, the overall direction

of movement of ground water in this portion of King County is probably to the west toward the Duwamish Waterway.

## **2.0 RELEASE INFORMATION**

There has been one known release at the site. Approximately 50 gallons of diesel fuel was released to the surface soils due to a crack in a fuel tank of a parked refrigerated truck trailer. Shallow surface staining was visible over an area of approximately 80 feet by 45 feet (3,600 square feet). Total depth of the impacted soil was approximately 6 inches. This remedial action consisted of the excavation and removal of petroleum-affected soils. Ground water was not encountered during the excavation.

## **3.0 SOIL CHARACTERIZATION AND INDEPENDENT REMEDIAL ACTION**

The scope of this soil characterization and independent remedial action was to remove soil containing TPH concentrations in exceedance of the applicable cleanup level. The scope of work implemented included:

- Collect one composited sample of the stained surface soils to characterize the impacted soils
- Removal of petroleum-affected soil to an offsite permitted facility for treatment by thermal desorption
- Collection of post-excavation confirmatory samples for chemical analysis to demonstrate that TPH concentrations in soil were below the MTCA Method A soil cleanup levels
- Backfilling the excavation and covering the area with gravel

Soil sampling, excavation, backfilling, and transport of removed materials to the selected treatment facility was conducted by Envirotech Systems, Inc. (Seattle, Washington) who was subcontracted to Clean Harbors Environmental Services, Inc. (Commerce, California) who was contracted directly to GE Capital. Clean Harbor's and Envirotech's work was monitored by a Dames & Moore geologist who field-screened the excavated soil, guided excavation, and selected post-excavation soil sample locations and observed post-excavation soil sample collection. Soils were transported to TSP, Inc. for treatment of the petroleum hydrocarbon contaminated soils by high temperature thermal treatment and asphalt incorporation at their Ecology-permitted facility in Tacoma, Washington.

### **3.1 SELECTION OF CLEANUP STANDARDS**

Since petroleum hydrocarbon as diesel was the only compound suspected at the site, the site was an appropriate candidate for a routine cleanup as defined in WAC 173-340-130. Therefore, Method A cleanup levels were selected for soil at the site as specified in WAC 173-340-740. The MTCA Method

A cleanup level for diesel and oil range hydrocarbons in soil is 200 mg/kg. The goal of the soil cleanup actions at the site was to remove soils containing hydrocarbon concentrations above the cleanup levels.

### 3.2 SOIL ASSESSMENT

On March 27, 1996, Envirotech Systems, Inc. collected a total of three surface soil samples from the visually stained area to provide a site-specific characterization of the spill. The three soil samples were combined into one composite sample (labeled 6-082-10-1). The location of the three soil samples is shown on Figure 2. The composite sample was submitted to On-Site Environmental, an Ecology-accredited laboratory for analysis of diesel range petroleum hydrocarbons by Washington method WTPH-D (extended). A concentration of 8,800 mg/kg of TPH as diesel (with TPH components in the carbon range from C6 to C20) was detected in the composite sample. The laboratory analytical reports including the sample chromatogram is presented in Appendix A.

### 3.3 REMEDIATION, CONFIRMATORY SAMPLING AND DISPOSAL/TREATMENT OF SOILS

Soils were Microtip photoionization detector (PID) field screened during the excavation process. Soils in the stained area were excavated until visual and PID screening did not indicate the presence of hydrocarbons. Soil in an area of approximately 80 feet by 45 feet was removed to depths ranging from 4 inches to 6 inches (Figure 3). Imported fill was encountered to the total depth of the excavation. Photographs of the excavation activities are provided in Figure 2.

Approximately 38 cubic yards of soils containing TPH as diesel at concentrations above 200 mg/kg were removed from the site on April 6, 1996 and transported to TSP, Inc. for treatment by high temperature thermal treatment and asphalt incorporation. Copies of the soil disposal/treatment weight manifests are presented in Appendix B.

Following soil removal, seven confirmatory soil samples were collected and submitted to On-Site Environmental for analysis of TPH as diesel (extended) in order to evaluate if the cleanup level was achieved. Soil samples were collected using dedicated sampling spoons directly into laboratory provided jars. Soils consisted of gravelly sand, however, pieces of asphaltic concrete were also present in the subsurface soils. Soil sample locations are shown on Figure 3.

The results of the confirmatory sampling and analyses are summarized in Table 1 and indicate that the cleanup level of 200 mg/kg was achieved at 6 of the 7 sample locations. TPH in the carbon range of C16 to C34 was detected in SS-2 through SS-5 and SS-7 at concentrations ranging from 32 mg/kg to 70 mg/kg which is below the cleanup level. At location SS-1, TPH was detected at a concentration of 390 mg/kg, however, the chromatogram for sample SS-1 indicates the carbon range of TPH components was from C16 to C34. TPH was not detected in soil sample SS-6. The carbon range found in confirmatory soil samples SS-1 through SS-7 is heavier than the site-specific diesel characterization sample (6-082-10-1) where TPH ranged from C6 to C20. The TPH detection in the confirmatory soil samples (SS-1 through SS-7) appears

to be attributed to the presence of asphalt rather than diesel associated with the spill. Therefore, the TPH concentration in SS-1 attributed to diesel is below the 200 mg/kg cleanup level. The laboratory analytical report including sample chromatograms is presented in Appendix A.

Following sampling, the excavations were backfilled with clean fill and compacted with the backhoe.

#### **4.0 CONCLUSIONS**

The Independent Remedial Action (IRA) associated with the removal of diesel affected soils at the Seattle GE TIP facility has been completed. Pursuant to the IRA program requirements, a copy of the IRA Report Summary Form is presented in Appendix C. Based on the results presented in this report, soil impacted by the diesel fuel release identified at the site have been removed and the remaining soils met the MTCA Method A soil cleanup levels for TPH as diesel.

#### **5.0 REFERENCES**


Washington Department of Ecology, 1994a, Draft Guidance on Preparing Independent Remedial Action Reports, Publication No. 94-18, March 1, 1994.

Washington Department of Ecology, 1994b, Guidance for Remediation of Petroleum Contaminated Soils, Publication No. 91-30, Revised April 1994.


Liesch, Pierce, and Walters, 1963, Geology and Ground-Water Resources of Northwestern King County, Water Supply Bulletin No. 20.

**TABLE 1  
SOIL SAMPLE ANALYTICAL RESULTS**

Soil Sample Number	TPH Analytical Result (WTPH-D extended) mg/kg	TPH Carbon Range Detected
<b>Site-Specific Characterization Sample</b>		
6-082-10-1	8,800	C6 to C20
<b>Post-Excavation Confirmatory Soil Samples</b>		
6-082-10-SS1 (SS-1)	390	C20 to C30
6-082-10-SS2 (SS-2)	33	C20 to C30
6-082-10-SS3 (SS-3)	32	C20 to C30
6-082-10-SS4 (SS-4)	70	C20 to C30
6-082-10-SS5 (SS-5)	63	C20 to C30
6-082-10-SS6 (SS-6)	< 25	Not Applicable
6-082-10-SS7 (SS-7)	52	C16 to C36+



**PROJECT SITE**



SOURCE: USGS 7.5-minute topographic map; Seattle South, Washington; dated 1983

**SITE LOCATION MAP**

Job No. 28171-391-122  
**DAMES & MOORE**

GE Transport International  
9801 Martin Luther King Way South, Seattle, Washington  
FIGURE 1




Diesel Spill Area Prior to Removal Action  
View to North (4/6/96)



Diese Spill Area Following Removal Action  
View to North (4/6/96)


## PHOTOGRAPHS

Job No. 28171-391-122



LEGEND


- ◆ Soil samples combined to make composite sample 6-082-10-1 for spill characterization
- ⊙ Confirmatory soil sample location and number (note sample number prefix is 6 -082-10)
- ▨ Approximate area of visual staining



**SITE PLAN AND SOIL SAMPLE LOCATIONS**

**APPENDIX A**

**LABORATORY ANALYTICAL REPORTS  
AND CHAIN-OF-CUSTODY FORMS**



April 1, 1996

Mike Jeffers  
Envirotech Systems, Inc.  
18820 Aurora Ave. No., Suite 201  
Seattle, WA 98133

Re: Analytical Data for Project 6-082-10  
Laboratory Reference No. 9603-095

Dear Mike:

Enclosed are the results of the analyses, and associated quality control data, of samples submitted on March 28, 1996.

The standard policy of OnSite Environmental Inc., is to store your samples for 30 days from the date of receipt. If you require longer storage, please contact the laboratory.

We appreciate the opportunity to be of service to you on this project. If you have any questions concerning the data, or need additional information, please feel free to call me.

Sincerely,

A handwritten signature in black ink, appearing to read 'D. Baumeister'.

David Baumeister  
Project Chemist

Enclosures

Date of Report: April 1, 1996  
Samples Submitted: March 28, 1996  
Lab Traveler: 03-095  
Project: 6-082-10

**WTPH-D (extended)**

Date Extracted: 3-28-96  
Date Analyzed: 3-28-96

Matrix: Soil  
Units: mg/Kg (ppm)

Client ID	Lab ID	Dilution Factor	Total Petroleum Hydrocarbons	Surrogate Recovery*	Flags	MRL
6-082-10-1	03-095-1	50	8800	---	S,L	1250

\*o-Terphenyl

S - Surrogate recovery data not available due to the necessary dilution of the sample.

L - Quantitated from C7-C34 as diesel fuel #2.

Date of Report: April 1, 1996  
Samples Submitted: March 28, 1996  
Lab Traveler: 03-095  
Project: 6-082-10

**WTPH-D  
METHOD BLANK QUALITY CONTROL**

Date Extracted: 3-28-96  
Date Analyzed: 3-28-96

Matrix: Soil  
Units: mg/Kg (ppm)

Lab ID: MB0328S1

	Dilution Factor.	Total Petroleum Hydrocarbons	Surrogate Recovery*	Flags	MRL
Method Blank	1.0	ND	103%	L	25

\* o-Terphenyl  
L - Quantitated from C7-C34 as diesel fuel #2.

Date of Report: April 1, 1996  
Samples Submitted: March 28, 1996  
Lab Traveler: 03-095  
Project: 6-082-10

WTPH-D  
DUPLICATE QUALITY CONTROL

Date Extracted: 3-28-96  
Date Analyzed: 3-28-96

Matrix: Soil  
Units: mg/Kg (ppm)

Lab ID: 03-095-1

	Dilution Factor	Total Petroleum Hydrocarbons	Surrogate Recovery*	Flags	MRL
Sample	50	8150	---	S	1250
Duplicate	50	9630	---	S	1250
RPD		17%			

\* o-Terphenyl

S - Surrogate recovery data not available due to the necessary dilution of the sample.

Date of Report: April 1, 1996  
Samples Submitted: March 28, 1996  
Lab Traveler: 03-095  
Project: 6-082-10

**WTPH-D  
SPIKE BLANK QUALITY CONTROL**

Date Extracted: 3-28-96  
Date Analyzed: 3-28-96

Matrix: Soil  
Units: mg/Kg (ppm)

Lab ID: SB0328S1

	Dilution Factor	Total Petroleum Hydrocarbons	Percent Recovery	Surrogate Recovery*	Flags	MRL
Spike Blank @ 100 ppm	1.0	104	104%	123%		25

\* o-Terphenyl


Date of Report: April 1, 1996  
Samples Submitted: March 28, 1996  
Lab Traveler: 03-095  
Project: 6-082-10

Date Analyzed: 3-28-96

**% MOISTURE**

Client ID	% Moisture
6-082-10-1	10

File=C:\CP\DATA\032801.10R Sample name=03-095-1 1:50 Date printed= 03-29-1996 Time= 09:27:05  
0.00 to 36.00 min. Low Y = 0.32807 mv High Y = 1.32807 mv Span = 1.00000 mv



# CHAIN OF CUSTODY RECORD & LABORATORY ANALYSIS REQUEST

*DAB*

**ENVIROTECH SYSTEMS, INC.**

18820 AURORA AVE NO., STE 201, SEATTLE, WA 98133  
206-363-9000 FAX 206-546-1920

Project: 6-082-10 Assigned Lab ID: 03-095 Date: 3-28-96 # of Coolers: 1 Page 1 of 1

Client Contact: MIKE JEFFERS / LARRY CAMPBELL Analysis Requested Other

Phone: (206) 363-9000

Samplers: LARRY CAMPBELL

Sample ID	Date	Time	Matrix	# Cont	Lab ID	WTP#-D EXTENDED														
6-082-10-1	3-28	12:45	SOIL	1	1	X														

Comments/Special Instructions:  
ABOVE SAMPLE 1 SA  
COMPOSITE OF 3  
SAMPLES

Relinquished by (Signature):  
Larry Campbell

Printed Name:  
LARRY CAMPBELL

Company:  
ESI

Date: 3-28-96 Time:

Relinquished by (Signature):  
REC'D Teresa Hanson

Printed Name:  
Teresa Hanson

Company:  
ESI

Date: 3/28/96 Time: 2:50

Relinquished by (Signature):

Printed Name:

Company:

Date: Time

Relinquished by (Signature):

Printed Name:

Company:

Date: Time

Relinquished by (Signature):

Printed Name:

Company:


Date: Time

Relinquished by (Signature):

Printed Name:

Company:

Date: Time



April 15, 1996

Larry Campbell  
Envirotech Systems, Inc.  
18820 Aurora Ave. No., Suite 201  
Seattle, WA 98133

Re: Analytical Data for Project GE/TIP  
Laboratory Reference No. 9604-023

Dear Larry:

Enclosed are the results of the analyses, and associated quality control data, of samples submitted on April 8, 1996.

The standard policy of OnSite Environmental Inc., is to store your samples for 30 days from the date of receipt. If you require longer storage, please contact the laboratory.

We appreciate the opportunity to be of service to you on this project. If you have any questions concerning the data, or need additional information, please feel free to call me.

Sincerely,

A handwritten signature in black ink, appearing to read 'D. Baumeister'.

David Baumeister  
Project Chemist

Enclosures

Date of Report: April 15, 1996  
Samples Submitted: April 8, 1996  
Lab Traveler: 04-023  
Project: GE/TIP

WTPH-D (extended)

Date Extracted: 4-08-96  
Date Analyzed: 04-8&9-96

Matrix: Soil  
Units: mg/Kg (ppm)

Client ID	Lab ID	Dilution Factor	Total Petroleum Hydrocarbons	Surrogate Recovery*	Flags	MRL
6-082-10-SS1	04-023-1	1.0	390	101%	L	25
6-082-10-SS2	04-023-2	1.0	33	126%	L	25
6-082-10-SS3	04-023-3	1.0	32	111%	L	25
6-082-10-SS4	04-023-4	1.0	70	118%	L	25
6-082-10-SS5	04-023-5	1.0	63	96%	L	25
6-082-10-SS6	04-023-6	1.0	ND	124%	L	25
6-082-10-SS7	04-023-7	1.0	52	104%	L	25

\* o-Terphenyl  
L - Quantitated from C7-C34 as diesel fuel #2.

Date of Report: April 15, 1996  
Samples Submitted: April 8, 1996  
Lab Traveler: 04-023  
Project: GE/TIP

**WTPH-D  
METHOD BLANK QUALITY CONTROL**

Date Extracted: 4-08-96  
Date Analyzed: 4-08-96

Matrix: Soil  
Units: mg/Kg (ppm)

Lab ID: MB0408S1

	Dilution Factor	Total Petroleum Hydrocarbons	Surrogate Recovery*	Flags	MRL
Method Blank	1.0	ND	98%	L	25

\* o-Terphenyl  
L - Quantitated from C7-C34 as diesel fuel #2.

Date of Report: April 15, 1996  
Samples Submitted: April 8, 1996  
Lab Traveler: 04-023  
Project: GE/TIP

WTPH-D  
DUPLICATE QUALITY CONTROL

Date Extracted: 4-08-96  
Date Analyzed: 4-08-96

Matrix: Soil  
Units: mg/Kg (ppm)

Lab ID: 04-020-4

	Dilution Factor	Total Petroleum Hydrocarbons	Surrogate Recovery*	Flags	MRL
Sample	1.0	ND	108%		25
Duplicate	1.0	ND	112%		25
RPD		NA			

\* o-Terphenyl

Date of Report: April 15, 1996  
Samples Submitted: April 8, 1996  
Lab Traveler: 04-023  
Project: GE/TIP

WTPH-D  
SPIKE BLANK QUALITY CONTROL

Date Extracted: 4-08-96  
Date Analyzed: 4-08-96

Matrix: Soil  
Units: mg/Kg (ppm)

Lab ID: SB0408S1

	Dilution Factor	Total Petroleum Hydrocarbons	Percent Recovery	Surrogate Recovery*	Flags	MRL
Spike Blank @ 100 ppm	1.0	88.6	89%	109%		25
Spike Blank Duplicate	1.0	93.3	93%	112%		25
RPD		5.2%				


\*o-Terphenyl

Date of Report: April 15, 1996  
Samples Submitted: April 8, 1996  
Lab Traveler: 04-023  
Project: GE/TIP

Date Analyzed: 4-8-96


**% MOISTURE**

Client ID	% Moisture
6-082-10-SS1	12
6-082-10-SS2	11
6-082-10-SS3	12
6-082-10-SS4	11
6-082-10-SS5	11
6-082-10-SS6	12
6-082-10-SS7	4.0




SAMPLE: 6-082-10-SS1  
METHOD: WTPH-D (extended)


0.00 to 36.00 min. Low Y = 0.64986 mv High Y = 1.64986 mv Span = 1.00000 mv




SAMPLE: 6-082-10-SS2  
METHOD: WTPH-D (extended)



SAMPLE: 6-082-10-SS3  
METHOD: WTPH-D (extended)




SAMPLE: 6-082-10-SS4  
METHOD: WTPH-D (extended)




SAMPLE: 6-082-10-SS5  
METHOD: WTPH-D (extended)

0.00 to 36.00 min. Low Y = 0.64945 mv High Y = 1.64945 mv Span = 1.00000 mv



SAMPLE: 6-082-10-SS6  
METHOD: WTPH-D (extended)



SAMPLE: 6-082-10-SS7  
METHOD: WTPH-D (extended)

# CHAIN OF CUSTODY RECORD & LABORATORY ANALYSIS REQUEST

DAB

ENVIROTECH SYSTEMS, INC.

18820 AURORA AVE NO., STE 201, SEATTLE, WA 98133

206-363-9000 FAX 206-546-1920

Project: GE/TIP Assigned Lab ID: 04-023 Date: 4-6-96 # of Coolers: 1 Page      of     

Client Contact: <u>LARRY CAMPBELL</u>						Analysis Requested								Other	
Phone: <u>(206) 363-9000</u>						WTPH-D EXTENDED									
Samplers: <u>LARRY CAMPBELL</u>															
Sample ID	Date	Time	Matrix	# Cont	Lab ID										
<u>1</u> 6-082-10-551	<u>4-6-96</u>	<u>9:55</u>	<u>SOIL</u>	<u>1</u>		<u>X</u>								<u>(X)</u>	
<u>2</u> 6-082-10-552	<u>↓</u>	<u>10:00</u>	<u>↓</u>	<u>↓</u>		<u>X</u>								<u>(X)</u>	
<u>3</u> 6-082-10-553	<u>↓</u>	<u>10:04</u>	<u>↓</u>	<u>↓</u>		<u>X</u>								<u>(X)</u>	
<u>4</u> 6-082-10-554	<u>↓</u>	<u>10:10</u>	<u>↓</u>	<u>↓</u>		<u>X</u>								<u>(X)</u>	
<u>5</u> 6-082-10-555	<u>↓</u>	<u>10:16</u>	<u>↓</u>	<u>↓</u>		<u>X</u>								<u>(X)</u>	
<u>6</u> 6-082-10-556	<u>↓</u>	<u>10:20</u>	<u>↓</u>	<u>↓</u>		<u>X</u>								<u>(X)</u>	
<u>7</u> 6-082-10-557	<u>↓</u>	<u>10:24</u>	<u>↓</u>	<u>↓</u>		<u>X</u>								<u>(X)</u>	

Comments/Special Instructions: <u>PLEASE PROVIDE ASSOCIATED CHROMATOGRAMS</u>	Relinquished by (Signature): <u>Larry Campbell</u>	Relinquished by (Signature):	Relinquished by (Signature):
	Printed Name: <u>LARRY CAMPBELL</u>	Printed Name:	Printed Name:
	Company: <u>ESI</u>	Company:	Company:
	Date: <u>4/8/96</u> Time: <u>2:55 pm</u>	Date:                      Time	Date:                      Time
	Relinquished by (Signature): <u>Chris Ransom</u>	Relinquished by (Signature):	Relinquished by (Signature):
	Printed Name: <u>CHRIS RANSOM</u>	Printed Name:	Printed Name:
Company: <u>OSE</u>	Company:	Company:	
Date: <u>4/8/96</u> Time: <u>2:55 pm</u>	Date:                      Time	Date:                      Time	

**APPENDIX B**


**SOIL TREATMENT BILLS OF LADING AND MANIFESTS**

# Soil Recycling Certificate

TPS Technologies Inc. does hereby certify  
that 37.39 tons of petroleum - contaminated soil  
received from

GE Capital/TIP  
Envirotech Systems Inc. - Consultant  
9801 Martin Luther King Way  
Seattle, WA

Under Manifest/authorization number 03-00670  
have been properly recycled to approved regulatory standards  
at our Soil Recycling Facility in Tacoma, WA



Dated this 16th day of April, 1996

Sworn and Attested by:  
TPS Technologies Inc.

By: \_\_\_\_\_

*Jay M. Holt*

108760

# Manifest

## TPS Technologies Soil Recycling Non-Hazardous Soils

Manifest #

Date of Shipment: --	Responsible for Payment: CONSULTANT	Transporter Truck #:	Facility #: 103	Given by TPS: 00670	Load #: 201
-------------------------	--	----------------------	--------------------	------------------------	----------------

Generator's Name and Billing Address: G.E. CAPITAL/TIP 9801 MARTIN LUTHER KING WAY SEATTLE, WA 98118	Generator's Phone #: 206/725-6004	Generator's US EPA ID No.
	Person to Contact: DAVE DURON	
	FAX #: 206/725-0195	Customer Account Number with TPS:

Consultant's Name and Billing Address: ENVIROTECH SYSTEMS INC. 18820 AURORA AVE. NO.-SUITE 201 SHORELINE, WA 98133	Consultant's Phone #: 206/363-9000	
	Person to Contact: LARRY CAMPBELL	
	FAX #: 206/546-1920	Customer Account Number with TPS: 1001480

Generation Site (Transport from): (name & address) G.E. CAPITAL/TIP 9801 MARTIN LUTHER KING WAY SEATTLE, WA 98118	Site Phone #: 206/725-6004	BTEX Levels
	Person to Contact: DAVE DURON	TPH Levels
	FAX #: 206/725-0195	AVG. Levels

Designated Facility (Transport to): (name & address) TPS TECHNOLOGIES INC. 2800 104th STREET SOUTH TACOMA, WA 98444	Facility Phone #: 206/584-8430	Facility Permit Numbers
	Person to Contact: RENEE AVELINO	
	FAX #: 206/584-8309	

Transporter Name and Mailing Address: JACK GREY TRANSPORT, INC. 500 SO. 336th STREET-SUITE 102 FEDERAL WAY, WA 98003	Transporter's Phone #: 206/874-9848	Transporter's US EPA ID No.:
	Person to Contact: DOUG DeVRIES	Transporter's DOT No.:
	FAX #: 206/874-9820	Customer Account Number with TPS:

Description of Soil	Moisture Content	Contaminated by:	Approx. Qty:	Description of Delivery	Gross Weight	Tare Weight	Net Weight
Sand <input type="checkbox"/> Organic <input type="checkbox"/> Clay <input type="checkbox"/> Other <input type="checkbox"/>	0 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> 20% - over <input type="checkbox"/>	Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other <input type="checkbox"/>			108760	33980	74780
Sand <input type="checkbox"/> Organic <input type="checkbox"/> Clay <input type="checkbox"/> Other <input type="checkbox"/>	0 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> 20% - over <input type="checkbox"/>	Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other <input type="checkbox"/>			37.39		

List any exception to items listed above:

Generator's and/or consultant's certification: I/We certify that the soil referenced herein is taken entirely from those soils described in the Soil Data Sheet completed and certified by me/us for the Generation Site shown above and nothing has been added or done to such soil that would alter it in any way.

Print or Type Name: <i>Larry Campbell</i>	Generator <input type="checkbox"/> Consultant <input checked="" type="checkbox"/>	Signature and date:	Month Day Year 4   4   96
--	---	---------------------	------------------------------

Transporter's certification: I/We acknowledge receipt of the soil described above and certify that such soil is being delivered in exactly the same condition as when received. I/We further certify that this soil is being directly transported from the Generation Site to the Designated Facility without off-loading, adding to, subtracting from or in any way delaying delivery to such site.

Print or Type Name: <i>CR Dodge</i>	Signature and date:	Month Day Year 10   8   96
--	---------------------	-------------------------------

Discrepancies:

Recycling Facility certifies the receipt of the soil covered by this manifest except as noted above:

Print or Type Name: Renee Avelino - CSM	Signature and date:
--	---------------------

Generator and/or Consultant

Transporter

Recycling Facility



# Woodworth & Company, Inc.

## GENERAL CONTRACTORS

1200 East D Street / Tacoma, Washington 98421

Telephone (206) 383-3585

PO # 08259 LAKEVIEW PIT TICKET

Contractors Lic. # WOODW 377NO



Ticket # 88811  
Wmaster PEGGY NEFF  
Sale Loc.  
Saletype C JOB SALE

**CAUTION: HOT ASPHALT WILL BURN YOU!**

RECEIVED \*


CUSTOMER:		PURCHASE ORDER:				JOB LOAD		JOB TONS	
		TPS TECHNOLOGIES CONTAMINATED SOILS BROUGHT INTO LAKEVIEW PIT.				TOTAL 1		37.39	
						DAILY			

DATE	PLANT	SILO#	JOB	PLANT	TRUCK	SEQUENCE	REFEREN
04/08/96			62-		DD1		
TIME	08:25:						

MIXTURE	GROSS	TARE	NET WT. TONS	PRICE	TOTAL
200 PETRO CONTAM SOIL	108760	33980	37.39		

SPECIAL INSTRUCTIONS		74780 LB M		TAX % PAY THIS AMOUNT	
SCALE SERVICE					

CUBIC YDS	REMARKS	SCALE OPERATOR
	PIT B160	X [Signature]



**APPENDIX C**

**IRAP FORM**



# Independent Remedial Action Report Summary

This report summary is an important part of the Independent Remedial Action Report. Please complete the summary and submit it with your Independent Remedial Action Report. If this document does not accompany your cleanup report, or if it is not fully completed, your report cannot enter the review process necessary for Ecology to provide you with a "no further action" determination, or to remove your site from the hazardous sites lists.

FOR ECOLOGY USE ONLY			
ERTS No.	TCP ID No.	Date Received	<input type="checkbox"/> NEA <input type="checkbox"/> SHA Referral <input type="checkbox"/> Interim Action <input type="checkbox"/> Emergency Action
LUST No.	U.B.L. No.	Initial Investigation (Date)	
Reviewed by	Total Hours for Review		
Does the cleanup comply with cleanup standards? Yes <input type="checkbox"/> No <input type="checkbox"/>		Total fee:	

Please Print Clearly or Type

## General Information

Name of Site Owner GE Capital Company, Transport International Pool	Phone (610) 648-6764
Address 426 W. Lancaster Avenue, Devon, PA 19333-0950 <small style="display: flex; justify-content: space-between; font-size: small;">Street State/Province Zip County</small>	
Authorized Contact Ms. Karen Kern, Manager, Environmental Programs	Phone (610) 648-6764
Name of Facility Operator GE Transport International Pool	Phone (206) 725-6004
Address 9801 Martin Luther King Jr. Way S., Seattle, WA 98118 <small style="display: flex; justify-content: space-between; font-size: small;">Street State Zip</small>	
Authorized Contact Karen Kern, Manager Environmental Programs	Phone (610) 648-6764
Name of Consultant Julie K. Harvey	Phone (206) 728-0744
Name of Firm Dames & Moore, Inc.	
Address 2025 First Avenue, Suite 500 Seattle, WA 98121 <small style="display: flex; justify-content: space-between; font-size: small;">Street State Zip</small>	
Please indicate which of the above persons completed this report. If the report was completed by someone other than listed above, please provide their name, address, and a daytime phone. <div style="text-align: center; margin-top: 5px;">Dames &amp; Moore</div>	

## Report Information

Has a cleanup been conducted? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Is this a Leaking Underground Storage Tank (LUST) report? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Type of report (check all that apply) <input type="checkbox"/> Combined release and independent remedial action report <input checked="" type="checkbox"/> Independent remedial action report  <input type="checkbox"/> Interim action report <input type="checkbox"/> Final cleanup action report	Date release was reported to Ecology  June 5, 1996
	Date cleanup was completed  April 6, 1996

# Facility Information

Site Name **GE Transport International Pool**

Other Names (the site may be known as) **T.I.P.**

Site Control Person if other than Owner/Operator. (This must be a person who is on-site during normal working hours and is authorized and qualified to answer questions about the site, or a person who is available during normal business hours and has knowledge about the site and the remediation.)

Name **Karen Kern, Manager, Environmental Programs** Phone **(610) 648-6764**

Site Mailing Address (or site contact mailing address)

**426 W. Lancaster Avenue, Devon, PA 19333**

Site Location Address (including zip code)

**9801 Martin Luther King Jr. Way South, Seattle, WA, 98118**

Closest City	County (where site is located)
<b>Seattle, WA</b>	<b>King</b>

Ownership and Operator Type. Complete the table below by checking the appropriate box to identify the type of owner and operator for the facility. (For example, if the property owner is a port district and the operator a private individual, then check the boxes under owner identification column in the municipal, code #2 row, and under the operator identification column in the private party, code #1 row.)

Ownership/Operator Type	Code #	Owner Identification	Operator Identification
Private Party	1	X	X
Municipal (Public)	2		
County	3		
Federal	4		
State	5		
Tribal	6		
Mixed	7		
Other	8		
Unknown	9		
Public Entity Acquisition through Bankruptcy	10		
Financial Institution Acquisition through Bankruptcy	11		

Standard Industrial Classification (SIC) Codes. List all that apply. If none apply, or if you don't know your SIC code, list activities conducted at the site, e.g., automotive repair and maintenance, construction equipment storage, etc.

**7513**

Hazardous Substances Management Practices(s). The hazardous substance(s) cleaned up from the site was the result of which of the following sources, activities, or actions? Please circle all that apply to the facility.

1 = Drug Lab	7 = Pesticide Application
2 = Drift	8 = Pesticide Disposal
3 = A Leaking Impoundment	<b>9 = A Spill</b>
4 = Improper Handling	10 = Storm Drain
5 = Landfill	11 = Leaking Tank: (a) below ground; (b) above ground
6 = Land Application	12 = Unknown

End use of property (circle one) **COMMERCIAL** INDUSTRIAL RESIDENTIAL

### Release Information

Date of Release (if known) December 20, 1995	Date of Discovery December 20, 1995	Are there any drinking water systems affected? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown <input type="checkbox"/>				
If drinking water systems are affected, are the systems public, private, or both? (circle one) <i>N/A</i>		If drinking water systems are affected, has alternate drinking water been provided? Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown <input type="checkbox"/> <i>N/A</i>				
General Hazardous Substance Categories. Using the contaminants listed below, complete the table. (A more detailed description of the contaminants can be found in Appendix C of the guidance.)						
Contaminants. For each of the applicable contaminants, enter the appropriate letter designating the status of the contaminants: C = Confirmed or S = Suspended. (Contaminant status definitions are defined in Appendix C of the guidance.)		Affected Media				
		Ground Water	Surface Water	Drinking Water	Soil	Air
1.	Halogenated Organic Compounds					
2.	Metals - Priority Pollutants					
3.	Metals - Other					
4.	Polychlorinated Bi-Phenyls (PCBs)					
5.	Pesticides/Herbicides					
6.	Unleaded Gas					
	Leaded Gas					
	Diesel				X	
	Waste Oil					
	Heat Fuel					
	Other (Specify)					
7.	Phenolic Compounds					
8.	Non-Halogenated Solvents					
9.	Dioxins					
10.	Polynuclear Aromatic Hydrocarbons (PAHs)					
11.	Reactive Wastes					
12.	Corrosive Wastes					
13.	Radioactive Wastes					
14.	Conventional Contaminants Organics					
15.	Conventional Contaminants Inorganics					
16.	Base/Neutral Organic Compounds					
17.	Asbestos					

### Cleanup Information

Indicate cleanup level methods used by completing Table 5-A below. (check all that apply)

	Soil	Ground Water	Air	Surface Water
Method A - diesel	X			
B				
C				
Have these levels been met throughout the site? (circle only one)	<input checked="" type="radio"/> YES <input type="radio"/> NO	<input type="radio"/> YES <input type="radio"/> NO	<input type="radio"/> YES <input type="radio"/> NO	<input type="radio"/> YES <input type="radio"/> NO

Indicate the treatment methods used by completing Tables 5B - 5D below (check all that apply) (See Appendix D)

	Destruction or Detoxification				Media Transfer		
	Carbon Adsorption <sup>1</sup>	Biological Treatment	Chemical Destruction	Incineration	Air Stripping/ Air Sparging	Aeration/Vapor Extraction	Thermal Desorption
Soil	-NA-				-NA-		X
Ground Water				-NA-		-NA-	-NA-
Surface Water				-NA-		-NA-	-NA-
Air		-NA-				-NA-	
Wastes	-NA-				-NA-		-NA-

<sup>1</sup> Carbon followed by regeneration; use of granular activated carbon followed by landfilling would be classified in these tables as volume reduction and off-site landfill

Cleanup Information (continued)

**TABLE 5-C**

	Immobilization		Reuse/Recycling <sup>2</sup>	Separation/Volume Reduction		
	Vitrification	Solidification/ Stabilization	Specify	Solvent Extraction	Soil Washing	Physical Separation <sup>3</sup>
Soil						
Ground Water	-NA-	-NA-		-NA-	-NA-	
Surface Water	-NA-	-NA-		-NA-	-NA-	
Wastes						

<sup>2</sup>For example, reuse of free petroleum product recovered in a pump and treat system.  
<sup>3</sup>For example, oil/water separators.

**TABLE 5-D**

	Land Disposal/Containment		Institutional Controls	Others
	Containment or On-site Landfill	Off-site Landfill	Specify	Specify treatment method
Soil				
Ground Water		-NA-		
Surface Water	-NA-	-NA-		
Wastes				

**Lust Site Information**

Was free product encountered: on ground water? Yes  No  In excavation? Yes  No

Tank Description			Tank Status (Y or N)		
Tank ID	Product	Size	In Place?	Removed?	Closed in Place?

**Environmental Indicators**

Answer the following questions as they are applicable to your site:

How many cubic yards of soil have been treated? 39      Where soil treatment was conducted, was it done on-site, off-site, or both?  
 (circle one)

Provide the name and address of the facility where soil was treated off-site.  
 Name: TPS Technologies, Inc.  
 Address: 2800 104th Street South  
 State/Zip: Tacoma, WA 98444

Provide the name and address of the facility where soil was disposed.  
 Name: \_\_\_\_\_  
 Address: \_\_\_\_\_  
 State/Zip: \_\_\_\_\_

How many cubic yards of soil have been disposed of off-site? 0  
 (Calculate these quantities of soil while the soil is in place, prior to any excavation and/or treatment.)

If ground water pump and treatment was conducted, how many gallons of ground water have been treated to date? \_\_\_\_\_ gallons N/A

How many years is the ground water extraction system expected to continue in operation? \_\_\_\_\_ years N/A

**Corrective Actions for Dangerous Waste Facilities**

Does the facility have a dangerous waste identification number?  Yes. Specify \_\_\_\_\_  No

Is the facility a dangerous waste treatment, sludge, or disposal facility?  Yes  No

If yes, check appropriate regulatory status box

RCRA interim status  
 RCRA operating permit  
 RCRA post closure permit  
 Other, specify \_\_\_\_\_