



WA LEAK TESTING CHECKLIST FOR UNDERGROUND STORAGE TANKS (USTS)

UST ID #: 7691
County: King

This checklist certifies testing activities conducted in accordance with
Chapter 173-360A WAC. Read instructions on pages 4-7.

| | | |
|--|---|---|
| <input checked="" type="checkbox"/> PASS - All Section VI services performed have passing results. | | DATE TESTS CONDUCTED: 12/03/2020 |
| <input type="checkbox"/> FAIL - One or more components tested in Section VI require repair and re-testing. | | |
| I. UST FACILITY | | II. CERTIFIED SERVICE PROVIDER |
| Facility Compliance Tag #: A0500 | | Service Provider Name: Chris Kuykendall |
| UST ID #: 7691 | | Company Name: Northwest Tank & Environmental Services, Inc. |
| Site Name: 627 | | Address: 17407 59th Ave SE |
| Site Address: 15 East Sunset Way | | City: Snohomish State: WA Zip: 98296 |
| City: Issaquah | | Phone: (800) 742-9620 Email: info@nwtank.com |
| County: King | | ICC Certification Type: Tightness Testing ICBO- U3 |
| Site Phone: 425-427-2744 | | ICC Cert. #: 383722020-U3 Exp. Date: 10/17/2022 |
| III. UST OWNER/OPERATOR | | |
| Name: Jacksons Food Stores Phone: 208-888-6061 Email: richard.wright@jacksonsfoodstores.com | | |
| IV. UST SYSTEM INFORMATION Observations on test day. | | |
| 1. Tank ID #, as registered with Ecology or identified on AT G | 1 | 2 |
| 2. Tank Status. OP (Operational); TC (Temporary Closure) | OP | OP |
| 3. Product stored, including % of alternative fuels | Premium | Regular |
| 4. Tank or compartment capacity (gallons) | 12000 | 20000 |
| 5. Product pumping/flow method. Note as: P (Pressurized); NS (Non-safe Suction); SS (Safe Suction); Si (Siphon); GR (Gravity Fed) | Pressure | Pressure |
| Abbreviations for lines 5 and 6 below: Steel (ST); Fiberglass (FRP); Clad Steel (CLAD); Flexible (FLEX); Double Wall (DW); Single Wall (SW); Not Visible (NV) | | |
| 6. Tank material and construction observed | FRP | FRP |
| 7. Pipe material and construction observed | FRP | FRP |
| V. REASON FOR SERVICES PERFORMED (Check all that apply) | | |
| <input checked="" type="checkbox"/> Annual testing <input type="checkbox"/> 3-year testing | <input type="checkbox"/> Test after install/repair <input type="checkbox"/> Return UST system to operation | <input type="checkbox"/> Other (explain): |

| VI. SERVICES PERFORMED | | | |
|---|--|-------|--|
| Required: Include verification for each test performed. | | | |
| | #PASS | #FAIL | # REPAIRED & PASSING |
| SERVICES: | DESCRIPTIONS REQUIRED: (SEE INSTRUCTIONS P. 4-7) | | |
| ALLD Test (attach data) Test method used: LDT 890 Test method cert.exp.date: 10/24/2022 2 | 2 | | |
| Line Tightness Test (attach data) Test method used: Acurite Test method cert.exp.date: 10/24/2022 2 | 2 | | |
| Electronic Monitoring System Tests Controller.mfr/model: V-R TLS 350 Controller cert.exp.date: 7/23/2022 Monitor/controller 1 Probe 2 Sump Sensor Functionality 7 Tank Annular Sensor Functionality 2 | | | . RP 1200 Replaced and Retested Regular Fill sump VR 352 sensor with passing results |
| Overfill Equipment Test <input type="checkbox"/> Auto shutoff <input type="checkbox"/> Ball float valve <input checked="" type="checkbox"/> Overfill alarm 1 | | | |
| Fill/Spill Bucket Test (attach data) | | | |
| Tank-Top or Transition Sump Test (attach data) | | | |
| UDC Sump Test (attach data) | | | |
| Tank Tightness Test (attach data) 3rd-party certified test: Test method used: N/A Test method cert.exp.date: | | | |
| Other | | | |

| VII. EXPLANATIONS/PROBLEMS ENCOUNTERED: | |
|---|--|
| Provide additional test information. Explain irregularities. Describe problems encountered and how addressed.. | |
| Leak Detector: Comments - Tied in and tested from impacts in Disp 7/8. Upon tying in to Regular impact there was high bleedback (2400 ml). Replaced the siphon jet and pumped from each dispenser to purge air from the line. Both ALLD's passed the 3 GPH test in accordance with CFR 40 part 280.44. Line Test: Comments - Tied in and tested from impacts in Disp 7/8. Both lines passed the 0.01 GPH test in accordance with CFR 40 part 280.44. Tank Monitor: | |

--Tank_monitors--

#1: TLS 350 was tested per RP 1200 standards.

Backup battery was measured at 3.6v

Upon review of the setup, found Premium tank programmed for 4" floats. T1 Premium probe has 2" floats installed. Corrected setup to reflect equipment installed.

L5 Regular fill sump VR 352 sensor failed to alarm when tested. Replaced with a VR 352 SN: 444325. New sensor was tested with passing results.

Found L1 Premium STP sump sensor in liquid alarm on arrival. Premium STP sump has a large amount of water in it. Notified manager to have site maintenance to have the water removed.


Probes were removed and tested for High product, overfill, high water alarm and high water warning.

2- VR 352 Fill sump sensors, 2- VR 352 STP sump sensors, 4- VR 208 UDC sensors, and 2- VR 303 annular sensors were tested and confirmed operational to manufacturer specifications.

VR001 High level alarm was functionally tested to RP 1200 standards, by raising the product floats to 90% capacity, and was confirmed operational.

VIII. UST SITE AND SYSTEM DIAGRAM

Diagram required. Include North arrow.



PERSONS SUBMITTING FALSE INFORMATION ARE SUBJECT TO FORMAL ENFORCEMENT AND /OR PENALTIES UNDER CHAPTER 173-360A WAC.

IX. FINAL CHECK

Mark the following:

YES NO N/A

1. All checked services tested per recommended practices, code and/or manufacturer's requirements, and in accordance with state regulations.



2. Owner/operator provided with copy of the checklist and testing results.



3. Any faulty equipment or necessary repairs explained to owner/operator or site contact.



X. REQUIRED SIGNATURES

12/03/2020

Chris Kuykendall

Chris Kuykendall - Tech

Date

Signature of Certified Service Provider

Print or Type Name

12/04/2020

Andrew Marvin

Andrew Marvin

Date

Signature of Tank Owner or Authorized Representative

Print or Type Name

Monitoring System Certification

This form must be used to document testing and servicing of monitoring equipment. A separate certification or report must be prepared for each monitoring system control panel by the technician who performs the work. A copy of this form must be provided to the tank system owner/operator. The owner/operator must submit a copy of this form to the local agency regulating UST systems within 30 days of test date.

A. General Information

Facility Contact Person: Andrew Marvin

Make / Model Monitoring System: V-R TLS 350

Company Name: Jacksons Food Stores

Site Address: 15 East Sunset Way

UST Site ID: 7691

Date Of Testing: 12/03/2020

Site Name: 627

City, State, ZIP: Issaquah, WA 98027

Facility Phone Number: 425-427-2744

Serial #: 40321219805002

B. Inventory of Equipment Tested/Certified

| Tank #: 1 Premium | | Tank #: 2 Regular | |
|------------------------------------|-------------|------------------------------------|-------------|
| In-Tank Gauging Probe | Mag 1 Probe | In-Tank Gauging Probe | Mag 1 Probe |
| Annular Space or Vault Sensor: | 794380-303 | Annular Space or Vault Sensor: | 794380-303 |
| Piping Sump / Trench Sensor: | 794380-352 | Piping Sump / Trench Sensor: | 794380-352 |
| Fill Sump Sensor: | 794380-352 | Fill Sump Sensor: | 794380-352 |
| Mechanical Line Leak Detector: | N/A | Mechanical Line Leak Detector: | N/A |
| Electronic Line Leak Detector: | 8484 | Electronic Line Leak Detector: | 8484 |
| Tank Overfill / High Level Sensor: | HLA/DTFV | Tank Overfill / High Level Sensor: | HLA/DTFV |
| Other: | | Other: | |

| | | | |
|--------------------------------------|----------------------|--------------------------------------|----------------------|
| Dispenser ID: | 1/2 | Dispenser ID: | 3/4 |
| Dispenser Containment Sensors Model: | 794380-208 | Dispenser Containment Sensors Model: | 794380-208 |
| Shear Valves: Yes | Floats & Chains: N/A | Shear Valves: Yes | Floats & Chains: N/A |
| Dispenser ID: | 5/6 | Dispenser ID: | 7/8 |
| Dispenser Containment Sensors Model: | 794380-208 | Dispenser Containment Sensors Model: | 794380-208 |
| Shear Valves: Yes | Floats & Chains: N/A | Shear Valves: Yes | Floats & Chains: N/A |

C. Certification

I certify that the equipment identified in this document was inspected/serviced in accordance with the manufacturers' guidelines. Attached to this certification is information (e.g. manufacturers' checklists) necessary to verify that this information is correct and a Plot Plan showing the layout of monitoring equipment. For any equipment capable of generating such reports, I have also attached a copy of the report (check all that apply):

Technician Name: Chris Kuykendall

Certification Number:

Expiration Date:

Signature:



Testing Company Name: Northwest Tank & Environmental Services, Inc.

Address: 17407 59th Ave SE Snohomish, WA 98296

Date of Testing: 12/03/2020

D. Results of Testing/Service

| | |
|-------|--|
| Yes | Is the audible alarm operational? |
| Yes | Is the visual alarm operational? |
| Yes | Were all sensors visually inspected, functionally tested, and confirmed operational? |
| N/A | If alarms are relayed to a remote monitoring station, is all communications equipment operational? |
| No | For pressurized piping systems, does the turbine automatically shut down if the piping secondary containment monitoring system detects a leak, fails to operate, or is electrically disconnected? |
| N/A | If yes: which sensors initiate positive shut-down? |
| N/A | Did you confirm positive shut-down due to leaks and sensor failure/disconnection? |
| Yes | For tank systems that utilize the monitoring system as the primary tank overfill warning device (i.e. no mechanical overfill prevention valve is installed), is the overfill warning alarm visible and audible at the tank fill point(s) and operating properly? |
| 90% | If so, at what percent of tank capacity does the alarm trigger? |
| Yes | Was any monitoring equipment replaced? If yes, identify specific sensors, probes or other equipment replaced and list the manufacturer name and model for all replacement parts in Section E below. |
| Yes | Was liquid found in any secondary containment systems designed as dry systems? |
| Water | If yes, what type of liquid? |
| Yes | Was monitoring system set-up reviewed to ensure proper settings? Attach setup reports, if applicable. |
| Yes | Is all monitoring equipment operational per manufacturers specifications? |

In section E. below, describe how and when these deficiencies were or will be corrected.

E. Comments

TLS 350 was tested per RP 1200 standards. Backup battery was measured at 3.6v Upon review of the setup, found Premium tank programmed for 4" floats. T1 Premium probe has 2" floats installed. Corrected setup to reflect equipment installed. L5 Regular fill sump VR 352 sensor failed to alarm when tested. Replaced with a VR 352 SN: 444325. New sensor was tested with passing results. Found L1 Premium STP sump sensor in liquid alarm on arrival. Premium STP sump has a large amount of water in it. Notified manager to have sites maintenance to have the water removed. Probes were removed and tested for High product, overfill, high water alarm and high water warning. 2- VR 352 Fill sump sensors, 2- VR 352 STP sump sensors, 4- VR 208 UDC sensors, and 2- VR 303 annular sensors were tested and confirmed operational to manufacturer specifications. VR001 High level alarm was functionally tested to RP 1200 standards, by raising the product floats to 90% capacity, and was confirmed operational.

| State Tank ID | Product | Manual Stick Readings(inches) | Gauge Readings(inches) | Difference |
|---------------|---------|-------------------------------|------------------------|------------|
| 1 | Premium | 37.75 | 37.64 | .11 |
| 2 | Regular | 67.50 | 67.31 | .19 |

F. In-Tank Gauging / SIR Equipment

This section must be completed if in-tank gauging equipment is used to perform leak detection monitoring.

| | |
|-----|--|
| Yes | Has all input wiring been inspected for proper entry and termination, including testing for ground faults? |
| Yes | Were all tank gauging probes visually inspected for damage and residue buildup? |
| Yes | Was accuracy of system product level readings tested? |
| Yes | Was accuracy of system water level readings tested? |
| Yes | Were all probes reinstalled properly? |
| Yes | Were all items on the equipment manufacturer's maintenance checklist completed? |

G. Line Leak Detectors (LLD):

| | |
|-------|--|
| Yes | For equipment startup or annual equipment certification, was leak simulated to verify LLD performance? |
| 3 GPH | Leak Rate |
| Yes | Were all LLDs confirmed operational and accurate within regulatory requirements? |
| Yes | Was the testing apparatus properly calibrated? |
| N/A | For mechanical LLDs, does the LLD restrict product flow if it detects a leak? |
| Yes | For electronic LLDs, does the turbine automatically shut off if the LLD detects a leak? |
| Yes | For electronic LLDs, does the turbine automatically shut off if any portion of the monitoring system is disabled or disconnected? |
| Yes | For electronic LLDs, does the turbine automatically shut off if any portion of the monitoring system malfunctions or fails a test? |
| Yes | For electronic LLDs, have all accessible wiring connections been visually inspected? |
| Yes | Were all items on the equipment manufacturer's maintenance checklist completed? |

Automatic Line Leak Detector Test Results

Company Name: Jacksons Food Stores
Site Name: 627
Address: 15 East Sunset Way Issaquah, WA 98027
UST Site ID: 7691
Test Date/Time: 12/03/2020 07:13:29 am

Job ID Number: 95637
Technician Name: Chris Kuykendall
License Number: 383722020-U3
Expiration Date: 10/17/2022

| | | | |
|--|---|---|---------------------|
| Product: Premium Tank ID: 1 LD Type: Electronic | Make: Veeder Root Model: 8484 Serial#: 339764 | Operating Pressure: 31 Holding Pressure: 19 Bleedback (ml): 100 | Result: Pass |
| Additional Data For Electronic Leak Detectors Only # of tests run: 2 Alarm sound when 3GPH leak detected: Yes Handle signal while in alarm: No | | | |
| Product: Regular Tank ID: 2 LD Type: Electronic | Make: Veeder Root Model: 8484 Serial#: 339764 | Operating Pressure: 27 Holding Pressure: 21 Bleedback (ml): 100 | Result: Pass |
| Additional Data For Electronic Leak Detectors Only # of tests run: 2 Alarm sound when 3GPH leak detected: Yes Handle signal while in alarm: No | | | |

Leak detector testing conducted in accordance with the procedures and limitations of the LDT 890 leak detector tester. A leak is simulated at the highest point in the line using the LDT 890 calibrated to 3 gph at a metering pressure of 10 psi. The owner or operator of the UST system is required to ensure any failed leak detector is replaced before placing the line back in service.

The results of any sampling, testing, or monitoring shall be maintained for at least five years, or for another reasonable period of time determined by the department or delegated agency, except that the results of tank tightness testing conducted in accordance with CFR 40 Part 280.44 shall be retained until the next test is conducted.

Comments: Tied in and tested from impacts in Disp 7/8. Upon tying in to Regular impact there was high bleedback (2400 ml). Replaced the siphon jet and pumped from each dispenser to purge air from the line. Both ALLD's passed the 3 GPH test in accordance with CFR 40 part 280.44.

Technician Name: Chris Kuykendall
Signature:



Date: 12/03/2020

Line Tightness Test Results

Company Name: Jacksons Food Stores
 Site Name: 627
 Address: 15 East Sunset Way Issaquah, WA 98027
 UST Site ID: 7691
 Test Date: 12/03/2020

Job ID Number: 95637
 Technician Name: Chris Kuykendall
 License Number: 383722020-U3
 Expiration Date: 10/17/2022

Line Tightness Test Data

| | | | | | |
|----------------|----------|-------------------------|---------------|----------------------------|--------|
| Product: | Premium | Tank ID: | 1 | Start Time: | 12:37 |
| Approx Length: | 150 | STP MFG: | FE Petro 2 HP | End Time: | 13:07 |
| Size: | 2 | Operating Pressure: | 31 | Total Test Time: | 30mins |
| Line Material: | FRP | Test Pressure: | 48 | Final Leak Rate: | .00500 |
| Wall Type: | Single | Isolation Dispenser: | Impact Valve | Impact Valves Operational: | Yes |
| Boot Back: | Yes | Isolation Pump: | Ball Valve | Check Valve Location: | N/A |
| Line Type: | Pressure | Initial Cylinder Level: | .025 | Result: | Pass |
| | | Final Cylinder Level: | .0225 | | |

| | | | | | |
|----------------|----------|-------------------------|-----------------|----------------------------|--------|
| Product: | Regular | Tank ID: | 2 | Start Time: | 12:37 |
| Approx Length: | 200 | STP MFG: | FE Petro 1.5 HP | End Time: | 13:07 |
| Size: | 2 | Operating Pressure: | 27 | Total Test Time: | 30mins |
| Line Material: | FRP | Test Pressure: | 48 | Final Leak Rate: | .00500 |
| Wall Type: | Single | Isolation Dispenser: | Impact Valve | Impact Valves Operational: | Yes |
| Boot Back: | Yes | Isolation Pump: | Ball Valve | Check Valve Location: | N/A |
| Line Type: | Pressure | Initial Cylinder Level: | .025 | Result: | Pass |
| | | Final Cylinder Level: | .0225 | | |

Line tightness testing conducted in accordance with the procedures and limitations of the Acurite pipeline tester. A consistent leak rate of .01 gph or higher at 150% of normal operating pressure is considered a failure. The owner or operator of the UST system is required to report all failures to the appropriate agency within 24 hours.

The results of any sampling, testing, or monitoring shall be maintained for at least five years, or for another reasonable period of time determined by the department or delegated agency, except that the results of tank tightness testing conducted in accordance with CFR 40 Part 280.44 shall be retained until the next test is conducted.

Comments: Tied in and tested from impacts in Disp 7/8. Both lines passed the 0.01 GPH test in accordance with CFR 40 part 280.44.

Technician Name: Chris Kuykendall

Signature:



Date: 12/03/2020