

RECEIVED

JUL 12 2022

WA State Department
of Ecology (SWRO)

ENVIRONMENTAL CAP AND DRAINAGE SYSTEM INSPECTION REPORT

FORMER LOUISIANA PACIFIC/PONY LUMBER FACILITY

Prepared for

PORT OF TACOMA

ONE SITCUM PLAZA
TACOMA, WA 98421

June 15, 2022

Project No. M0615.24.001

For submittal to

WASHINGTON STATE DEPARTMENT OF ECOLOGY

SOUTHWEST REGIONAL OFFICE
TOXICS CLEANUP PROGRAM
300 DESMOND DRIVE SE
LACEY, WA 98503

Enforcement Order No. DE 92TC-S312 (December 21, 1992)
Washington State Department of Ecology Facility Site ID # 1209
Inspection Dates: February 24, 2022



MAUL
FOSTER
ALONGI

Prepared by


Maul Foster & Alongi, Inc.
2815 2nd Avenue, Suite 540, Seattle, WA 98121

ENVIRONMENTAL CAP AND DRAINAGE SYSTEM
INSPECTION REPORT


FORMER LOUISIANA PACIFIC/PONY LUMBER FACILITY

*The material and data in this report were prepared
under the supervision and direction of the undersigned.*

MAUL FOSTER & ALONGI, INC.



Brooke Harmon, PE
Project Engineer



Evelyn Lundeen, EIT
Staff Engineer

CERTIFICATION

I hereby certify that I am familiar with the facilities addressed in this report and that the inspection was conducted in accordance with acceptable engineering practices.



This digital seal certifies the signatory
and document content.

06-15-2022

Brooke Harmon, PE
Project Engineer

CONTENTS

| | |
|--|-----|
| CERTIFICATION | III |
| FIGURES AND TABLES | V |
| ACRONYMS AND ABBREVIATIONS | VI |
| 1 INTRODUCTION | 1 |
| 1.1 PURPOSE AND SCOPE | 1 |
| 1.2 FACILITY BACKGROUND | 1 |
| 2 FIELD OBSERVATIONS | 2 |
| 2.1 ENVIRONMENTAL CAP | 3 |
| 2.2 STORMWATER DRAINAGE SYSTEM | 4 |
| 3 STATUS AND RECOMMENDATIONS | 4 |
| 3.1 MAINTENANCE AND REPAIR PERFORMED SINCE PREVIOUS INSPECTION | 4 |
| 3.2 RECOMMENDATIONS | 5 |
| LIMITATIONS | |
| REFERENCES | |
| FIGURES | |
| TABLES | |

FIGURES AND TABLES

FOLLOWING REPORT:

FIGURES

- 1 SITE LOCATION
- 2 ENVIRONMENTAL CAP OBSERVATIONS

TABLES

- 1 ENVIRONMENTAL CAP ISSUES OBSERVED DURING 2022 INSPECTION
- 2 STORMWATER DRAINAGE SYSTEM ISSUES OBSERVED DURING 2022 INSPECTION

ACRONYMS AND ABBREVIATIONS

| | |
|-------------|---|
| Ecology | Washington State Department of Ecology |
| EPA | U.S. Environmental Protection Agency |
| inspections | environmental cap and drainage system inspections |
| ISGP | Industrial stormwater general permit |
| LP Pony | Former Louisiana Pacific/Pony Lumber Facility |
| MFA | Maul Foster & Alongi, Inc. |
| O&M | operations and maintenance |
| Port | Port of Tacoma |
| Site | 3701 Taylor Way, Tacoma, WA |
| WWLS | Wallenius Wilhelmsen Logistics Services, LLC |

1 INTRODUCTION

This report summarizes the field activities and results for the environmental cap and stormwater drainage system inspection conducted on behalf of the Port of Tacoma (Port) for Former Louisiana Pacific/Pony Lumber Facility (LP Pony). LP Pony is located at 3701 Taylor Way in Tacoma, Washington (the Site) (Figure 1). The facility is owned by the Port and operated by Wallenius Wilhelmsen Logistics Services, LLC (WWLS). The ground surface at LP Pony is covered by an environmental cap and has several stormwater drainage features, further described in this report.

Inspection activities were conducted in accordance with the requirements identified in Enforcement Order (EO) No. DE 92TC-S312 issued by the Washington State Department of Ecology (Ecology) to the Port (Ecology, 1992) and the operations and maintenance manual (Louisiana Pacific Corporation, 2000) with the exception that cracks wider than 1/8 inch were noted, rather than only those wider than 1/2 inch.

1.1 Purpose and Scope

The purpose of this report is to present the findings of the 2022 environmental cap and stormwater drainage system inspection at LP Pony. The purpose of the environmental cap is to prevent surface water infiltration, exposure of humans and the environment to underlying materials, and erosion. The stormwater drainage system is used to convey stormwater off the cap surfaces to prevent infiltration and erosion.

Maul Foster & Alongi, Inc. (MFA), performed the inspection on February 24, 2022, which included the following tasks:

- Inspection of the asphalt/concrete pavement for the presence of cracks or other failures in the pavement that allow surface water runoff to infiltrate the bark/slag surficial fill (e.g., cracks greater than 1/8 in. wide, sub-base material exposed, pavement edge deterioration, and general appearance).
- Evaluation of the structural and functional condition of the cap and drainage systems (including catch basins, maintenance holes, and oil/water separators).
- Evaluation of debris/sediment accumulation in the stormwater structures (if visible).

The inspection observations are presented in this report.

1.2 Facility Background

LP Pony encompasses approximately 18 acres. Between 1968 and 1969, approximately 1,800 tons of Asarco smelter slag was used as fill at the property to build stable ground for machinery. In 2004, Louisiana Pacific sold the property to Pony Lumber Company, which sold it to the Port in 2006. The Port has been the current property owner since then. The property is operated by WWLS as an

equipment storage yard. WWLS stores heavy machinery and accessories in uncovered areas across the cap.

Between November 1983 and June 1984, Ecology collected stormwater runoff samples at the Site (Norton and Johnson, 1985). Analytical results from stormwater samples indicated that metal concentrations above the U.S. Environmental Protection Agency (EPA) quality standards were discharged from the Site in stormwater. It was concluded that Asarco slag was leaching contaminants and that LP Pony's stormwater was contributing contamination in Hylebos Creek and the Hylebos Waterway, which run adjacent to the property.

In 1987, Ecology issued an order requiring a site investigation, groundwater investigation, and feasibility study; the results of these studies were presented in a site investigation report (CH2M Hill, 1987). In 1990, Ecology issued Remedial Action Order No. DE 90-S170, requiring Louisiana Pacific to evaluate the effectiveness of capping as a cleanup method and to prepare a cap design for the Site (Ecology, 1990). In 1993, following the issuance of the Engineering Design Report (CH2M Hill, 1993) and under Enforcement Order DE92TC-S312, Louisiana Pacific constructed a low-permeability concrete cap and stormwater drainage system on the Site. A restrictive covenant was recorded for the Site in 1993, limiting activities that may interfere with or reduce the effectiveness of the cleanup action and requiring that the Site be used only for industrial uses (Louisiana-Pacific Corporation, 1993).

In November 2016, Ecology conducted a periodic review of post-cleanup site conditions and site data to ensure that human health and the environment were protected on the Site. The review determined that the remedial actions conducted at the Site continue to be protective of human health and the environment (Ecology, 2016).

Groundwater monitoring has been conducted at monitoring wells since 1995 to monitor the effectiveness of the remedial action. Groundwater quality is monitored every 18 months (Ecology, 2011). The last groundwater monitoring event was conducted in February 2022 (described in a separate report [MFA, 2022]).

The Port is required to conduct environmental cap and drainage system inspections (inspections) every 30 months (Ecology, 2011). The last inspection was conducted in August 2019 (Windward, 2019). Cracks and other damage that were recommended for repair and monitoring were identified in the 2019 inspection. Repairs were completed in April 2022 to erosion near the east corner of the property, outside of the fenced cap area, Ecology was notified of prior to commencement of the work and after completion of work.

2 FIELD OBSERVATIONS

MFA conducted the 2022 inspection at LP Pony on February 24, 2022, noting new observations and following up on the results of the previous inspection. The inspection was led by a Washington State licensed professional engineer.

2.1 Environmental Cap

Inspectors were able to observe a majority of the paved surfaces with the exception of pavement located along the northern border of the Site. Pavement in this area was covered with WWLS inventory that limited inspectors' ability to observe pavement conditions. The locations of facility features and the LP Pony Site boundary are shown in Figure 2. Photographs depicting cap issues are provided in Table 1.

The cap generally showed consistent wear across the Site, with most of the damaged asphalt located in the portions of the Site used for heavy equipment storage. A slurry seal was previously applied over cracks running across the cap; the slurry seal is showing signs of wear and damage consistent with the previous inspection. Damage observed to the slurry seal appears to be the result of heavy equipment and includes chipping, cracking, divots, and flaking. No exposed sub-base material was observed during the inspection.

Cracking wider than 1/8 inch observed across the cap generally run parallel with rows of equipment. Several linear cracks were identified as being previously sealed, but the sealant has since worn to a point where there is visible unsealed gapping in cracks wider than 1/8 inch. Linear cracking in areas with old slurry seal was the primary damage observed across the Site during the inspection; a few areas with alligator cracking (interlaced or interconnected cracks) and divots were also observed. There are 17 sections of curb with damage, including several portions with cracks that extend through the vertical profile of the curb.

Two areas of erosion were observed near the cap edge (Table 1). The first erosion area, located along the fence line near MH12, shows subgrade undercut concrete. There does not appear to be cracking or damage to the cap at this time, but if erosion continues to undercut the cap, the cap may fail due to stress. The second area of erosion, located outside of the fence near catch basin CB1, included some gravel and concrete chunks observed outside of the fence near catch basin CB1.

The table below provides a summary of the cap conditions observed during the 2022 inspection; observations, photographs, and recommended actions keyed to specific locations are presented in Table 1 following this report.

Environmental Cap Conditions and Recommended Actions

| Required Inspection Element | Observed Condition | Recommended Action |
|---|---|--|
| Presence of cracks wider than 1/8 inch | Cracks wider than 1/8 inch were observed across the equipment storage area. | Repair pavement areas shown in Figure 2 and described in Table 1. |
| Pavement edge deterioration | 17 areas of curb damage were observed along cap edge. | Locations of pavement edge deterioration are shown in Figure 2 and described in Table 1. Repair as recommended in Table 1. |
| Sub-base material exposed | Exposed subbase was observed in one area with cap erosion | Locations of exposed sub-base material are shown in Figure 2 and described in Table 1 |
| Degradation, subsidence, general appearance | General wear of slurry seal observed across cap. | Reseal areas as recommended in Table 1. |

2.2 Stormwater Drainage System

The stormwater drainage system consists of 4 catch basins, 19 maintenance holes, 2 oil/water separators, and 6 treatment basins. In 2022, each drainage system component was inspected for general appearance, sediment and debris accumulation, and structural and functional condition. In general, the stormwater features were structurally sound and functioning normally. Most structures inspected contained water which limited the ability to see and assess sediment accumulation. MH3 was not successfully located during the previous 2019 inspection due to vegetation overgrowth in the area believed to contain the structure. The structure was not located during the 2022 inspection for the same reason. Catch basin CB4 and maintenance hole MH5 were not inspected due to a tight-fitting grate and locked maintenance hole cover respectively. Table 2 summarizes the observations made at each drainage structure.

3 STATUS AND RECOMMENDATIONS

3.1 Maintenance and Repair Performed Since Previous Inspection

3.1.1 Environmental Cap

The 2019 inspection report (Windward, 2019) recommended the following repairs:

- Apply sealant in crack at pavement observation location P1
- Repair curb on at observation location C3 where damage extended through vertical profile
- Patch cracked concrete at pavement observation location P2

As described in Section 2.1 and Table 1, the recommended repair items have not yet been completed.

3.1.2 Stormwater Drainage System

In general, the stormwater system appears to be functioning normally and effectively draining the environmental cap. The 2019 inspection report (Windward, 2019) recommended the following maintenance:

- Removal of accumulated sediment, debris, sheen, and floatables in catch basins and maintenance holes
- Consider replacement of bolts on maintenance hole lids located outside of facility fence
- Consider pumping out the oil/water separators to inspect and check for corrosion
- Removal of accumulated sediment and debris from treatment basins and screens

- Recommended removal of vegetation and dirt accumulated dirt around the assumed location of maintenance hole MH3 to locate structure

Some of the above maintenance issues were either not addressed since the last reporting period or are reoccurring. The tenant holds an Industrial Stormwater Permit and performs inspections and maintenance on the stormwater infrastructure as required by the permit. Section 2.2 and Table 2 described current repair/maintenance items observed during the 2022 inspection.

3.2 Recommendations

3.2.1 Environmental Cap

The following recommendations are based on this 2022 inspection:

- Repair curb with breaks through vertical profile, including observation areas C3, C4, C5, C7, C14, and C16 (Figure 2).
- Seal cracks identified for repair in Table 1.
- Fill the void beneath concrete slab at observation location E1.
- Repair concrete at location P2 (Figure 2). This location was not accessible during the 2022 inspection but based on site knowledge has not been repaired since first observed during the 2019 inspection.

Concrete across the cap was generally in satisfactory condition, with unsealed cracks identified across the facility. Size and frequency of unsealed cracks increased in areas of high vehicle traffic, including near the Site entrance. Slurry seal applied during previous cap repairs is showing wear exposing previously sealed cracks. It is recommended that these cracks be resealed as significant portions of missing sealant were observed in cracks wider than 1/8 inch across the Site. Required and recommended actions are described in further detail in Table 1.

3.2.2 Stormwater Drainage System

The following recommendations are based on this 2022 inspection:

- Remove garbage and debris from maintenance hole MH10 (Figure 2).
- Restore accessibility/grate fit of catch basin CB4.
- Remove sediment accumulation from maintenance holes MH1, MH2, MH8, MH10, MH15, MH16, MH17 and MH18 (Figure 2).
- Remove floatables and organic sheen from maintenance holes as identified in Table 2.
- Remove debris, sediment accumulation, and vegetation growth from treatment basins.
- Replace damaged and/or missing screens from treatment basins, as identified in Table 2.
- Repair curb of Treatment Basin TB1 and replace debris screen in front of grate.

- Clear vegetation from suspected location of maintenance hole MH3 to facilitate future inspection (Figure 2).
- Replace filter inserts in all catch basins.
- Pump out oil water separators and have inspected for corrosion.

Floatables and organic sheen was observed in several maintenance hole and catch basin structures. Structures should be cleaned in accordance with stormwater maintenance requirements. Catch basin inserts had sediment and debris accumulation which warrants replacement. Stormwater structures were generally in good condition and recommendations are limited to regular cleaning and maintenance procedures as outlined in the operations and maintenance manual (Louisiana Pacific Corporation, 2000) and as required by the tenant's stormwater permit. Required and recommended actions are further described in Table 2.

LIMITATIONS

The services undertaken in completing this report were performed consistent with generally accepted professional consulting principles and practices. No other warranty, express or implied, is made. These services were performed consistent with our agreement with our client. This report is solely for the use and information of our client unless otherwise noted. Any reliance on this report by a third party is at such party's sole risk.

Observations in this report are limited to environmental cap areas that were visible to the MFA field team. In some instances, portions of the cap surface may have been covered and not readily available for inspection. Inspection of stormwater structures was limited to observations made from the surface and by means of direct observation, probes (extendible poles to check for sediment), and photography. No confined space entry was performed. Observation of some stormwater structures was also limited by storm flow and/or the presence of damaged or sediment-laden catch basin inserts that could not be safely removed. No guarantee is made that all cap or stormwater deficiencies that could impact cap/drainage system performance were identified.

Opinions and recommendations contained in this report apply to conditions existing when services were performed and are intended only for the client, purposes, locations, time frames, and project parameters indicated. We are not responsible for the impacts of any changes in environmental standards, practices, or regulations subsequent to performance of services. We do not warrant the accuracy of information supplied by others, or the use of segregated portions of this report.

REFERENCES

CH2M Hill. 1987. Site investigation report.

CH2M Hill. 1993. Engineering report—Tacoma log sort yard RCC cap.

Ecology. 1990. Remedial Action Order No. DE 90-S170. Washington State Department of Ecology.

Ecology. 1992. Enforcement Order No. DE 92TC-S312. Washington State Department of Ecology.

Ecology, Port of Tacoma. 2011. Memorandum of understanding. Former log yard groundwater monitoring and cap inspection. Washington State Department of Ecology and Port of Tacoma.

Louisiana Pacific Corporation. 1993. Declaration of Restrictive Covenant.

Louisiana Pacific Corporation. 2000. Revised operation, maintenance manual, and monitoring plan for concrete log yard groundwater monitoring report.


MFA. 2022. LP Pony Groundwater Monitoring Letter.

Norton, D., and A. Johnson. 1985. Completion report on WQIS Project 1 for the Commencement Bay nearshore/tideflats remedial investigation: assessment of log sort yards as metal sources to Commencement Bay waterways, November 1983 to June 1984. Washington State Department of Ecology memorandum. February 27.

Windward, Landau. 2019. Port of Tacoma environmental cap inspection report. Former Louisiana Pacific/Pony Lumber facility. Windward Environmental LLC and Landau Associates, Seattle, WA.

FIGURES






Source:
 U.S. Geological Survey (2021) 7.5-minute
 topographic quadrangle: Poverty Bay;
 Township 21 north, range 3 east, section 36;
 Property boundary obtained from
 Pierce County GIS.

Legend
 Site Boundary

Figure 1
Site Location
 Former Louisiana Pacific-Pony Lumber
 Tacoma, Washington

 MAUL FOSTER ALONGI
 p. 971 544 2139 | www.maulfooster.com

This product is for informational purposes and may not have been prepared for, or be suitable for, legal, engineering, or surveying purposes. Users of this information should review or consult the primary data and information sources to ascertain the usability of the information.







Figure 2
Environmental
Cap Observations

Former Louisiana Pacific-Pony Lumber
 Tacoma, Washington

Legend

- Observation Type
- Catch Basin
 - Curb Observation
 - Erosion Observation
 - Maintenance Hole
 - Oil Water Separator
 - Pavement Observation
 - Treatment Basin
 - Site Boundary
 - Tax Lot

Note:
 Inspection performed on February 24, 2022.



Source:
 Aerial photograph obtained from Mapbox; tax lot data obtained from Pierce County GIS; monitoring well locations obtained from Anchor QEA site plan figure

MAUL FOSTER ALONGI
 p. 971 544 2139 | www.maulfooster.com

This product is for informational purposes and may not have been prepared for, or be suitable for, legal, engineering, or surveying purposes. Users of this information should review or consult the primary data and information sources to ascertain the usability of the information.



TABLES





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0624.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility



Table 1: Environmental Cap Issues Observed During 2022 Inspection

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|----|-------------------|--|---|--|
| C1 | curb | curb damage extending approximately 4 feet; damage limited to top 2-3 inches of curb; curb continues to function to control runoff | monitor and reevaluate for repair during next inspection cycle |  A photograph showing a section of a concrete curb that has been damaged, with a gap of approximately 4 feet. The curb is made of concrete and is surrounded by vegetation and a chain-link fence. |
| C2 | curb | curb damage extending approximately 2 feet; damage limited to top 2 inches of curb; loose pieces falling out; curb continues to function to control runoff | monitor and reevaluate for repair during next inspection cycle. |  A photograph showing a section of a concrete curb that has been damaged, with a gap of approximately 2 feet. The curb is made of concrete and is surrounded by vegetation and a chain-link fence. There are some wooden pallets and debris visible in the foreground. |





MAUL
FOSTER
ALONG

Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0624.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|----|-------------------|---|---|--|
| C3 | curb | curb damage through vertical profile; concrete crumbling and loose pieces falling out | repair curb |  |
| C4 | curb | piece of curb approximately 2 feet long broken off from end of curb; does not appear to be impacting drainage | Remove loose debris; monitor and reevaluate during next inspection cycle. |  |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0624.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|----|-------------------|--|---|--|
| C5 | curb | curb damage approximately 3 feet long at end of curb; rebar exposed and chunks of curb missing; does not appear to be impacting drainage | Remove loose debris; monitor and reevaluate during next inspection cycle. |  A photograph showing a concrete curb with significant damage at its end. A section of the curb is missing, exposing rebar. Debris is scattered on the ground nearby. |
| C6 | curb | curb damage approximately 4-5 feet long; exposed rebar and cracked top; does not appear to be impacting drainage | monitor and reevaluate during next inspection cycle |  A photograph showing a concrete curb with a long, deep crack and exposed rebar. The top surface of the curb is cracked and crumbling. A metal grate is visible in the foreground. |





MAUL FOSTER ALONG Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0624.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|----|-------------------|---|---|--|
| C7 | curb | piece of curb approximately 2 feet long broken off from end of curb; does not appear to be impacting drainage. | Remove loose debris; monitor and reevaluate during next inspection cycle. |  |
| C8 | curb | piece of curb with chunk of concrete missing from top 2 inches of curb; does not appear to be impacting drainage. | monitor and reevaluate during next inspection cycle |  |



MAUL FOSTER ALONG Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0624.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|--|---|--|
| C9 | curb | curb damage approximately 3 feet long; chunks of concrete breaking; damage limited to top 2-3 inches; does not appear to be impacting drainage | monitor and reevaluate during next inspection cycle |  A photograph showing a concrete curb with significant surface damage. The top layer of concrete is broken and crumbling, exposing the aggregate underneath. The damage is approximately 3 feet long. There are some plants and debris in the background. |
| C10 | curb | curb damage approximately 2 feet long; chunks of concrete breaking off; damage limited to top 4-5 inches of curb; does not appear to be impacting drainage | monitor and reevaluate during next inspection cycle |  A photograph showing a concrete curb with surface damage. The top layer of concrete is broken and crumbling, exposing the aggregate underneath. The damage is approximately 2 feet long. There are some plants and debris in the background. |





MAUL
FOSTER
ALONG

Project Name: Environmental Cap and Drainage System Inspection Report



Project Number: M0624.24.001

Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|---|---|--|
| C11 | curb | curb damage approximately 2 feet long; damage limited to top 2-3 inches; does not appear to be impacting drainage | monitor and reevaluate during next inspection cycle |  A photograph showing a concrete curb with a significant longitudinal crack. The crack runs across the top surface of the curb. The surrounding area is overgrown with weeds and grass. |
| C12 | curb | curb damage approximately 1 foot long; damage limited to top 2-3 inches; does not appear to be impacting drainage | monitor and reevaluate during next inspection cycle |  A photograph showing a concrete curb with a smaller longitudinal crack. The crack is shorter and less deep than the one in C11. The area is covered with dry leaves and some moss. |



MAUL FOSTER ALONG Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0624.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|--|---|--|
| C13 | curb | curb damage approximately 3 feet long; chunks of concrete breaking off; damage limited to top 2-3 inches; does not appear to be impacting drainage | monitor and reevaluate during next inspection cycle |  A photograph showing a concrete curb that is cracked and crumbling. The curb is situated next to a chain-link fence. There is some debris and a plastic bag on the ground near the curb. |
| C14 | curb | curb damage through vertical profile | repair curb |  A photograph showing a concrete curb that is severely damaged and broken through. The curb is situated next to a chain-link fence. There is a large amount of debris and a rusted metal barrel on the ground near the curb. |





MAUL
FOSTER
ALONG

Project Name: Environmental Cap and Drainage System Inspection Report



Project Number: M0624.24.001

Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|--|---|--|
| C15 | curb | curb damage approximately 3 feet long; exposed rebar; damage limited to top 2-3 inches; does not appear to be impacting drainage | monitor and reevaluate during next inspection cycle |  |
| C16 | curb | curb damage approximately 5 feet long; multiple breaks through vertical profile | repair curb |  |



MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0624.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|--|--|--|
| C17 | curb | approximately 4 feet long section of curb removed for installation of stairs and gate; damage through vertical profile adjacent to missing section | extend curb or add a structural control to prevent stormwater runoff from sheet flowing off-site |  |
| E1 | cap edge | material eroding from underneath cap near treatment basin 4 | fill void under concrete slab to prevent further erosion and/or cap failure |  |





MAUL
FOSTER
ALONG

Project Name: Environmental Cap and Drainage System Inspection Report



Project Number: M0624.24.001

Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|----|-------------------|---|---|--|
| E2 | cap edge | potential erosion near cap boundary; concrete chunks and gravel debris observed near cap edge | monitor and reevaluate during next inspection cycle |  |
| P1 | pavement | crack wider than 1/8 inch, approximately 12 lf; sealant missing in some places | reseal crack |  |
| P2 | pavement | unable to locate; suspected covered underneath equipment | observe during next inspection cycle | [no photograph] |



MAUL FOSTER ALONG Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0624.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|----|-------------------|--|--|--|
| P3 | pavement | missing chunk of previous slurry seal; approximately 1 foot by 1 foot long | monitor and reevaluate for repair during next inspection cycle |  |
| P4 | pavement | damage to old asphalt patch; crack approximately 1 inch wide along seam of patch | monitor and reevaluate for repair during next inspection cycle |  |





MAUL
FOSTER
ALONG

Project Name: Environmental Cap and Drainage System Inspection Report



Project Number: M0624.24.001

Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|----|-------------------|---|---------------------|--|
| P5 | pavement | sealant wear in crack network; approximately 100 square feet across; sealant missing in portions of sealed alligator cracks | reseal cracks |  |
| P6 | pavement | unsealed crack wider than 1/8 inch; two adjacent cracks approximately 200 lf | seal cracks |  |



MAUL FOSTER ALONG Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0624.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|----|-------------------|---|------------------------------------|--|
| P7 | pavement | unsealed crack wider than 1/8 inch; approximately 100 lf | seal crack |  |
| P8 | pavement | partially unsealed crack with vegetation growth; approximately 50 lf; previously sealed but sealant missing in places | remove vegetation and reseal crack |  |





MAUL
FOSTER
ALONGI

Project Name: Environmental Cap and Drainage System Inspection Report

Project Number: M0624.24.001



Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|---|--|--|
| P9 | pavement | slurry seal wear chipping and cracking | monitor and reevaluate for repair during next repair cycle |  |
| P10 | pavement | partially unsealed crack as wide as 4 inches in places; extends length of equipment row several hundred feet; previously sealed but sealant missing in places | reseal crack |  |





MAUL
FOSTER
ALONGI

Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0624.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|---|--|--|
| P11 | pavement | unsealed crack wider than 1/8 inch; approximately 20 lf | seal crack |  |
| P12 | pavement | pock marks in pavement; approximately 1 inch deep | monitor and reevaluate for repair during next inspection cycle |  |





MAUL FOSTER ALONG Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0624.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|--|--|--|
| P13 | pavement | pock marks in pavement; approximately 1 inch deep | monitor and reevaluate for repair during next inspection cycle |  A close-up photograph of a grey asphalt or concrete pavement surface. Several small, dark, irregularly shaped pits or pock marks are visible, some of which are approximately 1 inch deep. The top edge of the image shows the lower portion of a person's legs wearing brown work boots. |
| P14 | pavement | unsealed crack as wide as 1.5 inches in some places; approximately 15 lf | seal crack |  A photograph of a concrete or asphalt pavement surface showing a significant, unsealed crack. The crack runs diagonally across the frame and is approximately 1.5 inches wide in some sections. The surrounding pavement is a light grey color, and the crack is filled with dark material, possibly dirt or old sealant. |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0624.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|---|---------------------|--|
| P15 | pavement | unsealed crack wider than 1/8 inch; approximately 15 lf; previously covered with slurry seal, but seal has degraded | reseal crack |  |
| P16 | pavement | unsealed crack wider than 1/8 inch; approximately 20 lf; previously covered with slurry seal, but seal has degraded | reseal crack |  |





MAUL
FOSTER
ALONG

Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0624.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|---|--|--|
| P17 | pavement | unsealed crack wider than 1/8 inch; approximately 40 lf; previously sealed but sealant missing in most places | reseal crack |  |
| P18 | pavement | pavement gouging and cracking as wide as 5 inches in places; approximately 30 lf; does not appear to extend through cap | monitor and reevaluate for repair during next inspection cycle |  |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0624.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|--|----------------------------------|--|
| P19 | pavement | unsealed crack with vegetation growth; approximately 30 lf | remove vegetation and seal crack |  |
| P20 | pavement | unsealed crack wider than 1/8 inch; approximately 40 lf long | seal crack |  |





MAUL FOSTER ALONGI Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0624.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|-----|-------------------|---|----------------------------------|--|
| P21 | pavement | partially unsealed crack wider than 1/8 inch; approximately 50 lf | seal crack |  |
| P22 | pavement | unsealed crack with vegetation growth; approximately 5 lf | remove vegetation and seal crack |  |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0624.24.001
ALONG Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observation | Recommended Actions | Photographs |
|---|-------------------|--|------------------------------------|--|
| P23 | pavement | previously sealed crack with sealant missing; approximately 20 lf | reseal crack |  |
| P24 | pavement | previously sealed crack with sealant missing; vegetation growth in portions of crack; approximately 50 lf east of this point | remove vegetation and reseal crack |  |
| NOTES: C = curb ID = location identification number lf = linear feet P = pavement | | | | |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONG Location: Louisiana Pacific/Pony Lumber Facility

Table 2: Stormwater Drainage System Issues Observed During 2022 Inspection

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|-----|-------------------|--|--|---|---|--|
| CB1 | catch basin | structurally sound; functioning normally | 4 inches in insert; visible sediment accumulation in bottom of structure; water in structure and too deep to measure | insert in catch basin; no floatables or debris | remove sediment and debris from insert and structure in accordance with stormwater maintenance requirements |  |
| CB2 | catch basin | structurally sound; functioning normally | 5-6 inches in insert; structure full of water and too deep to measure | insert in catch basin; sediment accumulation and fabric tear in insert; floatables on surface | replace insert; remove floatables in accordance with stormwater maintenance requirements |  |




MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|-----|-------------------|---|--|---|---|--|
| CB3 | catch basin | structurally sound; functioning normally | debris in insert; structure full of water and too deep to measure | insert in catch basin; minor floatables in riser | remove floatables in accordance with stormwater maintenance requirements |  |
| CB4 | catch basin | could not observe interior of structure | several inches of sediment accumulated in insert | insert in catch basin; unable to open structure due to tight fit of grate | restore accessibility; replace insert; observe interior of structure during next inspection |  |




MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONG Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|-----|-------------------|--|--|--|--|--|
| MH1 | maintenance hole | structurally sound; functioning normally | visible sediment accumulation on pipes and structure walls; water in structure and too deep to measure | visible debris and floatables on surface | remove debris and floatables from structure in accordance with stormwater maintenance requirements |  |
| MH2 | maintenance hole | structurally sound; functioning normally | trace sediment accumulation on pipe; water in structure and too deep to measure | organic debris and floatables on surface | remove debris and floatables from structure in accordance with stormwater maintenance requirements |  |



MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|-----|-------------------|--|--|---|--|--|
| MH3 | maintenance hole | could not locate | nm | none | could not locate maintenance hole (consistent with 2019 inspection) | [no photograph] |
| MH4 | maintenance hole | structurally sound; functioning normally | water in structure and too deep to measure | lid overgrown; floatables and organic debris on surface, slight organic sheen | remove debris and floatables from structure in accordance with stormwater maintenance requirements |  |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONG I Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|-----|-------------------|--|--|----------------------------------|--|--|
| MH5 | maintenance hole | unable to inspect structure | nm | lid locked with large hex bolts. | observe during next inspection |  |
| MH6 | maintenance hole | structurally sound; functioning normally | water in structure and too deep to measure | organic debris on surface | remove debris in accordance with stormwater maintenance requirements |  |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|-----|-------------------|--|---|---|---------------------|--|
| MH7 | maintenance hole | structurally sound; functioning normally | water in structure and too deep to measure | no visible debris, floatables, or sheen | none |  |
| MH8 | maintenance hole | structurally sound; functioning normally | minimal visible accumulation in structure; water in structure and too deep to measure | no visible debris, floatables, or sheen | none |  |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|------|-------------------|--|--|--|--|--|
| MH9 | maintenance hole | structurally sound; functioning normally | water in structure and too deep to measure | no debris, floatables, or sheen | none |  |
| MH10 | maintenance hole | structurally sound; functioning normally | visible sediment accumulation up to pipe invert; too deep to measure | rebar, hose, and other debris in structure | remove sediment and debris from structure in accordance with stormwater maintenance requirements |  |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|------|-------------------|--|--|--|--|--|
| MH11 | maintenance hole | structurally sound; functioning normally | water in structure and too deep to measure | organic sheen with floatables on surface | remove floatables in accordance with stormwater maintenance requirements |  |
| MH12 | maintenance hole | structurally sound; functioning normally | water in structure and too deep to measure | debris on surface | remove debris in accordance with stormwater maintenance requirements |  |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|------|-------------------|--|--|---|---|--|
| MH13 | maintenance hole | structurally sound; functioning normally | water in structure and too deep to measure | floatables and trace organic sheen on surface | remove floatables in accordance with stormwater maintenance requirements |  |
| MH14 | maintenance hole | cracking in upper portion of structure; functioning normally | water in structure and too deep to measure | floatables on surface | remove floatables in accordance with stormwater maintenance requirements; monitor structure condition |  |





MAUL FOSTER ALONG Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0615.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|------|-------------------|--|--|---|--|--|
| MH15 | maintenance hole | structurally sound; functioning normally | sediment accumulation on structure walls and in pipes; water in structure and too deep to measure | no floatables, debris, or sheen | remove sediment accumulation in accordance with stormwater maintenance requirements |  |
| MH16 | maintenance hole | structurally sound; functioning normally | approximately 0.5 inches sediment accumulation in pipe; water in structure and too deep to measure | floatables and organic sheen on surface | remove sediment accumulation and floatables in accordance with stormwater maintenance requirements |  |





MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONG Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|------|-------------------|--|---|--------------------------------|---|--|
| MH17 | maintenance hole | structurally sound; functioning normally | approximately 0.25 inches sediment accumulation in pipe; water in structure and too deep to measure | floatables on surface | remove sediment and floatables in accordance with stormwater maintenance requirements |  |
| MH18 | maintenance hole | structurally sound; functioning normally | visible sediment accumulation in bottom of structure; water in structure and too deep to measure | no floatables, debris or sheen | remove sediment in accordance with stormwater maintenance requirements |  |





Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0615.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|------|---------------------|--|--|--|--|--|
| MH19 | maintenance hole | structurally sound; functioning normally | water in structure and too deep to measure | trace floatables on surface | remove floatables in accordance with stormwater maintenance requirements |  |
| OWS1 | oil/water separator | functioning normally | water in structure and too deep to measure | metal structure with signs of corrosion; floatables and sheen visible on water surface | pump out the oil/water separator for inspection; have a corrosion engineer evaluate maintenance hole walls for integrity |  |





MAUL FOSTER ALONG Project Name: Environmental Cap and Drainage System Inspection Report
 Project Number: M0615.24.001
 Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|------|---------------------|--|--|---|--|--|
| OWS2 | oil/water separator | functioning normally | water in structure and too deep to measure | metal structure with signs of corrosion; floatables and sheen visible on water surface | pump out the oil/water separator for inspection; have a corrosion engineer evaluate maintenance hole walls for integrity |  |
| TB1 | treatment basin | structurally sound; functioning normally | 1 inch accumulation in basin and approximately 1/8 inch in pipes | booms instead of screens in front of grates; organic debris in basin; sediment accumulation around basin; some deterioration of pavement curb on east corner of basin (rebar exposed) | replace missing screens; remove accumulated sediment in accordance with stormwater maintenance requirements; repair pavement curb if conditions worsen |  |



MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|-----|-------------------|--|-----------------------|--|--|--|
| TB2 | treatment basin | structurally sound; functioning normally | 0 inches | screens and basin in good condition | none |  |
| TB3 | treatment basin | structurally sound; functioning normally | 0 inches | gapping in west screen large enough to allow sediment bypass | repair screen in accordance with stormwater maintenance requirements |  |




Project Name: Environmental Cap and Drainage System Inspection Report
Project Number: M0615.24.001
Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|-----|-------------------|--|-----------------------|--|---|--|
| TB4 | treatment basin | structurally sound; functioning normally | 0 inches | inorganic debris in basin; visible sediment accumulation in screens | remove accumulated debris from screens in accordance with stormwater maintenance requirements |  |
| TB5 | treatment basin | structurally sound; functioning normally | 0.5 inches in basin | organic and inorganic debris in basin; southwest grate is cracked and covered in organic debris; accumulated sediment in screens | remove sediment accumulation and debris from basin in accordance with stormwater maintenance requirements; clear screens and grates |  |



MAUL Project Name: Environmental Cap and Drainage System Inspection Report
FOSTER Project Number: M0615.24.001
ALONGI Location: Louisiana Pacific/Pony Lumber Facility

| ID | Type of Structure | Observed Condition | Sediment Accumulation | Additional Observations | Recommended Actions | Photographs |
|-----|-------------------|--|-----------------------|--|---|---|
| TB6 | treatment basin | structurally sound; functioning normally | 0.75 inches in basin | blackberries beginning to grow into basin; organic and inorganic debris in basin; damage to north grate; north facing screen is torn; sediment accumulation on all screens | remove accumulated sediment and debris from basin and screens in accordance with stormwater maintenance requirements; trim blackberries; replace damaged screen |  |

NOTES:
 CB = catch basin
 ID = location identification number
 MH = maintenance hole
 nm = not measured
 OWS = oil/water separator
 TB = treatment basin