

File: 12019 Sound Transit Brooklyn Station Area 20240510

SHARP Report — Part 1 of 2

Go to site contamination history

• SHARP first SHARP		v2024.04.29	Ecology	Info
<ul> <li>SHARP rating</li> </ul>	Low		ERTS	634063
<ul> <li>SHARP date</li> </ul>	05/10/2024		CSID	12019
<ul><li>EJFlagged?</li></ul>	✓ – No Override		FSID	8342
<ul> <li>LD confidence level</li> </ul>	low		VCP	NW2704
<ul> <li>Cleanup milestone</li> </ul>	remedial investigation		UST ID	619989
• SHARPster	Zak Wall		LUST ID	6709

This section is blank if this is the first SHARP	

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	В3	low	multiple chemical types	<b>✓</b>
Groundwater	C3	high	risk to off-site people	<b>✓</b>
Surface water	D4	high	climate change impacts	$\bigcirc$
Sediment	D4	high	plant/animal tissue data	$\bigcirc$
Soil	C2	medium		

Location and land use info		
1000 NE 45th St, Seattle, King County, 98105		
Parcel(s)		
Responsible unit	NWRO	
Land use	menu ▼	

Sources reviewed	
2012-01-09 Phase II ESA	
2012-06-07 Initial Investigation Field Report	
2013-03-07 RI/FS Work Plan	
2016-12-19 UST Site Assessment	
2013-06-12 VCP RI/FS Work Plan Opinion Letter	



Primary census tract	Associated census tracts
53033005306	53033005305

Local demographics cor	mments
no comments	
Source/source area des	cription
	e station and former drycleaner are believed to be sources of contamination at
	d on the western neution of the site frame as early as 1020 until 1050. A

A former retail gasoline service station and former drycleaner are believed to be sources of contamination at the site. The gas station existed on the western portion of the site from as early as 1938 until 1956. A drycleaner operated on the eastern portion of the site from approximately 1943 until 1961. A used car lot also operated at the entire property from 1953 until 1961, and could be an additional source of contamination.

### Soil comments

Vinyl Chloride was detected in one soil sample collected in 2011 from boring GP-15 at a concentration of 0.00099 mg/kg slightly above the laboratory reporting limit of 0.00061 mg/kg. Updated soil information is needed to assess the presence/extent of vinyl chloride and other PCE-degradation compounds in media at the site.



Groundwater comments
no comments
Surface water comments
no comments
Sediment comments
no comments
Indoor air comments
PCE was detected at a concentration of 130 μg/L (well MW-3 in October 2011) above the Method B VI
groundwater screening level of 25 μg/L.
Additional factors comments
no comments



Go to top

Petroleum-related contaminants have been identified in soil and groundwater on the western portion of the
site and are believed to have originated from former service station operations. Chlorinated VOCs have been
identified in soil and groundwater on the eastern portion of the site and are likely associated with former
drycleaning operations. Arsenic and chromium have also been detected in groundwater samples collected from the western portion of the site at concentrations greater than MTCA Method A groundwater cleanup levels. In September 2016, as part of an interim remedial action, soil excavations were completed at the western and eastern portions of the site. During the excavations, two underground storage tanks (one 3,000-gallon and one 500-gallon) were encountered and removed from the western area. Based on the available reports, it is likely
that petroleum and chlorinated solvent-impacted soil remains on site.



Overflow -	- Site contamination and cleanup history
No overflow	

File: 12019 Sound Transit Brooklyn Station Area 20240510

**First SHARP** 

**SHARP** rating — Low

### SHARP Report — Part 2 of 2

Conceptual site model



05/10/2024

