

SHARP Report — Part 1 of 2

Go to cleanup history

SHARP first assessr	ment v2024.04.03	Ecology	Info
 SHARP rating 	Low	ERTS	na
 SHARP date 	4/10/2024	CSID	5994
EJFlagged?	SHARP it	FSID	38258847
 LD confidence level 	low	VCP	NW1824, NW0712
 Cleanup milestone 	post-cleanup controls & monitoring	UST ID	4279
 Assessor 	Vance Atkins	LUST ID	na

This section	is hla	nk if this	is the	first SHAR	P
THIS SECTION	is bia	IIK II UIIS	is me	III SL SHARI	

Assessment Media	Scores	Confidence	Additional Factors	
Indoor air	D4	high	multiple chemical types	\Diamond
Groundwater	C4	high	risk to off-site people	\Diamond
Surface water	D4	high	climate change impacts	\Diamond
Sediment	D4	high	plant/animal tissue data	\Diamond
Soil	D4	high		

Location and land use info			
16025-16223 International Blvd, SeaTac, King County, 98188			
Parcel(s)	9409400135, 9409400140, 2823049052, 9409400126, 9409400115, S 160th St		
	ROW, Port of Seattle property N of S 160th St		
Responsible unit	NWRO		
Land use	Commercial		

Sources reviewed
2024, Groundwater Sampling Report, Landau
2010. RIFS, Golder Associates



Primary census tract	Associated census tracts
53033028402	SHARP it

Local demographics comments	Go to top
no comments	

Source/source area description

Go to top

The Site showed the first development in the 1940s Since the 1960s, the MasterPark Facility property was mainly a construction staging area that supported the construction of

Interstate 5. The currently existing Louden property (aadjacent north parcel) buildings were constructed in the 1960s. More recently a number of small manufacturing and warehousing facilities operated at the MasterPark Facility property including public parking. The current use of the MasterPark Facility is a paved parking lot with a single administrative building supporting the business. The release or releases were identified as former USTs located in the northern portion of the Site. Limited soil contamination was identified at >25 feet below grade, and groundwater contamination was identified in the regional alluvial aquifer at depths of >50 feet.

Soil comments	Go to top
no comments	



Groundwater comments	Go to top
Groundwater is generally approx 50 feet below ground surface in the parking lot portion of the Site. F	low is the
west/southwest. Groundwater < MTCA cleanup levels except one well at north edge of site parcel with	n periodic
exceedances, currently monitoring for compliance through MNA.	
Surface water comments	Go to top
no comments	
Sediment comments	Go to top
no comments	<u>00 t0 t0p</u>
no comments	
Indoor air comments	Go to top
no comments	
Additional feature comments	Catatan
Additional factors comments	Go to top
no comments	



Site contamination and cleanup history

Go to top

An in situ air sparging and soil vapor extraction (IAS/SVE) system was operated at the Site from approximately May to July 2013, and December 2013 through July 2017 to remediate petroleum hydrocarbon-impacted groundwater. After the IAS/SVE system was deactivated in July 2017, performance groundwater monitoring was conducted on a semiannual basis from November 2017 through July 2019 to monitor changes in the petroleum hydrocarbon concentrations over time.

The results of the performance groundwater monitoring showed that petroleum hydrocarbon concentrations in the groundwater beneath the northern and northwestern parts of the subject property remained above the MTCA cleanup levels by July 2019. To reduce the remaining petroleum hydrocarbon concentrations in groundwater, the IAS/SVE system was operated from September 2019 through July, 2020, when it was deactivated prior to the July 2020 performance groundwater monitoring event. Based on the results of the January and July 2020 performance groundwater monitoring events, it appeared that the IAS/SVE system had effectively reduced the petroleum hydrocarbon concentrations in the groundwater beneath the subject property to levels that should naturally attenuate to below cleanup levels within a reasonable time frame. Confirmational groundwater monitoring has been conducted at the Site since October 2020. The Site is in general compliance with respect to MTCA cleanup levels with the excpetion of one well at the northern edge of the site. Ongoing monitoring is occurring for petroleum hydrocarbons and MNA constituents at that well and surrounding wells. The site is maintained under a restrictive covenant to retain an impevious surface.



Overflow - Site contamination and cleanup history	Go to top
No overflow	

04/10/2024 SHARP First Assessment

Low SHARP Rating

SHARP Report — Part 2 of 2

Conceptual site model



