


Spokane Roofing

SHARP Report — Part 1 of 2

[Go to site contamination history](#)

• SHARP first SHARP		v2024.04.29	Ecology Info	
• SHARP rating	Low		ERTS	731670
• SHARP date	06/30/2024		CSID	17047
• EJFlagged?				



Primary census tract	Associated census tracts
53063014500	SHARP it

Local demographics comments
no comments

Source/source area description
The possible source of the contamination is an underground storage tank.

Soil comments
no comments

Groundwater comments
no comments

**Surface water comments**

no comments

**Sediment comments**

no comments

**Indoor air comments**

no comments

**Additional factors comments**

no comments

## Site history

[Go to top](#)

On September 17, 2020 Stantec directed 10 borings to be drilled at depths ranging from 1.0 to 7.0 feet below ground surface (bgs). Borings could not go any deeper than 7 feet due to bedrock. No groundwater was encountered. Eleven soil samples were taken. Analytical results show arsenic, cadmium, lead, heavy oil and cPAHs were above MTCA Method A cleanup levels. Soil contamination above MTCA Method A cleanup level remain onsite. Site will be placed on the Confirmed and Suspected Contaminated Sites List.

**Overflow - Site contamination and cleanup history**

No overflow

## Spokane Roofing

17047 Spokane Roofing 20240630

First SHARP

SHARP rating — Low

## SHARP Report — Part 2 of 2

Conceptual site model

06/30/2024



### Assessment scores by environmental medium

