



**HARTCROWSER**

Earth and Environmental Technologies

**RECEIVED**

**OCT 08 1992**

**DEPT. OF ECOLOGY**

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102  
FAX 206.328.5581  
206.324.9530

J-3603

September 2, 1992

Ms. Karen Rose  
Snohomish County Public Utilities District, No. 1  
1802 - 75th Street SW  
Everett, Washington 98206

Re: Site Assessment Report  
Halls Lake Substation Remedial Services  
Professional Services Contract No. 2048

Dear Karen:

Hart Crowser is pleased to present to you this report of the findings of our site investigation at the Snohomish County PUD Halls Lake Substation located in Mountlake Terrace, Washington. This report includes chemical analytical results from soils and groundwater samples and our recommendations for remedial alternatives for this site. Work was completed in accordance with the Exhibit A "Scope of Work" included in Professional Services Contract No. 2048, and with the Hart Crowser work scope dated June 19, 1992.

#### **SUMMARY**

Hart Crowser completed a total of 11 borings and two monitoring wells in the upper and lower ditches and sump at the Halls Lake Substation (Figure 1). Soil samples were obtained at 2.5- and 5.0-foot-depth intervals as noted on the boring logs presented in Attachment A of this report. Soil samples were tested for total petroleum hydrocarbons (TPH), total lead, and toxicity characteristic leaching procedure (TCLP) lead as noted in the soil chemical analytical results, presented in Attachment B of this report and summarized on Figures 2 and 3.



Groundwater samples from the upper and lower ditch were tested for dissolved lead and TPH. Field conductivity and pH measurements were completed as part of Hart Crowser's routine groundwater sampling procedure and these results, along with groundwater chemical analytical results, are presented in Attachment B.

Based on our findings, lead and TPH concentrations exceed soil cleanup levels set by the Washington State Department of Ecology (Ecology) at the surface and upper 2.5 feet of soil along the entire centerlines of both the upper and lower ditches. More specifically, soil with TCLP lead exceeding the 5.0 mg/L hazardous waste limit (RCRA soil) extends from the surface to depths of approximately 1.75 feet and has a total estimated volume of 65 cubic yards. Soil exceeding MTCA cleanup standards (MTCA soil) was observed from a depth of 1.75 feet to 2.5 feet with a total estimated volume of 30 cubic yards.

Groundwater was found to be perched in the upper 15 feet beneath the surface of both ditches to within approximately 4 feet of the surface. Lead and TPH concentrations from the upper ditch groundwater sample were found to exceed MTCA Method A groundwater cleanup standards for lead and TPH.

We have proposed two alternatives for site remediation:

- ▶ Alternative 1 involves excavation and separation of soils into RCRA and MTCA stockpiles, and disposal of these soils at an appropriate hazardous or solid waste landfill. The estimated cost is about \$95,000; and
- ▶ Alternative 2 involves excavation and separation of the soils into RCRA and MTCA stockpiles, treatment of the RCRA soils to achieve MTCA cleanup standards and final disposal of the soil at a solid waste landfill. The estimated cost for this alternative is about \$110,000.

## **PROJECT BACKGROUND AND OBJECTIVES**

Hart Crowser was retained by the Snohomish County PUD to perform a site investigation of the Halls Lake Substation and adjoining right-of-way (ROW) to determine the extent and volume of soils contaminated with motor oil and lead in



order that the property may be remediated for worker safety and compliance with applicable state and federal laws.

Initial testing by the Snohomish PUD and Ecology indicated high concentrations of lead and petroleum in two ditches running east-west on the property (Figures 2 and 3). The suspected source of contamination is a nearby radiator shop, Ken's Radiator, that has a drainage pipe leading into the east end of the upper ditch.

The objective of this site investigation is to assess the extent of soil contamination that must be remediated to achieve the following cleanup standards that have already been negotiated between the PUD and Ecology:

- ▶ Inside the PUD yard, the lower of either 1,000 mg/kg total lead or 5.0 mg/L TCLP lead; and
- ▶ Within the ROW, 250 mg/kg total lead.

#### **PROJECT SCOPE OF WORK**

The following tasks were requested by the PUD and included as part of this work scope:

- ▶ Collect soil samples to assess the extent of soil contamination by placing soil borings in the drainage ditches and analyzing soil samples for total lead, TCLP lead, and total petroleum hydrocarbons (TPH by method 418.1);
- ▶ Collect groundwater samples to assess potential groundwater contamination for total lead and total petroleum hydrocarbons;
- ▶ Review remediation options and alternatives that are cost-effective to the PUD, and will accommodate the PUD's proposed use of the affected property and the PUD's current construction schedule; and
- ▶ Provide a written report to the PUD containing site investigation findings and site remediation recommendations within 30 days of the notice to proceed.



## RESULTS OF SOIL CHEMICAL ANALYSES

Refer to Figures 2 and 3 for boring locations and a summary of laboratory analytical results for soil samples from the upper and lower ditches, respectively. The following conclusions are based on these analytical results:

- ▶ A positive correlation was established between high lead and high TPH concentrations at all sample points; in almost all cases, where the TPH exceeded the MTCA cleanup standard of 200 mg/kg, the lead concentration also exceeded the negotiated MTCA cleanup standard.
- ▶ Concentrations of total lead in the soil exceeded the 1,000 and 250 mg/kg cleanup standards set by Ecology for inside the PUD yard (the upper ditch) and the ROW (the sump and lower ditch), respectively, in surface samples collected from centerline borings HC-1, HC-3, HC-5, HC-7 (sump), and HC-8. The only exception was HC-10, the last boring in the centerline of the lower ditch, which showed a surface lead concentration of 47 mg/kg.
- ▶ All samples collected from off-center of the ditches (borings HC-2, HC-6, and HC-9) showed lead concentrations below the cleanup standards.
- ▶ Concentrations of TCLP lead generally diminished to below the RCRA lead level of 5.0 mg/L at a depth of 1 to 2.5 feet beneath the ground surface along the centerlines of both ditches. The RCRA soil extends from the surface to an estimated average depth of about 1.75 feet.
- ▶ Concentrations of total lead in the soil diminished to below cleanup standards within a depth of about 2.5 feet below ground surface along the centerline of the ditches.
- ▶ Assuming lead RCRA soils extend from the surface to depths of 1.75 feet and to a total width of 4 feet across the ditch, total RCRA soil volume would be approximately 51 cubic yards. By including a 25 percent contingency, the estimated volume of RCRA soil is about 65 cubic yards.



- ▶ Assuming MTCA soils extend from depths of 1.75 to 2.5 feet and to a total width of 4 feet across the ditch, total MTCA soil volume would be approximately 22 cubic yards. By including a 25 percent contingency, the estimated volume of MTCA soil is about 30 cubic yards.
- ▶ Boring HC-1 soil test results showed instances of contamination deeper than expected. Boring HC-1A was installed to confirm the presence or absence of the lead at these deeper levels. Soil test results from HC-1A showed no deep lead contamination, indicating that the instances of deep lead contamination in HC-1 were most likely caused by sluffing of the high lead concentration soils at the surface into the deeper part of HC-1.

## RESULTS OF GROUNDWATER CHEMICAL ANALYSES

Groundwater depth in the upper ditch monitoring well (HCG-3) was measured at 3.9 feet beneath the ground surface. Groundwater depth in the lower ditch monitoring well (HCG-8) was measured at 4.3 feet beneath the ground surface. It appears that the perched groundwater table was below the vertical extent of soil contamination when we sampled in July 1992. It is unknown whether the groundwater table rises during the wet season to an elevation that is within the contaminated soil interval.

Both dissolved lead and TPH were detected in the upper ditch groundwater well at concentrations which exceeded MTCA Method A groundwater cleanup standards. Dissolved lead was detected at a concentration of 53  $\mu\text{g/L}$  and TPH detected at a concentration of 2,500  $\mu\text{g/L}$ . The MTCA Method A cleanup standard for these two constituents is 5.0  $\mu\text{g/L}$  for lead and 1,000  $\mu\text{g/L}$  for TPH. An assessment of the groundwater gradient was beyond the scope of this initial investigation, so at this time it is not known whether the contaminated groundwater has migrated beyond the source.

Monitoring well HCG-8 in the lower ditch was apparently completed in a boring that contained unset grout, which resulted in a pH of 12 and very high conductivity measurements. Because of the high water pH, analytical results from this well were invalidated. HCG-8 was a planned temporary well and a more permanent well is recommended for this area and for the upper ditch once soil remediation has



occurred. The permanent well should be sufficient for providing initial as well as ongoing groundwater analyses.

## SUMMARY OF RECOMMENDED REMEDIAL ALTERNATIVES

### *Soil Remediation*

We have included two recommended alternatives for soil cleanup. These alternatives are deemed the most cost-effective based on the calculated volumes of soil affected and the most time-effective given the time constraints of this project.

#### *Alternative 1 - Excavation and Direct Disposal*

Alternative 1 involves careful excavation of the contaminated soil in thin layers, and separation and placement of the layers into stockpiles of approximately 10 cubic yards in volume for testing and disposal designation. Soil stockpiles that exceed the TCLP lead limit of 5 mg/L (we estimate 65 cubic yards) will be shipped to the hazardous waste landfill in Arlington, Oregon. Remaining soil stockpiles that exceed the 1,000 mg/kg total lead cleanup standard from the upper ditch, or the 250 mg/kg total lead cleanup standard from the lower ditch (estimated to be about 30 cubic yards) will be shipped to a permitted solid waste landfill.

Excavation side walls and bottoms will be sampled and analyzed for total lead, TCLP lead (where necessary), and TPH to verify that the cleanup standards have been achieved.

Table 1 provides a summary of estimated costs for Alternative 1. The total estimated cost for excavation and direct disposal is \$95,000.

We assume that the site can be excavated without encountering the perched groundwater. If that is true, then no soil dewatering would be needed to pass the paint filter test for free liquid. If the excavation encounters perched water, then additional steps would be required to dewater the excavated soil.



### *Alternative 2 - On-Site Soil Treatment and Off-Site Disposal*

Alternative 2 involves excavation and segregation of the soils into RCRA and MTCA stockpiles. RCRA soil stockpiles would first be treated on site to reduce the TCLP lead level to below the RCRA cleanup level.

All excavated soils that then exceed the total lead limit of 1,000 mg/kg from the upper ditch or 250 mg/kg from the lower ditch would be shipped to a permitted solid waste landfill for ultimate disposal. Excavation side walls and bottoms will be sampled to verify that the cleanup standard has been achieved.

A treatability study would be performed by the Hart Crowser *FAST* Laboratory to determine the optimum treatment for stabilization of the RCRA soils to reduce the TCLP lead concentration to less than 5 mg/L. This method might involve the use of fly ash, Portland cement, or other materials mixed to achieve the desired result.

Table 2 provides a summary of estimated costs for Alternative 2. The total estimated cost for treatment and disposal is \$110,000.

### *Post-Cleanup Activities*

Once soil remediation has been accomplished using either Alternative 1 or Alternative 2 described above, the site will be restored with clean, approved structural backfill.

A site closure report will be prepared that summarizes final volumes of soil excavated, treatment methods used, if applicable, and final destination(s) of affected soils. Soil cleanup will be verified based on excavation side wall and bottom soil samples analytical results.

### *Groundwater Monitoring*

Finally, as part of this remediation effort, we recommend that groundwater monitoring wells be installed in or adjacent to the upper and lower ditches and that groundwater be sampled quarterly for a minimum of one year to assess groundwater quality improvements. By removal of the TPH and lead contaminant sources, the



perched groundwater should slowly improve in quality. We wish to emphasize, however, that given our limited knowledge about this groundwater hydraulic system and the type of co-contaminants that may be affecting it, it is impossible to predict to what degree and how soon groundwater quality improvements will occur.

#### **RECOMMENDED ADDITIONAL SITE WORK**

If, after a year's time, no improvement in groundwater quality is seen, you may wish to consider installing additional groundwater monitoring wells for the purposes of establishing flow directions and flow volumes, and to determine background quality of the groundwater.

#### **LIMITATIONS**

Work for this project was performed, and this letter report prepared, in accordance with generally accepted professional practices for the nature and conditions of the work completed in the same or similar localities, at the time the work was performed. It is intended for the exclusive use of Snohomish County Public Utilities District No. 1 for specific application to the referenced property. This report is not meant to represent a legal opinion. No other warranty, express or implied, is made.

Any questions regarding our work and this letter report, the presentation of the information, and the interpretation of the data are welcome and should be referred to the undersigned.





Snohomish County Public Utilities District No. 1  
September 2, 1992

J-3603  
Page 9

We trust that this report meets your needs.


Sincerely,

**HART CROWSER, INC.**



**SUSAN P. HARP**  
Project Engineer

PHS1.LR



**JAMES M. WILDER**  
Associate

**Attachments:**

Table 1 - Estimated Costs for Excavation and Off-site Disposal

Table 2 - Estimated Costs for Soil Treatment and Off-site Disposal

Figure 1 - Vicinity Map

Figure 2 - Chemical Analytical Results for Upper Ditch Soil Samples and  
Upper Ditch Boring Location Plan

Figure 3 - Chemical Analytical Results for Lower Ditch Soil Samples and  
Lower Ditch Boring Location Plan

Attachment A - Soil Boring Logs

Attachment B - Soil and Groundwater Chemical Analytical Results  
Hart Crowser *FAST* Laboratory and  
Sound Analytical Services, Inc.


Table 1 - Estimated Costs for Excavation and Off-site Disposal  
Sno PUD Halls Lake

<u>Basis:</u>				
Excavate and segregate soil with TPH or lead exceeding cleanup standard.				
Sample each 10-cy stockpile for disposal designation.				
Ship TCLP-lead soil to Arlington.				
Ship remaining soil to sanitary landfill.				
Restore site with structural backfill.				
Install groundwater monitoring well; 4 rounds of samples for Pb/TPH.				
Prepare site closure reports.				
DESCRIPTION	UNITS	QUANT.	UNIT COST	SUBTOTAL COST
<u>Permits and Approvals</u>				
CWMI approval	Ea	1	\$1,500	\$1,500
Sanitary landfill approval	Ea	1	\$100	\$100
Grading permit	Ea	1	\$800	\$800
Contracts and procurement	Ea	1	\$1,000	\$1,000
Subtotal				\$3,400
<u>Soil Remediation</u>				
Mobilization	Ea	1	\$2,000	\$2,000
Strategic Sidewall Sampling	Ea	25	\$250	\$6,250
Soil Excavation	Cy	95	\$28	\$2,660
Stockpile Sampling	Samples	10	\$250	\$2,500
Soil Loading	Ton	150	\$5	\$750
RCRA Ship/Disposal	Ton	98	\$245	\$24,010
Sanitary Ship/Disposal	Ton	45	\$65	\$2,925
Site Backfilling	Cy	95	\$20	\$1,900
Field Supervisor	Days	6	\$1,200	\$7,200
Sampling Technician	Days	6	\$600	\$3,600
Subtotal				\$53,795
<u>Groundwater Quality Monitoring</u>				
Mobilization	Ea	1	\$2,000	\$2,000
Sampling Plan	Ea	1	\$2,500	\$2,500
Well Installation	Ea	2	\$3,000	\$6,000
Well Sampling	Days	4	\$800	\$3,200
Water Analysis	Ea	10	\$200	\$2,000
Subtotal				\$15,700
<u>Remediation Documentation</u>				
Soil Remediation Report	Ea	1	\$3,000	\$3,000
Groundwater Quality Report	Ea	1	\$2,500	\$2,500
Subtotal				\$5,500
SUBTOTAL COST				\$78,395
CONTINGENCY (20%)				\$15,679
TOTAL COST				\$94,074

Table 2 - Estimated Costs for Soil Treatment and Off-site Disposal  
Sno PUD Halls Lake

<u>Basis:</u>				
Perform lead treatability tests.				
Excavate and segregate soil with TPH or lead exceeding cleanup standard.				
Treat TCLP-lead to under TCLP limits.				
Ship all soil to sanitary landfill.				
Restore site with structural backfill.				
Install groundwater monitoring well; 4 rounds of samples for Pb/TPH.				
Prepare site closure reports.				
DESCRIPTION	UNITS	QUANT.	UNIT COST	SUBTOTAL COST
<u>Permits and Approvals</u>				
RCRA/TBG Approval	Ea	1	\$5,000	\$5,000
Sanitary landfill approval	Ea	1	\$100	\$100
Grading permit	Ea	1	\$800	\$800
Contracts and procurement	Ea	1	\$1,000	\$1,000
Subtotal				\$6,900
<u>Soil Remediation</u>				
Treatability Tests	Ea	1	\$15,000	\$15,000
Mobilization	Ea	1	\$5,000	\$5,000
Strategic Sidewall Sampling	Ea	25	\$250	\$6,250
Soil Excavation/Segregation	Cy	95	\$28	\$2,660
Stockpile Sampling	Samples	10	\$250	\$2,500
Soil Stabilization	Ton	90	\$60	\$5,400
Landfill Shipping/Disposal	Ton	222	\$56.48	\$12,539
Site Backfilling	Cy	95	\$20	\$1,900
Field Supervisor	Days	7	\$1,200	\$8,400
Sampling Technician	Days	7	\$600	\$4,200
Subtotal				\$63,849
<u>Groundwater Quality Monitoring</u>				
Mobilization	Ea	1	\$2,000	\$2,000
Sampling Plan	Ea	1	\$2,500	\$2,500
Well Installation	Ea	2	\$3,000	\$6,000
Well Sampling	Days	4	\$800	\$3,200
Water Analysis	Ea	8	\$250	\$2,000
Subtotal				\$15,700
<u>Remediation Documentation</u>				
Soil Remediation Report	Ea	1	\$3,000	\$3,000
Groundwater Quality Report	Ea	1	\$2,500	\$2,500
Subtotal				\$5,500
SUBTOTAL COST				\$91,949
CONTINGENCY (20%)				\$18,390
TOTAL COST				\$110,338

# Vicinity Map



0 1/2 1  
Scale in Miles




**HARTCROWSER**

J-3603


8/92

Figure 1

Chemical Analytical Results for Upper Ditch Soil Samples



Upper Ditch Boring Location Plan




HC-1  
330.0  
TPH in mg/kg S1 Total Pb in mg/kg  
(TCLP Pb in mg/L)  
S2  
19


Boring Number  
Approximate Elevation in Feet  
Constituent and Concentration  
Sample Number and  
Approximate Sampling Interval  
Total Depth of Boring in Feet

NS Not Sampled  
NT Not Tested  
25U Not Detected at Detection Limit Indicated  
(D) Duplicate Sample


Chemical Analytical Results for Lower Ditch Soil Samples



Lower Ditch Boring Location Plan



●HC-9 Boring Location and Number



HC-8		Boring Number	
320.0		Approximate Elevation in Feet	
TPH in mg/kg	S1	Total Pb in mg/kg (TCLP Pb in mg/L)	NS Not Sampled
	S2	Sample Number and Approximate Sampling Interval	NT Not Tested
	21.5	Total Depth of Boring in Feet	25U Not Detected at Detection Limit Indicated

Hart Crowser  
J-3603

**ATTACHMENT A  
SOIL BORING LOGS**

ing Location: HC-1 (IN DITCH)  
N  
ation: Datum:  
Well Install. ☒ Yes ☐ No

**HARTCROWSER**

Boring HC-1 Date 7/22/92 Sheet 1 of 1  
Job SNOWMOUSE P.U.D. Job No. 3603  
Logged By CW Weather DRIZZLE  
Drilled By CAMPELL  
Drill Type/Method HSA 140 lb HAMMER  
Sampling Method 2" SPT  
Bottom of Boring 16.5 ATD Water Level Depth 3.8 ☒ No

S (%)		PID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION; Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS; Drill action, drill and sample procedures, water conditions, heave, etc...	SUMMARY LOG (Water & Date)
S	F		From	To	Type	Number					
Range	Att. Limits										
10	60		0	1		S-1	0		1715 (SOFT) MOIST BLACKISH TAN VY SANDY SILT - ORGANICS, ODOR - PETROL? BLACK STAINS IN SOIL	1-16 oz TAA	VY SANDY SILT
50	25		2.5	4.0		S-2	3	7	DENSE WET BROWNISH GRAY SILTY GRAVELLY SAND - NO STAIN OR ODOR	1-16 oz No STANDING H2O	SILTY GRAVELLY SAND
15	35		5	6.5		S-3	5	50/5	VY DENSE MOIST TAN GRAVELLY VY SILTY SAND TILL?	1-16 oz DRILLING VY HARD	GRAVELLY VY SILTY SAND
15	35		7.5	9.0		S-4	8	50/4	VY DENSE MOIST TAN GRAVELLY VY SILTY SAND	1-16 oz	
15	25		10	11.5		S-5	10	50/4	VY DENSE MOIST TAN GRAVELLY SILTY SAND	1-16 oz	GRAVELLY SILTY SAND
10	35					S-6	13	50/5	VY DENSE MOIST GRAY GRAVELLY VY SILTY SAND TILL?	1-16 oz	GRAVELLY VY SILTY SAND
10	35					S-7	15	50/2	VY DENSE MOIST GRAY GRAVELLY VY SILTY SAND	Poor RECOVERY 1-16 oz	
							17		BOTTOM OF BORING 16.5'		
							18				
							19				
							20				



Well Installation		Datum		Date		Location	
Yes	No	Yes	No	Yes	No	Yes	No
Well installed		Datum		Date		Location	
Boring H/L-1A		Job No. 3603		Sheet 1 of 2		Boring H/L-1A	
Drilled By C. J. HARRIS		Logged By C. J. HARRIS		Weather Sunny		Drill Type/Method HSR 140 lb HAMMER	
Sampling Method 20 SPI		Bottom of Boring 26.5		ATD Water Level Depth		No	
Penetration Resistance		SAMPLE RECOVERY		SAMPLE Type		SAMPLE Number	
DESCRIPTION: Den., moist., color, minor, major constituent, NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.		REMARKS: Drill action, drill and sample procedure, water conditions, heave, etc., etc.		SUMMARY LOG (Water & Date)			
0-1 (Loose) Moist dr. gravelly sand - silt. w/ gravelly sand - HIGH GRAVELS; silt. HAS BLACK STAINING - PETROL OIL. PIECES OF GLASS FOUND		1-1602		SAND			
5-6 VY DENSE WET GRAY BROWN SKTY W/ SANDY GRAVEL		1/3 - 1602		GRAVEL			
10-11 VY DENSE MOIST LT REDDISH BROWN SKTY GRAVELLY SAND		1/2 - 1602		GRAVEL			
15-16 K.5		1/2 - 1602		GRAVEL			
17-18		1/2 - 1602		GRAVEL			
19-20		1/2 - 1602		GRAVEL			

ing Location:

HARTCROWSER

Boring 4C-1A Date 7/30/92 Sheet 2 of 2  
Job SWP PUD Job No. 3603  
Logged By CLW Weather SUNNY 90°  
Drilled By CAMPBELL DRILLING  
Drill Type/Method HSA 140 lb HAMMER  
Sampling Method 2" SPT  
Bottom of Boring 26.5 ATD Water Level Depth No

ation: Datum:

Well Install. ☒ Yes ☐ No

S (%)		PID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION; Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS; Drill action, drill and sample procedures, water conditions, heave,...etc...	SUMMARY LOG (Water & Date)
S	F		From	To	Type	Number					
ange	Att. Limits										
			20	21.5	X	5-5	20	504	No RECOVERY	No SAMPLE	
							21				
							22				
							23				
							24				
35	15		25	26.5	X	5-6	25	503	VERY DENSE WET GRAY SILTY VY JANDY GRAVEL TILL?	POOR RECOVERY 1/8 7602	SILTY VY SANDY GRAVEL
5.0							26				
							27				
							28				
							29				
							30		B.O. BORING 26.5'		
							1				
							2				
							3				
							4				
							5				
							6				
							7				
							8				
							9				
							0				

ng Location:
 

☐
 HEATS RADIATOR

HC-2

ation:
 Datum:

Well Install.
 ☒
 Yes
 ☒
 No

Boring HC-2 Date 7/22/92 Sheet 1 of 1  
 Job SNOWHORNISH PUD Job No. 3603  
 Logged By CLW Weather DRIZZLE  
 Drilled By CAMPELL  
 Drill Type/Method HSA 140 lb HAMMER  
 Sampling Method 2" SPT  
 Bottom of Boring 16.5' ATD Water Level Depth 10.5' ☒ No

S (%)		PID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION; Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS; Drill action, drill and sample procedures, water conditions, heave, etc...	SUMMARY LOG (Water & Date)
S	F		From	To	Type	Number					
Range	Att. Limits										
35 -C	15		0	1		S-1	0		(LOOSE) MOIST RED BROWN SILTY VY SANDY GRAVEL	1-1602 SAMPLE	SILTY VY SANDY GRAVEL
5 -M	60		2.5	3.0		S-2	3	14	(STIFF) MOIST RED BROWN GRAVELLY SANDY SILT	1/2-1602	GRAVELLY SANDY SILT
5 -C	2		3.0	4.0		S-2A	4	16 27	DENSE MOIST GRAY RED BROWN VY SANDY GRAVEL Fe STAIN	1-1602	VY SANDY GRAVEL
15 -M	35		5	6.5		S-3	5	54	VY DENSE MOIST BROWNISH GRAY GRAVELLY VY SILTY SAND - TILL?	1-1602	GRAVELLY VY SILTY SAND
25 -M	25		7.5	9.0		S-4	8	33 50	VY DENSE MOIST-WET GRAY SILTY SANDY GRAVEL - Fe STAIN TILL?	1-1602 SAMPLE CONTAINS MORE MOISTURE THAN ABOVE - NO STANDING H2O	SILTY SANDY GRAVEL
30 -C	10		10	11.5		S-5	10	50 1/2	VY DENSE WET GRAY BROWN SL SILTY VY SANDY GRAVEL	POOR RECOVERY 1/4 1602 * STANDING H2O - MEAN AT 10.5' w/ SOUNDER	SL SILTY VY SANDY GRAVEL
20 -C			12.5	14.0		S-6	13	50 1/2	VY DENSE WET BROWN SANDY GRAVEL - SAND IS INTERBEDDED WITH THE GRAVELS	1-1602 STANDING H2O	SANDY GRAVEL
15 -F	35		15	16.5		S-7	15	50 1/2	VY DENSE MOIST GRAY SANDY VY SILTY GRAVEL	POOR RECOVERY APPEAR. TO HAVE GONE THROUGH H2O ZONE	SANDY VY SILTY GRAVEL
						S-8	17		BOTTOM OF BORING 16.5'		
						S-9	18		1545		
							19				
							20				

Boring Location:

Date: 7/23/02 Sheet 1 of 2  
 Job: SNOWHORN P.U.D. - HALLS LAKE Job No. 2603  
 Logged By: CLW Weather: PLY CLOUDY  
 Drilled By: CAMARILL DRILLING  
 Drill Type/Method: HSA 14016 HAMMER  
 Sampling Method: 2" SPT  
 Bottom of Boring: 31.5 ATD Water Level Depth: 3.9 ☒ ☐

Well Install. ☒ ☐

Depth (ft)	F	PID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION; Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS; Drill action, drill and sample procedures, water conditions, heave, etc...	SUMMARY LOG (Water & Date)
			From	To	Type	Number					
0	90		0	1	S-1		0		SOFT WET BLACK BROWN SL SANDY SILTY CLAY - HIGH ORGANICS; BLACK LAYERS IN CLAY; PETROL ODR	LOCATED IN DITCH 1-1602	SL SANDY SILTY CLAY
2.5	85		2.5	3.5	S-2		1		SOFT WET DR BROWN SANDY SILT - SOME YELLOW BLACK STAIN; ORGANICS - NO DETECTABLE ODR	1-1602	SANDY SILT
3.5	100		3.5	4	S-2A		2		SOFT WET DR RED BROWN SILTY CLAY - STRONG ROTTEN EGG ODR - HIGH ORGANICS	1-1602	SILTY CLAY
5.0	25		5.0	6.5	S-3		3		DENSE MOIST BROWN GRAY SILTY GRAVELLY SAND - SL Fe STAIN	1-1602	SILTY GRAVELLY SAND
7.5	15		7.5	9.0	S-4		4		DENSE WET GREEN BROWN SILTY SAND	POOR RECOVERY 1/2 - 1602	SILTY SAND
10.0	15		10.0	11.5	S-5		5		DENSE WET GREEN BROWN SL GRAVELLY SILTY SAND	1-1602	SL GRAVELLY SILTY SAND
12.5	2		12.5	14.0	S-6		6		W DENSE WET GREEN BROWN SL GRAVELLY SAND - POSSIBLE SLUFF - SAND DOESN'T APPEAR TO BE AS DENSE AS RECORDED	1-1602	SL GRAVELLY SAND
15	15		15	16.5	S-7		7		W DENSE WET GREEN BROWN SL GRAVELLY SILTY SAND - SOME OF SAND POSSIBLE SLUFF	1/4 1602	SL GRAVELLY SILTY SAND

g Location:


HARTCROWSER

Boring HC-3 Date 7/24/92 Sheet 2 of 2  
Job SNOWHORN P.U.D Job No. 3603  
Logged By CW Weather \_\_\_\_\_  
Drilled By CAMMELL DRILLING  
Drill Type/Method H517 140 lb HAMMER  
Sampling Method 2" SPT  
Bottom of Boring 31.5' ATD Water Level Depth 3.9 NO

tion: Datum:
Well Install. ☒ Yes ☐ No

S (%)		PID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION: Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS; Drill action, drill and sample procedures, water conditions, heave,...etc....	SUMMARY LOG (Water & Date)
S	F		From	To	Type	Number					
Age	Att. Limits										
5	25		20	21.5	X	58	20	50/6	14 DENSE MUST GRAY SILT GRAVELLY SILTY SAND TILL?	2' HEAVE 1-1602	FL GRAVELLY SILTY SAND
5	15		25	26.5	X	59	25	50/5	14 DENSE MUST TO WET GRAY SILTY GRAVELLY SAND	18" HEAVE 1-1602	SILTY GRAVELLY SAND
			30	31.5	X	546	30	50/4	No RECOVERY-HITTING ON TOP OF LG ROCK B.O.B 31.5'	DRILLING EASIER AT 26'	
							21				
							22				
							23				
							24				
							26				
							27				
							28				
							29				
							31				
							32				
							33				
							34				
							5				
							6				
							7				
							8				
							9				
							0				

g Location:



HARTCROWSER

Boring HC-5 Date 2/23/62 Sheet 1 of 1  
 Job INDIANOMIS P.U.D Job No. 3603  
 Logged By CLW Weather DRIZZLE  
 Drilled By CAMPBELL BERLING  
 Drill Type/Method HSA 140 lb HAMMER  
 Sampling Method 2" SPI  
 Bottom of Boring 14.0' ATD Water Level Depth \* No

ation: Datum:

Well Install. ☒ Yes ☒ No

(%)		PID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION: Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS: Drill action, drill and sample procedures, water conditions, heave,...etc...	SUMMARY LOG (Water & Date)
S	F		From	To	Type	Number					
5	45		0	1		S-1	0		(LOOSE) WET DR BROWN VY SILTY SAND - LOTS OF ORGANICS - THIN BLACK LAYERS PETROL? OIL - SHEEN ON WATER	STANDING H <sub>2</sub> O IN DITCH 1-16 02 JAN	VY SILTY SAND
	100		2.5	4		S-2	3	1	(SOFT) MOIST - WET DR BROWN BRN SILTY CLAY - HIGH IN ORGANICS - ROTTEN EGG ODOR: SOME BLACK STAIN	1-16 03	SILTY CLAY
5	45		5	6.5		S-3	5	4	MED DENSE WET GRAY VY SILTY SAND - THIN INTERBEDDED BANDS OF SILT + SAND - NO STAIN OR OIL	APPEAR TO BE IN WATER ZONE 1-16 02	VY SILTY SAND
2	20		7.5	8.5		S-4	8	10	DENSE WET GRAY SL GRAVELLY SILTY SAND	1-16 02	SL GRAVELLY SILTY SAND
10	20		8.5	9.0		S-4A	9	13	DENSE WET DR RED BROWN SILTY SAND - SEPARATED OUT FROM S-4 DUE TO STAINING	1-16 02	SILTY SAND
0	25		10	11.5		S-5	10	33	W DENSE "WET" GRAY GRAVELLY SILTY SAND TILL? SAMPLE WET DUE TO WATER RUNNING IN FROM DITCH	POOR RECOVERY 1/8 16 02	GRAVELLY SILTY SAND
25	25		12.5	14		S-6	13	52/5	VY DENSE MOIST GRAY SILTY SANDY GRAVEL	POOR RECOVERY 1/8 16 02	SILTY SANDY GRAVEL
							14		BOTTOM OF BORING 14'		
							15				
							16				
							17				
							18				
							19				
							20				

Boring Location: HC-5 HC-6


HART CROWSEY  
 Boring HC-6 Date 7/23/42 Sheet 1 of 1  
 Job SNOWHORNISH P.U.D. Job No. 3603  
 Logged By CLW Weather CLOUDY  
 Drilled By CARROLL DRILLING  
 Drill Type/Method HSA 140 lb HAMMER  
 Sampling Method 2" SPT  
 Bottom of Boring 19 ATD Water Level Depth \* NO

Station: Datum:

Well Install. ☒ Yes ☒ No

S (%)		PID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION: Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS: Drill action, drill and sample procedures, water conditions, heave, etc...	SUMMARY LOG (Water & Date)
S	F		From	To	Type	Number					
5	20										
5	20		0	1	S-1		0		(LOOSE) MOIST DK BROWN SILTY GRAVELLY SAND - ORGANICS NO STAIN OR ODOR	1-16 02	SILTY GRAVELLY SAND
10	25		2.5	4.0	S-2		3	4	LOOSE MOIST-WET RED BROWN SL GRAVELLY SILTY SAND - LOTS OF WOOD FRAGS	1/2 16 02	SL GRAVELLY SILTY SAND
5	95		5	6	S-3		7	9	STIFF MOIST DK RED BROWN SILT - LOTS OF WOOD - ROTTEN FEGG ODOR	1-16 02	SILT
15	25		6	6.5	S-3A		17		MED DENSE MOIST GRAY SILTY SAND	1-16 02	SILTY SAND
3	15		7.5	9.0	S-4		8	11	DENSE WET GRAY SILTY SAND - SOME Fe STAIN	1-16 02	
40	2		10	11.5	S-5		10	54/5	VY DENSE WET GRAY VY SANDY GRAVEL - TILL?	1/4-16 02	VY SANDY GRAVEL
40	2		12.5	14.0	S-6		13	33 52/3	VY DENSE WET GRAY VY SANDY GRAVEL - SL Fe STAIN	1-16 02	
10	20		15	16.5	S-7		15	50/3	VY DENSE WET GRAY SILTY GRAVELLY SAND - SL Fe STAIN WETNESS COULD BE COMING IN FROM ABOVE	POOR RECOVERY 1/16-16 02	SILTY GRAVELLY SAND
5	10		17.5	19	S-8		18	50/2	VY DENSE MOIST GRAY SL SILTY VY SANDY GRAVEL - SL Fe STAIN	POOR RECOVERY 1/8-16 02	SL SILTY VY SANDY GRAVEL
							19		B.O.B 19'		

\* LEE - HOLE OPEN - WILL DETERMINE H<sub>2</sub>O LEVEL 7/24/42 AM [3.4' OR 2.24']




Boring HC-7 Date 7/27/42  
 Job No. 303  
 Logged By [Signature]  
 Drilled By [Signature]  
 Sampling Method 2" SPT  
 Bottom of Boring 5.5' ATD Water Level Depth 4.5' No

Well Install.	Yes	No	Date	To	From	DEPTH	SAMPLE	Type	Number	SAMPLE RECOVERY	Penetration Resistance	REMARKS: Drill action, ures, water conditions, heave, etc...		LOG	(Water & Date)	SUMMARY

0.25	0	1	5-1									(LOOSE) MUST ON GROWN SILTY GRAVELLY SAND HIGH ORGANICS	1-1602	SANDY SILTY SAND		
0.15	2.5	4.0	5-2	X								(AND DENSE) WET GRAY SILTY GRAVELLY SAND-FO STAIN (DENSE) WET GRAY SILTY W/ CARBELL SAND - TILL	1-1602	SILTY W/ GRAVELLY SAND		
0.15	4.0	5.5	5-3	X								* COULD PENETRATE FURTHER WITH TOOL AT HAND				
0.15	4.0	5.5										DUE TO 40 LB HAMMER NO ALLOW CORALTS WERE TAKEN - NOT ENOUGH WEIGHT TO MOVE SPT THROUGH SOIL				






HARTCROWSER

Boring HC-8 Date 7/27/92 Sheet 1 of 1  
 Job SNOWBUSH P.D. Job No. 3603  
 Logged By CLW Weather SUNNY  
 Drilled By CAMPBELL DRILLING  
 Drill Type/Method HSA 140# HAMMER  
 Sampling Method 2" SPT  
 Bottom of Boring 21.5 ATD Water Level Depth 4.3 No


ation: Datum:  
 Well Install. ☒ Yes ☐ No

E (%)		ID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION: Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS: Drill action, drill and sample procedures, water conditions, heave,...etc...	SUMMARY LOG (Water & Date)
S	F		From	To	Type	Number					
Range	Att. Limits										
75	25		0	1	S-1		0		(LOOSE) MOIST Dk BROWN SILTY SAND - HIGH ORGANICS NO STAIN OR ODOR	1-16 oz	SILTY SAND
50	35		2.5	4.0	S-2		2		LOOSE MOIST-WET RED BRN GRAVELLY VY SILTY SAND ORGANICS, Fe STAIN, SL BLACK STAIN - NO ODOR	1-16 oz	GRAVELLY VY SILTY SAND
50	35		5	6.0	S-3		3		LOOSE WET BROWN GRAVELLY SILTY SAND - ORGANICS Fe STAIN	1-16 oz	
00			6.0	6.5	S-3A		5		MED DENSE WET GREEN GRAY SAND - SL Fe STAIN	1-16 oz	SAND
			7.5	9.0	S-4		8		No RECOVERY - HITTING ON TOP OF ROCK?	No SAMPLE	
55	20		10	11.5	S-5		10		VY DENSE WET GRAY GRAVELLY SILTY SAND - TILL?	1/2 - 16 oz	GRAVELLY SILTY SAND
			15	16.5	S-6		15		No RECOVERY - SPT - WET	No SAMPLE	
58	2		20	21.5	S-7		20		VY DENSE WET GRAY VY GRAVELLY SAND	Poor RECOVERY 1/4 - 16 oz	VY GRAVELLY SAND



ing Location: HART CROWSER  
Boring HC-9 Date 7/27/92 Sheet 1 of 1  
Job Sno P.U.D. Job No. 3603  
Logged By CLW Weather SUNNY  
Drilled By CAMARILL DRILLING  
Drill Type/Method HSA 146 lb HAMMER  
Sampling Method 2" SPT  
Well Install. ☒ Yes ☐ No  
Datum: Bottom of Boring 11.5' ATD Water Level Depth 4.9' No

S (%)		PID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION; Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS; Drill action, drill and sample procedures, water conditions, heave,...etc...	SUMMARY LOG (Water & Date)
S	F		From	To	Type	Number					
7	15		0	1		5-1	0		LOOSE DAMP BROWN SILTY GRAVELLY SAND - ORGANICS - NO STAIN OR ODOR	1-1602	SILTY GRAVELLY SAND
15	40		2.5	4.0		5-2	3		LOOSE DAMP-WET GRAVELLY VY SILTY SAND - ORGANICS	1-1602	GRAVELLY VY SILTY SAND
5	25		5.0	5.5		5-3	4		(LOOSE) MOIST ADA BROWN SL GRAVELLY SILTY SAND	1/4 - 1602	
0	55		5.5	6.5		5-4	4		STIFF VY WET GRANGE SANDY GRAVELLY SILT - VY HIGH Fe STAIN - ORGANICS	1-1602	SANDY GRAVELLY SILT
4	1		7.5	9.0		5-5	8	28	VY DENSE WET GRAY GRAVELLY SAND	1-1602	GRAVELLY SAND
5	1		10	11.5		5-5	10	45	VY DENSE WET GRAY GRAVELLY SAND	3/4 - 1602	
							11	506			
							12		B.O.B 11.5'		
							13				
							14				
							15				
							16				
							17				
							18				
							19				
							20				



**HARTCROWSER**

Boring HL-10 Date 7/27/92 Sheet 1 of 1

Job SNO. P.U.D. Job No. 3603

Logged By CWL Weather SUNNY

Drilled By CAMPELL DRILLING


Drill Type/Method HSA 140/16 HAMMER

Sampling Method 2" SPT

Bottom of Boring 21.5 ATD Water Level Depth No

S (%)		PID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION; Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS; Drill action, drill and sample procedures, water conditions, heave,...etc...	SUMMARY LOG (Water & Date)
S	F		From	To	Type	Number					
55	20		0	1		S-1	0		(LOOSE) DAMP BROWN SILTY GRAVELLY SAND - HIGH ORGANICS, NO STAIN OR ODOR	1-16 02	SILTY GRAVELLY SAND
-5	20		2.5	3.5		S-2	4		MED DENSE MOIST BROWN SILTY GRAVELLY SAND - ORGANICS	1/2 16 02	
65	25		3.5	4.0		S-2	41	24	DENSE MOIST RED BROWN SL GRAVELLY SILTY SAND - ORGANICS	1/2 - 16 02	SL GRAVELLY SILTY SAND
55	20		5.0	6.5		S-3	5	4	MED DENSE RED GRAY BRN SILTY GRAVELLY SAND	1-16 02	SILTY GRAVELLY SAND
55	15		7.5	9.0		S-4	8	17	DENSE WET GRAY SILTY SAND	3/4-16 02	SILTY SAND
65	10		10	11.5		S-5	10	17	VERY DENSE WET GRAY SL SILTY GRAVELLY SAND - TILL?	1-16 02	SL SILTY GRAVELLY SAND
70	15		15.0	16.5		S-6	15	15	VERY DENSE MOIST GRAY SILTY GRAVELLY SAND	1/2-16 02	SILTY GRAVELLY SAND
55	30		20	21.5		S-8	20	48	VERY DENSE WET GRAY GRAVELLY SILTY SAND	1/2 16 02	GRAVELLY SILTY SAND

ing Location:



HARTCROWSER

Boring HC-11 Date 7/30/92 Sheet 1 of 1  
Job SNO FUD Job No. 3603  
Logged By CWW Weather SUNNY 90°  
Drilled By CAMBIELL DRILLING  
Drill Type/Method RAMCO 14014 HAMMER  
Sampling Method 2" SPI  
Bottom of Boring \_\_\_\_\_ ATD Water Level Depth No

ation: Datum:


Well Install. ☒ Yes ☐ No

S (%)		PID or other	DEPTH		SAMPLE		SAMPLE RECOVERY	Penetration Resistance	DESCRIPTION; Den., moist., color, minor, MAJOR CONSTITUENT. NON-SOIL SUBSTANCES: Odor, staining, sheen, scrap, slag, etc.	REMARKS; Drill action, drill and sample procedures, water conditions, heave,...etc...	SUMMARY LOG (Water & Date)
S	F		From	To	Type	Number					
5	45		0	1		5-1	0		(LOOSE) MOIST BLACKISH OR BROWN VY SILTY SAND - HIGH ORGANICS - BLACK STAIN IN SILT - PETROL ODOR?	1-1602	
			2.5	4.0		5-2	3		SHUT DOWN DUE TO BREAKDOWN OF RAMCO DRILLING UNIT		
			5	6.5		5-3	6				
			7.5	9.0		5-4	8				
			10	11.5		5-5	11				
			15	16.5		5-6	16				
			20	21.5		5-7	20				

# Installation Report

# Monitoring Well HC-3

Project SNOWHOMISH P.U.D. Job No. 3603 Date 7/24/92  
 Location MYLK TERRACE (HALLS LANE) HC Observer CWW Driller TOM CAMPBELL  
 Type of Well (Observation, Sampling, Vapor Extraction) OBSERVATION



Remarks: MONITORING WELL LOCATED ~ 4' EAST OF ORIGINAL HC-3 IN DITCH. NEW BORING DRILLED TO 9.0'

Materials Tally:

(100lb) Sand	<u>3 BAGS (300lbs)</u>	Monument	<u>1</u>
(60lb) Cement	<u>4 BAGS (240lbs)</u>	PVC	<u>10'</u>
(50lb) Bentonite	<u>1 BAG (50lb)</u>	Other	<u></u>


# Installation Report

## Monitoring Well HC-8

Project SNODGRASS P.V.D. Job No. 3603 Date 7/27/92

Location MILL TERRACE, WA HC Observer CWU Driller CAMDELL

Type of Well (Observation, Sampling, Vapor Extraction) OBSERVATION



Remarks: ABANDONED HOLE FROM 10-20'

### Materials Tally:

(100lb) Sand 3 BAGS (300lb)

(60lb) Cement 6 BAGS (360lb)

Bentonite \_\_\_\_\_

Monument 1

PVC \_\_\_\_\_

Other \_\_\_\_\_

# Groundwater Sampling Data

Project SNOWBERRY P.U.D.  
Field Rep. CARL WOLFE

Job No. 3603  
Date 7/30/92

WELL NUMBER	DATE SAMPLED	WELL DEPTH IN FEET	DEPTH TO WATER IN FEET	DEPTH TO SEDIMENT IN FEET	SEDIMENT THICKNESS IN FEET	METHOD OF SAMPLING	COMMENTS	DO <sub>2</sub> %	T °C	pH	EC IN µMHOS	CASING VOLUME IN GALLONS	PURGE VOLUME IN GALLONS
HC-3 STICK UP 1.70'	7/30/92	8'	3.05			20' 55" BAILER	WILL BAIL DRY 2 TIMES BEFORE SAMPLING OR BROWN VY TURBID H <sub>2</sub> O - NO SHEEN OR OOR - 1/2" OF FINE SAND AT BOTTOM OF BUCKET	2.7	15.5	6.5 7.9 8.0	400 320 350	.82 gal	(1) DRY @ 4 gal (2) " " 3.5 gal
HC-8 STICK UP 2.0'	7/30/92	9'	4.62			"	OR BROWN VY TURBID H <sub>2</sub> O. NO SHEEN OR OOR - SL JUDDY PH + CONDUCTIVITY ARE OFF THE SCALE * WATER LEFT IN BUCKET DEVELOPED A SHEEN - NOT PETROL MORE LIKE A SOAPY FILM	4.8	15.9	12.0 11.5 11.7	7100 6500 6400	.71 gal	(1) DRY @ 1.0 gal (2) DRY AT .8 gal

Hart Crowser  
J-3603

**ATTACHMENT B**  
**SOIL AND GROUNDWATER CHEMICAL ANALYTICAL RESULTS**  
**HART CROWSER *FAST* LABORATORY AND**  
**SOUND ANALYTICAL SERVICES, INC.**





**HARTCROWSER**

Field Analytical Services and Technologies

**FAST**

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102-3699  
FAX 206.328.5581  
206.324.9530

**FAST Laboratory Analytical Report**

FROM: James Herndon, Analytical Chemist  
TO: Susan Harp, Project Engineer  
DATE: August 10, 1992  
CLIENT: Snohomish PUD  
SITE: Halls Lake  
RE: J-3603

Attached are the compiled results from analysis conducted on samples received and analyzed July 23, 1992. Analysis was performed for TPH-418.1 and Lead (7420). This report contains:

- ▶ Results for 8 soil samples presented on a dry weight basis.
- ▶ Results for method blanks.
- ▶ Recoveries for spiked samples.
- ▶ Differences for duplicate analyses.

**FAST**Site: Halls Lake  
J-3603

## Analytical Results

Results in ppm (mg/kg or mg/L)

Compound	Duplicate		HC-1 S-3	HC-1 S-5
	HC-1 S-1	HC-1 S-1		
Matrix	Soil	Soil	Soil	Soil
% Moisture	35%	35%	10%	11%
TPH-418.1	32,000	n/t	1,700	580
Lead	55,000	56,000	750	1,100

Compound	HC-1 S-7	HC-2 S-1	HC-2 S-3	HC-2 S-5
Matrix	Soil	Soil	Soil	Soil
% Moisture	8%	20%	11%	10%
TPH-418.1	1,700	25 U	25 U	25 U
Lead	2,300	25	5.0 U	5.0 U

U = indicates not detected at indicated detection limit.

n/t = test not performed.



Site: Halls Lake  
J-3603

Analytical Results, continued

Results in ppm (mg/kg or mg/L)

Compound	Duplicate	
	HC-2 S-5	HC-2 S-7
Matrix	Soil	Soil
% Moisture	n/a	7%
TPH-418.1	25 U	25 U
Lead	n/t	5.0 U

U = indicates not detected at indicated detection limit.  
n/t = test not performed.



Site: Halls Lake  
J-3603

Method Blanks

Results in ppm (mg/kg or mg/L)

Compound	
Matrix	Soil
TPH-418.1	25 U
Lead	5.0 U

U = indicates not detected at indicated detection limit.

**FAST**Site: Halls Lake  
J-3603

## Spikes

## % Recovery

Compound	MS		MSD	
	HC-2	S-5	HC-2	S-5
Matrix	Soil		Soil	
TPH-418.1	82%		89%	

## Duplicates

## Relative % Difference

Compound	HC-1 S-1		HC-2 S-5	
	Soil		Soil	
TPH-418.1			-8%	
Lead	0%			

# Sample Custody Record

DATE 7/23/92

PAGE 1 OF 1

**HARTCROWSER**

1910 Fairview Avenue East  
Seattle, Washington 98102-3699

JOB NUMBER <u>3603</u> LAB NUMBER _____ PROJECT MANAGER <u>S. HARP</u> PROJECT NAME <u>HALLS LAKE</u>					<b>TESTING</b>										NO. OF CONTAINERS	OBSERVATIONS/COMMENTS/ COMPOSITING INSTRUCTIONS	
SAMPLED BY: <u>C. Wolfe</u>					TPH (418.1)	Total Lead											
LAB NO.	SAMPLE	TIME	STATION	MATRIX													
	<u>H-C 1</u>	<u>8:00 AM</u>	<u>S-A</u>	<u>SOIL</u>	✓	✓											Likely to encounter very high lead levels in some samples.
	<u>S-1</u>				✓	✓											
	<u>S-2</u>				✓	✓											
	<u>S-3</u>				✓	✓											
	<u>S-4</u>				✓	✓											
	<u>S-5</u>				✓	✓											
	<u>S-6</u>				✓	✓											
	<u>S-7</u>				✓	✓											
	<u>HC-2</u>				✓	✓											
	<u>S-1, S-2</u>				✓	✓											
	<u>S-3, S-4</u>				✓	✓											
	<u>S-5, S-6</u>				✓	✓											
RELINQUISHED BY <u>S-H</u>		DATE <u>7/22</u>	RECEIVED BY <u>Valley Willow</u>		DATE <u>7/23</u>	TOTAL NUMBER OF CONTAINERS <u>14 samples</u> <u>2 boxes</u>										METHOD OF SHIPMENT <u>Hand delivered</u>	
SIGNATURE <u>C. Wolfe</u>		TIME <u>P.M.</u>	SIGNATURE <u>VALLEY TRAIL</u>		TIME <u>8:40</u>	SPECIAL SHIPMENT/HANDLING OR STORAGE REQUIREMENTS <u>Keep samples for future TELP testing</u>											
PRINTED NAME <u>HC</u>			PRINTED NAME <u>HC</u>														
COMPANY			COMPANY			DISTRIBUTION: 1. PROVIDE WHITE AND YELLOW COPIES TO LABORATORY 2. RETURN PINK COPY TO PROJECT MANAGER 3. LABORATORY TO FILL IN SAMPLE NUMBER AND SIGN FOR RECEIPT 4. LABORATORY TO RETURN WHITE COPY TO HART CROWSER											
RELINQUISHED BY <u>Don Harp</u>		DATE <u>7/23/92</u>	RECEIVED BY		DATE												
SIGNATURE <u>Don Harp</u>		TIME	SIGNATURE		TIME												
PRINTED NAME <u>Hart-Crowser</u>		TIME <u>8:00 AM</u>	PRINTED NAME														
COMPANY			COMPANY														



**HARTCROWSER**

Field Analytical Services and Technologies

**FAST**

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102-3699  
FAX 206.328.5581  
206.324.9530

*FAST* Laboratory Analytical Report

FROM: James Herndon, Analytical Chemist  
TO: Susan Harp, Project Engineer  
DATE: August 10, 1992  
CLIENT: Snohomish PUD  
SITE: Halls Lake  
RE: J-3603

Attached are the compiled results from analysis conducted on samples received and analyzed July 24, 1992. Analysis was performed for TPH-418.1 and Lead (7420). This report contains:

- ▶ Results for 8 soil samples presented on a dry weight basis.
- ▶ Results for method blanks.
- ▶ Recoveries for spiked samples.
- ▶ Differences for duplicate analyses.

Analytical Comment

Spike recoveries for lead on sample HC-5 S-3 were above control limits. The sample, spike, and spike duplicate were re-extracted and re-analyzed. The high lead recoveries were repeated in the re-analysis.

**EAST**Site: Halls Lake  
J-3603

## Analytical Results

Results in ppm (mg/kg or mg/L)

Compound	HC-5 S-1	HC-5 S-3	HC-5 S-5	HC-5 S-6
Matrix	Soil	Soil	Soil	Soil
% Moisture	39%	19%	12%	10%
TPH-418.1	7,900	41	88	25 U
Lead	5,400	80	150	5.6

Compound	HC-6 S-1	HC-6 S-3	HC-6 S-5	HC-6 S-7
Matrix	Soil	Soil	Soil	Soil
% Moisture	26%	62%	10%	10%
TPH-418.1	150	25 U	81	25 U
Lead	760	5.0 U	6.7	5.6

U = indicates not detected at indicated detection limit.





Site: Halls Lake  
J-3603

Method Blanks

Results in ppm (mg/kg or mg/L)

Compound	
-----	
Matrix	Soil
TPH-418.1	25 U
-----	
Lead	5.0 U
-----	

U = indicates not detected at indicated detection limit.

**FAST**Site: Halls Lake  
J-3603

## Spikes

## % Recovery

Compound	MS		MSD		MS		MSD	
	HC-5	S-3	HC-5	S-3	HC-6	S-7	HC-6	S-7
Matrix	Soil		Soil		Soil		Soil	
TPH-418.1					138%		138%	
Lead	174%		160%					

## Duplicates

## Relative % Difference

Compound	HC-5 S-3		HC-6 S-7	
Matrix	Soil		Soil	
TPH-418.1			0%	
Lead	8%			

# Sample Custody Record

DATE 7/24/92

PAGE \_\_\_\_\_ OF \_\_\_\_\_

## HARTCROWSER

1910 Fairview Avenue East  
Seattle, Washington 98102-3699

JOB NUMBER <u>3603</u> LAB NUMBER _____ PROJECT MANAGER <u>S. HARP</u> PROJECT NAME <u>HAIR LAKE</u> SAMPLED BY: <u>C. Dolbe</u>					<b>TESTING</b> <div style="display: flex; justify-content: space-between;"> <div style="writing-mode: vertical-rl; transform: rotate(180deg);">TPH 418.1</div> <div style="writing-mode: vertical-rl; transform: rotate(180deg);">Total Lead</div> </div>										NO. OF CONTAINERS	OBSERVATIONS / COMMENTS / COMPOSITING INSTRUCTIONS					
LAB NO.	SAMPLE	TIME	STATION	MATRIX																	
HC-5	S-1		4	SOIL	X	X															
	S-3		4	↓																	
	S-5		4																		
	S-6		4																		
HC-6	S-1		4																		
	S-3		4																		
	S-5		4																		
	S-7		4																		
RELINQUISHED BY					DATE	RECEIVED BY					DATE	TOTAL NUMBER OF CONTAINERS					METHOD OF SHIPMENT				
SIGNATURE <u>S. HARP</u> PRINTED NAME <u>HC</u> COMPANY _____					7/24/92  TIME 9:30	SIGNATURE <u>Rob Dolbe</u> PRINTED NAME <u>HC</u> COMPANY _____					7/24  TIME 9:35	SPECIAL SHIPMENT/HANDLING OR STORAGE REQUIREMENTS <u>Save samples for future TCLP analysis</u>					Hand Carried				
RELINQUISHED BY					DATE	RECEIVED BY					DATE	<b>DISTRIBUTION:</b> 1. PROVIDE WHITE AND YELLOW COPIES TO LABORATORY 2. RETURN PINK COPY TO PROJECT MANAGER 3. LABORATORY TO FILL IN SAMPLE NUMBER AND SIGN FOR RECEIPT 4. LABORATORY TO RETURN WHITE COPY TO HART CROWSER									
SIGNATURE					TIME	SIGNATURE					TIME										
PRINTED NAME						PRINTED NAME															
COMPANY						COMPANY															



**HARTCROWSER**

**FAST**

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102-3699  
FAX 206.328.5581  
206.324.9530

Field Analytical Services and Technologies

### FAST Laboratory Analytical Report

FROM: James Herndon, Analytical Chemist  
TO: Susan Harp, Project Engineer  
DATE: August 10, 1992  
CLIENT: Snohomish PUD  
SITE: Halls Lake  
RE: J-3603

Attached are the compiled results from analysis conducted on samples received and analyzed July 27, 1992. Analysis was performed for TPH-418.1 and Lead (7420). This report contains:

- ▶ Results for 7 soil samples presented on a dry weight basis.
- ▶ Results for method blanks.
- ▶ Recoveries for spiked samples.
- ▶ Differences for duplicate analyses.
- ▶ Recoveries for Buffalo River sediment quality control.

#### Analytical Comment

The duplicate value for TPH-418.1 on sample HC-6 S-2 is above control limits. The sample, spike, and spike duplicate were re-extracted and reanalyzed. The out of control difference was repeated in the reanalysis. The out of control condition is caused by matrix variation.

The concentration of Lead in sample HC-3 S-1 was greater than five times the concentration of the spike. The relative percent difference value was calculated from the sample concentration in the spike and spike duplicate.



Site: Halls Lake  
J-3603

## Analytical Results

Results in ppm (mg/kg or mg/L)

Compound	MS		MSD	
	HC-3 S-1	HC-3 S-1	HC-3 S-1	HC-3 S-3
Matrix	Soil	Soil	Soil	Soil
% Moisture	55%	55%	55%	12%
TPH-418.1	55,000	n/t	n/t	150
Lead	110,000	100,000	110,000	430

Compound	HC-3 S-5		HC-3 S-7		HC-3 S-9		HC-5 S-2	
	HC-3 S-5	HC-3 S-7	HC-3 S-9	HC-5 S-2	HC-3 S-5	HC-3 S-7	HC-3 S-9	HC-5 S-2
Matrix	Soil	Soil	Soil	Soil	Soil	Soil	Soil	Soil
% Moisture	14%	14%	9%	76%	14%	14%	9%	76%
TPH-418.1	25 U	25 U	33	1,200	25 U	25 U	33	1,200
Lead	64	120	49	320	64	120	49	320

U = indicates not detected at indicated detection limit.  
n/t = test not performed. n/a = not applicable.



Site: Halls Lake  
J-3603

Analytical Results, continued

Results in ppm (mg/kg or mg/L)

Compound	HC-6 S-2
Matrix	Soil
% Moisture	22%
TPH-418.1	65
Lead	120

U = indicates not detected at indicated detection limit.



Site: Halls Lake  
J-3603

Method Blanks

Results in ppm (mg/kg or mg/L)

Compound	
-----	
Matrix	Soil
TPH-418.1	25 U
-----	
Lead	5.0 U
-----	

U = indicates not detected at indicated detection limit.

**EAST**Site: Halls Lake  
J-3603

## Spikes

## % Recovery

Compound	MS	MSD
	HC-6 S-2	HC-6 S-2
Matrix	Soil	Soil
TPH-418.1	148%	103%

## Duplicates

## Relative % Difference

Compound	HC-3 S-1	HC-6 S-2
	Soil	Soil
TPH-418.1		36%
Lead	10%	





**EAST**

Site: Halls Lake  
J-3603

Buffalo River Sediment Quality Control

% Recovery

Compound

-----  
Matrix

Soil

Lead

84%  
-----

## Sample Custody Record

DATE 7/27

PAGE 1 OF 1

# HARTCROWSER

1910 Fairview Avenue East  
Seattle, Washington 98102-3699

JOB NUMBER <u>3603</u>						LAB NUMBER _____							TESTING																	OBSERVATIONS / COMMENTS / COMPOSITING INSTRUCTIONS											
PROJECT MANAGER <u>S. HARP</u>																																									
PROJECT NAME <u>HALL LAKE</u>																																									
SAMPLED BY: <u>C. Wolfe</u>																																									
LAB NO.		SAMPLE		TIME		STATION				MATRIX				Total Lead TPH 418.1																											
HC-3		S1		10:00 AM		<u>EPA</u>				SOIL				X	X																							24 hour T.A.T.			
		S3																																							
		S5																																							
		S7																																							
		S9																																							
HC-5		S-2		10:30 am		<u>EPA</u>				Soil				X	X																						"				
HC-6		S-2		10:30 am		<u>EPA</u>				Soil				X	X																							"			
RELINQUISHED BY				DATE		RECEIVED BY				DATE		TOTAL NUMBER OF CONTAINERS <u>FIVE TO BE TESTED SEVEN</u>										METHOD OF SHIPMENT <u>HAND DELIVERED</u>																			
SIGNATURE <u>[Signature]</u>				TIME <u>7/27</u>		SIGNATURE <u>[Signature]</u>				TIME <u>7/27</u>		SPECIAL SHIPMENT/HANDLING OR STORAGE REQUIREMENTS <u>SAVE SOX SAMPLES FOR FUTURE TCLP TESTS.</u>																													
PRINTED NAME <u>S. Harp</u>				TIME <u>10:00 AM</u>		PRINTED NAME <u>JLSun Hay</u>				TIME <u>11:00 AM</u>																															
COMPANY _____						COMPANY <u>HP</u>																																			
RELINQUISHED BY				DATE		RECEIVED BY				DATE		DISTRIBUTION:																													
SIGNATURE				TIME		SIGNATURE				TIME		1. PROVIDE WHITE AND YELLOW COPIES TO LABORATORY																													
PRINTED NAME						PRINTED NAME						2. RETURN PINK COPY TO PROJECT MANAGER																													
COMPANY						COMPANY						3. LABORATORY TO FILL IN SAMPLE NUMBER AND SIGN FOR RECEIPT																													
												4. LABORATORY TO RETURN WHITE COPY TO HART CROWSER																													



**HARTCROWSER**

Field Analytical Services and Technologies

**FAST**

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102-3699  
FAX 206.328.5581  
206.324.9530

## FAST Laboratory Analytical Report

FROM: James Herndon, Analytical Chemist  
TO: Susan Harp, Project Engineer  
DATE: August 10, 1992  
CLIENT: Snohomish PUD  
SITE: Halls Lake  
RE: J-3603

Attached are the compiled results from analysis conducted on samples received July 28, 1992, and analyzed July 29, 1992. Analysis was performed for TPH-418.1 and Lead (7420). This report contains:

- ▶ Results for 21 soil samples presented on a dry weight basis.
- ▶ Results for method blanks.
- ▶ Recoveries for spiked samples.
- ▶ Differences for duplicate analyses.
- ▶ Recoveries for Buffalo River sediment quality control.

### Analytical Comments

#### TPH-418.1 Analysis

Sample HC-1 S-7 contained insufficient sample for TPH analysis. TPH-418.1 results are not available for this sample.

The relative percent difference (RPD) for TPH-418.1 analysis on samples HC-7 S-3 and HC-10 S-3 were outside the control limits. The samples were re-extracted and re-analyzed. The RPD for sample HC-10 S-3 is outside the control limits on the re-analysis.



Site: Halls Lake  
J-3603

### Lead Analysis

The concentration of lead in sample HC-8 S-5 is greater than five times the spike level. Spike and spike duplicate recoveries were not calculated. The relative percent difference is calculated using the spike and spike duplicate concentrations.

The spike recoveries and RPD for sample HC-8 S-5 were outside control limits in the original analysis. The sample was re-extracted and re-analyzed. The RPD is outside control limits on the re-analysis. The matrix for sample HC-8 S-5 is variable.

**FAST**Site: Halls Lake  
J-3603

## Analytical Results

Results in ppm (mg/kg or mg/L)

Compound	HC-1 S-2	HC-1 S-3	HC-1 S-4	HC-1 S-5
Matrix	Soil	Soil	Soil	Soil
% Moisture	11%	10%	9%	11%
TPH-418.1	110	1,000	1,100	2,500
Lead	150	110	2,900	920

Compound	MS		MSD	
	HC-1 S-6	HC-1 S-6	HC-1 S-6	HC-1 S-7
Matrix	Soil	Soil	Soil	Soil
% Moisture	7%	7%	7%	8%
TPH-418.1	440	n/t	n/t	n/t
Lead	360	340	300	3,300

U = indicates not detected at indicated detection limit.  
n/t = test not performed. n/a = not applicable.

**FAST**Site: Halls Lake  
J-3603

## Analytical Results, continued

Results in ppm (mg/kg or mg/L)

Compound	HC-3 S-2	HC-7 S-1	HC-7 S-2	HC-7 S-3
Matrix	Soil	Soil	Soil	Soil
% Moisture	36%	24%	10%	9%
TPH-418.1	3,200	1,000	25 U	25 U
Lead	1,700	2,600	28	36

Compound	HC-8 S-1	HC-8 S-3	HC-8 S-5	HC-8 S-7
Matrix	Soil	Soil	Soil	Soil
% Moisture	34%	30%	12%	10%
TPH-418.1	940	25 U	25 U	25 U
Lead	7,000	5.0 U	92	5.0 U

U = indicates not detected at indicated detection limit.

**FAST**Site: Halls Lake  
J-3603

## Analytical Results, continued

Results in ppm (mg/kg or mg/L)

Compound	HC-9 S-1	HC-9 S-3	HC-9 S-5	HC-10 S-1
Matrix	Soil	Soil	Soil	Soil
% Moisture	7%	29%	11%	9%
TPH-418.1	46	25 U	25 U	47
Lead	35	25	7	47

Compound	HC-10 S-3	HC-10 S-5	HC-10 S-7
Matrix	Soil	Soil	Soil
% Moisture	12%	11%	13%
TPH-418.1	25 U	25 U	25 U
Lead	5.0 U	5.0 U	5.0 U

U = indicates not detected at indicated detection limit.

**FAST**

Site: Halls Lake  
J-3603

Method Blanks

Results in ppm (mg/kg or mg/L)

Compound

Matrix	Soil
TPH-418.1	25 U
Lead	5.0 U

U = indicates not detected at indicated detection limit.



**FAST**Site: Halls Lake  
J-3603

## Spikes

## % Recovery

Compound	MS		MSD		MS		MSD	
	HC-7	S-3	HC-7	S-3	HC-8	S-5	HC-8	S-5
Matrix		Soil		Soil		Soil		Soil
TPH-418.1		84%		110%				
Lead						58%		90%

Compound	MS		MSD	
	HC-10	S-7	HC-10	S-7
Matrix		Soil		Soil
TPH-418.1		72%		104%



**FAST**

Site: Halls Lake  
J-3603

## Duplicates

### Relative % Difference

Compound	HC-1 S-6	HC-7 S-3	HC-8 S-5	HC-10 S-7
Matrix	Soil	Soil	Soil	Soil
TPH-418.1		-27%		-36%
Lead	-13%		-43%	

## Buffalo River Sediment Quality Control

### % Recovery

Compound		
Matrix	Soil	Soil
Lead	87%	80%

# Sample Custody Record

DATE 7/28/92

PAGE 1 OF 2

## HART CROWSER

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102-3699

JOB NUMBER <u>3603</u> LAB NUMBER _____ PROJECT MANAGER <u>S HARP</u> PROJECT NAME <u>HALLS LAKE</u> SAMPLED BY: <u>C. Wolfe</u>					TESTING										NO. OF CONTAINERS	OBSERVATIONS / COMMENTS / COMPOSITING INSTRUCTIONS
					Total Lead	T <sub>PH</sub> 419.1										
LAB NO.	SAMPLE	TIME	STATION	MATRIX												
HC-1	S-3	3:00 PM	Re-run	SOIL	X	X										24 hr. TAT
↓	S-5		Re-run	SOIL												
↓	S-7		Re-run	SOIL												
HC-1	S-2		<del>S-2</del>	↓												
↓	S-4		<del>S-4</del>													
↓	S-6		<del>S-6</del>													
HC-3	S-2		<del>S-2</del>													
HC-7	S-1															
↓	S-2															
↓	S-3															
RELINQUISHED BY <u>Jason P. HARP</u> DATE <u>7/28</u> SIGNATURE <u>S. HARP</u> TIME <u>3:15</u> PRINTED NAME _____ COMPANY _____					RECEIVED BY <u>Sherry Laughlin</u> DATE <u>7/28/92</u> SIGNATURE <u>SHERRY LAUGHLIN</u> TIME <u>1535</u> PRINTED NAME <u>HC</u> COMPANY _____					TOTAL NUMBER OF CONTAINERS <u>16-06</u> METHOD OF SHIPMENT <u>HAND DELIVERED</u> <u>22 JARS.</u>						
RELINQUISHED BY _____      DATE _____ SIGNATURE _____      TIME _____ PRINTED NAME _____ COMPANY _____					RECEIVED BY _____      DATE _____ SIGNATURE _____      TIME _____ PRINTED NAME _____ COMPANY _____					SPECIAL SHIPMENT/HANDLING OR STORAGE REQUIREMENTS <u>SAVE SAMPLES FOR TELP ANALYSIS.</u>						
DISTRIBUTION: 1. PROVIDE WHITE AND YELLOW COPIES TO LABORATORY 2. RETURN PINK COPY TO PROJECT MANAGER 3. LABORATORY TO FILL IN SAMPLE NUMBER AND SIGN FOR RECEIPT 4. LABORATORY TO RETURN WHITE COPY TO HART CROWSER																

# Sample Custody Record

DATE \_\_\_\_\_

PAGE 2 OF 2

**HART CROWSER**

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102-3699

JOB NUMBER <u>3603</u> LAB NUMBER _____ PROJECT MANAGER <u>S. HARP</u> PROJECT NAME <u>LAKE LAKE</u> SAMPLED BY: <u>C. Wolfe</u>					<b>TESTING</b>										NO. OF CONTAINERS	OBSERVATIONS / COMMENTS / COMPOSITING INSTRUCTIONS
LAB NO.	SAMPLE	TIME	STATION	MATRIX												
11C 8	S-1	3:00 PM	SX	SOIL	X	X										24 m. TAT
	S-3															
	S-5															
	S-7															
	<del>S-7</del>															
11C 9	S-1															
	S-3															
	S-5															
11C 10	S-1															
	S-3															
	S-5															
	S-7															
RELINQUISHED BY		DATE	RECEIVED BY		DATE	TOTAL NUMBER OF CONTAINERS <u>22 Total 1602</u>					METHOD OF SHIPMENT					
SIGNATURE <u>J. HARP</u>		7/23	SIGNATURE <u>Sherry Laughlin</u>		7/28/12	SPECIAL SHIPMENT/HANDLING OR STORAGE REQUIREMENTS  <u>SAVE SAMPLES</u>										
PRINTED NAME <u>J. HARP</u>		TIME <u>330</u>	PRINTED NAME <u>SHERY LAUGHLIN</u>		TIME <u>1535</u>											
COMPANY			COMPANY													
RELINQUISHED BY		DATE	RECEIVED BY		DATE	DISTRIBUTION: 1. PROVIDE WHITE AND YELLOW COPIES TO LABORATORY 2. RETURN PINK COPY TO PROJECT MANAGER 3. LABORATORY TO FILL IN SAMPLE NUMBER AND SIGN FOR RECEIPT 4. LABORATORY TO RETURN WHITE COPY TO HART CROWSER										
SIGNATURE		TIME	SIGNATURE		TIME											
PRINTED NAME			PRINTED NAME													
COMPANY			COMPANY													



**HARTCROWSER**

**FAST**

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102-3699  
FAX 206.328.5581  
206.324.9530

Field Analytical Services and Technologies

*FAST* Laboratory Analytical Report

FROM: James Herndon, Analytical Chemist  
TO: Susan Harp, Project Engineer  
DATE: August 28, 1992  
CLIENT: Snohomish PUD  
SITE: Halls Lake  
RE: J-3603

Attached are the compiled results from analysis conducted on samples received and analyzed July 31, 1992. Analysis was performed for TPH-418.1 and Lead (7420). This report contains:

- ▶ Results for 4 soil samples presented on a dry weight basis.
- ▶ Results for method blanks.
- ▶ Recoveries for spiked samples.
- ▶ Differences for duplicate analyses.
- ▶ Recoveries for Buffalo River sediment quality control.

**EAST**

Site: Halls Lake  
J-Snohomish PUD

# Analytical Results

Results in ppm (mg/kg or mg/L)

Compound	HClA-S1	HClA-S2	HClA-S3	HClA-S6
Matrix	Soil	Soil	Soil	Soil
% Moisture	24%	9%	10%	11%
TPH-418.1	10,000	25 U	25 U	230
Lead	48,000	69	6	13

U = indicates not detected at indicated detection limit.

**FAST**

Site: Halls Lake  
J-Snohomish PUD

Method Blanks

Results in ppm (mg/kg or mg/L)

Compound

Matrix	Soil
TPH-418.1	25 U
Lead	5.0 U

U = indicates not detected at indicated detection limit.

**FAST**Site: Halls Lake  
J-Snohomish PUD

## Spikes

## % Recovery

Compound	MS	MSD
	HC1A-S2	HC1A-S2
Matrix	Soil	Soil
TPH-418.1	126%	143%

## Duplicates

## Relative % Difference

Compound	HC1A-S2
Matrix	Soil
TPH-418.1	-13%





**FAST**

Site: Halls Lake  
J-Snohomish PUD

Buffalo River Sediment Quality Control

% Recovery

Compound

Matrix

Soil

Lead

90%

1910 Fairview Avenue East  
Seattle, Washington 98102-3699

**FAST****HARTCROWSER**

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102-3699  
FAX 206.328.5581  
206.324.9530

Field Analytical Services and Technologies

### FAST Laboratory Analytical Report

FROM: James Herndon, Analytical Chemist  
TO: Susan Harp, Project Engineer  
DATE: September 1, 1992  
CLIENT: Snohomish PUD  
SITE: Halls Lake  
RE: J-3603

Attached are the compiled results from analysis conducted on samples received August 7, 1992, and analyzed August 10, 1992. Analysis was performed for TPH-418.1 and Lead (7420). This report contains:

- ▶ Results for 1 soil sample presented on a dry weight basis.
- ▶ Results for method blanks.
- ▶ Recoveries for spiked samples.
- ▶ Differences for duplicate analyses.
- ▶ Recoveries for Buffalo River sediment quality control.

#### Analytical Comment

Spike and spike duplicate recovery values for lead analysis were outside control limits for sample HC8-S2. The total sample was homogenized, re-extracted and re-analyzed. Spike recoveries for the re-analysis were outside of control limits. Metal flecks within the sample matrix cause variations in the sample results. Sample results are close to, but do not exceed, five times the spike concentration. Relative percent difference (RPD) values are calculated from spike percent recoveries.



Site: Halls Lake  
J-Snohomish PUD

### Analytical Results

Results in ppm (mg/kg or mg/L)

Compound	Duplicate	
	HC8-S2	HC8-S2
Matrix	Soil	Soil
% Moisture	26%	n/t
TPH-418.1	58	51
Lead	270	n/t

U = indicates not detected at indicated detection limit.  
n/t = test not performed.

**FAST**

Site: Halls Lake  
J-Snohomish PUD

Method Blanks

Results in ppm (mg/kg or mg/L)

Compound	
-----	
Matrix	Soil
TPH-418.1	25 U
-----	
Lead	5.0 U
-----	

U = indicates not detected at indicated detection limit.

**EAST**Site: Halls Lake  
J-Snohomish PUD

## Spikes

## % Recovery

Compound	MS	MSD	MS
	HC8-S2	HC8-S2	HC8-S2
Matrix	Soil	Soil	Soil
TPH-418.1			126%
Lead	20%	0%	

## Duplicates

## Relative % Difference

Compound	HC8-S2
Matrix	Soil
TPH-418.1	13%
Lead	200%



**FAST**

Site: Halls Lake  
J-Snohomish PUD

Buffalo River Sediment Quality Control

% Recovery

Compound

Matrix

Soil

Lead

87%

# Sample Custody Record

DATE 8/7/92

PAGE 1 OF 1

**HARTCROWSER**

1910 Fairview Avenue East  
Seattle, Washington 98102-3699

JOB NUMBER <u>3603</u> LAB NUMBER <u>      </u> PROJECT MANAGER <u>S. HARP</u> PROJECT NAME <u>HALS LAKE</u> SAMPLED BY: <u>C. Wolfe</u>					<b>TESTING</b> <div style="display: flex; justify-content: space-between;"> <div style="writing-mode: vertical-rl; transform: rotate(180deg);">TPH (4/18.1)</div> <div style="writing-mode: vertical-rl; transform: rotate(180deg);">Total Lead</div> </div>										NO. OF CONTAINERS	OBSERVATIONS/COMMENTS/ COMPOSITING INSTRUCTIONS				
LAB NO.	SAMPLE	TIME	STATION	MATRIX	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>														
HC-8	S-2	4:25pm		SOIL															1	24 hr. TAT

RELINQUISHED BY		DATE	RECEIVED BY		DATE	TOTAL NUMBER OF CONTAINERS		METHOD OF SHIPMENT	
 SIGNATURE SUSAN P. HARP PRINTED NAME HC COMPANY		8/7	 SIGNATURE CHERRY L. LACHLAN PRINTED NAME HC COMPANY		8/7/92	1		Hand delivered	
		TIME			TIME	SPECIAL SHIPMENT/HANDLING OR STORAGE REQUIREMENTS Save sample for future TCLP		DISTRIBUTION: 1. PROVIDE WHITE AND YELLOW COPIES TO LABORATORY 2. RETURN PINK COPY TO PROJECT MANAGER 3. LABORATORY TO FILL IN SAMPLE NUMBER AND SIGN FOR RECEIPT 4. LABORATORY TO RETURN WHITE COPY TO HART CROWSER	



# SOUND ANALYTICAL SERVICES, INC.

SPECIALIZING IN INDUSTRIAL & TOXIC WASTE ANALYSIS

4813 PACIFIC HIGHWAY EAST, TACOMA, WASHINGTON 98424 - TELEPHONE (206)922-2310 - FAX (206)922-5047

Report To: Hart Crowser

Date: August 5, 1992

Report On: Analysis of Soil & Water

Lab No.: 26077

Page 1 of 5

## IDENTIFICATION:

Samples received on 07-31-92

Project: Hall's Lake

## ANALYSIS:

Lab No. 26077-1

Client ID: HC-3 (water)

TPH per EPA Method 418.1

Date Extracted: 8-3-92

Date Analyzed: 8-4-92

Total Petroleum  
Hydrocarbons, mg/l

2.5

Dissolved ICP Metals Per Method 6010

Date Digested: 8-3-92

Date Analyzed: 8-3-92

Lead, mg/l

0.053

Lab No. 26077-2

Client ID: HC-8 (water)

TPH per EPA Method 418.1

Date Extracted: 8-3-92

Date Analyzed: 8-4-92

Total Petroleum  
Hydrocarbons, mg/l

< 1.0

Dissolved ICP Metals Per Method 6010

Date Digested: 8-3-92

Date Analyzed: 8-3-92

Lead, mg/l

0.014

Continued . . .

# SOUND ANALYTICAL SERVICES, INC.

Hart Crowser  
Project: Hall's Lake  
Page 2 of 5  
Lab No. 26077  
August 5, 1992

Lab No. 26077-3

Client ID: HC-1 S2 (soil)

Toxicity Characteristic Leaching Procedure (TCLP) Method 1311  
ICP Metals by Method 6010  
Date Extracted: 8-3-92  
Date Analyzed: 8-4-92

<u>Contaminant</u>	<u>Concentration (mg/l)</u>	<u>Max Conc., (mg/l)</u>
Lead	1.1	5.0

Lab No. 26077-4

Client ID: HC-3 S2 (soil)

Toxicity Characteristic Leaching Procedure (TCLP) Method 1311  
ICP Metals by Method 6010  
Date Extracted: 8-3-92  
Date Analyzed: 8-4-92

<u>Contaminant</u>	<u>Concentration (mg/l)</u>	<u>Max Conc., (mg/l)</u>
Lead	4.2	5.0

Continued . . .

# SOUND ANALYTICAL SERVICES, INC.

Hart Crowser  
Project: Hall's Lake  
Page 3 of 5  
Lab No. 26077  
August 5, 1992

Lab No. 26077-5

Client ID: HC-5 S1 (soil)

Toxicity Characteristic Leaching Procedure (TCLP) Method 1311  
ICP Metals by Method 6010  
Date Extracted: 8-3-92  
Date Analyzed: 8-4-92

<u>Contaminant</u>	<u>Concentration (mg/l)</u>	<u>Max Conc., (mg/l)</u>
Lead	50	5.0

Lab No. 26077-6

Client ID: HC-5 S2 (soil)

Toxicity Characteristic Leaching Procedure (TCLP) Method 1311  
ICP Metals by Method 6010  
Date Extracted: 8-3-92  
Date Analyzed: 8-4-92

<u>Contaminant</u>	<u>Concentration (mg/l)</u>	<u>Max Conc., (mg/l)</u>
Lead	< 0.1	5.0

Continued . . .

# SOUND ANALYTICAL SERVICES, INC.

Hart Crowser  
Project: Hall's Lake  
Page 4 of 5  
Lab No. 26077  
August 5, 1992

Lab No. 26077-7

Client ID: HC-7 S1 (soil)

Toxicity Characteristic Leaching Procedure (TCLP) Method 1311  
ICP Metals by Method 6010  
Date Extracted: 8-3-92  
Date Analyzed: 8-4-92

<u>Contaminant</u>	<u>Concentration (mg/l)</u>	<u>Max Conc.,</u> <u>(mg/l)</u>
Lead	11	5.0

Lab No. 26077-8

Client ID: HC-8 S1 (soil)

Toxicity Characteristic Leaching Procedure (TCLP) Method 1311  
ICP Metals by Method 6010  
Date Extracted: 8-3-92  
Date Analyzed: 8-4-92

<u>Contaminant</u>	<u>Concentration (mg/l)</u>	<u>Max Conc.,</u> <u>(mg/l)</u>
Lead	18	5.0

Continued . . .

# SOUND ANALYTICAL SERVICES, INC.

Hart Crowser  
Project: Hall's Lake  
Page 5 of  
Lab No. 26077  
August 5, 1992

Lab No. 26077-9

Client ID: HC-1 S6 (soil)

ICP Metals Per Method 6010

Date Digested: 8-3-92

Date Analyzed: 8-3-92

Lead, mg/kg

76

Lab No. 26077-10

Client ID: HC-3 S3 (soil)

ICP Metals Per Method 6010

Date Digested: 8-3-92

Date Analyzed: 8-3-92

Lead, mg/kg

230

Lab No. 26077-11

Client ID: HC-5 S4 (soil)

ICP Metals Per Method 6010

Date Digested: 8-3-92

Date Analyzed: 8-3-92

Lead, mg/kg

83

SOUND ANALYTICAL SERVICES

  
STAN P. PALMQUIST

# SOUND ANALYTICAL SERVICES, INC.

SPECIALIZING IN INDUSTRIAL & TOXIC WASTE ANALYSIS

4813 PACIFIC HIGHWAY EAST, TACOMA, WASHINGTON 98424 - TELEPHONE (206) 922-2310 - FAX (206) 922-5047

---

## QUALITY CONTROL REPORT

TPH by Method 418.1

Client: Hart Crowser  
Lab No: 26077qc3  
Matrix: Soil  
Units: mg/kg  
Date: August 5, 1992

### METHOD BLANK

Parameter	Blank Value
Total Petroleum Hydrocarbons	< 1.0

# SOUND ANALYTICAL SERVICES, INC.

SPECIALIZING IN INDUSTRIAL & TOXIC WASTE ANALYSIS

4813 PACIFIC HIGHWAY EAST, TACOMA, WASHINGTON 98424 - TELEPHONE (206)922-2310 - FAX (206)922-5047

---

## QUALITY CONTROL REPORT

### METHOD BLANKS

Client: Hart Crowser  
Lab No: 26077qcl  
Matrix: Soil  
Units: mg/kg  
Date: August 5, 1992

#### Total Lead

Parameter	Blank Value
Lead	< 1.4

#### TCLP Lead

Parameter	Blank Value
Lead	< 0.1

# SOUND ANALYTICAL SERVICES, INC.

SPECIALIZING IN INDUSTRIAL & TOXIC WASTE ANALYSIS

4813 PACIFIC HIGHWAY EAST, TACOMA, WASHINGTON 98424 - TELEPHONE (206)922-2310 - FAX (206)922-5047

## QUALITY CONTROL REPORT

### Dissolved Lead

Client: Hart Crowser  
Lab No: 26077qc2  
Matrix: Soil  
Units: mg/kg  
Date: August 5, 1992

### DUPLICATE

Dup No. 26077-1

Parameter	Sample (S)	Duplicate (D)	RPD
Lead	0.053	0.059	10.7

PD = Relative Percent Difference  
=  $[(S - D) / ((S + D) / 2)] \times 100$

### MATRIX SPIKE / MATRIX SPIKE DUPLICATE RECOVERY

MSD No. 26077-1

Parameter	Sample Result (SR)	Spiked Sample Result (MS)	Spike Added (SA)	%R	Spike Dup Result (MSD)	RPD
Lead	0.053	0.070	0.020	85.0	0.066	5.9

R = Percent Recovery  
=  $[(MS - SR) / SA] \times 100$

PD = Relative Percent Difference  
=  $[(MS - MSD) / ((MS + MSD) / 2)] \times 100$



Page \_\_\_\_\_ of \_\_\_\_\_



**HARTCROWSER**

Hart Crowser, Inc.  
1910 Fairview Avenue East  
Seattle, Washington 98102-3699  
FAX 206.328.5581  
206.324.9530

th and Environmental Technologies

**Letter of Transmittal**

To: Snohomish County P.U.D. No. 1 Date: 9/2/92  
1802 - 75th Street SW  
Everett, Washington 98206 Job No. 3603

Attn: Ms. Karen Rose

Re: Halls Lake Substation

We are sending the following items:

Date	Copies	Description
9/2/92	2	Final version letter report
		Re: Site Assessment Report
		Halls Lake Substation Remedial Services
		Professional Services Contract No. 2048

These are transmitted:

- ☐ For your information      ☐ For action specified below      ☐ For review and comment      ☒ XXXX For your use      ☐ As requested

**Remarks**

Copies to: \_\_\_\_\_ By: Susan P. Harp

\_\_\_\_\_ Project Engineer

Title: \_\_\_\_\_