

• SHARP first SHARP		v2024.04.29	Ecology Info	
• SHARP rating	Low		ERTS	734657
• SHARP date	11/25/2024		CSID	17162
• EJFlagged?	⊘ - No Override		FSID	46936387
• LD confidence level	low		VCP	none
• Cleanup milestone	initial investigation		UST ID	none
• SHARPster	Vance Atkins		LUST ID	none

This section is blank if this is the first SHARP

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	high	multiple chemical types	⊘
Groundwater	D4	high	risk to off-site people	⊘
Surface water	D4	high	climate change impacts	⊘
Sediment	D4	high	plant/animal tissue data	⊘
Soil	D4	high		

#### Location and land use info

9418 35th Ave NE, Seattle, King County, 98115

Primary parcel 6844700005

Land use commercial

Responsible unit NWRO

#### Sources reviewed

2024, Dixon Environmental Services, Phase II Environmental Site Assessment:

Subsurface Investigation Report, King County Parcel #6844700005

Primary census tract	Associated census tracts
53033002200	53033002100 (adjacent west)

**Local demographics comments**

no comments

**Source/source area description**

A Site investigation completed in 2024 identified several potential contamination sources at the Site parcel associated with its use as an automotive repair facility. Two gasoline USTs and one waste oil UST were removed in 1990. Contaminated soil associated with gasoline UST product lines was removed and disposed of off-site. Additional areas of concern observed on-site in 2024 included: three underground hydraulic hoists, floor drains, and a waste oil AST and drum storage area without secondary containment. In 2024, seven soil borings were completed at the Site parcel. Four borings were installed adjacent to floor drains, hydraulic lifts, and the AST/drum storage area. Three borings were installed within or adjacent to former UST and soil remediation areas to confirm soil conditions. Soil samples were collected at depths of five to twelve feet below grade and analyzed for petroleum hydrocarbons, BETX compounds, and VOCs. Groundwater was not encountered during the soil investigation.

**Soil comments**

A total of 17 soil samples were collected from seven borings at depths of 5-12 feet below grade. Soil samples were analyzed for petroleum hydrocarbons, BETX compounds, and VOCs throughout the Site parcel. Contaminants of concern were either not detected, or were detected below cleanup levels, with the exception of tetrachloroethylene (PCE), which was detected in one sample at a concentration of 0.056 mg/kg vs 0.05 mg/kg MTCA soil cleanup level. Statistical analysis of eleven samples collected through the Site parcel indicated the 95% Upper Confidence Limit was below the MTCA soil cleanup level.

**Groundwater comments**

Groundwater was not encountered during the 2024 soil investigation or prior remedial activities. Area soil borings indicate that groundwater has not been encountered to depths of at least 30 feet.

**Surface water comments**

no comments

**Sediment comments**

no comments

**Indoor air comments**

Maximum known tetrachloroethylene (PCE) detection in Site soil 0.056 mg/kg.

**Additional factors comments**

no comments

Site history

[Go to top](#)

The Site parcel was initially developed as a residential property in the 1930s. The parcel was redeveloped as a fuel/service station in the 1950s, with redevelopment to the same use in the 1960s. The fueling infrastructure was decommissioned in 1990, and the Site parcel has been used solely as automotive service facility since that time. During UST removal in 1990, petroleum contamination was identified in three areas: a pump island, adjacent to former USTs removed in 1967, and at a drywell. Based on field screening and laboratory analyses, a total of 625 cubic yards of contaminated soil was removed from the Site. The Site received a No Further Action from Ecology in 2012 (CSIDs 9340 and 9341).

This SHARP evaluates the non-UST issues addressed in 2024. Ecology concludes that no further action is required after successful remediation.

**Overflow - Site contamination and cleanup history**

No overflow

## Johnsons Auto Repair

17162 Johnsons Auto Repair 20241125

First SHARP

SHARP rating — Low

## SHARP Report — Part 2 of 2

Conceptual site model

11/25/2024



### Assessment scores by environmental medium

