

SHARP Report — Part 1 of 2

Go to site contamination history

• SHARP first SHARP		v2024.04.29	Ecology	Info
 SHARP rating 	Low		ERTS	none
 SHARP date 	08/21/2025		CSID	3057
EJFlagged?	✓ – No Override		FSID	1029
 LD confidence level 	high		VCP	none
 Cleanup milestone 	periodic review		UST ID	none
• SHARPster	Thomas Praisewater		LUST ID	none

This section is blank if this is the first Shal	section is blank if this is the first SHA	ARI	R
---	---	-----	---

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	high	multiple chemical types	0
Groundwater	C2	high	risk to off-site people	✓
Surface water	D4	medium	climate change impacts	✓
Sediment	D4	high	plant/animal tissue data	\Diamond
Soil	C1	high		

Location and land use info

901 Port Way, Vancouver, Clark County, 98660

Primary parcel 58919000, 58920000

Land use industrial Responsible unit SWRO

Sources reviewed	
Third Periodic Review (2020)	



Primary census tract	Associated census tracts
41005	

	Local	lem	oa	rar	shi	ics	cor	nm	enf	ts
-		 	~9	. ~r	,,,,,				••••	-

A zero v	was applied to	all EJscreen	parameters	because the	EJscreen websit	te was not av	vailable at t	he time of
rating.								

Source/source area description

Lead, TPH-G and TPH-D, cPAHs, 1,2,4 trimethylbenzene and arsenic have been detected in the soil at this Site. BEP, arsenic, beryllium, chromium(VI), copper, lead, vinyl chloride, and thallium have been detected in the shallow aquifer as well as the deeper, unconsolidated aquifer beneath the Site. Several excavation events were part of the cleanup action at this site, with tons of contaminated soil being removed to appropriate landfills and clean imported fill being put in its place. An asphalt cap covers all detected areas of contamination, and the Site has been subject to institutional controls and long-term groundwater monitoring in since 2001. The cleanup action is reviewed every five years.

Soil	comments

no comments

Groundwater comments

Vinyl chloride has been consistently detected in the groundwater at this Site. In the past, it was detected in a number of Cell 2 wells; in the recent past, only one well has shown vinyl chloride detections: C2-MW-11(R2). This well most recently detected a concentration of 0.450 ug/L on 3/25/25, which exceeds the Method A cleanup level of 0.2 ug/L. However, this detection is lower than the last sampling event, and continues a trend of decreasing concentrations over the past several sampling events. Vinyl chloride was not detected in previous soil sampling, and its source is unknown.



e.	urfa	^^	wo.t	~r	^^	mm	00	+~
. 71	IIIIA	CH	wai	er	c:c		en	ıs

Vinyl chloride is consistently detected in a shallow groundwater bearing zone that empties into the Columbia River. This detection is decreasing, but remains above Method A cleanup levels. The Columbia River in this area has not been analyzed for vinyl chloride.

Sediment comments	
no comments	
Indoor air comments	
no comments	

Additional factors comments

This site sits on the banks of the Columbia River in a floodplain, and could be theoretically impacted by climate change factors.



Site history Go to top The former Fort Vancouver Plywood (FVP) Site is located at 901 Port Way, at the end of 8th Street and Port Way, in the industrial-zoned area along the bank of the Columbia River. The Port of Vancouver (Port) owned the property since 1912. The Site, consisting of an approximately 15.8 acres property, was a former plywood mill. The Site buildings included a wood processing and plywood manufacturing plant, chemical storage structures, a boiler house, a maintenance shop, a fuel storage area, a log storage area, a warehouse/retail plywood store, and an office building. The Site has always been used for industrial purposes for over 100 years. Currently the property is being used for industrial purposes and it will continue to be used for industrial activities in the future. Initially, wood cutting for a nearby ship building facility was done on the Site. Since 1930, the Site has been used for the manufacture of plywood. The FVP operated a plywood mill, producing plywood from raw logs or green veneer at the Site from at least 1955. All the plywood mill operations were completely stopped in 1997. All structures and equipment (except the office building) were demolished and removed in summer of 1997 to ensure thorough investigation and cleanup. The Port demolished the remaining office building in summer of 2013.



Overflow -	Site contamination and cleanup history
No overflow	

3057 Fort Vancouver Plywood 20250821 First SHARP

SHARP rating — Low

SHARP Report — Part 2 of 2

Conceptual site model



08/21/2025

