
PHASE II ENVIRONMENTAL SITE ASSESSMENT
at
Wondrak-Itek Property
1602 Rudkin Road
Yakima, Washington

UST# 4274

Prepared for:

Central Valley Bank
Attn. Bruce Galbrain
2205 South First Street
Yakima, Washington 98903

Prepared by:

Peter Trabusiner
Engineer

NetCompliance Products & Services, Inc.
210 N. Perry Street, Suite B
Kennewick, Washington 99336
(509) 736-1187

PHASE II ENVIRONMENTAL SITE ASSESSMENT

Client:	Central Valley Bank P.O.Box 10207 Yakima, WA 98909
Point of Contact:	Bruce Galbrain/Loan Officer
Property:	1602 Rudkin Road Yakima, Washington 98903
Environmental Engineer:	P. Trabusiner
Project Number:	48-001-095
Report Date:	February 7, 2000

APPENDIX

- USGS 7.5 Minute Topographic Map
 -
 - Site Location Map
 -
 - Site Drawing
 -
 - Site Photographs
 -
 - Laboratory Report
-

EXECUTIVE SUMMARY

According to the State of Washington Toxic Cleanup Program Site Register from October, 1999, and the Washington State Leaking Underground Storage Tank List from July, 1999, the subject site is listed as possibly contaminated by petroleum hydrocarbons.

Central Valley Bank, in Yakima, retained NetCompliance Products & Services, Inc. (NCP&S), of Kennewick, Washington, as the environmental consultant to conduct a limited Phase II Site assessment of the subject property at 1602 Rudkin Road, in Yakima, Washington. On January 5, 2000, Mr. Peter Trabusiner, an engineer and employee with NCP&S, conducted the UST's site check and supervised the soil testing. The weather was sunny with temperatures in the forties.

3-Kings Environmental, Inc. from Kennewick, Washington, conducted the soil testing. Five test holes were excavated with a backhoe. The samples were taken directly from the center of the bucket according to Washington Department of Ecology (WA-DOE) sampling and testing guideline from 1994. The test-holes were located approximately at the same locations where records indicated previously removed underground storage tanks. Soil samples were taken at 8 or 12 foot depth from the test holes. No groundwater was evident during the excavation activities.

Analysis of selected soil samples taken during the activities was conducted by OnSite Environmental, Inc. in Redmond, Washington, an EPA and State of Washington accredited laboratory.

The one underground storage tank system (UST's) investigated was situated on the north side of the former truck wash facility. According to a report obtained from the DOE office in Yakima, two 8000 gallon USTs were removed in 1996 by Russel Crane Service, Inc. According to a letter from DOE dated June 5, 1997, the performance of the site closure and the closure report by Cayuse Environmental, did not meet the minimum requirements of the Washington Administrative Code 173 360 and therefore the subject site was considered as being possibly contaminated.

The other USTs system investigated contained two 500 gallon waste oil tanks located at the southeast and the southwest corners of the shop building. According to the closure report conducted in 1994 by White Shield, Inc., and a copy provided by the DOE in Yakima, *laboratory analysis of soil samples revealed petroleum contamination exceeding the MTCA Method A Cleanup Levels in the soil taken from the bottom of the two separate excavations. The analytical laboratory results indicated contamination below MTCA cleanup levels on the walls of the excavations.*

The subject property is one rectangular parcel of land with improvements. The site is occupied by the ITEK, Inc. trailer manufacturing and maintenance facility, an old truck wash and the new Wondrak commercial fuel station. The site is located at the southwest quadrant of Rudkin Road and east of Viola Avenue, in Yakima, Washington. Residential development is located adjoining to the west and south of the property. Interstate I-82 is immediately to the east of the property, with the Yakima River located about 1000 feet further to the east. The urban center of Yakima is approximately 1/2 mile to the northwest.

During the present site investigation by NCP&S, petroleum hydrocarbon contamination in the diesel and heavy oil range was detected at both USTs locations. The laboratory test results (WA-TPH-HCID followed by TPH-Dx) confirmed and supported our site investigation.

PHASE II ENVIRONMENTAL SITE ASSESSMENT OVERVIEW

Purpose:

The purpose of this Phase II Site Assessment was to investigate, review, assess, and evaluate--through research, document and record review, visual and physical observations.

- Contamination by petroleum products.
- The possibility that these materials are or may have been introduced--by internal generation, external introduction, or unknown sources--into the structure or subject property.
- A brief overview, evaluation, and assessment of the severity of the current potential environmental risk based upon known standards or applicable regulations.

Unless specifically noted within the text of this report, this Site Assessment does not include or address groundwater.

Protocol:

The procedure for this Phase II Environmental Site Assessment was to perform in practical and reasonable steps--employing currently available technology, existing regulations, and generally acceptable engineering practices--an investigation to ascertain the possibility, presence, or absence of environmental releases or threatened releases as limited by the Scope of Work.

Objectives:

- To attempt to accomplish all appropriate inquiry into ownership and uses of the property consistent with good commercial or customary practice, in an effort to minimize liability.
- To conduct an investigation of the property that will assist ownership's positioning within the "safe harbor" section of the Federal Superfund liability in 42 U.S.C. §9601(35).
- To provide environmental information that will assist in evaluating ownership's risk of potential loss or value impairment of the security interest, due to environmental defects. To provide information for decisions and operational limitations concerning the National Pollution Contingency Plan under CERCLA, Lender Liability Final Rule 40 CFR Part 300 XI.

Although this Assessment cannot absolutely quantify and qualify every possible past and present environmental risk, the assessment does provide a partial information basis for reasonable decision making regarding the potential for environmental liabilities and risk, based upon the current site-specific situation, assessment limitations, and methods of evaluation.

GENERAL OVERVIEW

Central Valley Bank, in Yakima, retained NetCompliance Products & Services, Inc. (NCP&S), of Kennewick, Washington, as the environmental consultant to conduct a limited Phase II Site assessment of the subject property at 1602 Rudkin Road, in Yakima, Washington. On January 5, 2000, Mr. Peter Trabusiner, an engineer and employee with NCP&S, conducted the UST's site check and supervised the soil testing. The weather was sunny with temperatures in the forties. 3-Kings Environmental, Inc. from Kennewick, Washington, conducted the soil testing. Five test holes were excavated with a backhoe. The samples were taken direct from the center of the bucket according to the Washington Department of Ecology (WA-DOE) sampling and testing guideline from 1994. The test-holes were located approximately at the same locations where records indicated previously removed underground storage tanks. Soil samples were taken at 8 or 12 foot depth from the test holes.

Analysis of selected soil samples taken during the activities was conducted by OnSite Environmental, Inc. in Redmond, Washington, an EPA and State of Washington accredited laboratory.

SUBJECT PROPERTY SITE DESCRIPTION

Physical Setting Source:

Source of reference is a current United States Geological Survey (USGS) 7.5 Minute Topographic Quadrangle (quad) Map containing the subject property. The USGS 7.5-minute quad map has an approximate scale of 1" to 2,000 feet, shows physical features such as wetlands, water bodies, roadways, mines, and buildings. The USGS 7.5 quad map is considered to be the only Standard Physical Setting Source, and is sufficient as a single reference. A copy of the applicable map is included in the appendix.

The subject property is one rectangular parcel of land with improvements. The site is occupied by the ITEK, Inc. trailer manufacturing and maintenance facility, an old truck wash and the new Wondrak commercial fuel station. The site is located at the southwest quadrant of Rudkin Road and east of Viola Avenue, in Yakima, Washington. Residential development is located adjoining to the west and south of the property. Interstate I-82 is immediately to the east of the property, with the Yakima River located about half a mile further to the east. The urban center of Yakima is approximately 1/2 mile to the northwest, and the City of Union Gap to the southwest.

Visual Description:

The subject property fronts Rudkin Road, adjacent to Interstate 82, and along the south line of East Viola Avenue. The property is improved with two one-story light industrial buildings. Building "A" is located near the Rudkin Road frontage and measures 98 by 98 feet, for a gross building area of 9,702 square feet. Building "B" is located to the west side of the parcel, measuring 32 by 84 feet, for 2,688 gross square feet. Building "A" is occupied by ITEK, Inc., a truck trailer hitch assembly and repair business. Building "B" is currently vacant and used for storage. The buildings and the subject site appeared well maintained and clean. The observed sparse vegetation to the west of the property appeared not to be under chemical stress.

Surface Characteristics:

The rectangular property is flat with a light slope to the south. Storm water drains through the surface into the sub-soils and runoff is eventually directed to the south and east of the property. No pools, drains, sumps, pits, ponds, ditches were encountered at the time of our inspection. Approximately 70% of the subject property is covered by permeable surfaces such as compacted gravel and dirt.

Subsurface and Hydrological Characteristics:

Source: Soil Survey of Yakima County Area, Washington (United States Department of Agriculture, Soil Conservation Service, 1985).

The review of US Soil Conservation Corps data indicates that the subject property is underlain by Weirman fine sandy loam on 0 to 2 percent slopes.

This very deep, somewhat excessively drained soil is on low terraces and flood plains. It formed in mixed alluvium. Elevation is 700 to 1,700 feet.

Typically, the surface layer is grayish brown, fine sandy loam about 8 inches thick. The upper part of the underlying material is stratified, grayish brown and light brownish-gray, loamy fine sand about 13 inches thick, and the lower part to a depth of 60 inches or more is grayish-brown, extremely gravelly sand.

Permeability of this soil is rapid.

Available water capacity is low.

Runoff is slow, and the hazard of water erosion is slight. The hazard of soil blowing is high.

The average annual precipitation is 7 to 14 inches, the average annual air temperature is about 51 degrees F, and the average frost-free season is 130 to 180 days.

It should be noted that the characterization previously described is merely a generalization extrapolated from available soil data. In actuality, the subsurface of the subject property has likely been modified by cuts and fills for building foundation, grading and underground utilities.

Ground Water Conditions:

While precise information on groundwater depth on the subject property is unavailable. According to information obtained at the County Water Resource Department, the groundwater level is estimated to be 8 to 16 feet in the area of the subject property. No site specific well information is available.

The groundwater flow gradient follows the topographic to the southeast.

See well log information of the nearest sites in the appendix.

SITE INVESTIGATION

Previous UST Systems Information:

The one underground storage tank system (UST's) investigated was situated on the north side of the former truck wash facility. According to a report obtained from the DOE office in Yakima, two 8000 gallon USTs were removed in 1996 by Russel Crane Service, Inc. According to a letter from DOE dated June 5, 1997, the performance of the site closure and the closure report by Cayuse Environmental, did not meet the minimum requirements of the Washington Administrative Code 173-360 and therefore the subject site was considered as being possibly contaminated.

The other USTs system investigated contained two 500 gallon waste oil tanks located at the southeast and the southwest corners of the shop building. According to the *Conclusions* paragraph from the closure report conducted in 1994 by White Shield, Inc., (a copy was provided by the DOE in Yakima), *laboratory analysis of soil samples taken from the bottom of the two separate excavations revealed petroleum contamination exceeding the MTCA Method A Cleanup Levels in the soil. The analytical laboratory results indicated contamination below MTCA cleanup levels on the walls of the excavations.*

See copies of the reports from White Shield and Cayuse Environmental, in the appendix.

Sampling Methodology:

Mr. Trabusiner, an engineer with NCP&S, conducted soil sampling. Discrete grab samples were collected with fresh, clean, rubber gloves direct from the center of the excavator bucket, at 8' or 12' depth from the base and the sidewalls of each excavation. The samples were placed in four ounce glass containers with Teflon lined lids. The samples were stored in a cool environment until released, with a chain-of-custody, to the laboratory. The sampling tool was disposed of between samples. Analysis of the soil samples taken during the site activities was conducted by OnSite Environmental, Inc. in Redmond, Washington, an EPA and State of Washington accredited laboratory.

Field testing was done by utilizing the "head space" field screening method to detect the volatiles as measured by a Combustible Gas Instrument (CGI). All soil samples were non detect, However, due to the non-volatile nature of the heavy range petroleum hydrocarbons evident at the site, these results are not relied on.

Field Testing Methodology:

Soils are contained inside a sealed glass container and exposed to a heat source. The volatile components in the soil evaporate and are contained within the "head space." The Teflon probe of the CGI is inserted through the seal and the gases are extracted and measured within the CGI.

Analytical results from the Phase II investigation is contained in the following table.

Matrix: Soil

WTPH-Dx mg/Kg

SAMPLE ID.	LOCATION	Gasoline	Diesel	Heavy Oils
TP1-01	Hole 1/8'	ND	ND	790
TP1-02	Hole 1/12'	ND	ND	68
TP2-03	Hole 2/8'	ND	ND	ND
TP2-04	Hole 2/12'	ND	ND	650
TP3-05	Hole 3/8'	ND	210	560
TP3-06	Hole 3/12'	ND	ND	600
TP4-07	Hole 4/8'	ND	ND	79
TP5-08	Hole 5/8'	ND	ND	ND

All samples were tested for the presence of total hydrocarbons in the soil Method WA-TPH-HCID followed with TPH-Dx.

TPH-HCID or Total Petroleum Hydrocarbon Identification is a general purpose screening method for the presence of high level contamination of most organic compounds. If petroleum contamination is present, HCID is useful to determine the type (i.e. gasoline, diesel, and waste oil) and approximate concentration.

Conclusion:

Organic petroleum hydrocarbon contamination in the diesel and heavy oil range was detected during the soil testing. Laboratory tests confirmed and supported our site investigative conclusions.

The analytical results revealed contamination in excess of the Washington State Model Control Act (MTCA) Cleanup Levels at the former UST's location north of the truck wash and at the southwest corner of the shop building. Both locations could be easily remedied by soil excavation and off-site transport of the contaminated material.

During the course of the visual and physical inspection, no other potential environmental risks or recognized environmental conditions indicating the presence of hazardous conditions were observed.


STATEMENT OF THE ENVIRONMENTAL PROFESSIONALS

Statement of Quality Assurance

I have performed this Phase II Site Assessment in accordance with generally accepted environmental practices and procedures, as of the date of this Report. I have employed the degree of care and skill ordinarily exercised under similar circumstances by reputable environmental professionals practicing in this area. The conclusions contained within this Assessment are based upon site conditions I readily observed or which were reasonably ascertainable and present at the time of my Site inspection.

The conclusions and recommendations stated in this report are based upon personal observations made by myself and other employees of NCP&S, Inc. and also upon information provided by others. I have no reason to suspect or believe that the information provided is inaccurate.

Signature of Environmental Professional- P. Trabusiner



Engineer

Statement of Quality Control

The objective of this Phase II Site Assessment was to ascertain the potential presence or absence of environmental releases or threatened releases that could impact the subject property, as delineated by the Scope of Work. The procedure was to perform reasonable steps in accordance with the existing regulations, currently available technology, and generally accepted engineering practices in order to accomplish the stated objective.

The Scope of this Assessment does not purport to encompass every report, record, or other form of documentation relevant to the property being evaluated. To the best of my knowledge, this Environmental Site Assessment has been performed in compliance with NCP&S, Inc. Standard Operating Procedures protocol for Phase II Environmental Site Assessments.

Signature of Environmental Quality Control

Quality Control

Environmental Assessment Report Limitations:

The enclosed Phase II Environmental Site Assessment has been performed for the exclusive use of Central Valley Bank in Yakima, Washington, or agents specified by them for the transaction at issue concerning the subject property located at 1602 Rudkin Road, in Yakima, Washington.

The purpose of an environmental investigation is to evaluate potential or actual effects of past or current practices on a given site. In performing an environmental investigation, a balance must be struck between reasonable inquiry into environmental issues and an exhaustive analysis of every conceivable issue of possible concern. This environmental assessment contains NCP&S opinion regarding environmental issues of concern and/or additional issues that may need to be addressed. In rendering our professional opinion, NCP&S warrants that the services provided within the scope of this assessment were performed, within the limits described, in accordance with generally accepted environmental consulting principles and practices. No other warranty, expressed or implied, is made. The following paragraphs describe the assumptions and standard parameters under which such opinion is rendered.

Any opinions and/or recommendations presented in this report apply to site conditions existing at the time of performance of services. NCP&S is unable to report on or accurately predict events that may affect the site after performance of services, whether occurring naturally or caused by human forces. NCP&S assumes no responsibility for conditions NCP&S did not investigate, or conditions not generally recognized as environmentally unacceptable at the time services were performed.

Where subsurface work was performed, NCP&S professional opinions are based in part on the interpretation of data from discrete sample locations that may not represent actual conditions at the non-sampled locations.

Except where there is expressed concern of our client, or where specific environmental contaminants have previously been reported by others, naturally occurring toxic substances, potential environmental contaminants located inside buildings, or contaminant concentrations not of current environmental concern, may not be addressed in this document.

No assessment is thorough enough to exclude the presence of hazardous materials at a given site. Therefore, if specific hazardous materials have not been identified during this assessment, the lack of such identifications should not be construed as a guarantee of the absence of hazardous materials, but merely as the result of services performed within the scope, limitations, and cost of work done.

NCP&S is not responsible for the effects of changes in applicable environmental standards, practices, or regulations after the performance of services.

Services provided for this assessment were performed in accordance with NCP&S agreement and understanding with our client, which may not be fully disclosed in this report. Opinions and/or recommendations are intended for the client, purpose, site, location, time frame, and project parameters indicated.

This report was prepared solely for the use of Central Valley Bank, and should be reviewed in its entirety; NCP&S is not responsible for subsequent separation, detachment, or partial use of this document. Any reliance on this report by a third party shall be at such party's sole risk.


SITE ASSESSMENT PLUS REPORT

SITE INVENTORY

MAP ID	PROPERTY AND THE ADJACENT AREA (within 1/8 mile)	VISTA ID DISTANCE DIRECTION	A			B					C		D				
			NPL	CORRACTS	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	WATER WELLS	RCRA VIOL	TRIS	UST/AST	ERNS	C/NRTP
1	YAKIMA STP 2220 EAST VIOLA YAKIMA, WA 98901	1850876 0.00 MI NA													X		
1	WONDRACK DISTRIBUTING, INC., 1602 RUDKIN RD YAKIMA, wa 98903	6887930 0.00 MI NA							X		X				X		
2	MOBILE FLEET SVC INC MAIN LOCATION VIOLA 2003 E VIOLA YAKIMA, WA 98901	280083 0.06 MI W							X						X		X

MAP ID	SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile)	VISTA ID DISTANCE DIRECTION	A			B						C			D	
			NPL	CORRACTS	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	WATER WELLS	RCRA VIOL	TRIS	UST/AST	ERNS
3A	USGS WATER WELL ID #463500120282801 , WA	9671594 0.15 MI NW										X				
3B	USGS WATER WELL ID #463502120282701 , WA	9671602 0.17 MI NW										X				
4	KMART 4439 2304 E NOB HILL BLVD YAKIMA, WA 98901	1847095 0.21 MI N												X		

MAP ID	SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile)	VISTA ID DISTANCE DIRECTION	A			B						C			D	
			NPL	CORRACTIS	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	WATER WELLS	RCRA VIOL	TRIS	UST/AST	ERNS
5	MAID O'CLOVER CORPORATION 1802 E NOB HILL YAKIMA, wa 98901	1847082 0.34 MI NW						X						•		
5	MAID O CLOVER 1802 E NOB HILL BLVD YAKIMA, WA 98901	2884152 0.34 MI NW			X											



X = search criteria; • = tag-along (beyond search criteria).

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 197901901


Date of Report: December 13, 1999

Version 2.6.1

Page #6

PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

Leak Report Date:	7/27/95
Remediation Start Date:	4/10/95
Remediation Status:	CLEANUP STARTED
Media Affected:	SOIL
Region / District:	C
STATE UST - State Underground Storage Tank / SRC# 6183	
Agency Address:	WONDRACK DISTRIBUTING, INC. 1602 RUDKIN RD YAKIMA, WA 98901
Underground Tanks:	7
Aboveground Tanks:	NOT REPORTED
Tanks Removed:	4
Tank ID:	1U
Tank Contents:	UNLEADED GAS
Tank Age:	4
Tank Size (Units):	10000 (GALLONS)
Tank Status:	ACTIVE/IN SERVICE
Leak Monitoring:	NOT AVAILABLE
Tank Piping:	NOT AVAILABLE
Tank Material:	FRP CLAD STEEL
Tank ID:	1U
Tank Contents:	UNLEADED GAS
Tank Age:	4
Tank Size (Units):	10000 (GALLONS)
Tank Status:	ACTIVE/IN SERVICE
Leak Monitoring:	NOT AVAILABLE
Tank Piping:	NOT AVAILABLE
Tank Material:	FRP CLAD STEEL
Tank ID:	1U
Tank Contents:	DIESEL
Tank Age:	4
Tank Size (Units):	10000 (GALLONS)
Tank Status:	ACTIVE/IN SERVICE
Leak Monitoring:	NOT AVAILABLE
Tank Piping:	NOT AVAILABLE
Tank Material:	FRP CLAD STEEL
Tank ID:	1U
Tank Contents:	USED OIL, WASTE OIL
Tank Age:	16
Tank Size (Units):	1100 (GALLONS)
Tank Status:	REMOVED
Leak Monitoring:	NOT AVAILABLE
Tank Piping:	NOT AVAILABLE
Tank Material:	COATED STEEL
Tank ID:	1U
Tank Contents:	USED OIL, WASTE OIL
Tank Age:	16
Tank Size (Units):	1100 (GALLONS)
Tank Status:	REMOVED
Leak Monitoring:	NOT AVAILABLE
Tank Piping:	NOT AVAILABLE
Tank Material:	NOT AVAILABLE
Tank ID:	1U
Tank Contents:	OTHER
Tank Age:	16
Tank Size (Units):	NOT REPORTED (NOT AVAILABLE)
Tank Status:	REMOVED
Leak Monitoring:	NOT AVAILABLE
Tank Piping:	NOT AVAILABLE
Tank Material:	COATED STEEL
Tank ID:	1U
Tank Contents:	OTHER
Tank Age:	16
Tank Size (Units):	NOT REPORTED (NOT AVAILABLE)
Tank Status:	REMOVED
Leak Monitoring:	NOT AVAILABLE
Tank Piping:	NOT AVAILABLE
Tank Material:	COATED STEEL
WA Toxics - Washington Toxics / SRC# 6410	
Agency Address:	WONDRACK DISTRIBUTING (TWO REPORTS) 1602 RUDKIN ROAD YAKIMA, WA 98901
Region:	CENTRAL
State Detail Description:	NO
Contact:	NOT REPORTED
EPA/Agency ID:	N/A



* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 197901901


Date of Report: December 13, 1999

Version 2.6.1

Page #11

SITE ASSESSMENT PLUS REPORT

Street Map




For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403

Report ID: 197901901

Date of Report: **December 13, 1999**

Page #5





FORMER LOCATION OF THE TWO 8000 GALLON USTs.



TEST HOLE, TYPICAL.



FORMER LOCATION OF WASTE OIL UST AT THE SOUTHEAST CORNER OF THE SHOP BUILDING.




ALL TEST HOLES WERE BACK FILLED WITH THE EXCAVATED MATERIAL.



EXCAVATION WORK FOR SOIL TESTING AT THE TRUCK WASH.



FORMER LOCATION OF WASTE OIL UST AT THE SOUTHWEST CORNER OF THE SHOP BUILDING.





**OnSite
Environmental Inc.**
Analytical Testing and Mobile Laboratory Services

January 18, 2000

Peter Trabusiner
Net Compliance
210 N. Perry, Suite B
Kennewick, WA 99336

Re: Analytical Data for Project ITEC, Inc.
Laboratory Reference No. 0001-047

Dear Peter:

Enclosed are the analytical results and associated quality control data for samples submitted on January 11, 2000.

The standard policy of OnSite Environmental Inc. is to store your samples for 30 days from the date of receipt. If you require longer storage, please contact the laboratory.

We appreciate the opportunity to be of service to you on this project. If you have any questions concerning the data, or need additional information, please feel free to call me.

Sincerely,



David Baumeister
Project Manager

Enclosures

Date of Report: January 18, 2000
Samples Submitted: January 11, 2000
Lab Traveler: 01-047
Project: ITEC, Inc.

NWTPH-HCID

Date Extracted: 1-11-00
Date Analyzed: 1-11-00

Matrix: Soil
Units: mg/Kg (ppm)

Client ID:	TP1-01	TP1-02	TP2-03
Lab ID:	01-047-01	01-047-02	01-047-03

Gasoline:	ND	ND	ND
PQL:	27	26	27

Diesel Fuel:	ND	Diesel Fuel #2	ND
PQL:	55	52	53

Heavy Oil:	Heavy Oil	ND	ND
PQL:	110	100	110

Surrogate Recovery:			
o-Terphenyl	123%	130%	132%

Flags:

Date of Report: January 18, 2000
Samples Submitted: January 11, 2000
Lab Traveler: 01-047
Project: ITEC, Inc.

NWTPH-HCID

Date Extracted: 1-11-00
Date Analyzed: 1-11&12-00

Matrix: Soil
Units: mg/Kg (ppm)

Client ID:	TP2-04	TP3-05	TP3-06
Lab ID:	01-047-04	01-047-05	01-047-06

Gasoline:	ND	ND	ND
PQL:	27	27	27

Diesel Fuel:	ND	ND	ND
PQL:	55	54	53

Heavy Oil:	Heavy Oil	Heavy Oil	Heavy Oil
PQL:	110	110	110

Surrogate Recovery:			
o-Terphenyl	134%	130%	114%

Flags:

Date of Report: January 18, 2000
Samples Submitted: January 11, 2000
Lab Traveler: 01-047
Project: ITEC, Inc.

NWTPH-HCID

Date Extracted: 1-11-00
Date Analyzed: 1-11&12-00

Matrix: Soil
Units: mg/Kg (ppm)

Client ID:	TP4-07	TP5-08
Lab ID:	01-047-07	01-047-08

Gasoline:	ND	ND
PQL:	28	26

Diesel Fuel:	ND	Diesel Fuel #2
PQL:	56	53

Heavy Oil:	Heavy Oil	ND
PQL:	110	110

Surrogate Recovery:		
o-Terphenyl	136%	138%

Flags:

Date of Report: January 18, 2000
Samples Submitted: January 11, 2000
Lab Traveler: 01-047
Project: ITEC, Inc.

**NWTPH-HCID
METHOD BLANK QUALITY CONTROL**

Date Extracted: 1-11-00
Date Analyzed: 1-11-00

Matrix: Soil
Units: mg/Kg (ppm)

Lab ID: MB0111S1

Gasoline: ND
PQL: 25

Diesel Fuel: ND
PQL: 50

Heavy Oil: ND
PQL: 100

Surrogate Recovery:
o-Terphenyl 114%

Flags

Date of Report: January 18, 2000
Samples Submitted: January 11, 2000
Lab Traveler: 01-047
Project: ITEC, Inc.

NWTPH-Dx

Date Extracted: 1-13-00
Date Analyzed: 1-13-00

Matrix: Soil
Units: mg/Kg (ppm)

Client ID:	TP1-01	TP1-02	TP2-04
Lab ID:	01-047-01	01-047-02	01-047-04

Diesel Fuel:	ND	ND	ND
PQL:	28	26	28

Heavy Oil:	790	68	650
PQL:	55	52	55

Surrogate Recovery:			
o-Terphenyl	97%	89%	76%

Flags:

Date of Report: January 18, 2000
Samples Submitted: January 11, 2000
Lab Traveler: 01-047
Project: ITEC, Inc.

NWTPH-Dx

Date Extracted: 1-13-00
Date Analyzed: 1-13-00

Matrix: Soil
Units: mg/Kg (ppm)

Client ID:	TP3-05	TP3-06	TP4-07
Lab ID:	01-047-05	01-047-06	01-047-07

Diesel Fuel:	ND	ND	ND
PQL:	27	27	28

Heavy Oil:	560	600	79
PQL:	54	53	56

Surrogate Recovery:			
o-Terphenyl	98%	119%	84%

Flags:

Date of Report: January 18, 2000
Samples Submitted: January 11, 2000
Lab Traveler: 01-047
Project: ITEC, Inc.

NWTPH-Dx

Date Extracted: 1-13-00
Date Analyzed: 1-13-00

Matrix: Soil
Units: mg/Kg (ppm)

Client ID: TP5-08
Lab ID: 01-047-08

Diesel Fuel: 210
PQL: 26

Heavy Oil: ND
PQL: 53

Surrogate Recovery:
o-Terphenyl 127%

Flags:

Date of Report: January 18, 2000
Samples Submitted: January 11, 2000
Lab Traveler: 01-047
Project: ITEC, Inc.

NWTPH-Dx
METHOD BLANK QUALITY CONTROL

Date Extracted: 1-13-00
Date Analyzed: 1-13-00

Matrix: Soil
Units: mg/Kg (ppm)

Lab ID: MB0113S1

Diesel Fuel: ND
PQL: 25

Heavy Oil: ND
PQL: 50

Surrogate Recovery:
o-Terphenyl 117%

Flags:

Date of Report: January 18, 2000
Samples Submitted: January 11, 2000
Lab Traveler: 01-047
Project: ITEC, Inc.

NWTPH-Dx
DUPLICATE QUALITY CONTROL

Date Extracted: 1-13-00
Date Analyzed: 1-13-00

Matrix: Soil
Units: mg/Kg (ppm)

Lab ID: 01-047-07 01-047-07 DUP

Diesel Fuel: ND ND
PQL: 25 25

RPD: N/A

Surrogate Recovery:
o-Terphenyl 84% 86%

Flags:

Date of Report: January 18, 2000
Samples Submitted: January 11, 2000
Lab Traveler: 01-047
Project: ITEC, Inc.

Date Analyzed: 1-11-00

% MOISTURE

Client ID	Lab ID	% Moisture
TP1-01	01-047-01	9.0
TP1-02	01-047-02	4.0
TP2-03	01-047-03	6.0
TP2-04	01-047-04	9.0
TP3-05	01-047-05	7.0
TP3-06	01-047-06	6.0
TP4-07	01-047-07	10
TP5-08	01-047-08	5.0



USTFILE

STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

15 West Yakima, Suite 200 • Yakima, Washington 98902-3401 • (509) 575-2490

June 5, 1997

CERTIFIED MAIL
P 581 915 693

Mr. Don Werst
Yakima Transport Service
1602 Rudkin Road
Yakima WA 98901

*Wondrack
Distributing*

Dear Mr. Werst:

During an investigation into Cayuse Environmental's actions on a site in Yakima it was found that Cayuse Environmental and its employees did not have the necessary certifications to perform work on Underground Storage Tanks as required by Washington Administrative Code 173-360, Underground Storage Tank Regulations.

A review of Washington Department of Ecology's files found that Cayuse Environmental performed work at your site that did not meet the minimum standards of the regulations. Permitting a unlicensed individual to work on Underground Storage Tanks could result in fines to the owner of the Underground Storage Tanks. Ecology is not considering issuing fines to the site owners at this time.

Cayuse Environmental, your service provider, did not have the required certifications. I have performed a brief review of your site and found the reports submitted by Cayuse Environmental do not meet the minimum requirements of the Washington Administrative Code 173 360, Underground Storage Tank Regulations. Ecology will consider your site as being possibly contaminated. Ecology is not requiring you to do additional work or testing at your site. If you do additional work, Ecology will note the corrective actions you did and, if appropriate, consider your site as a clean closure.

Ecology can provide limited free Technical Assistance to your site. A detailed review of your site greater than 30 minutes will require other arrangements.

Ecology does not believe your site is an immediate threat to human health or the environment; the completeness of the decommissioning of the Underground Storage Tanks and the site cleanup are in question based on the information in Ecology files.



CONTENT

SECTION 1 - 1.0 INTRODUCTION

- * 1.1 PURPOSE
- * 1.2 SCOPE OF WORK

SECTION 2 - 2.0 BACKGROUND INFORMATION

- * 2.1 SITE LOCATION
- * 2.2 SITE DESCRIPTION AND HISTORY
- * 2.3 SOIL DESCRIPTION
- * 2.4 GROUND WATER

SECTION 3 - 3.0 FIELD ACTIVITIES

- * 3.1 GENERAL INVESTIGATION METHODS
- * 3.2 TANK CLEANING, INSPECTION, AND DISPOSAL
- * 3.3 EXCAVATION OF PETROL CONTAMINATION SOIL
- * 3.4 SOIL SAMPLES

SECTION 4 - INVESTIGATION RESULTS

- * SOIL SAMPLING RESULTS

SECTION 5 - 5.0 CONCLUSION AND RECOMMENDATION

- * 5.1 CONCLUSION

SECTION 6 - LIMITATIONS

SECTION 7 - MAPS

SECTION 8 - ANALYSIS

SEE PAGE 8

4.0 INVESTIGATION RESULTS

4.1 Soil Sampling Results

Soil samples were collected from the sides and bottom of both tanks. Soil which contained diesel contamination was stockpiled for later. Disposal field screening was used to determine when enough soil had been excavated and stockpiled best for soil samples were collected and sent to Spetra Labs of Tacoma, WA. For analysis of soil sample map and analysis of soil sample are located in the back of this report.

5.0 CONCLUSION AND RECOMMENDATION

5.1 Conclusion and Recommendations

Soil samples confirmed that no further contaminated soil present at this site. All contaminated has been disposed of. No ground water was encountered, therefore it is recommended no further work is needed at this site.

6.0 LIMITATIONS

In performing our professional services, CE uses a degree of care ordinarily exercised under similar circumstances by members of our profession. No warranty, expressed or implied, is made or intended. Our conclusions and recommendations developed from our field and laboratory investigation reported herein are based upon this firm's understanding of the project and are in concurrence with generally accepted practice.

4-95


[illegible]

9511

Don Werst

Yakima WA.

4-95



Tank locations

Ruck K

Track Wash


Shop

9511

Don Werst

Ya Kima

4-95



Truck
wash

Shop





UNDERGROUND STORAGE TANK Site Check/Site Assessment Checklist

C. 40001934
~~102302~~ K.R.
PR 24 1995

The purpose of this form is to certify the proper investigation of an UST site for the presence of a release. These activities shall be conducted in accordance with Chapter 173.360 WAC. A description of the various situations requiring a site check or site assessment is provided in the guidance document for UST site checks and site assessments.

This Site Check/Site Assessment Checklist shall be completed and signed by a person registered with the Department of Ecology to perform site assessments.

Two copies of the results of the site check or site assessment should be included with this checklist according to the reporting requirements in the guidance document for UST site checks and site assessments.

For further information about completing this form, please contact the Department of Ecology UST Program.

The completed checklist should be mailed to the following address:

Underground Storage Tank Section
Department of Ecology
Mail Stop PV-11
Olympia, WA 98504-8711

1. UST SYSTEM OWNER AND LOCATION

UST Owner/Operator: Don Werst
Owners Address: 1602 Rudkin Rd
Street
Union Gap WA.
City State
Telephone: (509) 575-1830
ZIP-Code

Site ID Number (on invoice or available from Ecology if tank is registered): ~~102302~~
Site/Business Name: Don Werst
Site Address: 1602 Rudkin Rd.
Street
Union Gap WA. Yakima
City State County
ZIP-Code

2. SITE CHECK/SITE ASSESSMENT CONDUCTED BY:

Registered Person: Bryan Mull
Address: 60 Olden Way
Street
Toppenish WA.
City State
Telephone: (509) 865-5086
ZIP-Code

3. TANK INFORMATION

1. Tank ID Number (as registered with Ecology): 1 and 2 2. Year installed: 1985
3. Tank capacity in gallons: 2 x 8000 Gallons 4. Last substance stored: Diesel

4. REASON FOR CONDUCTING SITE CHECK/SITE ASSESSMENT

Check one:

- ☐ Investigate suspected release due to on-site environmental contamination
- ☐ Investigate suspected release due to off-site environmental contamination
- ☐ Extend temporary closure of UST system for more than 12 months
- ☐ UST system undergoing change-in-service
- ☐ UST system permanently closed-in-place
- ☒ UST system permanently closed with tank removed
- ☐ Required by Ecology or delegated agency for UST system closed before December 22, 1988
- ☐ Other (describe): _____

5. CHECKLIST

Each item of the following checklist shall be initialed by the person registered with the Department of Ecology whose signature appears below.

	Yes	No
1. Has the site check/site assessment been conducted according to applicable procedures specified in the UST site check/site assessment guidance issued by the Department of Ecology?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Has a release from the UST system been confirmed? <i>NOTE: Owners/operators must report all confirmed releases to the Department of Ecology or delegated agency within 24 hours.</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Are the results of the site check/site assessment enclosed with this checklist? <i>NOTE: Two copies of the site check/site assessment results must be submitted to the Department of Ecology according to the reporting requirements specified in the UST site check/site assessment guidance.</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

I hereby certify that I have been in responsible charge of performing the site check/site assessment described above.
Persons submitting false information are subject to penalties under Chapter 173.360 WAC.

4-17-95
Date

Bya Muth
Signature of Person Registered with Ecology

6. OWNER'S SIGNATURE

4/20/95
Date

Ronald L. Went
Signature of Tank Owner or Authorized Representative



UNDERGROUND STORAGE TANK Permanent Closure/Change-In-Service Checklist

C 40001934
102302 KB
6-4-95

The purpose of this form is to certify the proper closure/change-in-service of underground storage tank (UST) systems. These activities must be conducted in accordance with Chapter 173.360 WAC. Washington State UST rules require the tank owner or operator to notify Ecology in writing 30 days prior to closure or change-in-service of tanks. This must be done by completing the 30 Day Notice form (ECY 010-155).

This Permanent Closure Checklist shall be completed and signed by a Licensed Decommissioning Supervisor. The supervisor shall be on site when all tank permanent closure/change-in-service activities are being conducted. The firm which employs the licensed supervisor shall also be licensed by the Washington State Department of Ecology as a Service Provider. If any of the activities listed below have been supervised by a different licensed supervisor, a separate checklist must be filled out and signed by the licensed supervisor performing those activities.

For further information about completing this form, please contact the Department of Ecology UST Program.

A separate checklist must be completed for each UST system (tank and associated piping), except that UST systems at one site may be reported together by completing page 2 of this form separately for each system. The completed checklist should be mailed to the following address within 30 days of the completion of the closure or change-in-service.

Underground Storage Tank Section
Department of Ecology
Mail Stop PV-11
Olympia, WA 98504-8711

1. UST SYSTEM OWNER AND LOCATION

Site Owner/Operator:

Don Werst

Owners Address:

1602 Rudkin Rd.

Street

P.O. Box

Union Gap WA

City

State

ZIP-Code

Telephone:

(509) 575-1830

Site ID Number (on invoice or available from Ecology if tank is registered):

Site/Business Name:

Don Werst

Site Address:

1602 Rudkin Rd.

Street

Yakima

County

Union Gap WA

City

State

ZIP-Code

2. TANK PERMANENT CLOSURE/CHANGE-IN-SERVICE PERFORMED BY:

Firm:

Coyase Environmental

License Number: 5002224

Address:

600 Olden Way

Street

P.O. Box

Tappanish.

City

WA

State

ZIP-Code

Telephone:

(509) 865-5086

Licensed Supervisor:

Gordon Mull

Decommissioning
License Number: 5002563

This page must be completed separately for each tank permanently closed (decommissioned) or change-in-service at the site. For additional tanks you may photocopy this form prior to completing.

3. TANK CLOSURE/CHANGE-IN-SERVICE INFORMATION

1. Tank ID Number (as registered with Ecology): 01-02
2. Year installed: 84
3. Tank capacity in gallons: 2 x 8000 Gallon
4. Date of last use: 1993
5. Last substance stored: Diesel
6. Date of closure/change-in-service: 4-95
7. Type of closure: Closure with Tank Removal ☒ In-place Closure ☐ Change-in-Service ☐
8. If in-place closure is used, the tank has been filled with the following substance: _____
9. If change-in-service, indicate new substance stored in tank: _____
10. Local permit(s) (if any) obtained from: _____
11. Has a site assessment been completed? Yes ☒ No ☐

Always contact local authorities regarding permit requirements.

Unless an external release detection system is operating at the time of closure or change in service, and a report is provided as specified in WAC 173-360-390, a site assessment must be conducted. This site assessment must be conducted by a person registered with the Department of Ecology to perform site assessments. Results of the site assessment must be included with the Site Assessment Checklist (ECY 010-158).

4. CHECKLIST

Each item of the following checklist shall be initialed by the licensed supervisor whose signature appears below.

	Yes	No	NA*
1. Has all liquid been removed from product lines?	X		
2. Has all product piping been capped or removed?	X		
3. Have all non-product lines been capped or removed?	X		
4. Have all liquid and accumulated sludges been removed from the tank?	X		
5. Has the tank been properly purged or inerted?	X		
6. Have the drop tube, fill pipe, gauge pipe, pumps and other tank fixtures been removed?	X		
7. Have all tank openings been plugged or capped? NOTE: One plug should have 1/8 inch vent hole.	X		
8. Have all sludges removed from the tank been designated and disposed of in accordance with the state of Washington's dangerous waste regulations (Chapter 173-303 WAC)?	X		
9. If removed, was tank properly labeled and disposed of in accordance with all applicable local, state and federal regulations?	X		

*Item not applicable

I hereby certify that I have been the licensed supervisor present on site during the above listed permanent closure activities and to the best of my knowledge they have been conducted in compliance with all applicable state and federal laws, regulations and procedures pertaining to underground storage tanks.

Persons submitting false information are subject to penalties under Chapter 173-360 WAC.

Date

Signature of Licensed Supervisor

5. ADDITIONAL REQUIRED SIGNATURES

Date

Signature of Licensed Service Provider (firm) Owner or Authorized Representative

Date

Signature of Tank Owner or Authorized Representative



SPECTRA Laboratories, Inc.

2221 Ross Way • Tacoma, WA 98421 • (206) 272-4850

April 11, 1995

Cayuse Environmental
60 Olden Way
Toppenish, WA 98948

Attn: Bryan Mull

PO #9511
Project: Werth
Sample Matrix: Soil
Date Sampled: 4-5-95
Date Received: 4-7-95
Date Analyzed: 4-7-95
Spectra Project: S504-045

<u>Spectra #</u>	<u>Sample ID:</u>	<u>WTPH-D, mg/Kg</u>	<u>Surrogate Recovery</u> <u>p-Terphenyl</u>
2076	9511-01	3,800	111%
2077	9511-02	1,260	28%*
2078	9511-03	<25	28%*
2079	9511-04	<25	57%
2080	9511-05	<25	31%*
2081	9511-06	<25	39%*
2082	9511-07	<25	85%
2083	9511-08	<25	35%*
2084	9511-09	14,900	80%
Method Blank		<25	95%

*Out of limits due to sample matrix effects.

SPECTRA LABORATORIES, INC.



Steven G. Hibbs, Chemist



WHITE SHIELD, INC.

P.O. BOX 477 • GRANDVIEW, WA 98930 • (509) 882-1144
FAX (509) 882-4566



April 21, 1995

Joe Wondrack
529 East Kennewick Avenue
Kennewick, WA. 99336

Re: Site Check, Yakima Truck Service, 1602 Rudkin Road, Yakima, WA

Dear Mr. Wondrack:

White Shield Environmental Technician, Rick Funderburk a site assessor registered with the Washington State Department of Ecology Underground Storage Tank Program, performed a site check of the referenced facility on March 27, and 28, 1995. Refer to the attached Site Location Map.

The work included a visual site check to identify potential environmental concerns related to the property and soil sampling adjacent to two Underground Storage Tanks (USTs) located beneath concrete pavement to the north of the truck washing facility.

On March 27, under the direction of WSI, DKR Construction cut and removed the concrete pavement above the USTs. The soil in test pit #1, located on the east side of the UST's, consisted of brown clayey silt with river rock. Upon excavation of the test pit, a band of grey soil was unearthed at approximately 6" in depth. A soil sample was collected from the grey soil for field screening. The sample was analyzed in the field using Thin Layer Chromatography (TLC). Please refer to the attached description of Thin Layer Chromatography and the site map for sample location. Results from the field screening indicated diesel fuel contamination between 200 to 300 parts per million.

Upon further excavation, concrete was encountered above the UST at 3½ feet in depth. Mr. Werst, the site owner, stated that a truck load of concrete had been poured on top of the USTs to keep them from floating on the groundwater. DKR relocated 3' to the east of the original excavation and began to extend the test pit. The excavation began collapsing due to the unstable river rock. At approximately 6' in depth, the end of the UST was exposed. There appeared to be no noticeable rusting or pitting on the UST. A soil sample was collected from a depth of 12' next to the end of the UST. Field screening of the sample indicated that no apparent petroleum hydrocarbon contamination was present.

On March 28, a second test pit was excavated west of the UST's. A grey layer of soil was also discovered beneath the concrete pavement. At a depth of 6', the sidewalls of the test pit began collapsing. At this point it was decided not to excavate any further due to the close proximity of the foundation of the truck wash building. Refer to the attached Site Plan.

Mr. Joe Wondrack
April 21, 1995

Page 2

The site investigation also revealed a small diesel stain in the soil at the southeast corner of the truck wash. The stain appears to have originated from a dispenser that is currently being used in conjunction with the Above Ground Storage Tank. Overfill of the vehicles is suspected.


Another area of concern is a 55 gallon drum on a pallet located on the south side of the property. The drum appears to contain a heavy petroleum based product. The product has been spilled onto the surface of the soil. Also, to the south of the truck wash, runoff water from the truck washing operation is puddling on the outside of the building and soaking into the ground. Groundwater in the area is shallow and contaminated runoff could be affecting the groundwater quality. Refer to the Site Plan.

We appreciate the opportunity to provide you with technical assistance on this site. Please call us at (509) 882-1144 should you have any questions or need any additional information.

Sincerely,
WHITE SHIELD, INC.



Rick Funderburk
Project Manager




Stuart W. Fricke,
President

FIELD SCREENING WITH THIN LAYER CHROMATOGRAPHY

For field analysis of semi-volatile (diesel) and non-volatile compounds (motor oil), WSI uses Thin Layer Chromatography (TLC) for qualitative and quantitative analysis. This analytical technique utilizes the principle of chromatography to separate individual components for comparison to known standards.

TLC is classified as a solid-liquid chromatographic system, meaning there are two phases through which an extract of the sample is passed; a solid phase (silica gel) and a liquid phase (a solvent such as hexane).

The solid phase is stationary and is coated on a glass plate. During the chromatography process, the liquid phase carries the sample through the solid phase. The solvent moves at a fairly constant rate through the solid phase. However, the compound in the sample (analyte) are partitioned by a relative attractiveness of the analyte between the solid phase and the liquid phase. Analytes strongly attracted to the silica will remain on the silica longer and move more slowly than analytes that are not as strongly attracted to the silica. When the chromatography is stopped, the distance the analyte has moved relative to the distance the solvent has moved is used to identify the compound. When the plate is viewed under ultraviolet light, the analytes can be seen and compared to standards of known concentration for quantitative analysis.



SITE LOCATION MAP



WHITE SHIELD

INC.

P.O. BOX 477, 801 GRANDRIDGE ROAD, GRANDVIEW, WA 98930
TELEPHONE: (509) 882-1144 VOICE (509) 882-4666 FAX

JOB

1X101-0495

SHEET NO.

1

OF

1

CALCULATED BY

1

DATE

1

CHECKED BY

1

DATE

1

SCALE

1/15



RUDKIN ROAD

TEST PIT #2

Concrete
PAD

TEST PIT #1

UST'S

Truck
WASH

AST

STAIN
AREA

DISPENSER

HAZARDOUS Truck
SERVICE

RUNOFF

55 GALLON
Drum

I-82

SITE MAP

UNDERGROUND STORAGE TANK INFORMATION UPDATE

Please check all of the information on this page to make sure it is correct. Make any changes on this page, and fill in any missing or incorrect information in the corrected information column on the right.

1. TANK OWNER INFORMATION

OWNER NUMBER: U0001934
OWNER NAME: DON WERST
OWNER ADDRESS: 4515 SNOW MT RD
YAKIMA, WA 98908-2842
OWNER PHONE: (509) 965-2694

2. TANK SITE INFORMATION

SITE NUMBER: 004274
SITE NAME: ZERR TRUCKING
SITE ADDRESS: 1602 A RUDKIN RD.
YAKIMA, WA 98901-
SITE COUNTY: YAKIMA
CONTACT PERSON: HARLAN ZERR
CONTACT PHONE: (509) 452-8681

DON WERST
1602 A RUDKIN RD.
YAKIMA, WASH. 98901
YAKIMA
DON WERST
509-965-2694

3. TANK INFORMATION

TANK ID: 1
TANK STATUS: OPERATIONAL
SUBSTANCE STORED: DIESEL FUEL
TANK SIZE: 5000-9999 GALLONS
INSTALLATION DATE: 10-01-1983

OUT OF SERVICE TEMPORARY

4. TANK FEE INFORMATION

The Annual Fee is for the Period 7/01/94 - 6/30/95

Tanks that are temporarily closed will not receive a permit but are subject to annual tank fees. Payments should be made by check or money order - no cash please. Return update form and payment to the Department of Ecology, P.O. Box 5128, Lacey, WA 98503-0210, or use return envelope provided.

Disputes must be made in writing. If you have general questions, please call 1-800-826-7716 (Voice) or (206) 407-7155 (TDD)

ANNUAL FEE INFORMATION FOR ALL TANKS AT THIS SITE:

INVOICE NUMBER: UST47025 SITE NUMBER: 004274
4 TANKS AT \$75.00 EACH; DUE FOR CURRENT YEAR: \$300 ; TOTAL DUE FOR ALL YEARS: \$300
DATE DUE: JUNE 1, 1994

PREVIOUS YEARS' OUTSTANDING FEES:
1990: \$0 1991: \$0 1992: \$0 1993: \$0 1994: \$0

5. OWNER MUST SIGN IN THIS BLOCK TO RECEIVE VALID PERMITS

SWORN STATEMENT: I hereby swear under penalty of law that, based on my knowledge of the tank identified by the tank ID number, this tank is in compliance with applicable state requirements. Also, any new or corrected information required on this form has been entered accurately. I understand that false statements may result in this permit being immediately revoked and I may be subject to penalties under Chapter 173-360 WAC.

PRINT OR TYPE.

DONALD H. WERST

Name of UST owner or Authorized Representative

Donald H. Werst
Signature of UST Owner or Authorized Representative

4/19/94
Date Signed

509-965-2694
Telephone Number

(DO NOT DETACH - RETURN ALL PARTS OF THIS FORM TO ECOLOGY)

Underground Storage Tank Permit
Washington Department of Ecology
Please Display at the Underground Storage Tank Site.

UST TEST RESULTS
(PRECISION TANK TESTING)

♦ ♦ ♦

MILKY WAY
1602 RUDKIN ROAD
YAKIMA, WASHINGTON

May 20, 1992

Mr. Don Gutherie
MILKY WAY
1602 Rudkin Road
Yakima, WA 98901

RE: Precision Tank Test Results

Dear Mr. Gutherie:

Following, please find the results of the volumetric precision tank tests conducted on the two underground storage systems (USTs) located at 1602 Rudkin Road, Yakima, Washington. The final results are indicated on the cover sheet of the test packet; a site plot of the facility will indicate the location of each system tested. A brief summary of the results obtained is as follows:

DIESEL-EAST SYSTEM - (8,000 Gallons): Appendix A

A full system's precision test was conducted on this system at an elevation of 120 inches (25 inches above tank top). This UST system has a **suction type product delivery system**; the precision tank test conducted includes all of the system below fluid level. The precision test results (#0534) indicated a net final change (temperature corrected) in product volume of -0.049 gph (gallons per hour).

Based on the results obtained from the precision tank tests, this system does not appear to be losing product and has passed the leak detection integrity assessment.

DIESEL-WEST SYSTEM - (8,000 Gallons): Appendix B

A full system's precision test was conducted on this system at an elevation of 115 inches (20 inches above tank top). This UST system has a **suction type product delivery system**; the precision tank test conducted includes all of the system below fluid level. The precision test results (#0534) indicated a net final change (temperature corrected) in product volume of -0.0481 gph (gallons per hour).

Based on the results obtained from the precision tank tests, this system does not appear to be losing product and has passed the leak detection integrity assessment.

Underground Storage Tank Testing

Milky Way

Project #48-1467-39

We trust that this report satisfies your leak detection requirements. Enclosed are two copies of this report. Please retain one (1) copy for your files and another at the tank site facility as proof that these systems have been tested.

The precision tank tests were conducted in accordance with the technical requirements outlined in NFPA Publication #329 and EPA Publication 40 CFR Sub-part D -280.43 (c) and 280.44 (b). If you have additional questions or have comments concerning this report, please call (801) 974-5544 or 1-800-533-5709. We would be happy to assist you in any way possible.

Respectfully submitted,

Paul Krumm
Supervisor Testing Services

CERTIFICATE OF PRECISION LEAK TEST

CBC ENVIRO ENGINEERING CERTIFIES THE FOLLOWING:

DATE: 5-11-92

CERTIFIED TESTER: RJB

IBEX #:9111

	<u>SYSTEM(s)</u>	<u>TANK</u>	<u>LINES</u>	<u>PROD/LINE</u>
1.	8K-DIESEL-EAST	PASS	PASS	PASS
2.	8K-DIESEL-WEST	PASS	PASS	PASS
3.				
4.				
5.				
6.				
7.				
8.				

**ANY FAILURE LISTED MAY REQUIRE NOTIFICATION OF THE PROPER
LOCAL REGULATORY AGENCIES**

CONDITIONS OF CERTIFICATION

Because of the uncertainty of variable precision tank test conditions and the necessity of relying on facts and supporting services furnished by others, CBC Enviro Engineering is unable to guarantee the accuracy of any test data or chart interpretation or any other data furnished by CBC Enviro Engineering. CBC Enviro Engineering personnel will use their best efforts in gathering such information and their best judgment in interpreting it, but the Customer agrees that CBC Enviro engineering shall not be liable and the Customer shall indemnify CBC Enviro Engineering against any damages arising from the use of such information. CBC Enviro engineering will not be responsible for accidental or intentional interception of such data by others.

Both the Customer and CBC Enviro Engineering acknowledge that the subject equipment of this test includes extremely complex measurement techniques which to a large extent rely on generally accepted statistical computations. Each measurement made by the subject equipment, therefore, is made in accordance with accepted statistical averaging techniques which do not compensate for each statistical variable. CBC Enviro Engineering, therefore, makes no warranties other than the operability of the subject equipment, such warranty being limited to the cost of replacement or repair of the subject equipment.



PRECISION TANK & LINE TEST RESULTS

for

MILKY WAY
1602 RUDKIN ROAD
YAKIMA, WA 98901

DATE: 05/11/92
JOB #: 48-1467-39
PHONE: (509) 575-0039
STATE #:
TECHNICIAN: RJB
WATER TABLE: (+/-) 15 Feet
CONTACT: Mr. Don Guthrie
DATE; TIME (system was filled): 05/10/92 • 12 hr (+)
UNIT #: 9020
COUNTY: Yakima

TANK#	TANK SIZE	PRODUCT	TANK	FILL/VENT LINES	PRODUCT LINES	INCHES OF WATER IN TANK	PUMP TYPE	TANK MATERIAL
#1	8K	DIESEL-E	PASS	PASS	PASS	0"	SCT	SWS
#2	8K	DIESEL-W	PASS	PASS	PASS	0"	SCT	SWS

HYDROSTATIC LINE TEST RESULTS

PRODUCT	TEST RESULTS (GPH)	STATUS

AUTOMATIC LINE LEAK DETECTOR TEST RESULTS

PRODUCT	RESILIENCY (ml.)	OPENING TIME (SECONDS)	LEAK RATE (ml/min)	F.E. Holding Pressure	METERING Pressure	STATUS

ADDITIONAL INFORMATION: These are suction systems - all lines are flooded and included. The two tanks are manifolded together.


LEGEND

TRB = submersible turbine pump
SCT = suction pump
SWS = single walled steel tank
FRP = fiberglass reinforced plastic
PLT = product line test result
GPH = gallons per hour

SITE LOG	TIME
Arrive at site.....	06:00
Set up equipment.....	06:10
Bled product line.....	06:15
Bled vent/vapor lines..	n/a
Bled pumps.....	n/a
Start test.....	06:30
End test.....	08:45
Leave site.....	09:30


Technician Signature: Roger J. Brown State Certification #: W001278

The precision tank and hydrostatic line tests conducted on the above systems meet or exceed the requirements of the National Fire Protection Association (NFPA), Publication #329 and the technical standards mandated by the Environmental Protection Association (EPA), Publication 40 CFR Part 280.43 (c) and 280.44 (b). The mechanical line leak detector tests meet or exceed the requirements of the EPA regulation 40 CFR, Part 280.44 (a). The maximum allowable net rate of change for a "passing" system is (\leq) 0.05 GPH. No additional warranties are expressed or implied.




Site Layout For : MILKY WAY: 1602 RUDKIN RD., YAKIMA, WA


MO.0534 Temp. = 0.0597 Gph.



.25 Level = 0.0116 Gph.



Net Change Gal.




Scale 1 = .01 gal. 290

Tank No. 2
DSL-WEST TANK

Test Time 06:28:57
Length (Min.) 78.5
Level Precision.00016
Temp. Precision.00077
MILKY WAY: YAKIMA, WA.

NET CHANGE = -.0481 Gph.

Test Level -- -- --



APPENDIX B



WHITE SHIELD, INC.



P.O. BOX 477 • GRANDVIEW, WA 98930 • (509) 882-1144
FAX (509) 882-4566

January 11, 1995

Mr. Greg Huylar
Russell Crane Service Inc.
505 Locust Avenue
Yakima, WA 98902

Re: UST Closure Site Assessment Report - 1618 Rudkin Road, Yakima, Washington

Dear Mr. Huylar:

Enclosed, please find two copies of an Underground Storage Tank Closure Site Assessment Report for the above referenced site, as required by the Washington State Department of Ecology (WSDOE). Based on the data and findings reported herein, further cleanup action is required for the remediation of this site. WSI recommends insitu remediation of the remaining contaminants since any further removal of the contaminated soil material from the area would jeopardize the structural integrity of the adjacent building foundations.

The Washington State Department of Ecology (WSDOE) requires that you retain this report for a minimum of ten years. We recommend that you retain it indefinitely. The WSDOE also requires a copy of the Underground Storage Tank Permanent Closure/Site Assessment Checklist to be submitted to the WSDOE Olympia office, we have submitted the original form to the WSDOE and are including a copy in this report, for your records.

Since Russell Crane Service provided the decommissioning service at this site, please ensure that a copy of the Underground Storage Tank Permanent Closure/Site Assessment Notice is sent to the WSDOE Olympia office.

We appreciate the opportunity to provide you with technical assistance for your underground storage tank closure. Please call us at (509) 882-1144 should you have any questions or need any additional information.

Respectfully Yours,
WHITE SHIELD, INC.

Terry Miller
Terry Miller
Project Manager

William J. Goggin
William J. Goggin, P.E.
Chief Design Engineer


cc: Department of Ecology, Olympia Headquarters
Department of Ecology, Central Regional Office
Mr. Don Wurst, 1618 Rudkin Road, Yakima, WA

UST CLOSURE SITE ASSESSMENT REPORT

Site Location
1618 Rudkin Road
Yakima, Washington

Prepared For:
Mr. Greg Huylar
Russell Crane Service Inc.
505 Locust Avenue
Yakima, WA 98902

JANUARY, 1995



WHITE SHIELD

INC.

P.O. BOX 477, 801 GRANDRIDGE ROAD, GRANDVIEW, WA 98930
TELEPHONE: (509) 882-1144 VOICE (509) 882-4566 FAX

EXECUTIVE SUMMARY

White Shield, Inc. (WSI) provided site assessment services upon removal of two regulated Underground Storage Tanks (USTs), measuring approximately 8 feet x 8 feet 4.5 feet in height (square) with an estimated capacity of 500 gallons each. The tanks were used for storing used motor oil generated during truck servicing operations. The tanks were located at 1618 Rudkin Road, Yakima, Washington.

The used motor oil was conveyed to the tanks via PVC piping. The inlets and outlets were located adjacent to the south wall of a metal building. The USTs and piping were in good condition at the time of removal. A close inspection of the tanks revealed signs of incipient corrosion and pitting but no holes were observed.

Laboratory analysis of soil samples revealed petroleum contamination exceeding the MTCA Method A Cleanup Levels in the soil taken from the bottom of two separate excavations. The analytical laboratory results indicated contamination below the MTCA cleanup level on the walls of the excavations.

TABLE OF CONTENTS

1.0	Introduction	1
1.1	Purpose	1
1.2	Scope of Work	1
2.0	Background Information	1
2.1	Site Location	1
2.2	Site Description and History	3
2.3	Soils Description	3
3.0	Field Activities	5
3.1	General Investigative Methods	5
3.1.2	Soil Sampling	5
3.2	Tank Removals	6
3.3	Tank Inspection	6
3.4	Initial Sampling/Site Assessment	6
4.0	Soil Analysis Summary	7
4.1	Petroleum Analysis	7
5.0	Ground Water & Well Logs	7
6.0	End Use of Soil	10
7.0	Conclusion	10
8.0	Limitations	10

LIST OF FIGURES

FIGURE 1 - SITE LOCATION MAP	2
FIGURE 2 - SITE PLAN	4
FIGURE 3 - SAMPLING PLAN	8

LIST OF TABLES

TABLE I: SOIL FIELD SCREENING & LABORATORY ANALYTICAL RESULTS ..	9
--	---

LIST OF APPENDICES

Appendix A: Field Sampling Log	
Appendix B: Laboratory Reports and Chain of Custody	
Appendix C: Method A Cleanup Levels as established by the <u>Model Toxics Control Act, Chapter 173-340 WAC</u>	
Appendix D: Underground Storage Tank Site Check/Site Assessment Checklist	
Appendix E: Underground Storage Tank Temporary/Permanent Closure and Site Assessment Notice	
Appendix F: Table V. End Use Criteria for Petroleum Contaminated Soils	
Appendix G: Department of Ecology Well Logs	
Appendix H: Site Photographs	

1.0 Introduction

1.1 Purpose

This report describes findings and actions taken for work associated with the removal of two regulated Underground Storage Tanks (USTs), measuring approximately 8 feet x 8 feet x 4.5 feet, with a capacity of 500 gallons each. The tanks were located at 1618 Rudkin Road, Yakima, Washington. The Washington State Department of Ecology (WSDOE) requires a report for the closure of a regulated Underground Storage Tank (UST) site.

1.2 Scope of Work

White Shield, Inc. (WSI) provided site assessment services for the removal of two 500 gallon used motor oil USTs. Russell Crane Services Inc. provided the decommissioning services and removed the USTs from the site for cleaning and disposal. On Site Environmental, Inc. (OnSite), Redmond, Washington, provided the laboratory analytical services. Refer to Appendix B, Laboratory report and chain of custody and Table I, Soil Field Screening and Laboratory Analytical Results.

The initial site assessment services provided by WSI included 7 Thin Layer Chromatography (TLC) field screening tests for semi-volatile components. A total of 13 soil samples were also sent to the laboratory for analysis.

This report completes the site assessment services provided by White Shield, Inc.

2.0 Background Information

2.1 Site Location

The site is located at 1618 Rudkin Road, Yakima Washington. It is approximately 1.5 miles north of Valley Mall Boulevard/Rudkin Road intersection. The site is described as the tax parcel # 191329-43440 located in the SE 1/4, Section 29, T13N, R19E, W.M. Refer to Figure 1, Site Location Map.




FIGURE 1 - SITE LOCATION MAP

2.2 Site Description and History

The main structure on the subject site is a metal frame building which is utilized for truck servicing. The east half of the metal building is occupied by Better All Auto Sales and Transport and the west half is rented by Yakima Truck Service. The two underground storage tanks, with a capacity of 500 gallons each, were installed eight years ago at the southwest and the southeast ends of the metal building. The tank at the southeast end was used by Better All Auto Sales and Transport and the tank at the southwest end was used by Yakima Transport Service. The subject site is also occupied by an above ground storage tank, a truck wash and two diesel fuel underground storage tanks. Refer to Figure 2, Site Plan and Figure 3, Sampling Plan.

The USTs that were removed on December 14, 1994, are described as follows:

Tank Code	WSDOE UST Site number	Contents	Volume (gallons)
3	004274	used oil/w	500
4	004274	used oil/w	500

An interview with the site owner revealed that there were no underground tanks at the site prior to the installation of the two waste oil tanks. Currently, there are two diesel fuel underground storage tanks located to the north of the truck wash and a diesel fuel aboveground storage tank to the east. Refer to Figure 2, Site Plan.

2.3 Soils Description

The soil appeared to be predominantly inorganic silts, very fine sands, rock flour, silty or clayey fine sands (ML).



WHITE SHIELD

INC.

P.O. BOX 477, 801 GRANDRIDGE ROAD, GRANDVIEW, WA 98930
TELEPHONE: (509) 882-1144 VOICE (509) 882-4566 FAX

JOB _____

SHEET NO. _____

OF _____

CALCULATED BY _____

DATE _____

CHECKED BY _____

DATE

12/27/94

SCALE

NTS

NORTH




FIGURE 2 - SITE PLAN

3.0 Field Activities

3.1 General Investigative Methods

We visually inspected the USTs, the soil and the fill. We also used field screening, analytical laboratory analyses and interviews for data. The methods and general conclusions are discussed below.

3.1.1 Field Screening

For field analysis of semi-volatile (diesel) and non-volatile compounds (motor oil), WSI uses Thin Layer Chromatography (TLC) for qualitative and quantitative analysis. This analytical technique utilizes the principle of chromatography to separate individual components for comparison to known standards.

TLC is classified as a solid-liquid chromatographic system, meaning there are two phases through which an extract of the sample is passed; a solid phase (silica gel) and a liquid phase (a solvent such as hexane).

The solid phase is stationary and is coated on a glass plate. During the chromatography process, the liquid phase carries the sample through the solid phase. The solvent moves at a fairly constant rate through the solid phase. However, the compound in the sample (analyte) are partitioned by a relative attractiveness of the analyte between the solid phase and the liquid phase. Analytes strongly attracted to the silica will remain on the silica longer and move more slowly than analytes that are not as strongly attracted to the silica. When the chromatography is stopped, the distance the analyte has moved relative to the distance the solvent has moved is used to identify the compound. When the plate is viewed under ultraviolet light, the analytes can be seen and compared to standards of known concentration for quantitative analysis.

3.1.2 Soil Sampling

The Sampling Plan (refer to Figure 3) and the attached Field Sampling Log (Appendix A) show the location, depth and types of samples taken. In general, sample collection and control followed the following protocol:

1. Select a laboratory certified clean sample jar for sample collection.
2. Using clean latex gloves and clean sampling utensils (Alconox Detergent, chlorine solution, tap water rinse and distilled water rinse cycle) tightly pack the soil sample in the sample jar (8 oz.) to the top of the jar to prevent any airspace. Collect co-located samples using the same procedure.
3. Label the jar with the soil sample number, the type of laboratory test required, the date, name of site and sampler. The sample is then entered on the chain of custody form.
4. Cool the sample in wet ice to approximately 4 degrees centigrade.
5. Repack the samples for shipment to the laboratory in blue ice and a cooler.
6. Relinquish sample to courier for shipment to the laboratory.

3.2 Tank Removals

Hari Sharma, site assessor registered with the Washington State Department of Ecology Underground Storage Tank Program, performed the Site Assessment on December 14, 1994. The top of USTs had been exposed and the used motor oil transmission pipelines had been disconnected prior to the arrival of WSI personnel. All pipelines associated with the tanks have been removed.

Each excavation measured approximately 10 feet x 10 feet x 7 feet deep. The soil in the excavations appeared clean. The TLC field screening conducted on seven soil samples taken from the excavations revealed no apparent contamination.

3.3 Tank Inspection

Soil and scale attached to the tank was removed to completely expose the tanks for inspection. The tanks showed signs of incipient corrosion and pitting but no holes were observed. Refer to Photographs 4 and 5 for the condition of the tanks.

3.4 Initial Sampling/Site Assessment

On December 14, 1994, a total of 13 soil samples were collected from the excavations and the soil stockpile for TLC field screening and laboratory analysis. The TLC field screening of the samples RUC-0294-101, 102, 104, 105 from the excavation #1 and samples RUC-0294-202, 204, and 205 from the excavation #2 revealed no apparent contamination.

Samples RUC-0294-101 through 104 were collected from the east, south, west and north walls of the excavation #1 at a depth of approximately 3.5 feet. Sample RUC-0294-105 was collected from the bottom of the excavation #1 at a depth of 7 feet. The samples RUC-0294-106 through 108 were collected from the soil stockpile. The stockpile consists of approximately 20 yards of soil removed from the two excavations. The samples RUC-0294-201 through 205 were collected from the excavation #2. The samples RUC-0294-201 through 204 were collected at a depth of approximately 3.5 feet from the east, south, west and the north walls respectively. Sample RUC-0294-205 was collected from the bottom of excavation # 2 at a depth of 7 feet. Refer to Figure 3, Site Sampling Plan.

A total of 13 soil samples were sent to OnSite for laboratory analyses. The laboratory results revealed contamination levels below the MTCA cleanup level on the walls of both excavations. However, the bottom sample RUC-0294-105 from excavation #1 and the bottom sample RUC-0294-205 from the excavation #2 had total petroleum hydrocarbon contamination of 440 ppm and 310 ppm respectively. The two bottom samples were taken from directly below the waste oil inlets and the discharge outlets of the tanks which were located adjacent to the south wall of the metal building. Refer to Figure 3, Sampling Plan for bottom sample locations. Any further removal of the material from the bottom of the excavations will jeopardize the structural integrity of the building foundation. WSI recommends insitu bioremediation of the site to meet MTCA cleanup requirements. Refer to Table I and Appendix B for analytical laboratory results.

4.0 Soil Analysis Summary

4.1 Petroleum Analysis

The field screening and the laboratory analytical results are summarized in Table I. The Field Sampling Log is included as Appendix A, and the laboratory analytical report, as Appendix B.

5.0 Ground Water & Well Logs

Groundwater was not intersected in this excavation. Washington State Department of Ecology well logs are presented in Appendix G.



WHITE SHIELD

INC.

P.O. BOX 477, 801 GRANDRIDGE ROAD, GRANDVIEW, WA 98930
TELEPHONE: (509) 882-1144 VOICE (509) 882-4566 FAX

JOB _____

SHEET NO. _____ OF _____

CALCULATED BY _____ DATE 12/27/94

CHECKED BY _____ DATE _____

SCALE NTS


VIOLA AVENUE

NORTH


YAKIMA TRUCK
SERVICE

BETTER ALL AUTO
SALES AND TRANSPORT

RUDKIN
ROAD



EXCAVATION #2



EXCAVATION #1

FIGURE 3 - SAMPLING PLAN

TABLE I: SOIL FIELD SCREENING & LABORATORY ANALYTICAL RESULTS

LOCATION AND DEPTH	SAMPLE #	DATE	TLC ppm	418.1 Modified ppm
East wall/South wall 3.5 feet	RUC-0294-101/102	12/14/94	nd	73
West wall/North wall 3.5 feet	RUC-0294-103/104	12/14/94	nd*	nd
Bottom 7 feet	RUC-0294-105	12/14/94	nd	440
East wall/South wall 3.5 feet	RUC-0294-201/202	12/14/94	nd*	nd
West wall/North wall 3.5 feet	RUC-0294-203/204	12/14/94	nd*	nd
Bottom	RUC-0294-205	12/14/94	nd	310
Stockpile	RUC-0294-106 sp	12/14/94	nt	14,000
Stockpile	RUC-0294-107 sp	12/14/94	nt	360
Stockpile	RUC-0294-108 sp	12/14/94	nt	310

nt = Not Tested
nd = Not Detected

* Samples RUC-0294-103, RUC-0294-201 and 203 were not field screened.

6.0 End Use of Soil

Analytical laboratory results of the stockpile samples revealed evidence of petroleum contamination in excess of the Method A Cleanup Levels as established by the Model Toxics Control Act (WAC 173-340-720). The stockpile consists of Class 3 and Class 4 Soils and should be either properly disposed in compliance with WSDOE regulations or remediated on site to meet the MTCA cleanup requirements.

7.0 Conclusion

Analytical laboratory results revealed petroleum contamination in excess of the MTCA Cleanup Levels remaining in the bottom of the two excavations. Since further removal of the contaminated soil will jeopardize the structural integrity of the building foundation, WSI recommends insitu bioremediation of the site to meet the Method A Cleanup Levels as established by the Model Toxics Control Act (WAC 173-340-720).

8.0 Limitations

In performing our professional services, WSI uses a degree of care ordinarily exercised under similar circumstances by members of our profession. No warranty, expressed or implied, is made or intended. Our conclusions and recommendations, developed from our field and laboratory investigation reported herein, are based upon this firm's understanding of the project and are in concurrence with generally accepted practice.

APPENDIX A

DATE: 12/14/94.

PROJECT: RUSSEL CRANE

PROJECT# RUC-0294

CLIENT'S REP: DON WURST.

WEATHER: SNOWING.

LOCATION DATA: 505 LOCUST AVE, YAKIMA WASHINGTON

TAX PARCEL # 191323-32414

SW 1/4, SECTION 23, T13N, R19E, Wm.

OWNER: DON WURST.

- SITE VICINITY MAP
- SITE SKETCH.

HISTORY:

DATE OF INSTALLATION — 8 YEARS.

DATES OF USE AND CURRENT STATUS — waste oil

NUMBER OF TANKS — 2

LOCATION — 505 LOCUST AVENUE.

CAPACITY — 500 GALLON

Dimension

Age

Material of Construction of existing UST SYSTEM — steel

FILL PIPES, — PVC.

VENT PIPING — steel

PUMPS — none — pumped by dis

VALVES

DISTRIBUTION PIPING

Flex Connectors

• NUMBER AND LOCATION OF ANY PREVIOUSLY REMOVED USTS

• TYPES OF SUBSTANCES STORED — USED OIL

• DEPTH, WIDTH AND TYPE OF BEDDING / BACKFILL MATERIALS

004274 — SITE ID

OWNER — 001934

H. Sharm

9:00 Am. LEFT OFFICE. 12/14/98
 9:45 ARRIVED AT SITE AND ASKED GREG HUYLAR WHETHER
 12:45 DOE HAS BEEN GIVEN 30 DAY NOTICE OR NOT.
 DOE HAD NOT BEEN NOTIFIED - TALKED TO DON WURST
 AND LET HIM KNOW ABOUT THAT.
 - CALLED Jim CHULOS AND John weiffeld of WSDOE
 CENTRAL Regional Office and waited for
 30 minutes for them to return our calls - No
 response.
 - went to DOE OFFICE. Talked with John
 weiffeld. HE Accompanied us to the site
 and waived 30 day notice after I
 gave a letter to him.

12:45 Sketched site, took photographs of
 to 1:45 Vicinity; interviewed owner and other
 operator.
 - excavated minor amount of visibly
 contaminated soil and stockpiled it to
 the South EAST CORNER OF THE PROPERTY
 (REFER TO SKETCH).
 1:45 PULLED OUT TANKS - APPEARED TO BE
 IN FAIRLY GOOD CONDITION - CORROSION AND
 PITTING HAD STARTED. HOWEVER NO HOLES
 WERE PRESENT. THE MINOR CONTAMINATION
 AROUND THE FILL AND DISCHARGE PIPE.

1:45 to 4:45 CONDUCTED 7 TLC TESTS

TLC	RESULT
104 102	ND
105	ND
101	ND
204	ND
205	ND
202	ND
104	ND

Collected 13 Samples for Laboratory Analysis

sample	Location	DEPTH
101	E. Wall	3.5'
102	S. Wall	3.5'

Thurman

Used oil — Truck

P. 49

12/14/98

RUDKIM 120

WHITE GMC
VOLVO

24' Floor
Drilling

YAKIMA
TRUCK
SERVIE.
AND
BETTER
RCL
AUTO SALES
AND TRAMPET

BAIT

500 Gallon

YTS

500 Gallon


Waste
oil Tank

Thermoc
KING

PVC - fill PIPE
Steel - Vent

RECTANGULAR TANKS

8' X 8' X 4.5'



SETBACK = 10'

500 Gallon
Tank

YTS

SAMPLE	LOCATION	DEPTH	12/14/94	Y. 50
103	W. WALL	3.5'		
104	N. WALL	3.5'		
105	bottom	7'		
106 SP	Stockpile			
107 SP	Stockpile			
108 SP	Stockpile			
201	E. WALL	3.5'		
202	S. WALL	3.5'		
203	W. WALL	3.5'		
204	N. WALL	3.5'		
205	Bottom	7'		

Harishama



**OnSite
Environmental Inc.**

Analytical Testing and Mobile Laboratory Services

December 19, 1994
Lab Traveler #:12-046

Terry Miller
White Shield, Inc.
P.O. Box 477
Grandview, WA 98930

Dear Terry:

Enclosed are the results of the analyses of samples submitted on December 17, 1994 from Project RUC-0294.

We appreciate this opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to call me.

Sincerely,

Karl P. Homyik
Project Chemist

Enclosures

Date of Report: December 19, 1994
Samples Submitted: December 17, 1994
Lab Traveler: 12-046
Project: RUC-0294

EPA 418.1 Modified

Date Extracted: 12-19-94
Date Analyzed: 12-19-94

Matrix: Soil
Units: mg/Kg (ppm)

Client ID	Dilution Factor	Total Petroleum Hydrocarbons
RUC-0294-101/RUC-0294-102 Composite	2	73
RUC-0294-103/RUC-0294-104 Composite	2	<20
RUC-0294-105	2	440
RUC-0294-106sp	40	14000
RUC-0294-107sp	2	360
RUC-0294-108sp	2	310
RUC-0294-201/RUC-0294-202 Composite	2	<20
RUC-0294-203/RUC-0294-204 Composite	2	<20
RUC-0294-205	2	310

Date of Report: December 19, 1994
Samples Submitted: December 17, 1994
Lab Traveler: 12-046
Project: RUC-0294

**EPA 418.1 Modified
QUALITY ASSURANCE**

Date Extracted: 12-19-94
Date Analyzed: 12-19-94

Matrix: Soil
Units: mg/Kg (ppm)

	Dilution Factor	Total Petroleum Hydrocarbons
Method Blank	2	<20
Sample: 12-046-13	2	305
Duplicate	2	359
RPD		16%

COMPANY WHITE SHIELD, INC.

PROJECT # RUC-0294

PROJECT NAME RUSSEL CRANE

MANAGER ARI SHARMA

PM Terry Miller (KAT)



**OnSite
Environmental Inc.**

14924 NE 31st CIRCLE, REDMOND, WA 98052
PHONE (206) 883-3881 FAX (206) 885-4503

REQUESTED
TURNAROUND?

Normal

TRAVELER #
12-046

WTPH-HCID

WTPH-G/BTEX

WTPH-G

WTPH-D

WTPH-418.1

418.1 MODIFIED

Dash	Sample Number	Date Sampled	Time Sampled	Type	# Jars	Analysis Required					Comments
1	RUC-0294-101 Z	12/14/94	11:43:30 PM	Soil	1						3 => Composite
2	-102 Z	"	"		1						
3	-103 Z	"	"		1						
4	-104 Z	"	"		1						
5	-105	"	"		1						
6	-106 SP	"	"		1						
7	-107 SP	"	"		1						
8	-108 SP	"	"		1						
9	-201 Z	"	"		1						
10	-202 Z	"	"		1						
11	-203 Z	"	"		1						
12	-204 Z	"	"		1						
13	-205	"	"		1						

Submitted HANISH ARMA

Firm

Submitted

Firm

Date 12/16/94

Time

Received by [Signature]

Firm OnSite Environmental

Received by

Firm

Date 12/17/94

Time 1:30 pm

APPENDIX C

Table 2
Method A Cleanup Levels – Soil^a

Hazardous Substance	CAS Number	Cleanup Level
Arsenic		
Benzene	7440-38-2	20.0 mg/kg ^b
Cadmium	71-43-2	0.5 mg/kg ^c
Chromium	7440-43-9	2.0 mg/kg ^d
DDT	7440-47-3	100.0 mg/kg ^e
Ethylbenzene	50-29-3	1.0 mg/kg ^f
Ethylene dibromide	100-41-4	20.0 mg/kg ^g
Lead	106-93-4	0.001 mg/kg ^h
Lindane	7439-92-1	250.0 mg/kg ⁱ
Methylene chloride	58-89-9	1.0 mg/kg ^j
Mercury (inorganic)	75-09-2	0.5 mg/kg ^k
PAHs (carcinogenic)	7439-97-6	1.0 mg/kg ^l
PCB Mixtures		1.0 mg/kg ^m
Tetrachloroethylene		1.0 mg/kg ⁿ
Toluene	127-18-4	0.5 mg/kg ^o
TPH (gasoline)	108-88-3	40.0 mg/kg ^p
TPH (diesel)		100.0 mg/kg ^q
TPH (other)		200.0 mg/kg ^r
1,1,1 Trichloroethane	71-55-6	200.0 mg/kg ^s
Trichloroethylene	79-01-5	20.0 mg/kg ^t
Xylenes	1330-20-7	0.5 mg/kg ^u
		20.0 mg/kg ^v

^a Caution on misusing method A tables. Method A tables have been developed for specific purposes. They are intended to provide conservative cleanup levels for sites undergoing routine cleanup actions or those sites with relatively few hazardous substances. The tables may not be appropriate for defining cleanup levels at other sites. For these reasons, the values in these tables should not automatically be used to define cleanup levels that must be met for financial, real estate, insurance coverage or placement, or similar transactions or purposes. Exceedances of the values in these tables do not necessarily trigger requirements for cleanup action under this chapter.

^b Arsenic. Cleanup level based on background concentrations in the state of Washington.

^c Benzene. Cleanup level based on protection of ground water.

^d Cadmium. Cleanup level based on plant protection.

^e Chromium. Cleanup level based on health risks associated with inhalation of resuspended dust.

^f DDT. Cleanup level based on concentrations derived using the procedures in subsection (3)(a)(iii)(B) of this section.


^g Ethylbenzene. Cleanup level based on protection of ground water.

^h Ethylene dibromide. Cleanup level based on protection of ground water.

ⁱ Lead. Cleanup level based on preventing unacceptable blood lead levels.

- j Lindane. Cleanup level based on concentration derived using the procedures in subsection (3)(a)(iii)(B) of this section.
- k Methylene chloride. Cleanup level based on protection of ground water.
- l Mercury. Cleanup level based on protection of ground water.
- m PAHs (carcinogenic). Cleanup level based on concentration derived using the procedures in subsection (3)(a)(iii)(B) of this section.
- n PCB Mixtures. Cleanup level based on concentration derived using the procedures in subsection (3)(a)(iii)(B) of this section.
- o Tetrachloroethylene. Cleanup level based on protection of ground water.
- p Toluene. Cleanup level based on protection of ground water.
- q Total Petroleum Hydrocarbons (gasoline). Cleanup level based on protection of ground water.
- r Total Petroleum Hydrocarbons (diesel). Cleanup level based on protection of ground water.
- s Total Petroleum Hydrocarbons (other). Cleanup level based on protection of ground water.
- t 1,1,1 Trichloroethane. Cleanup level based on protection of ground water.
- u Trichloroethylene. Cleanup level based on protection of ground water.
- v Xylenes. Cleanup level based on protection of ground water.

APPENDIX D



UNDERGROUND STORAGE TANK Site Check/Site Assessment Checklist

For Office Use Only

Owner # _____

Site # _____

INSTRUCTIONS:

When a release has not been confirmed and reported, this Site Check/Site Assessment Checklist must be completed and signed by a person registered with the Department of Ecology. The results of the site check or site assessment must be included with this checklist. This form must be submitted to Ecology at the address shown below within 30 days after completion of the site check/site assessment.

SITE INFORMATION: Include the Ecology site ID number if the tanks are registered with Ecology. This number may be found on the tank owner's invoice or tank permit.

TANK INFORMATION: Please list all the tanks for which the site check and site assessment is being conducted. Use the tank ID number if available, and indicate tank capacity and substance stored.

REASON FOR CONDUCTING SITE CHECK/SITE ASSESSMENT: Please check the appropriate item.

CHECKLIST: Please initial each item in the appropriate box.

SITE ASSESSOR INFORMATION: This form must be signed by the registered site assessor who is responsible for conducting the site check/site assessment.

Underground Storage Tank Section
Department of Ecology
P. O. Box 47655
Olympia, WA 98504-7655

SITE INFORMATION

Site ID Number (on invoice or available from Ecology if the tanks are registered): 004274

Site/Business Name: BETTER ALL AUTO SALES AND TRANSPORT & YAKIMA TRANSPORT SERVICE.

Site Address: 1618 RUDKIN ROAD Telephone: (509) 575-1830

Street

YAKIMA

City

WA

State

98901

ZIP Code

TANK INFORMATION

Tank ID No.

Tank Capacity

Substance Stored

3

500

USED MOTOR OIL

4

500

USED MOTOR OIL

REASON FOR CONDUCTING SITE CHECK/SITE ASSESSMENT

Check one:

- ☐ Investigate suspected release due to on-site environmental contamination.
- ☐ Investigate suspected release due to off-site environmental contamination.
- ☐ Extend temporary closure of UST system for more than 12 months.
- ☐ UST system undergoing change-in-service.
- ☐ UST system permanently closed-in-place.
- ☒ UST system permanently closed with tank removed.
- ☐ Abandoned tank containing product.
- ☐ Required by Ecology or delegated agency for UST system closed before 12/22/88.
- ☐ Other (describe): _____

CHECKLIST


Each item of the following checklist shall be initialed by the person registered with the Department of Ecology whose signature appears below.

	YES	NO
1. The location of the UST site is shown on the vicinity map.	HS	
2. A brief summary of information obtained during the site inspection is provided. (see Section 3.2 in the Site Assessment Guidance)	HS	
3. A summary of UST system data is provided. (see Section 3.1)	HS	
4. The soils characteristics at the UST site are described. (see Section 5.2)	HS	
5. Is there apparent groundwater in the tank excavation?		HS
6. A brief description of the surrounding land is provided. (see Section 3.1)	HS	
7. Information has been provided indicating the number and types of samples collected, methods used to collect and analyze the samples, and the name and address of the laboratory used to perform the analyses.	HS	
8. A sketch or sketches showing the following items is provided:		
- location and ID number for all field samples collected	HS	
- groundwater samples distinguished from soil samples (if applicable)	NA	
- samples collected from stockpiled excavated soil	HS	
- tank and piping locations and limits of excavation pit	HS	
- adjacent structures and streets	HS	
- approximate locations of any on-site and nearby utilities	HS	
9. If sampling procedures different from those specified in the guidance were used, has justification for using these alternative sampling procedures been provided? (see Section 3.4)	N/A	
10. A table is provided showing laboratory results for each sample collected including: sample ID number, constituents analyzed for and corresponding concentration, analytical method and detection limit for that method.	HS	
11. Any factors that may have compromised the quality of the data or validity of the results are described.	HS	
12. The results of this site check/site assessment indicate that a confirmed release of regulated substance has occurred.	HS	

SITE ASSESSOR INFORMATION

<u>HARI SHARMA</u> PERSON REGISTERED WITH ECOLOGY		<u>WHITE SHIELD, INC.</u> FIRM AFFILIATED WITH	
BUSINESS ADDRESS: <u>801 GRANDRIDGE ROAD</u>		TELEPHONE: <u>209, 882-1144</u>	
<u>GRANDVIEW</u> CITY	<u>WA</u> STATE	<u>98930</u> ZIP+CODE	
I hereby certify that I have been in responsible charge of performing the site check/site assessment described above. Persons submitting false information are subject to penalties under Chapter 173-360 WAC.			
<u>12/29/94</u> Date		<u>Hari Sharma</u> Signature of Person Registered with Ecology	

APPENDIX E



**UNDERGROUND STORAGE TANK
TEMPORARY/PERMANENT CLOSURE
and SITE ASSESSMENT NOTICE**

See back of form for instructions

Please ☒ the appropriate box(es)

Please type or print information

☐ Temporary Tank Closure ☒ Permanent Tank Closure ☐ Change-In-Service ☐ Site Assessment/ Site Check

For Office Use Only

Owner # _____

Site # _____

SITE INFORMATION:

Site ID Number (on invoice or available from Ecology if the tanks are registered): 004274
Site/Business Name: YAKIMA TRANSPORT SERVICE & BETTER ALL AUTO SALES AND TRANSPORT
Site Address: 1618 RUDKIN ROAD Telephone: (509) 575-1830
YAKIMA WA 98901
City State ZIP Code

TANK INFORMATION:

Tank ID	Closure Date	Tank Capacity	Substance Stored
<u>3</u>	<u>12/14/94</u>	<u>500 Gallon</u>	<u>MOTOR OIL</u>
<u>4</u>	<u>12/14/94</u>	<u>500 Gallon</u>	<u>MOTOR OIL</u>

**CONTAMINATION
PRESENT AT THE
TIME OF CLOSURE**

☐ Yes ☐ No



Check unknown if no obvious contamination was observed and sample results have not yet been received from analytical lab.

UST SYSTEM OWNER/OPERATOR:

UST Owner/Operator: Donald L. Wierst
Owners Signature: Donald L. Wierst Telephone: (509) 965-2694
Address: 1618 RUDKIN ROAD
YAKIMA WA 98901
City State ZIP Code

TANK CLOSURE/CHANGE-IN-SERVICE PERFORMED BY:

Service Provider: RUSSELL CRANE SERVICE, INC. License Number: _____
Licensed Supervisor: _____ Decommissioning License Number: _____
Supervisors Signature: _____
Address: 505 LOCUST AVENUE
YAKIMA WA 98901
City State ZIP Code
Telephone: (____) _____

SITE CHECK/SITE ASSESSMENT CONDUCTED BY:

Name of Registered Site Assessor: HARI SHARMA
Telephone: (509) 882-1144
Address: 801 GRANDRIDGE ROAD
GRANDVIEW WA 98930
City State ZIP Code

PLEASE READ CAREFULLY

INSTRUCTIONS

This form is to be completed by the Tank Owner and submitted to Ecology within 30 days of tank closure.

Mark the appropriate box(es) for temporary tank closure, permanent tank closure, change-in-service, or site assessment.

Permanent Closure and Change-in-Service require a site assessment be performed.

SITE INFORMATION:

Fill in the site information. Be sure to include the Ecology site ID number. This number may be found on the invoice or permit. Include a contact telephone number so any problems may be resolved quickly.

TANK INFORMATION:

List the tanks that were closed. Please use tank ID numbers and indicate the date of permanent closure. Be sure to attach your Underground Storage Tank Permits for any tanks that are now closed.

UST SYSTEM OWNER/OPERATOR:

Please fill in the owner's/operator's name, address, and telephone number. Be sure to sign this form.

TANK CLOSURE/CHANGE-IN-SERVICE PERFORMED BY:

List the closure company. Companies that provide UST services MUST be licensed by Ecology. Ask to see their supervisor's license. Make sure the licensed supervisor signs this form.

SITE CHECK/SITE ASSESSMENT CONDUCTED BY:

Fill in the site assessor information for permanent closure or change-in-service. Mark the appropriate box showing whether contamination from the underground tank(s) was or is present at the site. A site check/site assessment MUST be conducted by a site assessor who is registered with Ecology.

If contamination at the site is found or suspected, the appropriate Ecology Regional Office must be notified within 24 hours. If the contamination is confirmed, a site characterization report must be submitted to the regional office within 90 days. If contamination is not confirmed, a site assessment report must be submitted to the above address within 30 days.

Tanks exempt from notification requirements are:

Farm or residential tanks, 1100 gallons or less, used to store motor fuel for personal or farm use only. The fuel must not be for resale or used for business purposes.

Tanks used for storing heating oil that is used on the premises where the tank is located.

Tanks with a capacity of 110 gallons or less.

Equipment or machinery tanks such as hydraulic lifts or electrical equipment tanks.

Emergency overflow tanks, catch basins, or sumps.

Return this completed form to:

Underground Storage Tank Section

Department of Ecology

P. O. Box 47655

Olympia, WA 98504-7655

**For more information call toll free in the state of Washington
1-800-826-7716 or (206) 438-7137**

APPENDIX F

TABLE V. END USE CRITERIA FOR PETROLEUM-CONTAMINATED SOILS

Analyte	Analytical Method	Soil Class (ppm)			
		1	2	3	4
Heavy fuel hydrocarbons (C24-C30)	WTPH-418.1 mod.	<60	60-200	200-2000	>2000
Diesel (C12-C24)	WTPH-D	<25	25-200	200-500	>500
Gasoline (C6-C12)	WTPH-G	<5	5-100	100-250	>250
Benzene	8020	<0.005	0.005-0.5	≤0.5	>0.5
Ethylbenzene	8020	<0.005	0.005-20	≤20	>20
Toluene	8020	<0.005	0.005-40	≤40	>40
Xylenes (total)	8020	<0.005	0.005-20	≤20	>20

Treatment is recommended for all Class 3 and 4 soils.

NOTES:

Class 1 Soil Uses:

Any use which will not cause threat to human health or the environment.

Class 2 Soil Uses:

Backfill at the cleanup site

Fill in commercial or industrial areas

Cover or fill in permitted landfills

Road subgrade or other road construction fill

Fill in or near: wetlands, surface water, ground water, drinking water wells or utility trenches is NOT recommended. Use as residential topsoil is also NOT recommended.

Class 3 Soil Uses:

Treatment

Disposal at the original site (no solid waste disposal permit needed)

Road construction (no solid waste disposal permit needed)

Use or disposal in permitted, municipal landfills

Permitted as a new PCS landfill

(An evaluation should be made to ensure that disposal will not cause a threat to human health or the environment, e.g. use near water bodies)

Class 4 Soil Uses:

Treatment

Disposal in a permitted, municipal landfill

Permitted as a new PCS landfill

APPENDIX G