


LOST / UST



USA


Site # 384923

UPRR #'S
Site # 096 and 025
TANK I, 2nd + pine street

C LS
384923
07246


~~PACIFIC COAST~~
~~NURSERY~~

**SITE ASSESSMENT REPORT
FOR
UNION PACIFIC RAILROAD
YAKIMA, WASHINGTON
Section 19**



SEPTEMBER 1990


By USPCI
5665 Flatiron Parkway
Boulder, CO 80301
(303) 938-5500




**SITE ASSESSMENT REPORT
FOR
UNION PACIFIC RAILROAD
YAKIMA, WASHINGTON**

SEPTEMBER 1990

**By USPCI
5665 Flatiron Parkway
Boulder, CO 80301
(303) 938-5500**





USPCI, INC.

Remedial Services

September 27, 1990

Ms. Susan Bergdorf
Washington Department of Ecology
801 Summitview
Yakima, WA 98902

Dear Ms. Bergdorf:

Enclosed is one copy of USPCI's site assessment for two underground storage tanks, which were previously located in Yakima, Washington. If you have any questions, please do not hesitate to call.

Sincerely,

Curt G. Hull
Program Manager
Environmental Assessments

Enclosure

cc: Alan Jensen, UPRR
Roger Fitch, UPRR
John Yellich, USPCI





TABLE OF CONTENTS

1.0 INTRODUCTION 1
2.0 UST CLOSURE ACTIVITIES 1
3.0 SITE INVESTIGATION 4
4.0 CHEMISTRY 10
5.0 HYDROGEOLOGY 10
6.0 CONCLUSIONS AND RECOMMENDATIONS 11

LIST OF FIGURES

Figure 1 - Site Location Map 2
Figure 2 - Site Map Tank 1 3
Figure 3 - Site Map Tank 4 5
Figure 4 - Water Well Location Map 6
Figure 5 - Monitoring Well Location Map 8
Figure 6 - Soil Boring Location Map 9
Figure 7 - Groundwater Contour Map 12



1.0 INTRODUCTION


USPCI, a wholly owned subsidiary of Union Pacific Corporation, is pleased to present this initial site assessment for an underground storage tank (UST) investigation in Yakima, Yakima County, Washington. Union Pacific Railroad owned and operated the two UST's discussed in this report. One 200 gallon steel UST located at approximately 2nd and Pine street was removed on November 9, 1989, and one 19,000 gallon steel UST located approximately 800 feet north of the Nob Hill Blvd. railroad overpass was removed on November 11, 1989 (Figure 1). According to Union Pacific personnel, the 200 gallon UST was used to store gasoline, and the 19,000 gallon UST was used to store diesel fuel. Mr. Alan Jensen, Manager of Engineering Maintenance at Union Pacific, was the contact person on this project for USPCI. This assessment report will include a discussion of the UST closure activities, encompassing excavation procedures, monitoring, sample locations, sample analysis and tank disposition; a discussion of the site investigation, which will include background information, drilling, sampling and analytical results; conclusions and recommendations.

2.0 UST CLOSURE ACTIVITIES

In a letter dated September 13, 1989, USPCI informed the State of Washington, Department of Ecology (DEQ), of our intention to remove three USTs in Yakima. A copy of the notification letter is included. Five USTs were removed in Yakima during the month of November. An amended Washington State Underground Storage Tank Notification Form is included. The tanks covered by this report are designated as tanks 1 and 4 on the amended form.

On November 9, 1989, USPCI excavated and closed the 200 gallon UST by removal. Throughout the tank closure process, the atmosphere in the vicinity of the excavation was monitored with a photoionization detector (PID) to test the presence of volatile organics. This testing was performed in order to determine the need for respiratory protection during the excavation process and as a preliminary test for leakage. All readings taken with the PID during the excavating were background levels. The tank appeared to be in good condition and there was no visual evidence of the tank having leaked. The initial explosive limit of the tank atmosphere was 80%. The tank was then purged with dry ice to inert the atmosphere within it.

After the tank was removed from the excavation, three soil samples were collected from the bottom of the excavation, cooled to approximately 4 degrees centigrade and sent to Industrial Laboratories in Denver, CO, for analysis (Figure 2). Industrial Laboratories analyzed the soil samples for total petroleum hydrocarbons (TPH) using EPA method 418.1; benzene, toluene, ethylbenzene and xylenes (BTEX) using EPA method 8020; lead using



QUADRANGLE LOCATION




USPCI <small>A Subsidiary of Union Pacific Corporation</small>	
YAKIMA, WASHINGTON	
FIGURE 1 SITE LOCATION MAP	
<small>SCALE: 1" = 2000'</small>	<small>APPROVED/DATE</small>



WEST SPRUCE STREET

SOUTH 2ND STREET




MAIN TRACKS

LEGEND



SAMPLE LOCATION



EXCAVATION BOUNDARY

USPCI

A Subsidiary of
Union Pacific Corporation

YAKIMA, WASHINGTON

**FIGURE 2
SITE MAP
TANK 1**

DWS, NO. 98120-115

APPROVED, DATE

EP Toxicity; and ignitability using EPA method 1010. The tank was then loaded onto a railroad car and transported to Tanks Away in Denver, CO, for disposal. The disposal certificate is attached.

On November 11, 1989, USPCI excavated and closed the 19,000 gallon UST by removal. Throughout the tank closure process, the atmosphere in the vicinity of the excavation was monitored with a PID. All readings taken were background levels. The tank appeared to be in good condition, however, contaminated soil was observed in the bottom of the excavation. The initial explosive limit of the tank atmosphere was 0%. The tank was then purged with dry ice to inert the atmosphere within it.

After the tank was removed from the excavation, three soil samples were collected from the bottom of the excavation, cooled to approximately 4 degrees centigrade and sent to Industrial Laboratories in Denver, CO, for analysis (Figure 3). Industrial Laboratories analyzed the soil samples for the same parameters as the samples collected for the 200 gallon tank. The tank was then loaded onto a railroad car and transported to Tanks Away in Denver, CO, for disposal. The disposal certificate is attached.


Results of the laboratory analysis for the soil samples indicated levels of TPH for the 200 gallon tank, ranging from 45 parts per million (ppm) to 580 ppm. BTEX results were all non detected at a detection limit of 10 ppm. Lead ranged from <0.01 milligrams per liter (mg/l) to 0.02 mg/l. None of the samples were ignitable to 140 degrees fahrenheit. Laboratory results for the 19,000 gallon tank indicated levels of TPH ranging from 290 ppm to 11,400 ppm. BTEX and lead results were non detected and none of the samples were ignitable to 140 degrees fahrenheit. Laboratory analysis are attached.

3.0 SITE INVESTIGATION

Background information for this project was collected by contacting the US Geological Survey (USGS) and the State of Washington DEQ.


Geology has been mapped by the USGS as alluvium deposits overlaying the Yakima basalt.

Information for existing wells within a one-half mile radius of the 19,000 gallon UST site, was requested from the DEQ. Water Well Reports were received for 17 wells, located at 12 sites within the requested area (Figure 4). Proposed use for the wells included domestic, industrial, and test well. The domestic and industrial wells were all cased to a minimum of 31 feet below ground surface, and the test wells were cased to 7 feet below ground surface.



- LEGEND**
- ⊕ SAMPLE LOCATION
 - EXCAVATION BOUNDARY

USPCI <small>A Subsidiary of Union Pacific Corporation</small>	
YAKIMA, WASHINGTON	
FIGURE 3 SITE MAP TANK 4	
<small>DWG. NO.</small> 96120-114	<small>APPROVED/DATE</small>



● WATER WELLS FOR WHICH LOGS WERE AVAILABLE



QUADRANGLE LOCATION



USPCI

A Subsidiary of
Union Pacific Corporation

YAKIMA, WASHINGTON

FIGURE 4
WATERWELL LOCATION MAP

SCALE: 1" = 2000'

APPROVED/DATE

On April 25, 1990, USPCI drilled three monitoring wells (Figure 5) to investigate the extent of TPH contamination in the soil around the 19,000 gallon UST excavation. Monitoring well YAK-MW-1 was drilled to a depth of 25 feet below grade (BG) using an ODEX drilling system. Water was encountered at approximately 20 feet BG. Two inch PVC screen was installed from 15.0 feet to 25.0 feet BG, with solid wall two inch PVC installed from grade to 15.0 feet BG. The annular space between the PVC and the boring wall was filled with filter sand from 11.0 feet to 25.0 feet BG, bentonite pellets from 9.0 feet to 11.0 feet BG, and concrete from grade to 11.0 feet BG. A drive over was installed at grade level to protect the PVC casing, and a locking cap was installed on the top of the two inch PVC casing to secure the well from vandalism.


Monitoring wells YAK-MW-2 and YAK-MW-3 were drilled to a depths of 25.0 feet BG and constructed as described above. During drilling of YAK-MW-2, a slight hydrocarbon odor was observed in the cutting samples from approximately 15 feet BG.

Drill cutting samples were collected from YAK-MW-1 at depths of 10 feet and 15 feet BG, from YAK-MW-2 at depths of 10 feet and 15 feet BG, and from YAK-MW-3 at depths of 7 feet and 15 feet BG. All samples were placed into glass bottles supplied by the laboratory, cooled to approximately 4 degrees centigrade, and sent to Hager Laboratories, Inc. (HLI) in Golden, CO, for analysis. Drilling and sampling equipment, other than the laboratory supplied sample bottles, were decontaminated in the field using a portable steam cleaner, prior to the drilling of the boring.

After well construction was complete, the wells were developed using a hand bailer. The bailer was decontaminated using a portable steam cleaner prior to use in each well. Once the wells were developed, water samples were collected using decontaminated bailers, placed into 40 milliliter (ml) glass vials, cooled to approximately 4 degrees centigrade, and sent to HLI for analysis.

On April 25 and 26, 1990, USPCI drilled two soil borings (Figure 6) to investigate the extent of TPH contamination in the soil around the 200 gallon UST excavation. Soil borings YAK-MW-4 and YAK-SB-2 were drilled to depths of 20 feet below grade (BG) using an ODEX drilling system. During drilling no evidence of petroleum hydrocarbon contamination were observed.

Drill cutting samples were collected from depths of 9 feet BG and 19 feet BG for both soil borings. All samples were placed into glass bottles supplied by the laboratory, cooled to approximately 4 degrees centigrade, and sent to HLI in Golden, CO, for analysis. Drilling and sampling equipment, other than the laboratory supplied sample bottles, were decontaminated in the field using a portable steam cleaner, prior to the drilling of the boring. After drilling and sampling were completed, the soil borings were filled with drill cuttings.



LEGEND

● MONITORING WELL LOCATION



USPCI <small>A Subsidiary of Union Pacific Corporation</small>	
YAKIMA, WASHINGTON	
FIGURE 5 MONITORING WELL LOCATION MAP	
<small>DWG#</small> 96120-112	<small>APPROVED/DATE</small>



WEST SPRUCE STREET

SOUTH 2ND STREET



TOOLHOUSE

129'

21'



YAK-SB-2

▲ YAK-MW-4

33'



TOOLHOUSE

MAIN TRACKS

LEGEND



SOIL BORING LOCATION



EXCAVATION BOUNDARY

USPCI

A Subsidiary of
Union Pacific Corporation

YAKIMA, WASHINGTON

**FIGURE 6
SOIL BORING LOCATION MAP
TANK 1**

DWG. NO. 96120-116

APPROVED/DATE

Following the completion of the site investigation, the wells were surveyed to establish the locations necessary for the state drilling permits and the elevations of the top of drive overs (TODO's).

4.0 CHEMISTRY

BTEX were analyzed by EPA method 8020 on soil samples, and EPA method 602 on water samples. TPH were analyzed by EPA method 418.1 on all soil and water samples.

Laboratory analysis indicated measurable BTEX in the soil ranging from less than 1 microgram per kilogram (ug/kg) to 15 ug/kg. TPH ranged from less than 4 ppm to 1,670 ppm in the soil samples. BTEX and TPH were non detected in the water samples at detection limits of 1 ug/l and 4 ppm, respectively. Results from the TPH and BTEX analysis for the soil samples are summarized below. Laboratory analysis are attached.

Analytical Results From Soil Samples

SAMPLE	TPH (ppm)	BENZENE (ug/kg)	TOLUENE (ug/kg)	ETHYL BENZENE (ug/kg)	XYLENES (ug/kg)
MW-1A	125	<1	<1	<1	<1
MW-1B	68	<1	<1	<1	<1
MW-2A	733	<1	<1	<1	<1
MW-2B	1,670	<1	1	4	15
MW-3A	<4	<1	<1	<1	<1
MW-3B	26	<1	<1	<1	<1
MW-4A	92	<1	<1	<1	<1
MW-4B	<4	<1	<1	<1	<1
SB-2A	1,030	<1	<1	<1	<1
SB-2B	17	<1	<1	<1	<1

5.0 HYDROGEOLOGY

On April 26, 1990, depths to groundwater were measured in the three monitoring wells. Depths ranged from 21.13 feet below TODO to 21.46 feet below TODO. No free product was observed floating on top of the groundwater.

In order to determine the direction of groundwater gradient, and possible groundwater flow, groundwater elevations were calculated for each well by subtracting the depth to water from the TODO elevation.


Using the calculated groundwater elevations, a groundwater contour map was created for the area around the 19,000 gallon UST excavation for April 26, 1990 (Figure 7). As shown, the groundwater gradient, is towards the east-northeast.

6.0 CONCLUSIONS AND RECOMMENDATIONS

Elevated levels of TPH were encountered at this site during the UST excavation and the following site investigation. From visual observations it appears that the elevated readings of TPH were not caused by the UST leaking, but may have been caused by occasional spills during filling and/or dispensing of product from the tank. Additionally, laboratory analysis of collected groundwater samples indicate that the groundwater has not been impacted at this time.

Due to the elevated levels of TPH in the soil in the vicinity of the 200 gallon UST, USPCI recommends excavating the soils to a depth of approximately 10 feet below grade. During the excavating, head space analysis should be conducted on the excavated soils, with the results used as a field determination for the extent of excavating. Upon completion of the excavating, soil samples should be collected from the bottom of the excavation in order to evaluate the effectiveness of the remediation. Should the results from the TPH analysis be below 100 ppm, this site will be considered clean. If the results from the TPH analysis are above 100 ppm, additional remediation will be recommended.

With the elevated levels of TPH in the soil at the vicinity of the 19,000 gallon UST, USPCI recommends excavating the soils to a depth of approximately 19 feet below grade. Prior to excavation, groundwater samples should be collected from the monitoring wells and analyzed to confirm no deterioration of the groundwater has occurred due to the TPH in the soils. If the laboratory analysis confirm no groundwater deterioration has occurred, the monitoring wells will be removed and abandoned during the excavation process. During the excavating, head space analysis should be conducted on the excavated soils, with the results used as a field determination for the extent of excavating. Upon completion of the excavating, soil samples should be collected from the bottom of the excavation in order to evaluate the effectiveness of the remediation. Should the results from the TPH analysis be below 100 ppm, this site will be considered clean. If the results from the TPH analysis are above 100 ppm, additional remediation will be recommended. In the event that the groundwater analysis indicate elevated levels of TPH or BTEX, addition monitoring wells will need to be installed and further recommendations forwarded.




LEGEND

- MONITORING WELL LOCATION
- GROUNDWATER CONTOUR LINE



USPCI <small>A Subsidiary of Union Pacific Corporation</small>	
YAKIMA, WASHINGTON	
FIGURE 7	
GROUNDWATER CONTOUR MAP	
APRIL 26, 1990	
<small>DWG#</small> 96120-113	<small>APPROVED/DATE</small>



USPCI, INC.

Remedial Services

September 13, 1989

Underground Storage Tank Notification
Hazardous and Solid Waste Program
Department of Ecology, M/S PV-11
Olympia, WA 98504-8711

This letter serves as the 30 day notice of the Union Pacific Railroad's intention to remove 25 underground storage tanks in Washington. USPCI, a wholly owned subsidiary of the Union Pacific Corporation, will perform the removals and accompanying site assessments. The attached list is the tanks and their locations that will be removed. All removal and tank cleaning will be done in accordance with 40 CFR 280 and 281, 29 CFR 1910, API Bulletin No. 1604, and API Publication No. 2015.

All liquids in the tanks will be removed for reuse or recycling by either the Union Pacific Railroad or USPCI prior to tank removal.

Throughout excavation of the tank a photoionization detector along with visual inspection of the soil will be used to detect the presence of contamination. If contamination is found the Washington Department of Ecology will be notified within 24 hours. On-site gas chromatograph analysis will also be used to determine the extent of contamination. Once the on-site instruments indicate that all contaminated soils have been removed a minimum of three samples will be collected in the excavation for off-site laboratory analysis. These samples will be analyzed for Total Petroleum Hydrocarbons, and in the gasoline tank excavations EP toxicity for lead. If groundwater is encountered in the excavation a sample will be collected and analyzed for the same analytes.


The Washington Department of Ecology will be consulted to determine the proper disposal option for contaminated soil. The tanks will be cleaned and scrapped or disposed of in USPCI's industrial landfill in Utah.

5665 Flatiron Parkway
Boulder, Colorado 80301
(303) 938-5500
FAX (303) 938-5520

Washington Department of Ecology
September 13, 1989
Page 2

This is a brief description of how work will proceed in these tank removals. If you have any questions, please call me at (303)938-5569.

Sincerely,



~~Curtis G. Hull~~
Senior Geologist
Environmental Assessments

CGH:mr
Attachment
cc: J. A. Yellich, USPCI
S. Beck, USPCI
A. Jensen, UPRR
R. Fitch, UPRR

Union Pacific Railroad - UST in Washington

<u>Location</u>	<u>Tank No.</u>	<u>Size</u>	<u>Contents</u>
Cheney	1	500	Gasoline
Chester	1	500	U
Dishmen	1	500	Diesel
Garfield	1	500	Diesel
Garfield	2	500	Gas
Hooper Junction	1	500	Gas
Hooper Junction	2	250	Gas
La Cross	1	250	Gas
Matthews	1	500	Gas
Oakesdale	1	500	Gas
Page	3	250	Gas
Page	4	250	Gas
Prescott	1	500	Gas
Riparia	1	500	Gas
South Elma	1	250	Gas
Starbuck	1	500	Gas
Tekoa	1	500	Gas
Tekoa	2	500	Diesel
Thorton	1	500	Gas
Touchet	1	500	Gas
Walker	1	500	Gas
Winona	1	500	Gas
Winona	2	500	Gas
Yakima	1	10,000	Diesel
Yakima	2	1,000	Diesel

WASHINGTON STATE UNDERGROUND STORAGE TANK NOTIFICATION FORM

IMPORTANT: PLEASE READ ALL INSTRUCTIONS ON PAGES 1-1 AND 1-2 BEFORE ENTERING INFORMATION.

- ABOVEGROUND TANKS MUST BE REPORTED IF THE CONNECTED UNDERGROUND PIPING COMPRIZES AT LEAST 10% OF THE OVERALL STORAGE SYSTEM (TANK AND PIPING)
- A SEPARATE FORM MUST BE USED FOR EACH SITE, EXCEPT FOR SITES WITH ONLY ONE TANK EACH. SEE THE GENERAL INSTRUCTIONS (PAGE 1-3) FOR THE DEFINITION OF A SITE AND DETAILS ON REPORTING SITES WITH ONE TANK EACH.
- THERE IS ROOM IN SECTION VI FOR INFORMATION CONCERNING 15 TANKS IF YOU HAVE MORE THAN 15 TANKS. PHOTOCOPY BOTH PAGES OF SECTION VI BEFORE ENTERING ANY INFORMATION. IF YOU HAVE MORE THAN ONE SITE, EITHER OBTAIN MORE FORMS FROM THE DEPARTMENT OF ECOLOGY OR BE SURE TO ALSO PHOTOCOPY THIS PAGE.)
- PLEASE TYPE, OR PRINT IN INK, THE SIGNATURE UNDER "CERTIFICATION" (SECTION V) MUST BE SIGNED IN INK.

I. OWNERSHIP OF THE TANK(S)

Please enter information regarding the owner of the tank(s). If the ownership of the tank(s) is uncertain enter information regarding the owner of the facility where the tank(s) are located, or information regarding the former owner of the tank(s). Please circle the correct letter, indicating who the information given better refers to:

- A. **OWNERSHIP UNCERTAIN** **CURRENT OWNER OF TANK(S)** **FORMER OWNER OF TANK(S)** **PROPERTY OWNER**

6. OTHER (PLEASE SPECIFY)

UNION PACIFIC RAILROAD
 1416 DODDS STREET
 OMAHA
 402-271-2262
 NE 60179

Type of Owner or Facility CODE TYPE CODE TYPE CODE TYPE

A. Service Station 0 Industrial/Manufacturing M City/Town S Port District

B. Bulk Plant 1 Private Institution N County T Utility District

C. Petroleum Distributor 2 Residential (Non-Farm) O State U Fire Dept./District

D. Commercial Store 3 Farm P Federal (Military)* V Other Special Service District (e.g. airport, water)

E. Auto Dealer 4 Airport Q Federal (Non Military)* W Other

F. Other Commercial/Other 5 Interstate R Suburban District

II. CONTACT PERSON AT THE TANK LOCATION

The contact person should be the individual responsible for regularly monitoring the operation of the tank(s)

RELEADES
 503-249-2314
 Area Code Phone Number

FORM 807 88-08 (10/88) GI 4-228

STATE USE ONLY

III. SITE OF THE TANK(S)

(If the same as Section I, check box here See the General Instructions (Page 1-2, 2 a) for the definition of a site.

YAKIMA ROUNDOUSE AND DEPOT
 YAKIMA SECTION 30 T 13 N R 19 E
 W A

YAKIMA
 YAKIMA
 YAKIMA
 W A
 8-23-90

IV. THE TOTAL NUMBER OF TANKS AT THIS SITE

1. Number of tanks containing petroleum, which are now in use
2. Number of tanks which have stored petroleum, but are not now in use
3. Number of tanks containing regulated chemicals, which are now in use
4. Number of tanks which have stored regulated chemicals, but are not now in use

TOTAL NUMBER OF TANKS: 5

Please mark this box if the site is located on land within an Indian reservation or on other Indian trust lands

V. CERTIFICATION (Please read and sign after completing Section VI)

I, county under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents to the best of my knowledge and belief, the submitted information is true, accurate, and complete.

L. A. SCHMID

ENVIRONMENTAL ENGINEER

4-29-86
 Date Signed

by JCH

Signature (PLEASE SIGN IN INK)

VI. INFORMATION REGARDING INDIVIDUAL TANKS (See instructions regarding individual tanks, Page 1-2)

a. Tank Identification	b. Tank Status	c. Age of the Tank	d. Capacity of the Tank	e. Tank Construction	f. Leak Detection	g. Cathodic Protection	h. Internal Protection
1	C	UNK	A	A	O	F	H
2	C	G	E	A	O	I	H
3	C	G	C	A	O	E	H
4	C	UNK	E	A	O	F	H
5	C	UNK	A	A	O	F	H

a. Tank Identification
 Please list your tanks numerically (1, 2, 3, etc.) or use an established tank identification number or code. The information in this column should apply to the tank identified in the corresponding row of this column.

b. Tank Status
 Please put the correct letter for each tank in the appropriate row of the column below:

c. Age of the Tank
 If the year of installation of the tank is known, please enter the appropriate row if the exact year of installation is not known, please estimate as closely as possible, using the grouping shown below (Choose a letter and put it in the appropriate row):

d. Capacity of the Tank
 Please put the correct letter for each tank in the appropriate row of the column below if the exact capacity is not known, please choose an estimate:

e. Tank Construction
 Please put all the letters which apply to each tank in the appropriate row of the column below (If "Other" (O) please enter type of material)

f. Leak Detection
 Please put all the letters which apply to each tank in the appropriate row of the column below (If "Other" (O) please enter type of detection)

g. Cathodic Protection
 Please put the correct letter for each tank in the appropriate row of the column below (If "Other" (O) please also enter the type of protection)

h. Internal Protection
 Please put the correct letter for each tank in the appropriate row of the column below (If "Other" (O) please also enter the type of protection)

A Carbon Steel
B Stainless Steel
C Steel, type unknown
D Nonferrous Noncorrosive Plastic
E Plastic
F Fiberglass
G Aluminum
H Other Material (please specify)
I Unknown Material
J Single Walling
K Double Walling
L Has secondary containment
M Has breather protection

A Tightness/Leak test within past year
B In tank system
C In piping system
D Subject gauge
E Electronic sensor
F Manually sampled vent(s)
G Wall of detection
H In ground detector
I In ground detector in secondary tank
J Rainwater monitoring (see L)
K Groundwater monitoring (see L)
L Spill Prevention Control and Countermeasure Plus
M Other (please specify)

A Sacrificial Anodes/Aluminum Type
B Impressed Current Type
C Other Type (please specify)
D Cathodically Protected, Type Unknown
E None
F Unknown

A Rubber Lining
B Alkyd Lining
C Epoxy Lining
D Phenolic Lining
E Glass Lining
F Other Lining (please specify)
G Lead, type unknown
H Unknown
I Other internal protection (please specify)
J Unknown

CERTIFICATE
NUMBER

3341

TANKS



INC.

Charles E. Quigley
9037 Mandel St.
Federal Heights, Colo. 80221

(303) 429-0729

CERTIFICATE OF DISPOSAL

THE TANK DESCRIBED BELOW, A UNDERGROUND STORAGE TANK FOR HYDROCARBON PRODUCTS, HAS BEEN RECEIVED AT TANKS AWAY INC. SITE AND HAS BEEN HANDLED IN A SAFE MANNER AND HAS BEEN RENDERED SAFE AND HARMLESS TO HUMAN AND ANIMAL LIFE. THE PROCEDURE USED MEETS ALL STATE AND FEDERAL REQUIREMENTS APPLICABLE AT DATE OF DISPOSAL.

LOCATION THAT TANK WAS REMOVED FROM;

Union Pacific Railroad R.R. Car UP 98412

DESCRIPTION OF TANK:

SIZE 10 ft. by 33ft.

GALLONS 20,000

MANUFACTURE Keyes Tank and Supply

JOB PLATE 7GA

SERIAL NUMBER A 981853

CERTIFICATE OF DISPOSAL ISSUED TO U.S.P.C.I.


DATE OF ISSUE 6-26-90

DISPOSAL WORK PERFORMED BY Charles E. Quigley

CERTIFICATE
NUMBER

3330

TANKS



INC.

Charles E. Quigley
9037 Mandel St.
Federal Heights, Colo. 80221.

(303) 429-0729

CERTIFICATE OF DISPOSAL

THE TANK DESCRIBED BELOW, A UNDERGROUND STORAGE TANK FOR HYDROCARBON PRODUCTS, HAS BEEN RECEIVED AT TANKS AWAY INC. SITE AND HAS BEEN HANDLED IN A SAFE MANNER AND HAS BEEN RENDERED SAFE AND HARMLESS TO HUMAN AND ANIMAL LIFE. THE PROCEDURE USED MEETS ALL STATE AND FEDERAL REQUIREMENTS APPLICABLE AT DATE OF DISPOSAL.

LOCATION THAT TANK WAS REMOVED FROM;

Union Pacific Railroad R.R. Car UP 914058
Yakima 1

DESCRIPTION OF TANK:

SIZE 1ft. 9in. by 9ft. Torpedo Type

GALLONS 160

MANUFACTURE N/A

JOB PLATE N/A

SERIAL NUMBER N/A

CERTIFICATE OF DISPOSAL ISSUED TO U.S.P.C.I.

DATE OF ISSUE 6-26-90

DISPOSAL WORK PERFORMED BY Charles E. Quigley



**i n d u s t r i a l
LABORATORIES**

THE INDUSTRIAL LABORATORIES COMPANY

**Complete Consulting Chemistry Service
Bacteriological & Analytical Testing**

1450 East 62nd Avenue
P.O. Box 16207
Denver, Colorado 80216
(303) 287-9691 FAX (303) 287-0964

Analysis Report

USPCI, INC.
5665 FLATIRON PARKWAY
BOULDER, CO 80301
CURT G. HULL

Page: 1
Date Received: 11/15/89
Date Reported: 11/27/89
Lab Number: 1942
Customer P.O.: 8953450

Sample Marked: UST REMOVAL, UNION PACIFIC, YAKIMA, WA, PROJ. 89-53-450

----INTERIM REPORT----

ANALYSIS	UNITS	YAK-4. BG. 11-11-89 3:30	YAK-4. N. 11-11-89 3:30	YAK-4. M. 11-11-89 3:30	YAK-4. S. 11-11-89 3:30
P TOXICITY EXTRACTION		-	-	-	-
EAD	mg/L	ND<0.01	ND<0.01	ND<0.01	ND<0.01
ASS IDENTIFICATION IGNITABILITY		**	**	**	**

**NOT IGNITABLE TO 140 DEGREES F.

ND< MEANS NONE DETECTED LESS THAN.



Industrial LABORATORIES

THE INDUSTRIAL LABORATORIES COMPANY

Complete Consulting Chemistry Service
Bacteriology & Analytical Testing

1450 East 62nd Avenue
P.O. Box 16207
Denver, Colorado 80216
(303) 287-9691 FAX (303) 287-0964

Analysis Report

USPCI, INC.
5665 FLATIRON PARKWAY
BOULDER, CO 80301
CURT G. HULL

Page: 1
Date Received: 11/15/89
Date Reported: 12/08/89
Lab Number: 1942-5
Customer P.O.: 8953450

Sample Marked: UST REMOVAL, UNION PACIFIC, YAKIMA, WA, PROJ. 89-53-450

ANALYSIS	UNITS	YAK-4. BG.	YAK-4. N.	YAK-4. M.	YAK-4. S.
		11/11/89 3:30	11/11/89 3:30	11/11/89 3:30	11/11/89 3:30
TOTAL PETROLEUM + HYDROCARBONS	PPM	320	350	290	11,400
BENZENE	PPM	ND	ND	ND	ND
TOLUENE	PPM	ND	ND	ND	ND
XYLENE	PPM	ND	ND	ND	ND
ETHYLBENZENE	PPM	ND	ND	ND	ND

ND< MEANS NONE DETECTED LESS THAN.



**Industrial
LABORATORIES**

THE INDUSTRIAL LABORATORIES COMPANY

Complete Consulting Chemistry Service
Bacteriological & Analytical Testing

1450 East 62nd Avenue
P.O. Box 16207
Denver, Colorado 80216
(303) 287-9691 FAX (303) 287-0964

Analysis Report

USPCI, INC.
5665 FLATIRON PARKWAY
BOULDER, CO 80301
CURT G. HULL

Page: 1
Date Received: 11/15/89
Date Reported: 12/08/89
Lab Number: 1942-2
Customer P.O.: 8953450

Sample Marked: UST REMOVAL, UNION PACIFIC, YAKIMA, WA. PROJ. 89-53-450

ANALYSIS	UNITS	YAK-1. BG.	YAK-1. E.	YAK-1. M.	YAK-1. W.
		11/9/89	11/9/89	11/9/89	11/9/89
TOTAL PETROLEUM HYDROCARBONS	PPM	3:14 880	3:14 160	3:14 45	3:14 580
BENZENE	PPM	ND	ND	ND	ND
TOLUENE	PPM	ND	ND	ND	ND
XYLENE	PPM	ND	ND	ND	ND
ETHYLBENZENE	PPM	ND	ND	ND	ND
SP. TOXICITY (EXTRACTION)		-	-	-	-
LEAD	mg/L	ND<0.01	ND<0.01	ND<0.01	ND<0.01
CLASS IDENTIFICATION - IGNITABILITY		**	**	**	**

**NOT IGNITABLE TO 140 DEGREES F.

ND< MEANS NONE DETECTED LESS THAN.



U.S.
 POLLUTION
 CONTROL INC.
 Remedial Services

LOG

BORING NO.

WELL NO. YAK-MW-1

CLIENT: UP RAILROAD			JOB NUMBER: 96120		
PROJECT: YAKIMA DEPOT			LOCATION: YAKIMA WASHINGTON		
DRILLED BY: P. C. EXPLOR.		DRILLER: DAVID MOTT		METHOD: ODEX	
DATE START: 4/23/90	DATE COMP: 4/23/90	SURF. EL: 1042.38 MSL	TD: 25.0' BGS		
LOGGED BY: JOHN L. WHEELER		APPROVED BY:		DEPTH TO WATER: 21.13' TODD	

WELL COMP	DPT	DESCRIPTION	GRAPHIC LOG USCS CODE	HNU	SAMPLE NUMBER	TPH ppm
	0	0.0 to 25.0 SAND AND GRAVEL		ND		
	10			ND		
	10			ND	YAK-MW-1A	125
				ND		
				GW		
					YAK-MW-1B	68
	20					
		TOTAL DEPTH 25.0'				
	30					
	40					

U.S.
POLLUTION
CONTROL INC.


LOG

BORING NO.

Remedial Services

WELL NO. YAK-MW-2

CLIENT: UP RAILROAD			JOB NUMBER: 98120		
PROJECT: YAKIMA DEPOT			LOCATION: YAKIMA WASHINGTON		
DRILLED BY: P. C. EXPLOR.		DRILLER: DAVID MOTT		METHOD: ODEX	
DATE START: 4/29/90	DATE COMP: 4/29/90	SURF. EL: 1041.87 MSL		TD: 25.0' BGS	
LOGGED BY: JOHN L. WHEELER		APPROVED BY:		DEPTH TO WATER: 22.46' TODD	

WELL COMP	DPT	DESCRIPTION	GRAPHIC LOG USCS CODE	HNU	SAMPLE NUMBER	TPH ppm
	0	0.0 to 25.0 SAND AND GRAVEL WELL GRADED				
	10			GW		YAK-MW-2A 733
	20				YAK-MW-2B 1670	
	30	TOTAL DEPTH 25.0'				
	40					



U.S
 POLLUTION
 CONTROL INC.
 Remedial Services

LOG

BORING NO.

WELL NO. YAK-MW-3

CLIENT: UP RAILROAD			JOB NUMBER: 96120		
PROJECT: YAKIMA DEPOT			LOCATION: YAKIMA WASHINGTON		
DRILLED BY: P. C. EXPLOR.		DRILLER: DAVID MOTT		METHOD: ODEX	
DATE START: 4/23/90	DATE COMP: 4/23/90	SURF. EL: 1041.92 MSL	TD: 25.0' BGS		
LOGGED BY: JOHN L. WHEELER		APPROVED BY:		DEPTH TO WATER: 21.34' TODO	

WELL COMP	DPT	DESCRIPTION	GRAPHIC LOG USCS CODE	HNU	SAMPLE NUMBER	TPH ppm
	0	0.0 to 7.0 SILTY SAND, MEDIUM GRAINED SOME GRAVEL		SP	YAK-MW-3A	<4
	7.0 to 25.0	GRAVELS				
		TOTAL DEPTH 25.0'				
	10					
	20					
	30					
	40					


U.S.
POLLUTION
CONTROL INC.

LOG

BORING NO. YAK-MW-4

Remedial Services

WELL NO.



CLIENT: UP RAILROAD				JOB NUMBER: 96120			
PROJECT: YAKIMA DEPOT			LOCATION: YAKIMA WASHINGTON				
DRILLED BY: P. C. EXPLOR.		DRILLER: DAVID MOTT		METHOD: ODEX			
DATE START: 4/23/90		DATE COMP: 4/23/90		SURF. EL:		TD: 20' BGS	
LOGGED BY: JOHN L. WHEELER			APPROVED BY:		DEPTH TO WATER:		
WELL COMP	DPT	DESCRIPTION	GRAPHIC LOG USCS CODE	HNU	SAMPLE NUMBER	TPH ppm	
	0	0.0 to 20.0 SAND AND GRAVEL					
	10			GW		YAK-MW-4A	92
	20				YAK-MW-3B	<4	
	30						
	40	TOTAL DEPTH 20.0'					

U.S.
 POLLUTION
 CONTROL INC.
 Remedial Services

LOG

BORING NO. YAK-SB-2

WELL NO.

CLIENT: UP RAILROAD			JOB NUMBER: 96120			
PROJECT: YAKIMA DEPOT			LOCATION: YAKIMA WASHINGTON			
DRILLED BY: P. C. EXPLOR.		DRILLER: DAVID MOTT		METHOD: ODEX		
DATE START: 4/26/90		DATE COMP: 4/26/90		SURF. EL:		
				TD: 20.0' BGS		
LOGGED BY: JOHN L. WHEELER		APPROVED BY:		DEPTH TO WATER:		
WELL COMP	DPT	DESCRIPTION	GRAPHIC LOG USCS CODE	HNU	SAMPLE NUMBER	TPH ppm
	0	0.0 to 4.0 SAND AND GRAVEL		GW		
		4.0 to 20.0 RIVER GRAVEL, SOME SAND		GP	YAK-SB-2A	1030
	10					
	20	TOTAL DEPTH 20.0'			YAK-SB-2B	17
	30					
	40					



HAGER
LABORATORIES, INC.

Box 4012
Golden, Colorado 80401
(303) 278-3400 (800) 282-1835
FAX # (303) 278-2121

REPORT ON SERVICE NUMBER 47737EN
May 7, 1990

Customer Project Code: SP#928

To: Mr. John L. Wheeler
U.S. Pollution Control, Inc.
5665 Flatiron Parkway
Boulder, CO 80301

Analysis: The following samples were submitted for analysis:
Ten soil samples for EPA Method 418.1 for total petroleum hydrocarbons and EPA Method 8020 for BTEX.
Three water samples and one blank for EPA Method 602 for BTEX.
Three water samples for EPA Method 418.1 for total petroleum hydrocarbons.

Method: TOTAL PETROLEUM HYDROCARBONS
Approximately 10 grams of sample was extracted with freon 113. The extract was analyzed by infrared spectroscopy. Quantification was achieved by measuring the intensity of the carbon-hydrogen single bond absorbance in the samples to the carbon-hydrogen single bond absorbance in standards of known concentration.

BTEX IN SOILS

EPA Method 8020 for volatile aromatics in soil was used to measure BTEX. A weighted sample of soil was mixed with reagent water. An internal standard was added to the aliquot. Helium was bubbled through the water contained in a specially designed chamber. The purgable organics were swept from the water onto a sorbent trap. The trap was then heated and back flushed with helium to sweep the purgables onto a fused silica gas chromatographic column. The gas chromatographic column was then temperature programmed to separate the purgables which were detected with a Photoionization Detector (PID).

EPA 602 - VOLATILE AROMATIC ORGANICS (WATER) BY GC

An internal standard was added to a 5ml water sample. Helium was bubbled through the water contained in a specially designed chamber. The purgable organics are swept from the water onto a sorbent trap. The trap was then heated and back flushed with helium to remove the purgables onto a fused silica gas chromatographic column. The gas chromatographic column was then temperature programmed to separate the purgables which are detected by a Photoionization Detector (PID).

SN 47737EN
May 7, 1990

TABLE 1

Sample Number	Hager Reference #	Analysis	Concentration (ug/kg)	Detection Limit (ug/kg)
YAK-MW-1A	AB21266	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
YAK-MW-1B	AB21267	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
YAK-MW-2A	AB21268	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
YAK-MW-2B	AB21269	benzene	ND	1.
		toluene	1.	
		ethyl benzene	4.	
		xylene	15.	
YAK-MW-3A	AB21270	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
YAK-MW-3B	AB21271	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
YAK-MW-4A	AB21272	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.

ND indicates not detected at the specified detection limit.

SN 47737EN
May 7, 1990

TABLE 2

Sample Number	Hager Reference #	Analysis	Concentration (ug/kg)	Detection Limit (ug/kg)
YAK-MW-4B	AB21273	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
YAK-SB-2A	AB21278	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
YAK-SB-2B	AB21279	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
Sample Number	Hager Reference #	Analysis	Concentration (ug/L)	Detection Limit (ug/L)
YAK-MW-1	AB21274	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
YAK-MW-2	AB21275	benznee	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
YAK-MW-3	AB21276	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.
FIELD BLANK	AB21277	benzene	ND	1.
		toluene	ND	1.
		ethyl benzene	ND	1.
		xylene	ND	1.

ND indicates not detected at the specified detection limit.

SN 47737EN
May 7, 1990

TABLE 3

Sample Number	Hager Reference #	Analysis	Concentration (mg/kg)	Detection Limit (mg/kg)
YAK-MW-1A	AB21266	TPH	125.	
YAK-MW-1B	AB21267	TPH	68.	
YAK-MW-2A	AB21268	TPH	733.	
YAK-MW-2B	AB21269	TPH	1670.	
YAK-MW-3A	AB21270	TPH	ND	4.
YAK-MW-3B	AB21271	TPH	26.	
YAK-MW-4A	AB21272	TPH	92.	
YAK-MW-4B	AB21273	TPH	ND	4.
YAK-SB-2A	AB21278	TPH	1030.	
YAK-SB-2B	AB21279	TPH	17.	

Sample Number	Hager Reference #	Analysis	Concentration (mg/L)	Detection Limit (mg/L)
YAK-MW-1	AB21274	TPH	ND	4.
YAK-MW-2	AB21275	TPH	ND	4.
YAK-MW-3	AB21276	TPH	ND	4.

ND indicates not detected at the specified detection limit.

Page Two, SN47737EN
U.S. Pollution Control, Inc.
May 7, 1990

Results: The results are found on Tables 1-3.

Discussion: Laboratory data are filed and available upon request.

If you have any questions, please contact our Technical Services Department, at (303)278-3400 or toll free at (800)282-1835.

Submitted by: R. C. Stites
Ronald Stites
Environmental Manager

RS/lh