

Department of Ecology - Environmental Report Tracking System

ERTS # 654375

Initial Report

External Reference #

Caller Information

First Name TOM Last Name MEYER
 Business Name SEATTLE CITY LIGHT
 Street Address
 Other Address
 City State WA Zip
 E-mail tom.meyer@seattle.gov Confidential_FL ☐
 Phone Ext Type
 (206) 386-9168 Business

Where did it happen

Berth Anchorage
 Location Name SCL NEWHALEM PENSTOCK
 Street Address SOUTH OF NEWHALEM
 Other Address
 City/Place NEWHALEM State WA Zip
 County - Region WHATCOM NWRO FS ID 10891
 WIRA #
 Waterway SKAGIT RIVER Type RIVER
 Latitude Longitude
 Topo Quad 1:24:000 DIABLO DAM
 Direction/Landmark (mile post, cross roads, township/range)

What happened

Spills Program Oil Spill? N

Incident Date 7/18/2014 Received Date 12/31/2014 14:55
 Medium SOIL
 Material OTHER HAZARDOUS
 Quantity Unit
 Source PUBLIC AGENCY
 Cause OTHER
 Activity OTHER
 Impact
 Vessel Name
 Hull Number

Primary Potentially Responsible Party Information

First Last
 Name
 Business Name SEATTLE CITY LIGHT
 Street Address
 Other Address
 City State WA Zip
 Phone Ext Type
 E-mail

Additional Contact Information

Name Phone Ext Type

More Information

From: Meyer, Tom [mailto:Tom.Meyer@seattle.gov]
 Sent: Wednesday, December 31, 2014 2:55 PM
 To: Bardy, Louise (ECY)
 Cc: Musa, Donna K. (ECY); Vick, Heather (ECY)
 Subject: Seattle City Light Newhalem Penstocks

Hello Louise.

This email is to notify the Department of Ecology of Seattle City Light's discovery and preliminary investigation of lead impacts to soils along the Penstock at our Newhalem Hydropower project. The site is located in the Skagit Valley near Newhalem, WA. The attached report prepared by Hart Crowser summarizes findings from a preliminary soil sampling investigation conducted in summer 2014. During 2015 we plan to conduct a limited remedial investigation and feasibility study on the alignment to better define the impacts to soils and determine our best course of action.

Currently City Light is in the planning phase of an engineering project that will replace the support saddles along the penstock's entire overland length in response to federal (FERC) requirements. Due to the nature of the project, including the remote location and very difficult access to portions of the penstock, we anticipate the saddle project will not be completed until late 2016. Soils managed or removed as part of the saddle replacement project will be sampled and managed as contaminated waste where appropriate and disposed of accordingly. Preliminary sampling indicates that lead-impacted soils do not designate as dangerous.

Further actions to remove or contain impacted soil resulting from the RI/FS findings would follow the saddle replacement project. Likewise, a determination of whether to enter the site into the Voluntary Cleanup Program will likely be made after the RI/FS.

Please feel free to contact me with questions.

Tuesday, May 19, 2015

*** The Initial report contains only information provided to Ecology from the complainant.

Page 1 of 5

Department of Ecology - Environmental Report Tracking System

ERTS # 654375

Happy New Year

-Tom Meyer

TOM MEYER
SEATTLE CITY LIGHT
ENVIRONMENTAL AFFAIRS & REAL ESTATE

tom.meyer@seattle.gov
TEL (206) 386-9168

CC: Heather Vic, Donna Musa

[Entry Person](#) MUSA TCP, DONNA

[Entry Date](#) 1/28/2015

ERTS # 654375

Referral

Referral Method		Person Referred to MUSA TCP, DONNA	Referral # 190261
<input type="radio"/> E-mail ERTS number		Phone (425) 649-7136 Fax (425) 649-7098	Primary <input checked="" type="checkbox"/>
<input type="radio"/> E-mail attachment		E-mail DMUS461@ECY.WA.GOV	
<input checked="" type="radio"/> Print		Program/Organization TOXICS CLEANUP	
<input type="radio"/> Telephone		Address 3190 160th AVE SE	
		City Bellevue WA 98008-5452	
		Region/Location NWRO	
		Referral Date 1/2/2015	

ERTS # 654375

Followup

Inspector Information

Referral # 190261
☒ Lead Inspector MUSA TCP, DONNA
 Program/Organization TOXICS CLEANUP

* Region/Location NWRO

of Ecology Staff 1 Overtime ☐

Action

E-MAIL	2/18/2015	2/18/2015
TCP - SIS	5/19/2015	5/19/2015

Where did it happen

Berth Anchorage
 Location Name SCL NEWHALEM PENSTOCK
 Street Address SOUTH OF NEWHALEM
 Other Address
 City/Place NEWHALEM State WA Zip
 County WHATCOM Region NWRO FS ID
 Waterway SKAGIT RIVER Type RIVER
 WRIA #

Followup #1

What happened

Incident Date 7/18/2014 Spills Program Oil Spill? N Latitude Longitude
 Topo Quad 1:24,000 DIABLO DAM
 Direction/Landmark (mile post, cross roads, township/range)

Medium

SOIL

Material

OTHER HAZARDOUS

Quantity	Unit	Est
		<input type="checkbox"/>

Source Regulated? ☐
 PUBLIC AGENCY

Cause

OTHER

Potentially Responsible Party Information

Check if the primary PRP provided notice to Ecology ☐

Primary ☒ First Last
 Name

Business Name SEATTLE CITY LIGHT

Street Address

Other Address

City	State WA	Zip
Phone	Ext	Type
E-mail		

Activity

OTHER

Impact

Vessel

Narrative

Tamara Cardona, NWRO TCP, reviewed documentation for Initial Investigation:

COMPLAINT (Brief Summary of ERTS Complaint): Seattle City Lights submitted a report in which soil contamination was documented at levels above MTCA Method A for lead and Method B for PAH's. Seattle City Lights hired Hart Crowser to screen and sample soil for heavy metals and SVOCs adjacent to the penstock support saddles near the Newhalem powerhouse, where additional work that may impact soil is planned.

CURRENT SITE STATUS (Brief Summary of why Site is recommended for Listing or NFA):

Concentrations of lead in surface soil are up to 10 times the MTCA Method A cleanup levels in an area that can potentially be accessed by the public. Additional information should be obtained on whether the extent of the penstock is accessible to the public. The area sampled is near a public campground and could potentially serve as a walking trail.

PAHs are also above the MTCA Method B cleanup levels.

It is recommended that additional TCLP analysis is completed during future work since no correlation was observed between the lead concentrations and TCLP results.

OBSERVATIONS: Description (If site visit made, please be sure to include the following: site observations, site features and cover, chronology of events, sources/past practices likely responsible for contamination, presence of water supply wells and other potential exposure pathways, etc.):

Document reviewed:

Hart Crowser; Seattle City Light Newhalem Penstock Soil Sampling/ XRF Survey; September 22, 2014.

Hart Crowser conducted an investigation, in support of the penstock pedestal replacement project, to determine how to dispose of potentially contaminated soil likely to be disturbed by the project.

Potential sources of contamination to the soil included: sandblasting (likely used to remove coats of paint which may have contained lead); sandblast grit (possibly containing heavy metals); and wood supports for the penstock, which may have contained wood preservatives.

ERTS # 654375

A field survey was conducted by establishing 6 transects along the penstock near the Newhalem powerhouse. Each transect was established at ~100 foot intervals perpendicular to the penstock. Starting with a sample from underneath the penstock, samples were collected moving 3 feet away in each direction. Each location was screened using a portable XRF (X ray fluorescence spectrometer) for metals associated to sandblast grit, lead based paint, or wood preservatives (chromium, lead, copper, arsenic, and zinc). A total of 57 samples were screened. 16 of the soil samples were sent to an analytical laboratory for confirmation of the five target metals. Two samples were also selected near the support saddle for SVOC analysis. In addition, two samples away from the penstock were collected as background samples. Four of the samples with the highest lead concentration were also analyzed for TCLP.

In general, a good correlation between XRF screening samples and laboratory confirmation samples was observed for lead. Although, the results were slightly lower with the XRF than the lab analysis. Laboratory results for lead for the highest 14 XRF screened samples ranged from 9.6 – 2000 mg/kg. Background samples indicated lead concentrations of 12 and 42 mg/kg.

Results for zinc, chromium III, and cadmium were below the MTCA Method A cleanup level. Results for copper were below the Method B cleanup level. Arsenic exceeded the MTCA Method A cleanup level in one sample with a concentration of 25 mg/kg. Note that chromium results were compared to Chromium III cleanup levels, however laboratory analysis was for total chromium; these concentrations ranged from 11-40 mg/kg including background samples.

None of the four TCLP results exceeded the 5 mg/L for lead. However; the lead concentrations and TCLP results showed no correlation, therefore it is recommended that additional TCLP sampling is completed during future work.

PAHs concentrations exceeded the Method B cleanup level in both samples analyzed. These samples were collected near the wood support for the penstock in an area that was visibly stained.

Recommendation: List on CSCSL.

New TCP file "Seattle City Light Newhalem Penstock"

Vessel Emergency ☐

Entry Person: MUSA TCP, DONNA

Entry Date 2/18/2015