



Electronic Copy

STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

PO Box 47775 • Olympia, Washington 98504-7775 • (360) 407-6300
711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341

June 25, 2015

Mr. Michael Chun
Associated Environmental Group, LLC
605 11th Avenue SE, Suite 201
Olympia, WA 98501

Re: Further Action at the following Site:

- **Site Name:** Holts Quik Chek Market
- **Site Address:** 400 N Pacific Ave., Kelso, WA 98626
- **Facility/Site No.:** 87376683
- **Cleanup Site ID No.:** 6797
- **VCP Project No.:** SW1445

Dear Mr. Chun:

The Washington State Department of Ecology (Ecology) received your request for an opinion on your independent cleanup of the Holts Quik Chek Market facility (Site). This letter provides our opinion. We are providing this opinion under the authority of the Model Toxics Control Act (MTCA), Chapter 70.105D RCW.

Issue Presented and Opinion

Is further remedial action necessary to clean up contamination at the Site?

YES. Ecology has determined that further remedial action is necessary to clean up contamination at the Site.

This opinion is based on an analysis of whether the remedial action meets the substantive requirements of MTCA, Chapter 70.105D RCW, and its implementing regulations, Chapter 173-340 WAC (collectively "substantive requirements of MTCA"). The analysis is provided below.

Description of the Site

This opinion applies only to the Site described below. The Site is defined by the nature and extent of contamination associated with the following releases:

- Petroleum constituents into the soil and groundwater.

Please note a parcel of real property can be affected by multiple sites. At this time, we have no information that the Property is affected by other sites.

Basis for the Opinion

This opinion is based on the information contained in the following documents:

1. Associated Environmental Group, LLC (AEG), April 2015 Holt's Quik Chek Quarterly Groundwater Sampling Results Report, May 19, 2015.
2. AEG, January 2015 Holt's Quik Chek Quarterly Groundwater Sampling Results Report, February 4, 2015.
3. AEG, Holt's Quik Check Quarterly Groundwater Sampling Results Summary, December 3, 2014.
4. State of Washington Department of Ecology (Ecology), Site Hazard Assessment, March 26, 2014.
5. AEG, Proposed Supplemental Remedial Investigation Work Plan, July 15, 2011.
6. State of Washington Department of Ecology (Ecology), Further Action Determination, June 18, 2007.
7. Farallon Consulting, LLC (Farallon), Final Quarter of Groundwater Monitoring, May 24, 2007.
8. Farallon, Site Closure Report, Holts Quik Chek Site, March 9, 2007.

Those documents are kept in the Central Files of the Southwest Regional Office of Ecology (SWRO) for review by appointment only. You can make an appointment by calling the SWRO resource contact at (360) 407-6365.

This opinion is void if any of the information contained in those documents is materially false or misleading.

Analysis of the Cleanup

Ecology has concluded that **further remedial action** is necessary to clean up contamination at the Site. That conclusion is based on the following analysis:

1. Characterization of the Site.

Ecology has determined your characterization of the Site **is not** sufficient to establish cleanup standards and select a cleanup action.

On June 18, 2007, Ecology issued a Further Action Determination through the Voluntary Cleanup Program (VCP) (Fig. 1). The determination was based on the review of work performed at the Site from December 1997 through May 2007. Ecology had the following general comments:

- The characterization did not meet the substantive requirements of MTCA. Sufficient soil (Fig. 2) and groundwater samples (Fig. 3) will need to be collected to determine the full extent of contamination present throughout the Site. Enough samples need to be collected to be certain that contamination is not affecting adjacent properties.
- Downgradient monitoring well MW-5 had contamination above MTCA Method A cleanup levels. Although the latest monitoring results had showed concentrations below the regulatory levels, contamination may be present downgradient of well MW-5. Additional borings or wells should be constructed downgradient of MW-5 to determine if groundwater contamination is present above the MTCA Method A cleanup levels.
- It is not apparent whether soil contamination remains above MTCA Method A cleanup levels on the Holt's Quik Chek Market property (Fig. 4).

Following the Further Action Determination letter from June 18, 2007, a VCP Status Request was sent to the owner by Mr. Chuck Cline (Ecology VCP Site Manager) on January 13, 2011. Due to a lack of progress, the VCP was terminated on February 15, 2011. The Site enrolled again for a brief time beginning May 18, 2011. A Proposed Supplemental Remedial Investigation Work Plan by AEG was received by Ecology on July 19, 2011.

The Supplemental Remedial Investigation Work Plan proposed additional soil borings with soil and groundwater sampling. An Opinion Letter was never issued and following a period of inactivity, the Site was terminated again from the VCP on February 4, 2013.

A Site Hazard Assessment was conducted by Ecology during March 2014. The Site was given a ranking score of "2" which was effective beginning with the August 2014 update of the state Hazardous Sites List.

Since the Further Action Determination Letter was issued June 18, 2007, three groundwater monitoring events were conducted. The events occurred on October 7, 2014, January 20, 2015, and April 22, 2015. Monitoring wells MW-1 through MW-5 were sampled and analyzed for gasoline (TPH-G), benzene, toluene, ethylbenzene, and xylene (BTEX). The only detection was TPH-G in MW-1, MW-2, and MW-5. Although detected, the numbers were well below the MTCA Method A cleanup level of 800 micrograms per liter ($\mu\text{g/l}$) with benzene detected or 1,000 $\mu\text{g/l}$ without detection of benzene. MW-6, which is located southwest and downgradient of the property, appears to have been sampled six times from September 1997 through the last event conducted on December 23, 2004. During the last event, benzene was detected at 13 $\mu\text{g/l}$, which is above the MTCA Method A cleanup level of 5 $\mu\text{g/l}$ for groundwater.

Based on a review of the above-listed reports, Ecology has the following comments:

1. Monitoring wells MW-1 through MW-5 have had at least four consecutive quarters with results either non-detect or below MTCA Method A cleanup levels. No further sampling is required from these monitoring wells. Monitoring well MW-6 was last sampled on December 23, 2004 and showed an exceedance above the MTCA Method A cleanup level of 5 µg/l for benzene. All other parameters were below their applicable cleanup level. MW-6 should continue to be sampled and analyzed for benzene.
2. MW-5 and MW-6 are the downgradient wells based on the groundwater contour map produced by Farallon. As stated in the 2007 Opinion Letter, additional wells or borings should be advanced downgradient of MW-5. MW-6 had benzene detected above the cleanup level during the last sampling event. Additional borings or wells should be advanced in this area as well to determine the downgradient extent of benzene.
3. The "Site Plan Showing Groundwater Contours (9/21/06)" produced by Farallon shows the groundwater flow direction to the west. In all future groundwater monitoring reports by AEG, it is stated that groundwater direction could not be determined due to lack of a professional survey to obtain actual elevations of monitoring wells. It should be noted that the casing rim elevation is shown for MW-1 through MW-6 in the Table 3 Summary of Groundwater Elevation Data of the March 9, 2007 Site Closure Report by Farallon. If this (casing elevation) has changed for some reason, the wells should be surveyed again so accurate data can be obtained. The groundwater flow direction and gradient need to be determined, not just assumed. It is very common for the groundwater flow direction to vary greatly throughout the season. Based on the results, further wells or borings may be required to determine the extent of downgradient contamination.
4. The Historical Soil Analytical Results from samples collected by AGI Technologies (AGI) and by EMCON in 1997 confirm soil contamination at depths ranging from 7 feet below ground surface (bgs) to 27.5 feet bgs. TPH-G exceedances ranged from 200 milligrams per kilogram (mg/Kg) to 12,000 mg/Kg. Exceedances above the MTCA Method A soil cleanup level for BTEX were also confirmed. As stated in the June 18, 2007 Opinion Letter, "In addition, it is not apparent whether soil contamination still remains above the MTCA method A cleanup levels on the Holts Quik Chek Market property. If soil remains it is possible that a restrictive covenant could be filed with the Cowlitz County Auditor's office. However, monitoring would be required to determine that soil contamination is not an issue for human health or the environment."
5. Once a release to groundwater has been documented, Ecology requires four consecutive quarters of monitoring with sample results below the applicable cleanup levels before a Site can be considered clean and a NFA determination made. This is to observe any changes in results due to seasonal fluctuations of the groundwater table as well as accurately determine a groundwater flow direction and gradient, which can also fluctuate seasonally.

6. In accordance with WAC 173-340-7490, a TEE needs to be completed for the Site. Please fill out the TEE form (and supporting documentation as appropriate) and submit it to Ecology. The form can be found on our website at <http://www.ecy.wa.gov/biblio/ecy090300.html>.
7. In accordance with WAC 173-340-840(5) and Ecology Toxics Cleanup Program Policy 840 (Data Submittal Requirements), data generated for Independent Remedial Actions shall be submitted simultaneously in both written and electronic format. For additional information regarding electronic format requirements, see the website <http://www.ecy.wa.gov/eim>. Be advised that according to the policy, any reports containing sampling data that are submitted for Ecology review are considered incomplete until the electronic data has been entered. Please ensure that data generated during on-site activities is submitted pursuant to this policy. **Data must be submitted to Ecology in this format for Ecology to issue a NFA determination. Be advised that Ecology requires up to two weeks to process the data once it is received.**

2. Establishment of cleanup standards.

Ecology has determined the cleanup levels and points of compliance you established for the Site do not meet the substantive requirements of MTCA. MTCA Method A soil and groundwater cleanup levels for unrestricted land use are being used for the Site.

Standard points of compliance are being used for the Site. The point of compliance for protection of groundwater shall be established in the soils throughout the Site. For soil cleanup levels based on human exposure via direct contact or other exposure pathways where contact with the soil is required to complete the pathway, the point of compliance shall be established in the soils throughout the Site from the ground surface to 15 feet bgs. In addition, the point of compliance for the groundwater shall be established throughout the Site from the uppermost level of the saturated zone extending vertically to the lowest most depth that could potentially be affected by the Site.

Additional characterization is warranted prior to setting cleanup levels and establishing points of compliance.

3. Selection of cleanup action.

Ecology has determined the cleanup action you selected for the Site does not meet the substantive requirements of MTCA.

4. Cleanup.

Ecology has determined the cleanup you performed does not meet any cleanup standards at the Site.

Further investigation is needed consisting of soil and groundwater data collection to help determine the potential extent of residual contamination.

Cleanup methods to date have included a biosparging and an in-situ chemical oxidation remediation using activated sodium persulfate.

Limitations of the Opinion

1. Opinion does not settle liability with the state.

Liable persons are strictly liable, jointly and severally, for all remedial action costs and for all natural resource damages resulting from the release or releases of hazardous substances at the Site. This opinion **does not**:

- Resolve or alter a person's liability to the state.
- Protect liable persons from contribution claims by third parties.

To settle liability with the state and obtain protection from contribution claims, a person must enter into a consent decree with Ecology under RCW 70.105D.040 (4).

2. Opinion does not constitute a determination of substantial equivalence.

To recover remedial action costs from other liable persons under MTCA, one must demonstrate that the action is the substantial equivalent of an Ecology-conducted or Ecology-supervised action. This opinion does not determine whether the action you performed is substantially equivalent. Courts make that determination. *See* RCW 70.105D.080 and WAC 173-340-545.

3. State is immune from liability.

The state, Ecology, and its officers and employees are immune from all liability, and no cause of action of any nature may arise from any act or omission in providing this opinion. *See* RCW 70.105D.030 (1) (i).


Mr. Michael Chun
June 25, 2015
Page 7

Contact Information

Thank you for choosing to clean up the Site under the Voluntary Cleanup Program (VCP). After you have addressed our concerns, you may request another review of your cleanup. Please do not hesitate to request additional services as your cleanup progresses. We look forward to working with you.

For more information about the VCP and the cleanup process, please visit our web site: www.ecy.wa.gov/programs/tcp/vcp/vcpmain.htm. If you have any questions about this opinion, please contact me by phone at (360) 407-6179 or e-mail at ptur461@ecy.wa.gov.

Sincerely,



Paul Turner, L.HG
SWRO Toxics Cleanup Program

PBT: knf

Enclosures: A -Description and Aerial Photo of the Site
 Fig. 1- June 18, 2007 Further Action Determination
 Fig. 2- Historical Soil Analytical Results for Petroleum Hydrocarbons and Lead
 Fig. 3-Analytical Results for Groundwater Samples
 Fig. 4- Site Plan Showing Monitoring Well and Soil Boring

By certified mail: 9171999991703489835872

cc: Mr. Han Kim
 Mr. Scott Rose, Ecology
 Ms. Dolores Mitchell, Ecology

Enclosure A

Description and Aerial Photo of the Site

The subject property is located at the northeast corner of the intersection of North Pacific Avenue and Cowlitz Way at 400 North Pacific Avenue in Kelso, Washington. The property is approximately 10,000 square feet and comprised of one building, two fuel pump islands, and an asphalt parking lot. The building is a 3,000 square-foot convenience store and deli. The area surrounding the subject property is comprised of a mix of commercial and residential development. Located immediately north of the property is Lee's Transmission. To the east is a parking lot and across Third Avenue is the Dahl Funeral Home. Located to the south, across Cowlitz Way, is the First Methodist Church and a vacant lot. Located to the west across North Pacific Avenue is commercial office space and residential properties. The property lies approximately 700 feet east of the Cowlitz River.

Based on prior research, Holts Quik Chek was listed at the subject property address since 1981. The property was listed as Short Stop gasoline station in 1979. From 1960 to 1979 it was listed as Partch's Mobil Service Station. Sanborn maps indicate that a gasoline station was present on the property as far back as 1927. The current owner purchased the property in 2006.



400 N Pacific Ave
400 N Pacific Ave, Kelso, WA 98626

Google Google





400 N Pacific Ave
400 N Pacific Ave, Kelso, WA 98626

Google Google



Figure 1

June 18, 2007

Further Action Determination

Ecology's Toxics Cleanup Program has reviewed the following information regarding the Site:

1. EMCON, Phase I, Environmental Site Assessment Report, Holt's Quik Chek Market, 400 North Pacific Avenue, Kelso, Washington, December 5, 1997.
2. EMCON, Phase II Site Investigation Report, Holt's Quik Chek Market, 400 North Pacific Avenue, Kelso, Washington, September 4, 1997.
3. EMCON, Additional Phase II Site Investigation, 2nd Quarter Groundwater Sampling, and Soil Vapor Extraction (SVE) Pilot Test Report, Holt's Quik Chek Market, 400 North Pacific Avenue, Kelso, Washington, November 26, 1997.
4. EMCON, Quarterly Groundwater Sampling Report – December 1997, Holt's Quik Chek Market, Kelso, Washington, April 28, 1998.
5. Farallon Consulting, L.L.C., Site Closure Report, Holt's Quik Chek Site, 400 North Pacific Avenue, Kelso, Washington, March 9, 2007.
6. Farallon Consulting, L.L.C., Final Quarter of Groundwater Monitoring, Holt's Quik Chek Site, 400 Pacific Avenue, Kelso, Washington, May 24, 2007.

The documents listed above will be kept in the Central Files of the Southwest Regional Office of Ecology (SWRO) for review by appointment only. Appointments can be made by calling the SWRO resource contact at (360) 407-6365.

The Site is defined by the extent of contamination caused by the following release(s):

- Petroleum hydrocarbons and associated constituents in Soil;
- Petroleum hydrocarbons and associated constituents in Ground Water.

The Site is more particularly described in Enclosure A to this letter, which includes a detailed Site diagram. The description of the Site is based solely on the information contained in the documents listed above.

Based on a review of the independent remedial action report and supporting documentation listed above, Ecology has determined that the independent remedial action(s) performed at the Site are not sufficient to meet the substantive

requirements contained in MTCA and its implementing regulations, Chapter 70.105D RCW and Chapter 173-340 WAC, for characterizing and addressing any of the contamination at the Site. Therefore, pursuant to WAC 173-340-515(5), Ecology is issuing this opinion that **further remedial action is necessary** at the Site under MTCA.

AGI Technologies, Inc. (AGI) constructed 12 borings (P1 through P12) at the property on March 27 and 28, 1997 (Figure 3). The borings were advanced to depths between 16 and 24 ft bgs. Ground water was encountered in the borings at depths between 16 and 24 ft bgs. Soil samples were collected continuously from a depth of approximately 2 ft bgs to the total depths of the borings. Water samples were collected from borings locations P1, P2, P6, P8, P9, and P10 (fine-grained materials prevented the collection of water samples from the other boreholes). Soil samples indicated elevated concentrations of total petroleum hydrocarbons (TPH) in boring locations P6, P8, P9, and P11. The sample taken at 16 ft bgs at P11 also contained elevated concentrations of benzene, toluene, ethylbenzene, and/or total xylenes (BTEX). This sample was also analyzed by EPA Method 7421 for total lead. Elevated concentrations of TPH and BTEX were detected in water from borehole locations P6, P8, P9, and P10.

In 1997, EMCON installed six monitoring wells (MW-1 through MW-6) on or adjacent to the Holt's Quik Chek property to depths of 28 to 31 ft bgs (Figure 2a). Soil samples were collected from the boreholes during construction. Table 1 shows the soil sample results for both the AGI investigation and the EMCON monitoring well construction.

The six wells have been monitored intermittently since 1997. Farallon Consulting, L.L.C. (Farallon) has performed quarterly monitoring and sampling of the wells since March 2004. Ground-water sampling results are shown in Table 2. The general water table ground-water flow direction on the property is to the west, and has been consistent throughout each monitoring session (Figure 4). Ground water was encountered between 15 and 25 ft bgs on site; however, ground water was 10 ft bgs for monitoring well MW-6. Monitoring well MW-6 is located cross-gradient from the site, but the ground-water elevation is 10 ft higher than the ground water on the site. In addition, EMCON noted that there was a gasoline station located in the southwest corner of the intersection of North Pacific Avenue and Cowlitz Way where monitoring well MW-6 was installed. Based on this, the ground-water contamination present in monitoring well MW-6 does not appear to be associated with the site. However, monitoring well MW-5 is located across North Pacific Avenue and down-gradient from the Holt's Quik Chek property. The ground-water analytical results from monitoring well MW-5 have exceeded Model Toxics Control Act (MTCA) Method A cleanup levels only once in the last six quarters. The last four quarterly monitoring events have indicated that all monitoring wells are below MTCA Method A cleanup levels.

Hart Crowser installed a biosparging system at the site in the spring of 2003. The system consisted of sparging air at approximately 0.1 cubic foot per minute (cfpm) in each of the eight sparge wells, which were designated as sparge wells SW-1 through SW-8 (Figure 5). Air was sparged into the subsurface water to raise dissolved oxygen levels to enhance the natural biodegradation processes. TPH and BTEX concentrations at the site were reduced to levels close to MTCA Method A cleanup levels as a result of the operation of the biosparge system. The biosparge system was operated until September 2005 when Farallon completed an in-situ chemical oxidation remediation using activated sodium persulfate, a chemical oxidant commonly used in the electronics industry for etching. According to Farallon, the oxidation potential expressed as electron volts is approximately 2.6 electron volts for activated sodium persulfate. The energy required to break carbon-hydrogen bonds for gasoline range organics (GRO) require about 1.0 electron volt to break, while carbon-carbon bonds require 2.5 electron volts or more to break. The carbon-carbon bonds making up the benzene take approximately 2.0 electron volts to break. The sodium persulfate was applied at the site with hydrogen peroxide as the activating agent to ensure sufficient oxidation potential to destroy GRO and BTEX constituents present. Two-hundred gallons of 5% sodium persulfate catalyzed with 10% hydrogen peroxide was injected into monitoring wells MW-2, MW-4, and MW-5. In addition, approximately 50 gallons of the activated sodium persulfate solution was injected into the eight sparge wells. The chemical oxidation was successful in removing the residual soil contamination that was impacting ground water based on analytical results obtained from four subsequent quarters of ground-water monitoring. No additional soil samples were collected after operating the biosparge system for four years and implementing the in-situ chemical oxidation remediation alternative. However, the ground-water analytical information obtained for the monitoring wells on the site since September 2005 indicates that residual soil concentrations that may be present are not causing adverse impacts to ground-water quality. The wells adjacent to and down-gradient of the underground storage tank (UST) source area have all indicated that TPH and associated constituent concentrations are below the MTCA Method A cleanup levels.

During the process of evaluating the extent of contamination for ground water, monitoring wells were constructed. However, down-gradient monitoring well MW-5 had contamination above MTCA Method A cleanup levels. The latest monitoring results showed concentrations below MTCA regulatory levels. However, contamination may be present down-gradient of monitoring well MW-5. Additional borings or wells should be constructed down-gradient of monitoring well MW-5 to determine if ground-water is present above MTCA Method A cleanup levels.

In addition, it is not apparent whether soil contamination still remains above MTCA Method A cleanup levels on the Holt's Quik Chek Market property. If soil remains it is possible that a restrictive covenant could be filed with the Cowlitz County Auditor's office. However, monitoring would be required to determine that soil contamination is not an issue for human health and the environment.

Apparently, a feasibility study was not conducted prior to Hart Crowser installing a biosparging system and operating the system. Farallon should also have provided a feasibility evaluation prior to conducting the chemical oxidation remediation using activated sodium persulfate.

A substantive requirement of MTCA is to conduct "sufficient investigations to characterize the distribution of hazardous substances present at the site, and threat to human health and the environment." [WAC 173-340-350] The contamination that defines the "site" may go onto the right-of-way and onto adjacent properties, as well as beneath buildings. The property interest may extend into the right-of-way to the centerline, but the "site" may extend further.

This characterization does not meet the substantive requirements of the Model Toxics Control Act (MTCA). Sufficient soil and ground-water samples will need to be collected to determine the full extent of contamination present throughout the site. Enough samples need to be collected to be certain that contamination is not affecting adjacent properties. Samples should be collected to the west of monitoring well MW-5 to determine the extent of contamination.

Once the full extent of contamination has been determined, it will be necessary to develop a feasibility study before the final cleanup, based on the information obtained in the characterization effort. This feasibility study should include all practicable methods of treatment in addressing the site cleanup. If no contamination is present west of the monitoring well MW-5 and contamination is not present in the soil, then the remediation is considered complete and no further action is required.

Any cleanup action selected for a site must meet some minimum requirements. These requirements include, but are not limited to the following:

- *Compliance with Cleanup Standards. If a cleanup alternative does not comply with cleanup standards, the alternative is considered an "interim action" and not a "cleanup action."*

- Compliance with Applicable State and Federal Laws. Cleanup levels and actions must comply with existing state or federal laws.
- Protecting Human Health and the Environment. The cleanup action selected must either reduce or remove (destroy) the contamination, restoring the site to cleanup levels, or contain the contamination in such a way that will minimize future exposure of humans and/or ecological receptors. Cleanup action alternatives that achieve cleanup levels at the applicable points of compliance and comply with applicable state and federal laws are presumed to be protective of human health and the environment.
- Providing for Compliance Monitoring. The cleanup action selected must provide for monitoring to verify that the cleanup action achieves cleanup or other performance standards and that the cleanup action remains effective over time.
- Using Permanent Solutions to the Maximum Extent Practicable. Permanent solutions (cleanup actions) are actions in which cleanup standards can be met without further action being required, such as monitoring or institutional controls. To select the most practicable permanent solution from among those cleanup action alternatives that are protective of human health and the environment requires conducting a disproportionate cost analysis. This analysis compares costs and benefits of alternatives and selecting the alternative whose incremental costs are not disproportionate to the incremental benefits. The comparison is quantitative, but is often qualitative and requires best professional judgment.
- Providing for a Reasonable Restoration Time Frame. Some cleanup methods, such as natural attenuation, can take years to restore a site, depending on the contaminants. When evaluating alternative methods of cleanup, the time it takes to restore the site will need to be considered. MTCA has certain criteria that need to be applied when evaluating restoration time frame.

Because contamination may remain in the ground water and in the soil that could be considered part of the Site, the feasibility study should address this contamination.

Should it be determined that a permanent cleanup action cannot be implemented, a disproportionate cost analysis shall be applied. The analysis shall compare costs and benefits of the cleanup action alternatives evaluated in the feasibility study. The costs and benefits to be compared and the disproportionate cost analysis are described in MTCA WAC 173-340-360(3)(e) and (f). It may also be necessary to determine whether a cleanup action provides for a reasonable restoration time frame as described in WAC 173-340-360(4).

*An attorney assigned to Ecology from the Attorney General's Office (AGO) has provided opinions concerning property abutting right-of-ways in the State of Washington. The general rule in Washington is that "The conveyance of land bounded by or along a highway carries title to the center of the highway unless there is something in the deed or surrounding circumstances showing an intent to the contrary." *Christian v. Purdy*, 60 Wash. App. 798, 801 (1991). This rule applies to streets and alleys as well as highways. *Id.* Further, "[d]eeds may expressly exclude streets, but, unless they do, the implication is that the street is included." *Bradley v. Spokane & Inland Empire R.R.*, 79 Wash. 455, 460 (1914). Any contamination that will be left in place on the property and/or within the right-of-way will require a restrictive covenant that will be placed there by the person "who has been named as a potentially liable person or who has not been named as a potentially liable person by the department but meets the criteria in RCW 70.105D.040 for being named a potentially liable person." The covenant shall be executed by the property owner and recorded with the register of deeds for the county in which the site is located. Therefore, it is important to determine the full extent of contamination and responsibilities for filing a restrictive covenant if contamination is to remain, either in the soil and/or the ground water within the right-of-way, or beneath a building.*

All sampling data shall be submitted to Ecology according to the requirements of WAC 173-340-840(5), in printed form and in electronic form capable of being transferred into the Department's data management system. Electronic data submittal requirements are provided at <http://www.ecy.wa.gov/eim/>.

Please note that this opinion is based solely on the information contained in the documents listed above. Therefore, if any of the information contained in those documents is materially false or misleading, then this opinion will automatically be rendered null and void.


The state, Ecology, and its officers and employees make no guarantees or assurances by providing this opinion, and no cause of action against the state, Ecology, its officers or employees may arise from any act or omission in providing this opinion.

Mr. Han Kim
June 18, 2007
Page 8

Again, Ecology appreciates your initiative in conducting independent remedial action and requesting technical consultation under the VCP. As the cleanup of the Site progresses, you may request additional consultative services under the VCP, including assistance in identifying applicable regulatory requirements and opinions regarding whether remedial actions proposed for or performed at the Site meet those requirements.

If you have any questions regarding this opinion, please contact me at (360) 407-6267.

Sincerely,



Charles S. Cline
SWRO Toxics Cleanup Program

CSC/ksc:Holt's Quik ChekFA

Enclosures: Enclosure A: (text + 6 figures)
2 Tables

Cc: Mr. Terry Montoya, P.E., Project Manager, Farallon Consulting, L.L.C.
Mr. Paul Turner, Ecology
Mr. Robert Warren, Ecology

Figure 2

Historic Soil Analytical Results For Petroleum Hydrocarbons and Lead

Table 1
Historic Soil Analytical Results for Petroleum Hydrocarbons and Lead
 Holt's Quik Chek Market
 400 North Pacific Avenue
 Kelso, Washington
 Farallon PN: 359-001

Sample Identification	Date Sampled	Sampled By	Depth (ft) ¹	Soil Analytical Results (milligrams per kilogram)									
				GRO ²	DRO ³	ORO ³	Benzene ⁴	Toluene ⁴	Ethylbenzene ⁴	Xylenes ⁴	Total Lead ⁵		
P1-22	3/27/1997	AGI	22.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P2-18	3/27/1997	AGI	18.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P3-12	3/27/1997	AGI	12.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P4-18	3/27/1997	AGI	18.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P5-12	3/27/1997	AGI	12.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P6-20	3/27/1997	AGI	20.0	1900	-	-	<0.05	<0.1	<0.1	1.2	<8	<8	-
P6-25	3/27/1997	AGI	25.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P7-12	3/27/1997	AGI	12.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P7-20	3/27/1997	AGI	20.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P8-20	3/28/1997	AGI	20.0	200	-	-	<0.05	0.2	0.4	0.4	7.8	7.8	-
P8-16	3/28/1997	AGI	16.0	250	-	-	<0.05	0.1	0.4	0.4	8.4	8.4	-
P8-24	3/28/1997	AGI	24.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P9-12	3/28/1997	AGI	12.0	710	-	-	<0.05	<0.1	<0.1	1.5	3.7	3.7	-
P9-28	3/28/1997	AGI	28.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P12-12	3/28/1997	AGI	12.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P10-24	3/28/1997	AGI	24.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P11-16	3/28/1997	AGI	16.0	12,000	-	-	8.7	220	110	110	760	760	-
P11-24	3/28/1997	AGI	24.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P12-12	3/28/1997	AGI	12.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
P12-20	3/28/1997	AGI	20.0	<5	-	-	<0.05	<0.1	<0.1	<0.1	<0.1	<0.1	-
MW-1-14	6/24/1997	EMCON	14-15.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
MW-2-9.5	6/24/1997	EMCON	9.5-11	5,760	334*	ND	2.4	6.7	25	25	23	23	ND
MW-2-27	6/24/1997	EMCON	27-27.5	436	ND	ND	ND	ND	0.8	0.8	1.6	1.6	ND
MW-3-19	6/25/1997	EMCON	19-20.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
MW-4-19	6/25/1997	EMCON	19-20.5	1,280	209*	ND	ND	0.3	0.5	0.5	2	2	ND
MW-4-21.5	6/25/1997	EMCON	21.5-23	12	ND	ND	ND	ND	ND	ND	ND	ND	ND
SB-5-14.5	9/26/1997	EMCON	14-15.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
SB-6-7	9/26/1997	EMCON	7.0	2,270	37.2	ND	1.21	1.92	9.09	9.09	4.97	4.97	ND
SB-6-19.5	9/26/1997	EMCON	19.5-20	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
MTCVA Method A Cleanup Levels for Soil⁶				30	2,000	2,000	0.03	7	6	6	9	9	250

NOTES:
 Results in **BOLD** denote concentrations above MTCVA Method A cleanup levels.
 < denotes result is less than laboratory practical quantitation limit or analyte not detected at or above the reporting limit listed.
¹Depth in feet below ground level.
²Analyzed by Northwest Method WTPH-G.
³Analyzed by Northwest Method WTPH-D (extended).
⁴Analyzed U.S. Environmental Protection Agency (EPA) Method 5030/8020.
⁵Analyzed by EPA Method 6010A.
⁶Washington State Department of Ecology Model Toxics Control Act Cleanup Regulation (MTCVA) Method A Soil Cleanup Level, Table 740-1 of Section 900 of Chapter 173-540 of the Washington Administrative Code, as amended February 2001.

- = not analyzed
 ND = not detected
 * = Detected hydrocarbons in the diesel range appear to be due to the overlap of gasoline-range hydrocarbons.
 DRO = total petroleum hydrocarbons (TPH) as diesel-range organics
 GRO = TPH as gasoline-range organics
 ORO = TPH as heavy oil-range organics

Figure 3

Analytical Results For Groundwater Samples

Table 2
Analytical Results of Groundwater Samples
Holt's Quik Check
Kelso, Washington
Farallon PN: 359-001

Monitoring Well Identification	Sample Identification	Date Sampled	Sampled By	Analytical Results						
				Benzene ¹	Toluene ¹	Ethylbenzene ¹	Total Xylenes ¹	GRO ²	DRO ³	ORO ³
MW-3	HQM-062797-2	6/27/1997	EMCON	0.8	<0.50	<0.50	<1.0	90.7	<250	<500
	MW-3-092697	9/26/1997	EMCON	<0.50	<0.50	<0.50	<1.0	<80	<250	<500
	MW-3-121597	12/15/1997	EMCON	1.3	<0.50	<0.50	<1.0	<80	<250	<500
	MW-3-031398	3/13/1998	EMCON	<0.50	<0.50	2.82	5.18	143	<250	<500
	061198-MW-3	6/11/1998	EMCON	<0.50	<0.50	<0.50	<1.0	<80	<250	<500
	MW-3	3/13/2004	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	MW3-122304	12/23/2004	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	MW3-031705	3/17/2005	Farallon	<0.50	<0.50	<0.50	<1.0	<80	—	—
	MW3-062805	6/28/2005	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	MW3-092805	9/28/2005	Farallon	<1.0	<1.0	<1.0	<3.0	<100	—	—
MW-4	MW3-122905	12/29/2005	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	MW-3-032406	3/24/2006	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	HQM-062797-4	6/27/1997	EMCON	1.6	<0.50	0.67	<1.0	691	<250	<500
	MW-4-092697	9/26/1997	EMCON	<0.50	<0.50	<0.50	<1.0	255	<250	<500
	MW-4D-092697	9/26/1997	EMCON	<0.50	<0.50	<0.50	<1.0	190	<250	<500
	MW-4-121597	12/15/1997	EMCON	3.78	<0.50	<0.50	<1.0	331	<250	545
	MW-4D-121597	12/15/1997	EMCON	3.76	<0.50	<0.50	<1.0	289	<250	<500
	MW-4-031398	3/13/1998	EMCON	<0.50	<0.50	1.74	3.26	124	<250	<500
	061198-MW-4	6/11/1998	EMCON	<0.50	<0.50	<0.50	<1.0	205	<250	<500
	MW4-122304	12/23/2004	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
MW-4	MW4-031705	3/17/2005	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	MW4-062805	6/28/2005	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	MW4-092805	9/28/2005	Farallon	<1.0	<1.0	<1.0	<3.0	<100	—	—
	MW4-122905	12/29/2005	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	MW-4-032406	3/24/2006	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	MW-4-092106	9/21/2006	Farallon	<0.500	<0.500	<0.500	<1.00	<50.0	—	—
MTCA Method A Cleanup Levels for Groundwater ⁴				5	1,000	700	1,000	800	500	500

Table 2
Analytical Results of Groundwater Samples
Holt's Quik Check
Kelso, Washington
Farallon PN: 359-001

Monitoring Well Identification	Sample Identification	Date Sampled	Sampled By	Analytical Results						
				Benzene ¹	Toluene ¹	Ethylbenzene ¹	Total Xylenes ¹	GRO ²	DRO ³	ORO ³
MW-1	HQM-062797-1	6/27/1997	EMCON	<0.50	<0.50	<0.50	<1.0	<80	<250	<500
	MW-1-092697	9/26/1997	EMCON	<0.50	<0.50	<0.50	<1.0	<80	<250	<500
	MW-1-121597	12/15/1997	EMCON	<0.50	<0.50	<0.50	<1.0	<80	<250	<500
	MW-1-031398	3/13/1998	EMCON	<0.50	<0.50	0.64	<1.0	<80	<250	<500
	061198-MW-1	6/11/1998	EMCON	<0.50	<0.50	<0.50	<1.0	<80	<250	<500
	MW1-122304	12/23/2004	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	MW1-031705	3/17/2005	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	MW1-062805	6/28/2005	Farallon	<0.50	<0.50	<0.50	<1.0	<50	—	—
	HQM-062797-3	6/27/1997	EMCON	20.8	15.7	142	287	4,880	268	<500
	MW-2-092697	9/26/1997	EMCON	25.5	22.3	174	372	7,750	<250	<500
MW-2	MW-2-121597	12/15/1997	EMCON	33.3	20.5	238	461	8,650	<250	<500
	MW-2-031398	3/13/1998	EMCON	3.32	6.46	103	202	3,100	<250	<500
	MW-2-031398-D	3/13/1998	EMCON	2.72	5.74	94	181	2,860	<250	<500
	061198-MW-2	6/11/1998	EMCON	4.12	3.92	106	178	4,090	291	<500
	061198-MW-20	6/11/1998	EMCON	6.06	9.4	117	195	4,560	282	<500
	MW-2	3/13/2004	Farallon	12.2	1.89	15.1	7.47	2,560	—	—
	MW2-081904	8/19/2004	Farallon	4.4	1.56	7.45	4.06	1,110	—	—
	MW2-122304	12/23/2004	Farallon	4.54	0.507	1.56	1.15	678	—	—
	MW2-031705	3/17/2005	Farallon	2.25	<0.50	1.62	<1.0	506	—	—
	MW2-062805	6/28/2005	Farallon	7	<0.50	0.866	<1.0	940	—	—
MW-2	MW2-092805	9/28/2005	Farallon	11.5	<1.0	5.06	<3.0	1,060	—	—
	MW2-122905	12/29/2005	Farallon	0.908	<0.50	<0.50	<1.0	108	—	—
	MW2-032406	3/24/2006	Farallon	3.54	<0.50	<0.50	<1.0	362	—	—
	MW2-062906	6/29/2006	Farallon	<0.500	<0.500	<0.500	<1.00	219	—	—
	MW-2-092106	9/21/2006	Farallon	2.95	<0.500	<0.500	<1.00	248	—	—
	MTCA Method A Cleanup Levels for Groundwater ⁴				5	1,000	700	1,000	800	500

Table 2
Analytical Results of Groundwater Samples
Holt's Quik Check
Kelso, Washington
Farallon PN: 359-001

Monitoring Well Identification	Sample Identification	Date Sampled	Sampled By	Analytical Results							
				Benzene ¹	Toluene ¹	Ethylbenzene ¹	Total Xylenes ¹	GRO ²	DRO ³	ORO ³	
MW-5	MW-5-092697	9/26/1997	EM/CON	14.5	1.07	20.8	17.7	2,740	<250	<500	
	MW-5-121597	12/15/1997	EM/CON	22.7	3.06	0.93	<1.0	2,510	<250	<500	
	MW-5-031398	3/13/1998	EM/CON	4.48	<0.50	9.03	1.47	1,080	<250	<500	
	061198-MW-5	6/11/1998	EM/CON	12.1	0.66	3.18	<1.0	1,730	<250	<500	
	MW-5-031705	3/17/2005	Farallon	7.48	0.983	1.77	3.65	1,190	—	—	
	MW-5-062805	6/28/2005	Farallon	4.67	<0.50	12.3	3.18	2,140	—	—	
	MW-5-092805	9/28/2005	Farallon	2.19	<1.0	<1.0	<3.0	<100	—	—	
	MW-5-122905	12/29/2005	Farallon	<5.0	<5.0	145	55	3,530	—	—	
	MW-5-032406	3/24/2006	Farallon	2.91	<0.50	0.92	1.27	373	—	—	
	MW-5-062906	6/29/2006	Farallon	<0.500	0.576	<0.500	<1.00	710	—	—	
MW-6	MW-5-092106	9/21/2006	Farallon	1.11	0.831	1.90	<1.00	180	—	—	
	MW-6-092697	9/26/1997	EM/CON	31.1	2.42	14	9.55	2,070	<250	<500	
	MW-6-121597	12/15/1997	EM/CON	210	6.32	<1.0	3.38	416	<250	<500	
	MW-6-031398	3/13/1998	EM/CON	244	<2.50	4.76	<5.0	<400	284	<500	
	061198-MW-6	6/11/1998	EM/CON	500	8.35	26	<5.0	750	354	<500	
	MW-6-081904	8/19/2004	Farallon	3.13	0.693	<0.50	<1.0	<50	—	—	
MTCA Method A Cleanup Levels for Groundwater ⁴				5	1,000	700	1,000	800	500	500	

NOTES:

Bold result exceeds Washington State Model Toxics Control Act Cleanup Regulation Method A groundwater cleanup level.

< denotes result is less than the laboratory practical quantitation limit listed or analyte not detected at or above the reporting limit.

— denotes sample not analyzed for specific analyte.

¹ Analyzed by U. S. Environmental Protection Agency Method 8021B.

² Analyzed by Northwest Method NWTPH-G.

³ Analyzed by Northwest Method NWTPH-Dx.

⁴ Model Toxics Control Act Cleanup Regulation Method A cleanup levels for groundwater, Table 720-1 of Section 900 of Chapter 173-340 of the Washington Administrative Code, as amended February 2001.

DRO = total petroleum hydrocarbons (TPH) as diesel-range organics

GRO = TPH as gasoline-range organics

ORO = TPH as oil-range organics

Table 2 - Summary of Groundwater Analytical Results
Holt's Quik Check
Kelso, Washington


Sample Number	Date Collected	Volatile Organic Compounds (µg/l)				Gasoline (µg/l)
		Benzene	Toluene	Ethylbenzene	Xylenes	
MW-1	10/7/2014	<1.0	<1.0	<1.0	<3.0	<100
	1/20/2015	<1.0	<1.0	<1.0	<3.0	160
	4/22/2015	<1.0	<1.0	<1.0	<3.0	<100
MW-2	10/7/2014	<1.0	<1.0	<1.0	<3.0	<100
	1/20/2015	<1.0	<1.0	<1.0	<3.0	<100
	4/22/2015	<1.0	<1.0	<1.0	<3.0	140
MW-3	10/7/2014	<1.0	<1.0	<1.0	<3.0	<100
	1/20/2015	<1.0	<1.0	<1.0	<3.0	<100
	4/22/2015	<1.0	<1.0	<1.0	<3.0	<100
MW-4	10/7/2014	<1.0	<1.0	<1.0	<3.0	<100
	1/20/2015	<1.0	<1.0	<1.0	<3.0	<100
	4/22/2015	<1.0	<1.0	<1.0	<3.0	<100
MW-5	10/7/2014	<1.0	<1.0	<1.0	<3.0	<100
	1/20/2015	<1.0	<1.0	<1.0	<3.0	180
	4/22/2015	<1.0	<1.0	<1.0	<3.0	<100
POL (µg/l)		1.0	1.0	1.0	3.0	100
MTCA Method A Cleanup Levels (µg/l)		5.0	1,000	700	1,000	1,000 *

Notes:
 µg/l = micrograms per liter
 -- Not analyzed for constituent
 < Not detected at the listed laboratory detection limits
 POL = Practical Quantification Limit (Laboratory detection limit)
 Red Bold indicates the detected concentration exceeds Ecology MTCA Method A cleanup level
 Bold indicates the detected concentration is below Ecology MTCA Method A cleanup levels
 * TPH-Gasoline Cleanup Level with no presence of Benzene anywhere at the Site

Figure 4

Site Plan Showing

Monitoring Well and Soil Boring Locations



LEGEND

- MW-6 MONITORING WELL (EMCON 1997)
- P12 PUMP BORING (EMCON 1997)
- SITE BOUNDARY
- PUMP ISLAND
- UNDERGROUND STORAGE TANK
- CATCH BASIN

SOURCE: BASE MAP PREPARED FROM A DRAWING PROVIDED BY EMCON ENTITLED "PROPOSED MONITORING WELL LOCATIONS" DATED AUGUST 1997.



FIGURE 3

SITE PLAN SHOWING SOIL BORING AND MONITORING WELL LOCATIONS
 HOLT'S QUIK CHEK
 400 NORTH PACIFIC AVENUE
 KELSO, WASHINGTON
 FARALLON P.I.: 359-001

FARALLON CONSULTING
 975 5th Avenue Northwest
 Issaquah, WA 98027

Drawn By: DEW | Checked By: TM | Date: 2/7/07 | Disk Reference: 359001

