

INITIAL INVESTIGATION FIELD REPORT

ERTS # <u>547010</u> County <u>King</u> Parcel # <u>3225059061</u> FS ID # 55481441

SITE INFORMATION				
Site Name (e.g., Co. name over door):	Site Address (including City and Zip+4):	Site Phone:		
Hilton Hotel	300 112 th Avenue SE	(425)455-1300		
	Bellevue, WA 98004			
Site Contact and Title (if any):	Site Contact Address (including City and Zip+4) if any:	Site Contact Phone:		
Harry Goren, PBS Environmental	2517 Eastlake Avenue East, Ste 100	(206)233-9639		
Ray, Hotel Facilities Engineer	Seattle, WA, 98102	FAX(206)762-4780		
Site Owner:	Site Owner Address (including City and Zip+4):	Site Owner Phone:		
PD Bellevue Associates LLC		() - () -		
Site Owner Contact (if any):	Site Owner Contact Address (including City and Zip+4) if any:	Owner Contact Phone: () - () -		
Previous/Additional Site Owner(s):	Previous/Additional Site Owner(s) Address (including City and Zip+4):	Phone: () - () -		
Alternate Site Names:	Comments:	Is property > 10 acres?		
Formerly Double Tree Hotel		Yes 🗌 🛛 No 🖾		
Formerly Red Lion Motor Inn		9.55 acres		

Location: Quarter-Quarter: N1/2, SW, NE Section: 32 Township: 25 Range: 5					
Latitude: 47.60711					
Longitude: -122.19073					

INSPECTION INFORMATION

Inspection Date: 07/2	7/2010 Time: 12	2:00 □am ⊠pm	Entry Notice: Announced 🛛 Unannounced 🗌]
Photographs?	Yes 🖂	No 🗌	Weather: Clear 🖂 Rain 🗌 Temperature: 82	2 ° F
Samples?	Yes 🗌	No 🖂	Wind Direction: calm Wind Speed:	

RECOMMENDATION

No Further Action (due to):		ISIS ACTIONS (check all that apply):
Release or threatened release does not pose a threat		Site Hazard Assessment (MTCA List)
No release or threatened release		LUST List
Educational mailing		RCU (Reported Cleaned up)
Refer to program/agency ()		Comments:
Independent cleanup action completed (i.e., remediated)	\square	

COMPLAINT (Brief summary of ERTS):

In February 1997, analytical results from a groundwater sample collected from the pit during removal of a 430gallon emergency power generator (EPG) UST indicated diesel range petroleum impacts above MTCA Method A cleanup levels.

SITE STATUS (Brief summary of site condition(s) after investigation):

Reported cleaned up. File was reviewed in 2006 by ECY LUST staff and final cleanup report was submitted.

Investigator: Audrey Heisey

Date Submitted: 10/19/2010

OBSERVATIONS

Description:

In February 1997 during removal of the emergency power generator UST at the site a groundwater sample was collected from the tank pit. The sample name is "MW-1" but was collected from the tank pit and was not a monitoring well. "MW-1" reported diesel and heavy oil range above MTCA (2420ppb and 9390ppb). Contractors removed 1.71 tons of contaminated soils and properly disposed. They then installed well MW-1 near the former UST pit sometime between February 1997 and February 1998. Well MW-1 was sampled February 1998 with analytical results below detection for diesel and oil range.

In 2005 a request was submitted by Mactec (consultant) requesting what is needed for No Further Action determination and a VCP application was submitted for the site. Ecology site manager reviewed the site (Dale Myers). He indicated the site was not eligible under MTCA. His recommendation was a referral to the Initial Investigation unit and issuance of an ERTS report.

July 2010, well MW-1 was sampled in association with the removal of an unregulated heating oil UST (HOT) with analytical results below detection for diesel and oil range hydrocarbons. GW-1 was collected from the 2010 HOT tank removal located about 20 feet downgradient of the former emergency power generator. Additionally, GW-1 was reported below detection for diesel and oil range hydrocarbons.

All soil samples were reported below MTCA Method A. Well MW-1 sample collected 2/23/1998 was reported below detection and well MW-1 and GW-1 samples collected 7/23/2010 were reported below detection.

An II was conducted for this site in association with a LUST database migration. Current review of the available data indicates since groundwater and soil are not impacted above MTCA and independent cleanup action was completed, the site is not a MTCA site and no further action is needed. See map attached. Description of past practices likely to be responsible for contamination:

ACTIVITIES OR PRACTICES RESPONSIBLE FOR CONTAMINATION:																			
Spill Pesticide dispo Landfill Drums Other – Descri							l	_UST Fank mproj mproj											
Are discharges per	nitted	l? (if y	es, de	escrib	e)	No Yes		Stan	dard I	ndust	rial C	odes	(if kno	own):	7011	-01			
CONTAMINANT(S)																		
AFFECTED MEDIA	CONTAMINANTS (#1-19: See contaminants key below) Enter letter designating status of contaminant: C = Confirmed (above MTCA Method A); S = Suspected; R = Remediated; B = Below MTCA Method A																		
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
Ground Water							R												
Surface Water																			
Drinking Water																			
Soil							В												
Sediment																			
Air																			
1 Base/neutral/acid	organ	nics			8 PI	henolic	comp	bounds	5	•			15 Co	onvent	ional o	contarr	ninants	s, orga	nic
2 Halogenated orga	anic co	mpou	nds		9 N	on-halo	ogena	ted so	lvents				16 Co	onvent	ional o	contam	ninants	s, inorg	ganic
3 Metals - Priority p	ollutar	nts		10 Dioxin					17 Asbestos										
4 Metals - Other			11 Polynuclear aromatic hydrocarbons (PA					AHs)	18 Ar	senic									
5 Polychlorinated b	Polychlorinated biPhenyls (PCBs) 12 Reactive				ve wastes 19 Methyl Tert-Butyl Ether (MTBE)														
6 Pesticides	les 13 Co				3 Corrosive wastes														
7 Petroleum produc	cts				14 R	adioad	ctive w	astes											

SITE INFORMATION				
Soil type Urban fill		Slope slight slope to	the east towa	rd retention pond
Site vegetation/cover pre	sent:			
Forest		Pasture/open field]
Bare soil		Wetlands]
Brush		Pavement	\boxtimes]
Landscaped	\boxtimes	Surface water	\boxtimes]
Other – Describe:				
<u> </u>				
Are there any drinking wate	r systems affected?		🗌 Yes	🛛 No
Municipal, private, or b	oth? (Circle)			
How many people are	estimated to be affected?			
Is there a potential for a rel	🗌 Yes	🖾 No		
Are there monitoring wells i		🗌 Yes	🛛 No	
Are there dry wells in the vi	cinity?		🗌 Yes	🖾 No

CONTAMINANT PATHWAYS AND TARGETS

	Ingestion	Inhalation	Contact
Ground Water			
Surface Water			
Drinking Water			
Soil			
Sediment			
Air			
Targets Possible:		Residential	
Human, adult		Industrial	
Human, children		Commercial	\boxtimes
	(See WARM Scoring Manual for		If yes, describe:
General Comments:			

SITE MAP/DIAGRAM

Site Name: Red Lion Inn. See also maps included with consultant reports under Red Lion Bellevue LUST 418509 and assessors map included with this report.



Looking north at the property from the southeast portion of the property toward the former EPG UST location. The former UST was located approximately below the AST shown at the right side of the enclosure.



View looking east toward hotel green space. The HOT and heavy equipment used to remove the HOT are visible on the left side of the frame. The former UST enclosure is on the left (just outside the frame).



View looking west toward hotel parking lot. The former UST enclosure is on the right (just outside the frame).

