

**Project Status Report II
Environmental Site Assessment
Old Port Blakely Mill
Bainbridge Island, Washington**

September 1992

Port Blakely Tree Farms
500 Union Street, Suite 830
Seattle, WA 98101



SHANNON & WILSON, INC.

400 N. 34th St., Suite 100
P.O. Box C-30313
Seattle, WA 98103
(206) 632-8020

September 16, 1992

Port Blakely Tree Farms
500 Union Street, Suite 830
Seattle, Washington 98101

**DRAFT
REVISIONS**

Attn: Mr. Charles Wilson

**RE: PROJECT STATUS REPORT II: ENVIRONMENTAL SITE ASSESSMENT
OLD PORT BLAKELY MILL SITE, BAINBRIDGE ISLAND, WASHINGTON**

Shannon & Wilson, Inc. (S&W) has performed an environmental site assessment in the vicinity of the Old Port Blakely Mill Site, Port Blakely, Bainbridge Island, Washington as shown in Figures 1, 2, and 3. Groundwater, test pit soil samples, and former log pond sediment sampling locations are identified in Figure 3, Exploration Locations. Field services were rendered during April 3rd through July 14, 1992 as outlined in the proposed scope modifications section of S&W's Project Status Report, dated March 1991.


You will find the analytical results reported for selected soil, groundwater, and sediment samples in Tables 1 through 6 correlated to specific sampling areas immediately surrounding Port Blakely Harbor.

Upon your review, Shannon & Wilson, Inc. will address each comment or question and submit a final report.


At your convenience, please contact Kimberly Fenske or Frank Pita at (206) 632-8020.

Respectfully,

SHANNON & WILSON, INC.



Kimberly A. Fenske
Geoenvironmental Engineer



Frank W. Pita, P.E. P.G.
Vice President Environmental Services

Enclosure: Project Status Report II

T-1198-02

EXECUTIVE SUMMARY

This report is a continuation of an environmental site assessment at Port Blakely Harbor, Bainbridge Island, Washington, which includes limited soil and groundwater sampling activities focused on the former mill site area. The purpose of this work was to assess levels of specific metals reported in S&W's March 1991, Project Status Report.

Four additional field activities were recommended in the "1991 report" to further assess metal concentration levels in groundwater and soil matrices in the immediate vicinity of the former mill site. These recommended activities are the subject of this report. State and federal regulatory levels are applied to the analytical results for illustrative comparisons and should not be construed as quantitative comparisons, or a statement of legally applicable standards.

The results indicate that the metal concentration levels in soil, sediment, and groundwater samples are below stringent cleanup levels promulgated by the state of Washington's Model Toxics Control Act (MTCA) and Sediment Quality Standards. Soil, groundwater, and sediment analytical results are listed in Tables 1, 2, and 5, respectively. The toxicity characteristic leachate procedure (TCLP) has been applied to soil samples from test pit nos. 1 and 10 with concentration level results below federal regulatory levels as listed in Table 4. Test pit and sediment samples reported in the "1991 report" are included for comparison in Table 3 entitled, Test Pit Soil Sample Comparisons and Table 6 entitled, Log Pond Sediment Comparisons.

TABLE OF CONTENTS

	<u>Page</u>
EXECUTIVE SUMMARY	
1.0 INTRODUCTION	1
2.0 PROPERTY LOCATION	1
3.0 ENVIRONMENTAL SITE ASSESSMENT	1
3.1 Project Status Report, March 1991	1
3.2 Project Status Report II: Field Screening Activities	2
3.2.1 Metal Concentrations in Groundwater and Soil	2
3.2.2 Old Mill Site Test Pit Soil Samples	3
3.2.3 Toxicity Characteristic Leachate Procedure	4
3.2.4 Former Log Pond Sediment Sampling	4
3.3 Discussion of Field Screening Analyses	4
4.0 CONCLUSIONS	5
5.0 LIMITATIONS	6
REFERENCES	7

LIST OF TABLES

Table No.

1	Test Pit Soil Results
2	Groundwater Sample Results
3	Test Pit Soil Sample Comparisons
4	Toxicity Characteristic Leachate Procedure
5	Log Pond Sediment Results
6	Log Pond Sediment Comparisons

LIST OF FIGURES

Figure No.

1	Vicinity Map
2	Site and Exploration Plan
3	Exploration Locations

TABLE OF CONTENTS (cont.)

LIST OF APPENDICES

- APPENDIX A - LOGS OF FIELD TEST PITS
- APPENDIX B - LABORATORY ANALYTICAL DOCUMENTATION
- APPENDIX C - CHAIN-OF-CUSTODY FORMS

PROJECT STATUS REPORT II
ENVIRONMENTAL SITE ASSESSMENT
OLD MILL SITE, PORT BLAKELY HARBOR
BAINBRIDGE ISLAND, WASHINGTON

1.0 INTRODUCTION

This report is a continuation of an environmental site assessment at Port Blakely Harbor, Bainbridge Island, Washington, which includes limited soil and groundwater sampling activities focused on the former mill site area. The purpose of this work was to assess levels of specific metals reported in S&W's March 1991, Project Status Report. The previous report will be referred to as the "1991 report" throughout the following discussions.

2.0 PROPERTY LOCATION

Port Blakely Harbor is located near the southeastern corner of Bainbridge Island, Washington, as illustrated in the Vicinity Map, Figure 1 and the Site and Exploration Plan, Figure 2. The property occupies approximately 1,060 acres encircling Port Blakely Harbor as delineated in Figure 1. Environmental site assessment activities were focused on the former millsite area primarily located northeast of the former log pond area or western end of Port Blakely Harbor.

3.0 ENVIRONMENTAL SITE ASSESSMENT

3.1 Project Status Report, March 1991

Shannon & Wilson's "1991 report" indicated that total metal levels were detected in soil and groundwater in the vicinity of the old mill site area and were detected higher than comparable Port Blakely sediments. At the time of the "1991 report", total petroleum hydrocarbons were not detected in any collected samples of soil or groundwater.

The "1991 report" proposed additional work to establish concentration levels of inorganic metals in the immediate mill site area and to determine if the detected levels of arsenic and lead (one sample) were an artifact or representative of general conditions. The present report, Project Status Report II coupled with "1991 report" data results, presents inorganic metal concentrations that have been identified in the former mill site area and Port Blakely Harbor sediments to aid in the assessment of inorganic metal concentration levels in the old mill site vicinity.

In addition, this Project Status Report II compares the sampled concentration levels to the most conservative, potentially applicable, regulatory standards in the state of Washington along with other risk-based standards. The regulations under the State Model Toxics Control Act (MTCA) provide three methods of determining cleanup standards. The Method "A" standards provide the most conservative cleanup level. The Method "A" level for arsenic is based on the Department of Ecology's identification of the background levels in the State Method "A" levels are used here for purposes of comparison to the states most stringent standard.

3.2 Project Status Report II: Field Screening Activities

The Project Status Report II's primary field objective consisted of determining if there was potential risk, as determined by the toxicity characteristic leachate procedure (TCLP), associated with the levels of contamination (i.e., arsenic and lead in groundwater samples) detected and reported in the "1991 report". Soil, groundwater, and sediment samples were taken as described in the four subsections below.

3.2.1 Metal Concentrations In Groundwater and Soil

Three groundwater samples were obtained from the former mill site area at the west coastal end of Port Blakely Harbor as indicated in Figure 3. Well points were driven to 10, 8, and 14-foot depths for wells designated, W1, W2, and W3, respectively. The total metal (unfiltered) analytical results reported for the three groundwater samples were compared to samples obtained for the "1991 report" and available regional (Kitsap county) information concerning the background concentration of metals in groundwater in the Port Blakely area. Analytical results and published Kitsap County data are collated in Table 2 entitled, Groundwater Sample Results, and are for illustrative comparisons.

The Kitsap County groundwater data for shallow wells were far below state and federal regulatory levels. The three groundwater samples collected from the former mill site area were below the state of Washington's MTCA cleanup levels for groundwater.

During field sampling, salt water was evident in the first two groundwater samples (T1198-WP001-100-GW-0 and T1198-WP002-101-GW-0 (W1 and W2)), but not apparent for the third sample designated, W3. Since arsenic is a naturally occurring constituent in freshwater and saltwater, a water sample (T1198-BG004-103-GW-0) from Port Blakely Harbor's former

log pond area was retrieved to serve as a relative metal concentration comparison for the three groundwater samples as listed in Table 3.

A soil sample (T1198-BG-012-SL-0, Table 1) was collected from test pit No. BG (Figure 3) upgradient from the historic mill site area to further assess metal concentration levels. As a comparison, total metal concentrations in the upgradient soil sample were below or equal (Cadmium, 2 ppm.) to the State of Washington's Model Toxic Control Act, Method "A" cleanup levels for soil.

Several pieces of "slag-like" material were discovered during a low tide interval in the former log pond area near the west end of Port Blakely Harbor. The historic use of foundry slag as ship ballast is inferred and its occasional presence may provide the source for the low levels of inorganic metals.

3.2.2 Old Mill Site Test Pit Soil Samples

Test pit soil samples were obtained in close proximity to previous test pit soil sample locations used for the "1991 report". Previous test pit locations were easily identifiable due to surface disturbances and backfill settlement depressions. Test pit locations closely correlated with previous test pit locations to adhere to an imposed protocol of consistent soil sampling approximately one foot above the quasi-static water level in the test pit. In S&W's opinion, this would enable the determination of appreciable change(s) in metal levels and toxicity characteristic leachate procedure results. Observational care was taken to locate the test pits outside the influence of the previous test pit disturbances, but close enough to observe similar undisturbed soil layers as illustrated in the field correlated Logs of Field Test Pits, Appendix A. The field test pit logs were produced during compilation of the "1991 report" and were used as field references.

Soil samples generally consisted of brown, gravelly, silty, fine to medium sand with intermittent debris of red brick fragments, sawdust, and burned wood material. Test pit soil samples were retrieved during a high interval tide cycle. During test pit excavation activities, a waiting period provided time for the water entering the pit bottom to reach a quasi-static level determined by observing water surface movement and periodically measuring the water surface from existing grade level of the test pit rim.

Two duplicate soil samples (T1198-TP1-004-SL-1 and T1198-TP10-011-SL-1) were submitted to the laboratory from Test Pit Nos. 1 and 10 for quality assurance and quality control (QA/QC). Soil samples were collected during a high tide interval approximately one foot above the water level encountered in the test pit.

3.2.3 Toxicity Characteristic Leachate Procedure

Two sample locations (test pit nos. 1 and 10) were chosen to provide a plausible north to south precipitation infiltration range to assess leaching characteristics utilizing the toxicity characteristic leachate procedure (TCLP). The same sampling protocol was utilized as described in the first paragraph of section 3.2.2 : Old Mill Site Test Pit Soil Samples.

The TCLP was employed as an indicator for the potential leaching of low levels of contaminants and to determine if the soils pose a substantial presence or potential hazard to human health or the environment. Both samples tested below TCLP federal regulatory levels.

3.2.4 Former Log Pond Sediment Samples

Sediment samples were taken from the former log pond area and at locations along the northerly coastal edge of Port Blakely Harbor as designated and illustrated in Figure 3. Analytical results are collated in Table 5 listing sediment concentration levels for total metals.

The "1991 report" contained samples designated, PBTF-Sed 4a and PBTF-Sed 4b, which are included for comparison in Table 6. Sediments sampled were compared to sediment quality standards of the State of Washington Administrative Code 173-204 (Chapter 173-204 WAC), which while not applicable here, provides a basis of comparison. Sediment sample concentrations occurred below levels regulated by the Washington state sediment standards, widely recognized as the most stringent in the nation.

3.3 Discussion of Field Screening Results

Sources of trace metals are commonly associated with natural processes of chemical weathering, soil leaching, and human activities (Viessman, 1985). When illustratively compared, groundwater metal concentration levels were below state (MTCA) and most federal regulatory levels (except, Barium and Zinc) as shown in Table 2 entitled, Groundwater Sample Results. Copper and zinc regulatory concentrations are secondary standards (aesthetics concerns) recommended for contaminant levels within the interim drinking water standards of the EPA Office of Water

Supply (Viessman, 1985) and currently not included within the State of Washington's Model Toxics Control Act cleanup standards. Total metal analyses for shallow and deep wells on Bainbridge Island were obtained from the Public Utility District No. 1 of Kitsap County (Kitsap County, 1991) located in Poulsbo, Washington for a regional comparison. Kitsap county's groundwater metal concentration levels were below state and federal regulatory levels used in the comparison. It should be noted that this groundwater is not considered a drinking water source.

Table 3 lists test pit total metal concentrations for the sampling event and includes two preliminary soil sample concentrations (TP1-S1 and TP8-S2) previously reported in the "1991 report". Because the sampling was not from an identical test pit, a comparison is made for illustrative purposes, and must not be interpreted quantitatively. Based on these comparisons, the concentration levels of Arsenic, Cadmium, Chromium, Mercury, Selenium, Silver, Copper, Nickel, and Zinc have diminished. The concentration level reduction may be the combined result of different localized soil conditions, higher water solubilities, tidal "flushing", and/or error in test results. Lead concentrations decreased from the preliminary sample designated, TP8-S2, which may be the result of localized conditions produced by historic mill site operations. Barium tends to have a lower solubility in groundwater and this attribute may account for its fairly stable value. None of the regulated metals reported for the test pit soil samples exceeded the State of Washington's MTCA Method "A" cleanup levels for soil.

As indicated in Tables 4 and 5, all TCLP and sediment sample analytical results were well below the federal regulatory levels and State Sediment Quality Standards, respectively.

4.0 CONCLUSIONS

This report presents the results of the environmental site assessment, Project Status Report II, to identify inorganic metal concentration levels in the vicinity of the former mill site area in Port Blakely on Bainbridge Island, Washington. Concentrations of all test pit soil samples, TCLP results, and sediment samples were significantly below or equaled the most stringent state or federal regulatory standards. Groundwater metal concentration levels are low when illustratively compared to current regional, state, and federal regulatory levels.

5.0 LIMITATIONS


The findings we have presented within this Project Status Report II are based on limited research at the facility. They should not be construed as a definite statement regarding all conditions at the property. Shannon & Wilson, Inc. performed this work phase employing our best professional judgment to describe conditions at the property.

The data presented in this Project Status Report II should be considered representative at the time of our observations. Changes in the conditions of the property can occur with time from both natural processes and human activities. Due to such changes, our observations and recommendations applicable to this facility may need to be revised wholly or in part, due to changes beyond our control.

This Project Status Report II was prepared for the exclusive use of Port Blakely Tree Farms, Inc.

SHANNON & WILSON INC.

Kimberly A. L. Fenske
Kimberly A. L. Fenske
Geoenvironmental Engineer



Frank W. Pita, P.E., P.G.
Vice President - Environmental Services

KLF:FWP/klf

9-17-92/T1198-02.LTR/T1198-lkd/lkd

REFERENCES

Public Utility District No. 1 of Kitsap County, Kitsap County Groundwater Management Plan (Draft), dated April 1991.

Viessman, Warren, Jr., and Hammer, Mark J., Water Supply and Pollution Control, Fourth Edition, Harper and Row Publishers, 1985.

TABLE 1
PORT BLAKELY TREE FARM : PORT BLAKELY MILLSITE
TOTAL METALS (1)
TEST PIT SOIL RESULTS (2)

SAMPLE DESIGNATION	FIGURE 3 DESIGNATION	ARSENIC (ppm, (3))	BARIUM (ppm)	CADMIUM (ppm)	CHROMIUM (ppm)	LEAD (ppm)	MERCURY (ppm)	SELENIUM (ppm)	SILVER (ppm)	COPPER (ppm)	NICKEL (ppm)	ZINC (ppm)
T1198-TP1-003-SL-0	1	11	85	<1	12	55	<1	<1	<1	9	11	27
T1198-TP1-004-SL-1, (4)	1	9	45	<1	9	13	<1	1	<1	8	8	23
T1198-TP2-006-SL-0	2	5	26	<1	19	7	<1	<1	<1	34	16	34
T1198-TP3-002-SL-0	3	3	5	<1	2	120	<1	<1	<1	24	2	13
T1198-TP4-005-SL-0	4	<1	1	<1	<1	18	<1	<1	<1	7	<1	19
T1198-TP5-009-SL-0	5	<1	1	<1	<1	<1	<1	<1	<1	<1	<1	<1
T1198-TP6-008-SL-0	6	<1	1	<1	<1	1	<1	<1	<1	2	1	5
T1198-TP7-007-SL-0	7	4	18	<1	14	7	<1	<1	<1	34	16	34
T1198-TP8-001-SL-0	8	6	300, (5)	<1	10	26	<1	<1	<1	55	10	60
T1198-TP10-010-SL-0	10	5	19	<1	27	7	<1	2	<1	51	26	35
T1198-TP10-011-SL-1, (4)	10	7	23	<1	30	8	<1	<1	<1	46	29	37
T1198-BG-012-SL-0	BG	8	270, (5)	2, (6) (j)	49	10	<1	2	<1	84	25	51
Potential Regulatory Levels, (6)		20.0		2.0	100.0	250.0	1.0					

Notes

- (1) Total metal by inductively coupled plasma (ICP) method 6010.
(2) As reported by Friedman and Bruya, Inc., Seattle, Washington.
(3) Parts Per Million (ppm).
(4) QA/QC duplicate.

- (5) The value reported exceeded the calibration range established for the sample.
(6) Model Toxic Control Act dated February 1991, Method "A" soil cleanup levels; only for comparison purposes.
(j) Soil sample retrieved outside former mill site area; cleanup level based on plant protection.

TABLE 2
PORT BLAKELY TREE FARM : PORT BLAKELY MILLSITE
TOTAL METALS (1)
GROUNDWATER SAMPLE RESULTS (2)

SAMPLE DESIGNATION	FIGURE 3 DESIGNATION	ARSENIC (ppm) (3)	BARIUM (ppm)	CADMIUM (ppm)	CHROMIUM (ppm)	LEAD (ppm)	MERCURY (ppm)	SELENIUM (ppm)	SILVER (ppm)	COPPER (ppm)	NICKEL (ppm)	ZINC (ppm)
T1198-WP001-100-GW-0	W1	<2	3	<0.5	1	<0.5	<1	<1	<0.5	1	1	3
T1198-WP002-101-GW-0	W2	<2	3	<0.5	<0.5	<0.5	<1	<1	<0.5	1	<0.5	7.8
T1198-WP003-102-GW-0	W3	2	4	<0.5	1	<0.5	<1	<1	<0.5	1	0.5	2
T1198-BG004-103-GW-0	PORT BLAKELY	<2	<1	<0.5	<0.5	<0.5	<1	<1	<0.5	<0.5	<0.5	2
KITSAP COUNTY, (4)		0.00981	0.195	0.002	0.00872	0.010		0.00481	0.00781			0.00
POTENTIAL REGULATORY LEVELS		5.0, (5)	1.0, (6)	5.0 (5)	50.0, (5)	5.0, (5)	2.0, (5)	10.0, (6)	50.0, (6)	1, (6)		5, (6)
<p>Notes</p> <p>(1) Total metal by inductively coupled plasma (ICP) method 6010.</p> <p>(2) As reported by Friedman and Brays, Inc, Seattle, Washington.</p> <p>(3) Parts Per Million (ppm)</p> <p>(4) Kitsap County Groundwater Management Plan (Draft) dated April 1991, Appendix H - Shallow Wells.</p> <p>(5) Model Toxic Control Act dated February 1991, Method "A" for groundwater cleanup levels; only for comparison purposes.</p> <p>(6) Interim Drinking Water Standards of the EPA Office of Water Supply, EPA 570/9-76-003 (Viessman, p. 218-9); only for comparison purposes.</p>												

TABLE 3
PORT BLAKELY TREE FARM : PORT BLAKELY MILLSITE
TOTAL METALS (1)
TEST PIT SOIL SAMPLE COMPARISONS (2)

SAMPLE DESIGNATION	FIGURE 3 DESIGNATION	ARSENIC (ppm, (3))	BARIUM (ppm)	CADMIUM (ppm)	CHROMIUM (ppm)	LEAD (ppm)	MERCURY (ppm)	SELENIUM (ppm)	SILVER (ppm)	COPPER (ppm)	NICKEL (ppm)	ZINC (ppm)
T1198-TP1-003-SL-0, (6)	1	11	85	<1	12	55	<1	<1	<1	9	11	27
TP1-S1, (7)	1	60	87	8	14	49	2	18	3	26	21	75
T1198-TP1-004-SL-1, (5)	1	9	45	<1	9	13	<1	1	<1	8	8	23
T1198-TP2-006-SL-0	2	5	26	<1	19	7	<1	<1	<1	34	16	34
T1198-TP3-002-SL-0	3	3	5	<1	2	120	<1	<1	<1	24	2	13
T1198-TP4-005-SL-0	4	<1	1	<1	<1	18	<1	<1	<1	7	<1	19
T1198-TP5-009-SL-0	5	<1	1	<1	<1	<1	<1	<1	<1	<1	<1	<1
T1198-TP6-008-SL-0	6	<1	1	<1	<1	1	<1	<1	<1	2	1	5
T1198-TP7-007-SL-0	7	4	18	<1	14	7	<1	<1	<1	34	16	34
T1198-TP8-001-SL-0, (6)	8	6	300, (4)	<1	10	26	<1	<1	<1	55	10	60
TP8-S2, (7)	8	110	290	10	29	77	10	25	14	68	30	89
T1198-TP10-010-SL-0	10	5	19	<1	27	7	<1	2	<1	51	26	35
T1198-TP10-011-SL-1, (5)	10	7	23	<1	30	8	<1	<1	<1	46	29	37
T1198-BG-012-SL-0	BG	8	270, (4)	2	49	10	<1	2	<1	84	25	51
Potential Regulatory Levels, (8)		20.0		2.0	100.0	250.0	1.0					

Notes

- | | |
|---|--|
| (1) Total metal by inductively coupled plasma (ICP) method 6010. | (6) Sampled April 3, 1992. |
| (2) As reported by Friedman and Bruya, Inc., Seattle, Washington. | (7) Sampled October 2, 1990 from same location. |
| (3) Parts Per Million (ppm) | (8) Model Toxic Control Act dated February 1991, Method "A" soil cleanup levels; only for comparison purposes. |
| (4) The value reported exceeded the calibration range established for the sample. | |
| (5) QA/QC duplicate. | |

TABLE 4
PORT BLAKELY TREE FARM : PORT BLAKELY MILLSITE
TOXICITY CHARACTERISTIC LEACHATE PROCEDURE (1)
TEST PIT SOIL RESULTS (2)

SAMPLE DESIGNATION	FIGURE 3 DESIGNATION	ARSENIC ppm, (3)	BARIUM (ppm)	CADMIUM (ppm)	CHROMIUM (ppm)	LEAD (ppm)	MERCURY (ppm)	SELENIUM (ppm)	SILVER (ppm)	COPPER (ppm)	NICKEL (ppm)	ZINC (ppm)
T1198-TP1-003-SL-0	1	<0.5	0.1	<0.5	<0.5	0.1	<0.1	0.1	<0.1	<0.5	<0.5	<0.5
T1198-TP10-010-SL-0	10	<0.5	<0.5	<0.5	<0.5	<0.5	<0.1	<0.1	<0.1	<0.5	<0.5	<0.5
Potential Regulatory Levels, (1)		5.0	100	1.0	5.0	5.0	0.2	1.0	5.0	a	a	a
Notes												
(1) TCLP metals in accordance with 40 CFR Part 261 et al., only for comparison purposes.												
(2) As reported by Friedman and Bruys, Inc., Seattle, Washington.												
(3) Parts Per Million (ppm)												
a - Not a TCLP analyte.												

TABLE 5
PORT BLAKELY TREE FARM : PORT BLAKELY MILLSITE
TOTAL METALS (1)
LOG POND SEDIMENT RESULTS (2)

SAMPLE DESIGNATION	FIGURE 3 DESIGNATION	ARSENIC (ppm, (3))	BARIUM (ppm)	CADMIUM (ppm)	CHROMIUM (ppm)	LEAD (ppm)	MERCURY (ppm)	SELENIUM (ppm)	SILVER (ppm)	COPPER (ppm)	NICKEL (ppm)	ZINC (ppm)
T1198-LP-013-SL-0	13	6	7	<0.5	6	38	<1	<1	<0.5	24	4	22
T1198-LP-014-SL-0	14	6	11	<0.5	11	41	<1	1	<0.5	27	8	37
T1198-LP-015-SL-0	15	6	9	<0.5	6	29	<1	<1	<0.5	16	5	23
T1198-LP-016-SL-0	16	9	10	<0.5	5	41	<1	<1	<0.5	31	5	15
T1198-LP-017-SL-0	17	8	11	<0.5	7	11	<1	<1	<0.5	9	8	25
T1198-LP-018-SL-0	18	9	8	<0.5	4	51	<1	<1	<0.5	21	3	25
T1198-LP-019-SL-0	19	5	10	<0.5	9	34	<1	<1	<0.5	44	8	37
T1198-LP-020-SL-0	20	5	12	<0.5	9	54	<1	<1	<0.5	31	10	41
Potential Regulatory Levels, (5)		57.0		5.1	260	450	0.41		6.1			410

Notes

- (1) Total metal by inductively coupled plasma (ICP) method 6010.
- (2) As reported by Friedman and Bruya, Inc., Seattle, Washington.
- (3) Parts Per Million (ppm)
- (4) Comparison values.

(5) Sediment Management Standards, Table 1, Chapter 173-204 WAC, dated April 1991; only for comparison purposes.

TABLE 6
PORT BLAKELY TREE FARM : PORT BLAKELY MILLSITE
TOTAL METALS (1)
LOG POND SEDIMENT COMPARISONS (2)

SAMPLE DESIGNATION	FIGURE 3 DESIGNATION	ARSENIC (ppm, (3))	BARIUM (ppm)	CADMIUM (ppm)	CHROMIUM (ppm)	LEAD (ppm)	MERCURY (ppm)	SELENIUM (ppm)	SILVER (ppm)	COPPER (ppm)	NICKEL (ppm)	ZINC (ppm)
PBTF-Sed 4a, (4)		12, (a)	8.5	0.3	3.6	4.1	0.8, (a)	3.7	0.6	4.1, (a)	4.3	7.0, (a)
PBTF-Sed 4b, (4)		15, (a)	2.8	0.3	4.4	4.7	0.9, (a)	4.7	0.4	3.4, (a)	6.0	8.7, (a)
T1198-LP-013-SL-0	13	6	7	<0.5	6	38	<1	<1	<0.5	24	4	22
T1198-LP-014-SL-0	14	6	11	<0.5	11	41	<1	1	<0.5	27	8	37
T1198-LP-015-SL-0	15	6	9	<0.5	6	29	<1	<1	<0.5	16	5	23
T1198-LP-016-SL-0	16	9	10	<0.5	5	41	<1	<1	<0.5	31	5	15
T1198-LP-017-SL-0	17	8	11	<0.5	7	11	<1	<1	<0.5	9	8	25
T1198-LP-018-SL-0	18	9	8	<0.5	4	51	<1	<1	<0.5	21	3	25
T1198-LP-019-SL-0	19	5	10	<0.5	9	34	<1	<1	<0.5	44	8	37
T1198-LP-020-SL-0	20	5	12	<0.5	9	54	<1	<1	<0.5	31	10	41
Potential Regulatory Levels, (5)		57.0		5.1	260	450	0.41		6.1			410

Notes

- (1) Total metal by inductively coupled plasma (ICP) method 6010.
- (2) As reported by Friedman and Bruys, Inc., Seattle, Washington.
- (3) Parts Per Million (ppm)
- (4) Sampled October 2, 1990 from same approximate location.

- (5) Sediment Management Standards, Table 1, Chapter 173-204 WAC, dated April 1991; only for comparison purposes.
- a : The analyte indicated was also found in the blank sample.

N

BAINBRIDGE ISLAND



SCALE IN MILES

○ State Highway
 — Streets
 — Dirt Roads
 ● Ferry
 ~ Water

□ Post Office
 □ Schools
 □ Public Boat Launching

● POINTS OF INTEREST
SEE REVERSE FOR LIST OF ITEMS SHOWN

BAINBRIDGE ISLAND CHAMBER OF COMMERCE
 A Subsidiary of Bainbridge Island, Inc.
 1000 West 1st St., P.O. Box 1000
 Bainbridge, WA 98147
 (206) 835-1111



Scale in Miles

NOTE

Map was adapted from the Bainbridge Island Chamber of Commerce map, 1987.

Port Blakely Tree Farms
Port Blakely, Washington


VICINITY MAP

July 1992



T-1198-02

SHANNON & WILSON, INC.
Geotechnical Consultants

FIG. 1




LEGEND

-  Wetland (Field Delineation by Jones & Stokes)
-  Breaklines

NOTE

Base from MacLearnsberry, Inc. map titled "Soil Log Map", dated 8-7-90.



Port Blakely Tree Farms
Port Blakely, Washington


SITE AND EXPLORATION PLAN

July 1992




T-1198-02


SHANNON & WILSON, INC.
Geotechnical and Environmental Consultants

FIG. 2



LEGEND

- 1  Test Pit Designation and Approximate Location
- 14  Log Pond/Sediment Sample Designation and Approximate Location
- W1  Groundwater Sample Designation and Approximate Location



NOTE

Base from MacLearnsberry, Inc. map titled "Soil Log Map", dated 8-7-90.

Port Blakely Tree Farms
Port Blakely, Washington

EXPLORATION LOCATIONS

July 1992

T-1198-02

SHANNON & WILSON, INC.
Geotechnical and Environmental Consultants

FIG. 3

FIG. 3

SHANNON & WILSON, INC.

APPENDIX A
LOGS OF FIELD TEST PITS

T-1198-02

LOG OF TEST PIT TP-1

PROJECT: Port Blakely Tree Farm

SOIL DESCRIPTION	Ground Water	% Water Content	Samples	Depth, Ft.	Sketch of <u>South</u> Pit Side	
					Horizontal Distance in Feet	Surface Elevation:
<p>① Loose, brown silty, sandy GRAVEL; dry</p> <p>② Loose, black silty, sandy GRAVEL; abundant charcoal and burned timbers; dry; trash includes wire mats and a metal pipe</p> <p>③ Loose, black silty, sandy GRAVEL; abundant charcoal and burned timbers; moist; soil becomes sandier with depth</p> <p>- brief rotten egg odor at 6.5 feet - no reading on MSA</p>			S-1 (Jar)	0	0	12
				2		
				4		
				6		
				8		
				10		
				12		

FIG. 0

LOG OF TEST PIT TP-2

SOIL DESCRIPTION	Ground Water	% Water Content	Samples	Depth, Ft.	Sketch of <u>South</u> Pit Side	
					Horizontal Distance in Feet	Surface Elevation:
<p>① Loose, dark brown, silty, medium SAND; dry (TOPSOIL)</p> <p>② Red masonry brick mixed in with topsoil; grades into next layer; dry</p> <p>③ Very loose, brown, medium SAND with shell fragments; stratified layers of SAND with 5-12% shell fragments and layers of SAND with >12% shell fragments; layers are 1/2" to 3" thick; moist (BEACH SANDS)</p> <p>NOTE: Ended test pit due to sides sloughing intensely.</p>				0		
				2		
				4		
				6		
				8		
				10		
				12		

FIG. 0

LOG OF TEST PIT TP-3

PROJECT: Port Blakely Tree Farm




FIG. 0

LOG OF TEST PIT TP-6

PROJECT: Port Blakely Tree Farm

SOIL DESCRIPTION	Ground Water	% Water Content	Samples	Depth, Ft.	Sketch of <u>North</u> Pit Side			
					Surface Elevation: Horizontal Distance in Feet			
					0	12		
<p>① Loose, black, fine sandy SILT; organic fines; roots; moist (TOPSOIL)</p>	∇		S-1 (Jar)	0				
<p>② Loose, black, silty, fine sand; lenses of loose, brown, silty SAND; abundant shell fragments; moist</p> <p>- burned timber and lenses of sawdust/wood chips encountered in soil at approximately 5.0 feet</p>				2				
<p>③ Loose, gray, sandy GRAVEL; wet</p>				8				
				10				
				12				

FIG. 0

LOG OF TEST PIT TP-7

PROJECT: Port Blakely Tree Farm

SOIL DESCRIPTION	Ground Water	% Water Content	Samples	Depth, Ft.	Sketch of <u>South</u> Pit Side		Surface Elevation:				
					Horizontal Distance in Feet						
					0	2	4	6	8	10	12
<p>① Loose, black, fine sandy SILT; organic fines; roots; moist (TOPSOIL)</p> <p>② Loose, brown, silty SAND, extremely abundant burned timbers; moist</p> <ul style="list-style-type: none"> - slight rotten egg odor - no registered reading on MSA - lots of burned timbers and at least 4 pilings made excavation extremely difficult <p>③ Loose, black, silty, sandy GRAVEL; wet</p>			S-1 (Jar)								
	∇				0	2	4	6	8	10	12
					8						
					10						
					12						

FIG. 0

LOG OF TEST PIT TP-8

PROJECT: Port Blakely Tree Farm




FIG. 0

LOG OF TEST PIT TP-10

PROJECT: Port Blakely Tree Farm




FIG. 0

SHANNON & WILSON, INC.

APPENDIX B
LABORATORY ANALYTICAL DOCUMENTATION

T-1198-02

FRIEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS

Andrew John Friedman
James E. Bruya, Ph.D.
(206) 285-8282

3008-B 16th Avenue West
Seattle, WA 98119
FAX: (206) 283-5044

April 8, 1992

Kim Fenske, Project Leader
Shannon & Wilson, Inc.
P.O. Box C-30313
Seattle, WA 98103


Dear Ms Fenske:

Enclosed are the results of the analyses of the samples submitted on April 3, 1992 from Project T-1198-02.

Review of the quality assurance data showed that some of the matrix spike recovery results were unexpectedly low. The poor recoveries appear to be due to the presence of a high level of dissolved solids and/or high levels of interfering elements. Examination of the spike blank and continuing calibration results showed that they were still within the expected range. These results suggest that the low recoveries are the result of a matrix effect associated with the sample. If this is not satisfactory for your particular project, please contact me as soon as possible.

We appreciate this opportunity to be of service to you on this project. If you have any questions regarding this material, or if you just want to discuss any aspect of your projects, please do not hesitate to contact me.

Sincerely,



Janet Sheldon, Chemist

JS/dp

Enclosures

FRIEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS

Date of Report: April 8, 1992
 Date Submitted: April 3, 1992
 Project: T-1198-02

RESULTS OF ANALYSES OF THE SOIL SAMPLES
 FOR TOTAL METALS BY
 INDUCTIVELY COUPLED PLASMA (ICP)
 METHOD 6010
 Results Reported as $\mu\text{g/g}$ (ppm)

<u>Sample #</u>	<u>T1198-TP8- 001-SL-0</u>	<u>T1198-TP3- 002-SL-0</u>	<u>T1198-TP1 003-SL-0</u>	<u>T1198-TP1- 004-SL-1</u>
<u>Analyte:</u>				
Arsenic	6	3	11	9
Barium	300 ^{ve}	5	85	45
Cadmium	<1	<1	<1	<1
Chromium	10	2	12	9
Lead	26	120	55	13
Mercury	<1	<1	<1	<1
Selenium	<1	<1	<1	1
Silver	<1	<1	<1	<1
Copper	55	24	9	8
Nickel	10	2	11	8
Zinc	60	13	27	23

ve - The value reported exceeded the calibration range established for the sample.

FRIEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS

Date of Report: April 8, 1992
Date Submitted: April 3, 1992
Project: T-1198-02

RESULTS OF ANALYSES OF THE SOIL SAMPLES
FOR TOTAL METALS BY
INDUCTIVELY COUPLED PLASMA (ICP)
METHOD 6010
Results Reported as $\mu\text{g/g}$ (ppm)

<u>Sample #</u>	<u>T1198-TP4-</u> <u>005-SL-0</u>	<u>T1198-TP2-</u> <u>006-SL-0</u>	<u>T1198-TP7-</u> <u>007-SL-0</u>	<u>T1198-TP6-</u> <u>008-SL-0</u>
<u>Analyte:</u>				
Arsenic	<1	5	4	<1
Barium	1	26	18	1
Cadmium	<1	<1	<1	<1
Chromium	<1	19	14	<1
Lead	18	7	7	1
Mercury	<1	<1	<1	<1
Selenium	<1	<1	<1	<1
Silver	<1	<1	<1	<1
Copper	7	34	34	2
Nickel	<1	16	16	1
Zinc	19	34	34	5

FRIEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS

Date of Report: April 8, 1992
 Date Submitted: April 3, 1992
 Project: T-1198-02

RESULTS OF ANALYSES OF THE SOIL SAMPLES
 FOR TOTAL METALS BY
 INDUCTIVELY COUPLED PLASMA (ICP)
 METHOD 6010
 Results Reported as $\mu\text{g/g}$ (ppm)

<u>Sample #</u>	<u>T1198-TP5- 009-SL-0</u>	<u>T1198-TP10- 010-SL-0</u>	<u>T1198-TP10- 011-SL-1</u>	<u>T1198-BG- 012-SL-0</u>
<u>Analyte:</u>				
Arsenic	<1	5	7	8
Barium	1	19	23	270 ^{ve}
Cadmium	<1	<1	<1	2
Chromium	<1	27	30	49
Lead	<1	7	8	10
Mercury	<1	<1	<1	<1
Selenium	<1	2	<1	2
Silver	<1	<1	<1	<1
Copper	<1	51	46	84
Nickel	<1	26	29	25
Zinc	<1	35	37	51

ve - The value reported exceeded the calibration range established for the sample.

FRIEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS

Date of Report: April 8, 1992

Date Submitted: April 3, 1992

Project: T-1198-02

RESULTS OF ANALYSES OF THE SOIL SAMPLES
 FOR TOTAL METALS BY
 INDUCTIVELY COUPLED PLASMA (ICP)
 METHOD 6010
 Results Reported as $\mu\text{g/g}$ (ppm)
Quality Assurance

<u>Sample #</u>	<u>Method Blank</u>	<u>T1198-TP10-011-SL-1 (Duplicate)</u>	<u>T1198-BG8-012-SL-O (Duplicate)</u>
<u>Analyte:</u>			
Arsenic	<1	6	7
Barium	<1	22	290 ^{ve}
Cadmium	<1	<1	2
Chromium	<1	27	51
Lead	<1	7	11
Mercury	<1	<1	<1
Selenium	<1	3	<1
Silver	<1	<1	<1
Copper	<1	54	88
Nickel	<1	26	26
Zinc	<1	36	55

ve - The value reported exceeded the calibration range established for the sample.

SHANNON & WILSON, INC.

APPENDIX C
CHAIN-OF-CUSTODY FORMS

T-1198-02

B-JS-4

Chain of Custody Record

Page 1 of 2
 Laboratory FB-I
 Attn: _____

Shannon & Wilson, Inc.
 400 N. 34th Street, Suite 100 11600 Olive Blvd., Suite 278
 Seattle, WA 98103 SL Louis, MO 63141
 (206) 832-8020 (314) 872-8170
 2056 Hill Road 5430 Fairbanks Street, Suite 3
 Fairbanks, AK 99707 Anchorage, AK 99518
 (907) 479-0900 (907) 561-2120

Analysis Parameters/Sample Container Description
 (include preservative if used)

Sample Identity	Lab No.	Time	Date Sampled	Comp.			Total Number of Containers	Remarks/Matrix
				Grp	Grp (Gas)	Grp (Liq)		
T1198-TP8-001-SL-0	28384/85	0855	4/3/92	✓	✓	✓	2	
T1198-TP3-002-SL-0	86/87	0915	4/3/92	✓	✓	✓	2	
T1198-TP1-003-SL-0	88/89	0940	4/3/92	✓	✓	✓	2	Note Change - DHT
T1198-TP1-004-SL-0	90/91	0940	4/3/92	✓	✓	✓	2	Change - DHT
T1198-TP4-005-SL-0	92/93	1005	4/3/92	✓	✓	✓	2	
T1198-TP2-006-SL-0	94/95	1025	4/3/92	✓	✓	✓	2	
T1198-TP7-007-SL-0	96/97	1050	4/3/92	✓	✓	✓	2	
T1198-TP6-008-SL-0	18/99	1112	4/3/92	✓	✓	✓	2	
T1198-TP5-009-SL-0	28400/01	1132	4/3/92	✓	✓	✓	2	
T1198-TP10-010-SL-0	02/03	1203	4/3/92	✓	✓	✓	2	Change - DHT

Relinquished By: 1	Relinquished By: 2	Relinquished By: 3
Signature: <u>Kim Fenske</u> Printed Name: <u>KIM FENSKE</u> Company: <u>SHANNON & WILSON</u>	Signature: _____ Printed Name: _____ Company: _____	Signature: _____ Printed Name: _____ Company: _____
Time: <u>1510</u> Date: <u>4-3-92</u>	Time: _____ Date: _____	Time: _____ Date: _____
Received By: 1 Signature: <u>[Signature]</u> Printed Name: <u>J. Sheldon</u> Company: <u>FBI</u>	Received By: 2 Signature: _____ Printed Name: _____ Company: _____	Received By: 3 Signature: _____ Printed Name: _____ Company: _____
Time: <u>1510</u> Date: <u>4-3-92</u>	Time: _____ Date: _____	Time: _____ Date: _____

Project Information

Project Number: T-1198-02
 Project Name: HL
 Contact: KIM FENSKE
 Ongoing Project? Yes No
 Sampler: VF/TF

Sample Receipt

Total Number of Containers: 24
 COC Seals/Intact? YN/NA
 Received Good Cond./Cold
 Delivery Method: _____
 (attach shipping bill, if any)

Instructions

Requested Turn Around Time: STANDARD

Special Instructions: (Coc to: 14042, 14043)

Distribution: Write - w/shipment - returned to Shannon & Wilson w/ Laboratory report
 Yellow - w/shipment - for consignee files
 Pink - Shannon & Wilson - Job File

Shannon & Wilson, Inc.
 400 N. 34th Street, Suite 100 Seattle, WA 98103
 (206) 632-8020
 2055 Hill Road Fairbanks, AK 99707
 (907) 479-0800

11500 Olive Blvd., Suite 276 St. Louis, MO 63141
 (314) 872-8170
 6430 Fairbanks Street, Suite 3 Anchorage, AK 99518
 (907) 561-2120

Chain of Custody Record

Page 2 of 2
 Laboratory FBI
 Attn: _____

Analysis Parameters/Sample Container Description
 (include preservative if used)

Sample Identity	Lab No.	Time	Date Sampled	Comp. (Grab)	BR (GSS/Colo)	TCLO	Total Number of Containers	Remarks/Matrix
T1198-TP10-011-SL-1	28404/05	1203	4/3/92	✓	✓		2	14042 YAH.
T1198-B68-012-SL-0	↓ 06/07	1252	4/3/92	✓	✓		2	J

Project Information

Project Number: T-1198-02
 Project Name: 74
 Contact: KIM FENSKE
 Ongoing Project? Yes No
 Sampler: KF/TF

Sample Receipt

Total Number of Containers
 COC Seals/Intact? Y/N/A
 Received Good Cond./Cold
 Delivery Method:
 (attach shipping bill, if any)

Instructions

Requested Turn Around Time: STANDARD

Special Instructions:
(Coc #'s: 14042, 14043)

Distribution: White - w/shipment - returned to Shannon & Wilson w/ Laboratory report
 Yellow - w/shipment - for consignee files
 Pink - Shannon & Wilson - Job File

Relinquished By: <u>1.</u> Signature: <u>Kim Fenske</u> Printed Name: <u>KIM FENSKE</u> Company: <u>SHANNON & WILSON</u>	Relinquished By: <u>2.</u> Signature: _____ Printed Name: _____ Company: _____	Relinquished By: <u>3.</u> Signature: _____ Printed Name: _____ Company: _____
Received By: <u>1.</u> Signature: <u>J. Sheldon</u> Printed Name: <u>J. Sheldon</u> Company: <u>FBI</u>	Received By: <u>2.</u> Signature: _____ Printed Name: _____ Company: _____	Received By: <u>3.</u> Signature: _____ Printed Name: _____ Company: _____

No. 10379



Shannon & Wilson, Inc.

400 N. 34th Street, Suite 100
Seattle, WA 98103
(206) 632-8020

11500 Olive Blvd., Suite 278
St. Louis, MO 63141
(314) 872-8170

2055 Hill Road
Fairbanks, AK 99707
(907) 479-0800

5430 Fairbanks Street, Suite 3
Anchorage, AK 99518
(907) 561-2120

Chain of Custody Record

4-JS-A

Page 1 of 1
Laboratory FBI
Attn: _____

Analysis Parameters/Sample Container Description

(Include preservative if used)

Comp. (Grab) RCRA 3/1/90
EPA (COC) YNMA

Sample Identity	Lab No.	Time	Date Sampled	Total Number of Containers	Remarks/Matrix
T1198-LP-013-SL-0	28516	1045	4-8-92	1	SEDIMENTS
T1198-LP-014-SL-0	28517	1100	4-8-92	1	LOG POND
T1198-LP-015-SL-0	28518	1115	4-8-92	1	
T1198-LP-016-SL-0	28519	1125	4-8-92	1	
T1198-LP-017-SL-0	28520	1135	4-8-92	1	
T1198-LP-018-SL-0	28521	1155	4-8-92	1	
T1198-B66-019-SL-0	28522	1240	4-8-92	1	
T1198-B65-020-SL-0	28523	1300	4-8-92	1	

Project Information		Sample Receipt	
Project Number: T1198-02	Total Number of Containers: 8		
Project Name: Pat Blakey	COC Seals/Intact? Y/N/NA		
Contact: KF	Received Good Cond./Cold		
Ongoing Project? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Delivery Method: <u>HAMP</u>		
Sampler: KF TP	(attach shipping bill, if any)		
Instructions			
Requested Turn Around Time: <u>NORMAL</u>		<u>STANDARD</u>	
Special Instructions: <u>COC # (14044, 14045)</u>			

Relinquished By: 1	Relinquished By: 2	Relinquished By: 3
Signature: <u>Kim Feuske</u>	Signature: _____	Signature: _____
Printed Name: <u>KIM FEUSKE</u>	Printed Name: _____	Printed Name: _____
Company: <u>SHANNON & WILSON</u>	Company: _____	Company: _____
Time: <u>1535</u>	Time: _____	Time: _____
Date: <u>4-8-92</u>	Date: _____	Date: _____
Received By: 1	Received By: 2	Received By: 3
Signature: _____	Signature: _____	Signature: _____
Printed Name: <u>M.A. DUNFEE</u>	Printed Name: _____	Printed Name: _____
Company: <u>FREDERICKS BRYANT, INC.</u>	Company: _____	Company: _____
Time: <u>3:40</u>	Time: _____	Time: _____
Date: <u>4-8-92</u>	Date: _____	Date: _____

Distribution: White - shipment - returned to Shannon & Wilson w/ Laboratory report
Yellow - shipment - for consignee files
Pink - Shannon & Wilson - Job File

7-JS-E
7-15-92 (8:55)

Shannon & Wilson, Inc.
 400 N. 34th Street, Suite 100
 Seattle, WA 98103
 (206) 632-8020

11500 Olive Blvd., Suite 276
 St. Louis, MO 63141
 (314) 872-8170

6430 Fairbanks Street, Suite 3
 Anchorage, AK 99518
 (907) 561-2120

Chain of Custody Record

Analysis Parameters/Sample Container Description
 (Include preservative if used)

Page 1 of 1
 Laboratory FBI
 Attn: FBI

Sample Identity	Lab No.	Time	Date Sampled	TOTALS		Remarks/Matrix
				Comp. (Grab)	Total Number of Containers	
T1198-WP001-100-6W-0 (3/1192)		1000	7/14/92	✓	✓	WATER/SEDIMENTS
T1198-WP002-101-6W-0 (3/1193)		1140	7/14/92	✓	✓	
T1198-WP003-102-6W-0 (3/1194)		1410	7/14/92	✓	✓	
T1198-BG004-103-6W-0 (3/1195)		1455	7/14/92	✓	✓	

Relinquished By: 1.	Relinquished By: 2.	Relinquished By: 3.
Signature: <u>Kim Fenske</u> Printed Name: <u>KIM FENSKE</u> Company: <u>SHANNON & WILSON</u>	Signature: _____ Printed Name: _____ Company: _____	Signature: _____ Printed Name: _____ Company: _____
Time: <u>0840</u> Date: <u>7-15-92</u>	Time: _____ Date: _____	Time: _____ Date: _____
Received By: 1. Signature: <u>Greg Monte</u> Printed Name: <u>Greg Monte</u> Company: <u>FBI</u>	Received By: 2. Signature: _____ Printed Name: _____ Company: _____	Received By: 3. Signature: _____ Printed Name: _____ Company: _____
Time: <u>0859</u> Date: <u>7-15-92</u>	Time: _____ Date: _____	Time: _____ Date: _____

Project Information

Project Number: T-1198-02
 Project Name: F
 Contact: KIM FENSKE
 Ongoing Project? Yes No
 Sampler: KIM FENSKE

Sample Receipt

Total Number of Containers: 4
 COC Seals/Intact? YNINA
 Received Good Cond./Cold: _____
 Delivery Method: _____
 (attach shipping bill, if any)

Instructions

Requested Turn Around Time: 5 DAY
 Special Instructions: CALL IF CONCENTRATIONS ABOVE REGULATORY LEVELS.

Distribution: White - w/shipment - returned to Shannon & Wilson w/ Laboratory report
 Yellow - w/shipment - for consignee files
 Pink - Shannon & Wilson - Job File