



STATE OF WASHINGTON  
DEPARTMENT OF ECOLOGY

PO Box 47775 • Olympia, Washington 98504-7775 • (360) 407-6300

June 10, 2016

Mr. Kevin R. Dunn  
Mitchell Bros Truck Line Inc.  
600 S.E. Maritime Avenue, #100 Building 3  
Vancouver, WA 98661

RE: NPDES Permit Number WAR004491

Dear Mr. Dunn:

Enclosed is the report from the Department of Ecology's recent Industrial Stormwater NPDES General Permit compliance inspection conducted at your facility on March 30, 2016. I would like to thank you for the time you spent with me during my visit.

Please contact me at (360) 407-6298 or [Kevin.Hancock@ecy.wa.gov](mailto:Kevin.Hancock@ecy.wa.gov) if you have any questions, comments or would like additional technical assistance.

Sincerely,

Kevin Hancock  
Industrial Stormwater Facility Manager  
Southwest Regional Office  
Water Quality Program

Enclosure: Industrial Stormwater Inspection Report







**REQUIREMENTS:**

1. Certify the updated SWPPP using the certification form found on page 63 of the permit, and keep it in the SWPPP.
2. The fueling truck Best Management Practice (BMP) oil booms are contaminated. There is oil leaving the contained area (see pictures 1, and 2). Immediately maintain the BMPs to prevent a discharge in accordance to your spill plan, and monthly inspections.

**REMINDER:**

1. If there is a surface stormwater discharge within 12-hours after discharge starts you must collect a sample. Do not wait until the end of the quarter to do your sampling; sample as soon in the quarter as there is a discharge. If there is no surface water discharge, you must submit a DMR to the Department stating that there was not a discharge in accordance to section 9 on page 37 of the ISWGP.
  - a. According to section 4.B.6, page 21 the permittee may suspend sampling for one or more parameters (other than "visible oil sheen") for a period of three years (12-quarters) based on consistent attainment of bench mark values when: Eight consecutive quarterly samples, collected after the effective date of this permit, demonstrate a reported value equal to or less than the benchmark value; or for pH, within the range of 5.0 - 9.0.

**Verify Latitude and Longitude**

Door: N 45.6143° W -122.64680°

Outfall: N 45.6138° W -122.64687°

- Announced  
 Unannounced

Name and Signature of Inspector	Agency/ Office Number	Date
Kevin P. Hancock 	Ecology/SWRO (360) 407-6298	6/7/16
Signature of Management/A Q Reviewer	Agency/ Office Number	Date
Steve Eberl 	Ecology/SWRO (360) 407-6293	6-13-2016

Photo 1 of 5: There is a tanker parked to fuel diesel. There are BMPs in place that require maintenance.




Photo 2 of 5: Oil staining and BMP needs maintenance.



Photo 3 of 5: The monitored outfall with treatment.



Photo 4 of 5: There is dirt from a gravel area around the entrance to the shop. This will contribute to high turbidity readings.



Photo 5 of 5: The entrance into the shop is being maintained.

