

Extend
Level One Response
only one BP in AB
Not set up for
Copper/Lead/TSS
in DB

DEPARTMENT OF ECOLOGY
JAN 09 2007
WATER QUALITY PROGRAM

SO3-001151D
STRIAL STORMWATER GENERAL PERMIT
DISCHARGE MONITORING REPORT

MONITORING PERIOD for 2006 Jan/Feb/Mar Apr/May/Jun Jul/Aug/Sep Oct/Nov/Dec
(year/quarter): year X

Facility/Site Information

TOTEM OCEAN TRLR EXP TOTE ALASKA TE
Location: 500 EAST ALEXANDER AVE
PORT OF TACOMA
County: PIERCE

Mailing Information

TOTEM OCEAN TRAILER EXPRESS
500 EAST ALEXANDER AVE
TACOMA, WA 98421-4217

Primary SIC Code: 4424

You must send a Discharge Monitoring Report (DMR) to Ecology **every quarter**. If there was **no discharge** or you have **suspended sampling** because of consistent attainment of benchmark values, mark the appropriate boxes and send the DMR to Ecology. Please read the instructions before completing the DMR.

Discharge Point		004				
Quarterly Monitoring		AVERAGE	MAXIMUM	UNITS	Sample Type	Events Sampled
Turbidity	Consistent Attainment		9.3	NTU	Grab	1
pH	Consistent Attainment		6.55	Standard Units	Grab	1
Zinc (total)	Consistent Attainment		340	µg/L	Grab	1
Copper	Consistent Attainment		15	µg/L	Grab	1
Lead	Consistent Attainment		ND	µg/L	Grab	1
Oil & Grease	Consistent Attainment		ND	mg/L	Grab	1
Total Suspended Solids	Consistent Attainment		23	mg/L	Grab	1

Discharge Point		003				
Quarterly Monitoring		AVERAGE	MAXIMUM	UNITS	Sample Type	Events Sampled
Turbidity	Consistent Attainment		22	NTU	Grab	1
pH	Consistent Attainment		7.18	Standard Units	Grab	1
Zinc (total)	Consistent Attainment		170	µg/L	Grab	1
Oil & Grease	Consistent Attainment		ND	mg/L	Grab	1
Total Suspended Solids	Consistent Attainment		8.4	mg/L	Grab	1


I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE, AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 USC § 1001 AND 33 USC § 1319. (PENALTIES UNDER THESE STATUTES MAY INCLUDE FINES UP TO \$10,000.00 AND OR MAXIMUM IMPRISONMENT OF BETWEEN SIX MONTHS AND FIVE YEARS.)

Rand Lymangrover,
Operations – Special Projects

NAME/TITLE PRINCIPAL EXECUTIVE OFFICE (TYPED OR
PRINTED)

DATE: MO DAY YEAR

1 05 07



SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR
AUTHORIZED AGENT

253-238-8487

TELEPHONE NUMBER

COMMENTS/EXPLANATIONS

The sampling event was conducted on December 04, 2006. The tide was up, so we elected to sample in the catch basin immediately prior to outfall #4. We sampled on Outfall #3 at the storm drain immediately upline from the outfall.

The zinc concentration in both samples was above the benchmark level. All other analytes were under the benchmark, and pH was within range. A Level One Response was conducted, and the summary is attached.

MEMORANDUM



206 624 9349 Phone
206 624 2839 Fax
www.retec.com

TO: Rand Lymangrover
FROM: Evan Andrews
DATE: 12/29/06

CLIENT: Totem Ocean Trailer Express
TASK: TOTE1-19550-200
RE: Level One Response Inspection

The stormwater sample taken December 04, 2006 from Outfalls 004 and 003 of Totem Ocean Trailer Express (TOTE) had zinc results above the benchmark levels. The laboratory analytical results, dated December 18, 2006, reported zinc at 340 µg/L at outfall 004 and 170 µg/L at outfall 003. These levels are above the zinc benchmark of 117 µg/L. All other analytes were below benchmark levels and pH was within range.

Level One Response Inspection

The Level One Response was conducted on December 21, 2006. The TOTE facility operates Roll-on/Roll-off cargo ship transportation services, where cargo trailers, vehicles, or equipment are driven onto the ship and secured for transport.

The likely source of zinc impacting Outfall #4 is fugitive dust from TOTE's neighbor to the east, Tru-Grit. The fugitive dust collects along the backside of the Maintenance Building and drains to Outfall 004.

Most of the potential sources of zinc reported by a recent Washington State Department of Ecology publication (2006) were observed at the TOTE facility. These sources included a perimeter chain-link fence, vehicles (personnel, service, and for shipping) whose tires and brakes may be sources of zinc, cargo containers and associated equipment (chassis, generators, refrigeration units), tires and hub caps in storage, transformers, metal buildings and canopied truck lanes with downspouts, and general equipment (steel pieces, drums, metal dumpsters).

Source Control/Operational Control Recommended Measures

Based on a previous Level One Response inspection, it was recommended that TOTE remove the fugitive dust collecting (from off-site sources) behind the maintenance building. In addition, it was recommended that Tote hand sweep areas that are not accessible by the street sweeper. This has been done.

Tote has completed a number of control measures. These include removing chain link fence rolls, sweeping behind the maintenance building where fugitive dust from the neighbor's property accumulates, and cleaning the catch basin filter bags. Tote may consider covering the tires stored outside of the Maintenance shop. Currently no changes to the SWPPP are warranted regarding zinc. Based on sampling results (i.e., below the action level) there is no need to conduct a Level Two or Three Response.

References

Washington State Department of Ecology, 2006. *A Survey of Zinc Concentrations in Industrial Stormwater Runoff*. Publication No. 06-03-009. January 2006.