

INITIAL INVESTIGATION FIELD REPORT

LUST ID: 4604 FS ID: 27				03 Site ID:		:
SITE NAME	Boeing	g Commerci	al Airplane Comp	any		
SITE LOCATIO	N INFOR	MATION			-	
Contact Person Name Title				Phone Number		
Mailing Address				City		Zip + 4
3003 W Casino Rd				Everett		98204
Site Location				Closest City	C	ounty
3003 W Casin	o Rd			Everett		-
Quarter-Quarter			Section	Township	Rar	10e
Latitude:			Degree	Minute		cond
Longitude:	Longitude: Degree		Degree	Minute		cond
INSPECTION IN	IFORMA	TION	C		MARKET	
Inspection Date Photographs	Yes	No		Inspection Time Weather: Clear	Type of Entry N	lotice Overcast
Videotape	Yes	No		Precipitation	Temperature	
Samples	Yes	No		Wind Direction	Wind Speed	
RECOMMENDA	ATION					
No Further Actio		site.				
Release or th	reatened	release does i	not pose a threat	Site Hazard Asses	sment	
No release or threatened release				Interim Action		
Educational Mailing				Emergency Action Plan		
Refer to another program/agency				Independent Cleanup Action In Progress		Completed
CONTAMINAN ⁷	T(S) (S	See Page 3 fo	or details)	III FTOGI		Completed
Soil Groundwater	oil Yes TPH and V)Cs		
DEPARTMENT	REVIEW	ı				
Investigator			Date			
Approved by						
Unit Supervisor REO				Date 5 /18/10		
Section Manager				Date		

In April 1992, a Phase I and II was conducted around the degreaser pit located in bldg 40-53. Borings were advanced and soil samples were collected. The results identified VOCs and TPH in the soil above MTCA. GW was not encountered in the borings. A UST report was included in the file with handwritten notes that it is for tank EV-16. The report is actually for EV-32 (LUST 4349) and is an extra copy. Left in file, but made a note on report on actual tank id and LUST number.