



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 5541

FS ID: 53376164

Site ID: 11638

SITE NAME Localizer SeaTac Intrnl Airport

SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number
Mailing Address		City Zip + 4
47 26'09"N 122 18'36"W		SeaTac 98188
Site Location		Closest City County
47 26'09"N 122 18'36"W		SeaTac
Quarter-Quarter	Section	Township Range
Latitude:	Degree	Minute Second
Longitude:	Degree	Minute Second

INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No	Weather: Clear	Partly Cloudy Overcast
Videotape Yes No	Precipitation	Temperature
Samples Yes No	Wind Direction	Wind Speed

RECOMMENDATION

No Further Action:

Yes

Release or threatened release does not pose a threat

No release or threatened release

Educational Mailing

Refer to another program/agency

Site Hazard Assessment

Interim Action

Emergency Action Plan

Independent Cleanup Action

In Progress

Completed

CONTAMINANT(S) (See Page 3 for details)

Soil	Yes	Gas, BTEX
Groundwater	No	

DEPARTMENT REVIEW

Investigator	Date
Approved by	
Unit Supervisor <i>DEO</i>	Date <i>4/18/14</i>
Section Manager	Date

COMMENTS

One UST was removed from this site in 1996. Soil samples taken during the tank removal indicated WTPHG & benzene levels above MTCA Method A cleanup levels. Approx. 185 CY of overexcavated PCS was removed from an excavation that was 20 feet long by 20 feet wide b 14 feet deep. This PCB was disposed off-site. Soil samples were taken from the excavation site and all of these samples had TPH and BTEX concentrations below MTCA Method A cleanup levels. All of the contaminated soil is believed to have been removed from the site. No GW monitoring was done. Ecology granted a 'RCU' in



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 5541

FS ID: 53376164

Site ID: 11638

SITE NAME Localizer SeaTac Intrnl Airport

2003 and suggested that the FAA join the VCP. More detail needs to be found out about GW in the area. No further info in files.
