

INITIAL INVESTIGATION FIELD REPORT

LUST ID: 243	37		FS ID : 726	679449	Site ID:	409
SITE NAME	Ferrill	s Auto Par	ts Inc			
SITE LOCATIO	N INFOR	RMATION				
Contact Person Name Title				Phone Number		
Mailing Address	3			City		Zip + 4
18306 Hwy 99				Lynnwood		98037
Site Location				Closest City C		unty
18306 Hwy 99	9			Lynnwood		
Quarter-Quarter Section			Section	Township	Range	
Latitude:			Degree	Minute	Sec	ond
Longitude:			Degree	Minute	Sec	ond
INSPECTION I	NFORMA	TION				
Inspection Date				Inspection Time	Type of Entry No	otice
Photographs	Yes	No		Weather: Clear	Partly Cloudy	Overcast
Videotape	Yes	No		Precipitation	Temperature	
Samples	Yes	No		Wind Direction	Wind Speed	
RECOMMEND	ATION	·	•		•	
No Further Actio	on:					
Yes. But no so as backfill.	oil sample	es from the	landfarming were obs	erved in the file and no	o indication if the trea	ated soil was used
Release or threatened release does not pose a threat				Site Hazard Asses	sment	
No release or threatened release				Interim Action		
Educational Mailing				Emergency Action Plan		
Refer to another program/agency				Independent Cleanup Action		
				In Progr	ess	Completed
CONTAMINAN	T(S) (S	See Page 3	for details)			
Soil	Yes		Diesel			
Groundwater	No		Diesei			
DEPARTMENT	REVIEW	1				
Investigator				Date		
Approved by		4			·	
Unit Supervisor Am				Date 5 /4/11		
Section Manager				Dat	te	
COMMENTS						

One diesel UST was removed from this property in 1990. Characterization samples indicated PCS was present but the excavation was backfilled after removal awaiting for better weather. In 1991, an Ecology II was conducted and indicated that all vehicles were drained before placing in the yard, no soil staining was visible at the site, and that the site is a model operation for a wrecking yard. In August 1991, cleanup of the former UST area was conducted. An undisclosed amount of PCS was overexcavated and



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 2437

FS ID: 72679449

Site ID: 409

SITE NAME

Ferrills Auto Parts Inc

landfarmed on-site. Confirmation soil samples from the excavation and GW were ND for TPH and BTEX. No soil samples from the landfarming were observed in the file and no indication if the treated soil was used as backfill. In 1998, Ecology sent letters to the owners requesting a cleanup report and the owners sent the report again. The final report was stamped as received in 1991. A note of the 1998 cover letter sent with the report copy says "the site status was already "reported cleaned up", so it's unclear why they were sent a letter".

HCID: 986