

INITIAL INVESTIGATION FIELD REPORT

LUST ID: 2571 Site ID: 101055 **FS ID**: 53813326 SITE NAME Cameron Enterprises VI SITE LOCATION INFORMATION Contact Person Name Title Phone Number Mailing Address City Zip + 4 2101 6th St 98312 **Bremerton** Site Location Closest City County 2101 6th St Bremerton Quarter-Quarter Section Township Range Latitude: Degree Minute Second Longitude: Degree Minute Second INSPECTION INFORMATION Inspection Date Inspection Time Type of Entry Notice Photographs Yes Nο Weather: Clear Partly Cloudy Overcast Videotape Yes Precipitation Temperature No Wind Direction Samples Yes No Wind Speed RECOMMENDATION No Further Action: Likely but file lacks documentation. Release or threatened release does not pose a threat Site Hazard Assessment No release or threatened release Interim Action Educational Mailing Emergency Action Plan Independent Cleanup Action Refer to another program/agency In Progress Completed CONTAMINANT(S) (See Page 3 for details) Soil Yes Gas, BTEX, HO. Groundwater No **DEPARTMENT REVIEW** Investigator Date Approved by Unit Supervisor Au Date 5 /3/1) Section Manager Date COMMENTS

Five USTs (gas, HO) were removed from this property in 1989. The file only has a short letter from the contractor, some loose analytical, and an Ecology Environmental Complaint Form. The letter stated that approx. 8 cy of PCS were overexcavated and landfarmed on-site and that a final composite soil sample collected from the excavation was below MTCA for Gas and BTEX. The analytical report from the laboratory has 9 soil samples from which only 2 were above MTCA for TPH (209.3 to 742.9 ppm) and BTEX was ND or below MTCA. Since no figure or explanation was provided with the letter or lab results,



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 2571

FS ID: 53813326

Site ID: 101055

SITE NAME

Cameron Enterprises VI

it is unknown if the two high samples were from stockpiles or the excavation and what was the nature of the rest of the samples. The contractor's letter indicated that Ecology determined that no additional work was needed at the site. The complaint form indicated that the remediation was successful.

HCID: 883