

File: 12408 Morningside Acres 20240429

SHARP Report — Part 1 of 2

Go to cleanup history

• SHARP first SHARP		v2024.04.29	Ecology	/ Info
 SHARP rating 	Medium		ERTS	644931
 SHARP date 	4/29/2024		CSID	12408
• EJFlagged?	🛇 - No Override		FSID	4321; 8101
 LD confidence level 	low		VCP	NW3345
 Cleanup milestone 	remedial investigation		UST ID	620146
• SHARPster	David Unruh		LUST ID	8259

This section is blank if this is the first SHARP

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	A1	medium	multiple chemical types	✓
Groundwater	C2	medium	risk to off-site people	✓
Surface water	D4	high	climate change impacts	\bigcirc
Sediment	D4	high	plant/animal tissue data	\Diamond
Soil	C2	high		

Location and land use info		
5001 to 5021 Rainier Ave S, Seattle, King County, 98118		
Parcel(s)	5649600135; 5649600133; 5649600130	
Responsible unit	NWRO	
Land use	commercial	

Sources reviewed
December 19, 2023, Property NFA Likely Opinion, Ecology
November 14, 2023, RI/FS/dCAP, Farallon Consulting
May 23, 2023, Opinion Letter, Ecology
December 12, 2022, Further Action Opinion, Ecology
September 24, 2019, TCE Risk Evaluation Memo, Ecology
September 5, 2019, VI Assessment, Farallon Consulting
October 31, 2013, Initial Investigation Field Report, Ecology
June 26, 2006, Limited Phase II ESA, Kleinfelder, Inc.



Primary census tract	Associated census tracts
53033010302	SHARP it

Local demographics comments	Go to top
no comments	

Source/source area description

Go to top

Releases at the Site include chlorinated solvents and petroleum hydrocarbons (TPH). Chlorinated solvents have been released at the central and southern parcels (5015 and 5021 Rainier Ave S, respectively) from a floor drain in the basement of the southern building. A small "fuel oil" underground storage tank (UST) appears to be the source of TPH at the southern parcel.

TPH including gasoline- (TPH-G), diesel- and oil-range (TPH-D+O), and benzene have been released to soil and groundwater at the northern parcel (5001 Rainier Ave S). These releases appear to be associated with historical service station infrastructure including USTs and pump islands. A limited release of 1,1,2-TCA and EDC is also present in groundwater at the northern parcel. The source of this release has not been identified.

Soil comments	Go to top

Shallowest soil data in vicinity of former pump islands and USTs on north parcel is 5 feet bgs.



Groundwater comments	Go to top
Eastern extent of contaminated groundwater not defined beneath Rainier Ave S ROW.	
Surface water comments	Go to top
no comments	
Sediment comments	Go to top
no comments	
Indoor air comments	Go to top
VI Assessment conducted in 2019 indicates that TCE and vinyl chloride are present below indoor air cle	
levels in the 5021 building. Concentrations of cis-1,2-DCE were above the Method B cleanup level for	
unrestricted use in one location in a storage area on the ground floor.	
Additional factors comments	Go to top
no comments	



Site contamination and cleanup history

Go to top

Contaminated soil was identified at the Site in 2006 during a Phase II Environmental Site Assessment. Additional investigations conducted from that time to the present have identified the extent of soil and groundwater contamination to the north, south, and west of the Site. Additional investigations are planned for the summer of 2024 to identify the eastern extent of contamination below the Rainier Ave S right-of-way.

2024 to identify the eastern extent of contamination below the namer rive 3 light of way.
To date, no remedial actions have occurred at the Site. The Site is currently in the process of negotiating a PPCD with Ecology to execute a cleanup action which was developed under the VCP. Based on review of the 2023 RI/FS/dCAP, Ecology determined that the preferred cleanup actions identified in this report would likely address soil, groundwater, and soil gas contamination within the property boundary and possibly throughout the site, pending further investigation.



Overflow - Site contamination and cleanup history	Go to top
No overflow	

File: 12408 Morningside Acres 20240429

First SHARP

Medium SHARP Rating

SHARP Report — Part 2 of 2

Conceptual site model



04/29/2024

