

20 April 2021

Ms. Sandra Treccani Site Manager Washington State Department Ecology 4601 North Monroe Street Spokane, Washington 99205

Subject: Cap Integrity Monitoring BNSF Railway Company, Hillyard Dross Cap Spokane, Washington KJ 2196114*00

Dear Ms. Treccani:

This letter provides the results of compliance monitoring activities conducted during 2021 at the BNSF Railway Company (BNSF) Hillyard Dross Cap site (Site), located at the southwestern intersection of Wellesley Avenue and Ferrall Street in Spokane, Washington. The Site is also referred to as the Aluminum Recycling Corporation Site in the Washington State Department of Ecology (Ecology) Consent Decree No. 01202037-9 (Ecology 2001).

The dross encapsulation cell (cap) and associated stormwater system were constructed between 2001 and 2003. The dross cap consists of a low permeability, 40-millimeter-thick, high-density polyethylene (HDPE) geomembrane placed over the graded and prepared dross and soil surface. The geomembrane is overlain by 18 to 30 inches of rounded gravel that acts as a drain to shed water off the geomembrane. A woven, permeable HDPE geotextile fabric is placed above the gravel and covered with approximately 18 inches of topsoil. The topsoil was hydroseeded upon installation.

Stormwater from the dross cap is directed to a channel along the perimeter of the cap, which drains either directly to the stormwater retention pond or to a sump located in the western portion of the Site. Stormwater that drains to the sump is pumped to the retention pond. Secondary overflow from the retention pond is routed to an onsite drywell.

Operation and maintenance (O&M) activities in 2021 consisted of annual remedial component system checks performed consistent with the approved O&M Plan. The annual inspection was completed on 6 April 2021 and included assessment of the following: (1) the dross cap; (2) the stormwater conveyance, evaporation, and disposal system; and (3) other physical facilities such as access roads, setbacks, fencing, electrical system, and groundwater monitoring wells.

No erosion or settlement of the dross cap was observed during 2021. Grasses and forbs were abundant on and surrounding the dross encapsulation cell during the growing season and were dormant during dry months, as is normal.

Stormwater conveyance, evaporation, and disposal system components were monitored in April 2021.

The evaporation pond that collects Site stormwater is located directly northeast of the dross encapsulation cell. Water level elevations measured in the pond are referenced to the North American Vertical Datum of 1988. Post-construction evaporation pond water level elevations are presented in Attachment A. The evaporation pond was not observed to be discharging to the overflow sump and drywell during April 2021.

Kennedy Jenks Ms. Sandra Treccani Washington State Department Ecology 20 April 2021 Page 2

Based on the field activities performed on 6 April 2021, the following conditions were noted:

- A hole had been cut in the fence surrounding the dross cap; repairs will be performed.
- Monitoring wells were observed to be in good condition.
- One monitoring well (MW-4) is in the work area of an ongoing Washington State Department of Transportation (WSDOT) project and will be converted to a traffic-rated flush mounted monument by WSDOT in the future.

Other physical features such as access roads and setbacks appeared to be in good condition in April 2021.

Site photograph logs from the field inspection have been included as Attachment B.

Please contact us at (503) 423-4018 if you have questions or concerns about the cap integrity monitoring.

Very truly yours,

Kennedy/Jenks Consultants, Inc.

alice Rolinan

Alice Robinson Project Manager

cc: Shane DeGross, BNSF Railway Company

51860 TONAL ENGINE Ryan Hultgren, P.E.

Principal Engineer

Attachments: Attachment A – Summary of Evaporation Pond Water Levels Attachment B – Site Photographs

Attachment A

Summary of Evaporation Pond Water Levels

| Date Measured | Water Level Elevation ^(a) (feet) |
|-------------------------|--|
| 8/26/2003 | 2,035.85 |
| 9/25/2003 | 2,035.64 |
| 10/30/2003 | 2,035.50 |
| 11/26/2003 | 2,035.60 |
| 12/22/2003 | 2,035.00 |
| 1/28/2004 | 2,030.04 |
| 02/20/04 ^(b) | 2,039.18 |
| 3/16/2004 | 2,039.18 |
| 4/19/2004 | 2,039.08 |
| | |
| 5/20/2004 6/16/2004 | 2,038.10 |
| | 2,038.81 |
| 7/26/2004 | 2,037.98 |
| 8/23/2004 | 2,037.73 |
| 9/13/2004 | 2,037.48 |
| 10/15/2004 | 2,037.52 |
| 11/8/2004 | 2,037.48 |
| 12/15/2004 | 2,038.52 |
| 01/28/05 ^(b) | 2,039.12 |
| 2/16/2005 | 2,039.06 |
| 3/10/2005 | 2,039.00 |
| 4/20/2005 | 2,039.02 |
| 5/14/2005 | 2,038.93 |
| 6/9/2005 | 2,039.02 |
| 7/14/2005 | 2,038.77 |
| 8/15/2005 | 2,037.77 |
| 9/27/2005 | 2,036.85 |
| 10/21/2005 | 2,037.85 |
| 11/3/2006 | 2,038.02 |
| 12/16/2006 | 2,037.85 |
| 01/17/06 ^(b) | 2,039.10 |
| 02/03/06 ^(b) | 2,039.10 |
| 03/17/06 ^(b) | 2,039.10 |
| 04/14/06 ^(b) | 2,039.10 |
| 05/03/06 ^(b) | 2,039.10 |
| 6/7/2006 | 2,038.18 |
| 7/6/2006 | 2,038.85 |
| 8/31/2006 | 2,038.85 |
| 9/13/2006 | 2,038.77 |
| 10/30/2006 | NM |
| 11/13/2006 | 2,038.89 |
| 12/4/2006 | 2,038.93 |
| 01/04/07 ^(b) | 2,039.14 |
| 02/02/07 ^(c) | NM |

| Date Measured | Water Level Elevation ^(a) (feet) |
|-------------------------|--|
| 03/06/07 ^(b) | 2,039.10 |
| 4/7/2007 | 2,036.87 |
| 5/3/2007 | 2,036.90 |
| 6/1/2007 | 2,038.94 |
| 07/03/07 ^(c) | NM |
| 8/1/2007 | 2,037.70 |
| 9/7/2007 | 2,037.07 |
| 10/9/2007 | 2,037.17 |
| 11/19/2007 | 2,037.24 |
| 12/20/2007 | 2,038.64 |
| 1/29/2008 | 2,039.39 |
| 2/6/2008 | 2,039.31 |
| 3/17/2008 | 2,039.39 |
| 04/04/08 ^(b) | 2,039.41 |
| 5/1/2008 | 2,039.27 |
| 6/16/2008 | 2,039.03 |
| 7/4/2008 | 2,038.69 |
| 8/5/2008 | 2,037.99 |
| 9/10/2008 | 2,037.59 |
| 10/7/2008 | 2,037.38 |
| 11/11/2008 | 2,037.56 |
| 12/5/2008 | 2,037.59 |
| 01/09/09 ^(b) | 2,039.57 |
| 02/22/09 ^(b) | 2,039.49 |
| 03/10/09 ^(b) | 2,039.55 |
| 04/09/09 | 2,039.39 |
| 5/4/2009 | 2,039.21 |
| 6/5/2009 | 2,038.79 |
| 7/10/2009 | 2,038.28 |
| 8/13/2009 | 2,037.69 |
| 9/8/2009 | 2,037.34 |
| 10/5/2009 | 2,036.65 |
| 11/12/2009 | 2,037.54 |
| 12/7/2009 | 2,037.75 |
| 01/19/10 ^(b) | 2,039.48 |
| 02/17/10 ^(b) | 2,039.49 |
| 03/08/10 ^(b) | 2,039.41 |
| 4/22/2010 | 2,039.32 |
| 5/12/2010 | 2,039.21 |
| 6/4/2010 | 2,039.30 |
| 7/30/2010 | 2,038.88 |
| 8/20/2010 | 2,038.47 |
| 9/9/2010 | 2,038.18 |

| Date Measured | Water Level Elevation ^(a) (feet) |
|---------------------------------|--|
| 10/11/2010 | 2,038.07 |
| 11/10/2010 | 2,038.42 |
| 12/10/10 ^(b) | 2,039.59 |
| 01/20/11 ^(b) | 2,039.49 |
| 02/17/11 ^(b) | 2,039.48 |
| 03/21/11 ^(b) | 2,039.49 |
| 04/09/11 ^(b) | 2,039.45 |
| 5/11/2011 | 2,039.39 |
| 06/10/11 ^(b) | 2,039.49 |
| 7/8/2011 | 2,039.09 |
| 8/8/2011 | 2,038.39 |
| 9/21/2011 | 2,037.39 |
| 10/12/2011 | 2,037.90 |
| 11/17/2011 | 2,037.89 |
| 12/9/2012 | 2,037.99 |
| 1/11/2012 | 2,038.29 |
| 02/16/12 ^(b) | 2,039.49 |
| 03/14/12 ^(b) | 2,039.49 |
| 04/07/12 ^(b) | 2,039.49 |
| 05/15/12 ^(b) | 2,039.37 |
| 6/12/2012 | 2,039.18 |
| 7/12/2012 | 2,038.79 |
| 8/22/2012 | 2,039.09 |
| 9/14/2012 | 2,037.51 |
| 10/22/2012 | 2,037.09 |
| November 2012 ^{(b)(d)} | NA |
| 12/12/12 ^(b) | 2,039.37 |
| 01/15/13 ^(b) | 2,039.27 |
| 10/24/2013 | 2,038.09 |
| 11/19/2013 | 2,038.09 |
| 12/18/2013 | 2,038.15 |
| 1/29/2014 | 2038.69 |
| 2/26/2014 ^(b) | 2,039.29 |
| 3/28/2014 ^(b) | 2,039.23 |
| 4/23/2014 | 2,039.13 |
| 5/28/2014 | 2,038.84 |
| 6/17/2014 | 2,038.61 |
| 7/28/2014 | 2,038.12 |
| 8/21/2014 | 2,037.39 |
| 9/17/2014 | 2,038.39 |
| 10/24/2014 | 2,038.31 |
| 11/25/2014 | 2,037.52 |
| 12/11/2014 | 2,038.39 |

| Date | Water Level Elevation ^(a) |
|------------|--------------------------------------|
| Measured | (feet) |
| 1/29/2015 | 2,039.39 |
| 2/20/2015 | 2,039.36 |
| 3/31/2015 | 2,039.39 |
| 4/24/2015 | 2,039.20 |
| 5/22/2015 | 2,038.89 |
| 6/25/2015 | 2,038.30 |
| 7/14/2015 | 2,037.94 |
| 8/10/2015 | 2,037.44 |
| 9/30/2015 | 2,036.84 |
| 10/28/2015 | 2,036.69 |
| 11/23/2015 | 2,036.78 |
| 12/18/2015 | 2,037.99 |
| 1/26/2016 | 2,039.41 |
| 2/25/2016 | 2,039.37 |
| 3/21/2016 | 2,039.44 |
| 4/22/2016 | 2,039.22 |
| 5/27/2016 | 2,039.01 |
| 6/28/2016 | 2,038.49 |
| 7/19/2016 | 2,038.09 |
| 8/18/2016 | 2,037.59 |
| 9/23/2016 | 2,037.04 |
| 10/21/2016 | 2,037.95 |
| 11/14/2016 | 2,039.39 |
| 12/22/2016 | 2,039.45 |
| 1/31/2017 | 2,039.47 |
| 2/27/2017 | 2,039.53 |
| 3/16/2017 | 2,039.49 |
| 4/19/2017 | 2,039.53 |
| 5/17/2017 | 2,039.43 |
| 6/15/2017 | 2,038.95 |
| 6/27/2018 | 2,038.59 |
| 4/23/2019 | 2,039.48 |
| 4/29/2020 | 2,039.19 |
| 4/6/2021 | 2,039.39 |

Notes:

- (a) Pond water surface elevation relative to NAVD 88. Water level elevation corresponds to the event gauge reading at the pond plus a base elevation of 2,036.59 feet mean sea level (MSL).
- (b) Water within the pond was discharging to overflow sump.
- (c) Not measured because the pond's staff gauge shifted position, requiring maintenance during subsequent operation and maintenance (O&M) visit.
- (d) Water level was within normal range for the time of year. However, a precise water level is not available
- NM = not measured.

NA = not available.

Attachment B

Site Photographs



Photo #1: Hole in fence enclosing the dross cap.



Photo #2: Stormwater retention pond and overflow sump.



Photo #3: Dross cap area.



Photo #4: Monitoring well MW-4; to be converted to a traffic-rated flush mount.