SHARF

SHARP Report — Part 1 of 2

Go to s	site cont	aminatio	n history

• SHARP first SHARP	v20	24.04.29	Ecology I	nfo
 SHARP rating 	Low		ERTS	726859
 SHARP date 	07/17/2024		CSID	17081
EJFlagged?	✓ – No Override		FSID	100002637
 LD confidence level 	low		VCP	none
 Cleanup milestone 	initial investigation		UST ID	none
• SHARPster	Cecilia Henderson		LUST ID	none

This section i	is blank	if this is	the first	SHARP
----------------	----------	------------	-----------	--------------

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	high	multiple chemical types	0
Groundwater	D4	medium	risk to off-site people	\Diamond
Surface water	D4	high	climate change impacts	\Diamond
Sediment	D4	high	plant/animal tissue data	\Diamond
Soil	D4	high		

Location and land use info

2210 Northeast 150th Street, Shoreline, King County, 98155

Primary parcel 1626049109
Land use recreational
Responsible unit NWRO

Sources reviewed	
Remedial Action Letter Report, PBS Engineering and Environmental LLC. June 13, 2024.	



Primary census tract	Associated census tracts
53033021100	none

Local demographics cor	mments
Local demographics con no comments	mments
Source/source area des	cription
site reportedly formerly conta unspecified date. In 2023, the	as South Woods Park owned by the City of Shoreline. The northern area of the ined a structure of unspecified purpose which was destroyed in a fire on an former structure area was observed to contain stockpiles of soil and debris. Soil stockpiles reported concentrations of petroleum constituents and lead exceeding ls.
Soil comments	
	in 2024 removed all known petroleum and lead impacted soil as confirmed with s.
Groundwater comments	
	d to maximum depth explored of 30 inches bgs.



Surface water comments
No surface water on site.
Sediment comments
No sediment on site.
Indoor air comments
No buildings on site.
Additional factors comments
no comments



Site history Go to top

In 2023, PBS inspected the site and observed stockpiles of soil and debris in the area of the former structure fire. PBS collected soil samples from the stockpiles which reported concentrations of TPH-G, TPH-D, BTEX, naphthalene, and lead exceeding MTCA Method A cleanup levels. These findings were reported to Ecology and assigned ERTS No. 726859.

In January 2024, the impacted soil/debris stockpiles were removed and the top two inches of soil underneath the stockpiles was excavated in an area encompassing approximately 46 by 75 feet. A total of 448.65 tons of impacted soil was transported off-site for disposal. Confirmation soil samples were collected at six inches bgs in the excavation area. Laboratory analytical results reported concentrations of lead exceeding MTCA Method A cleanup levels in two soil sampling areas (labeled SS-5 and SS-7) collected from the southwestern area of the excavation.

In February 2024, additional soil samples collected were collected in the SS-5 and SS-7 areas to 30 inches bgs to characterize remaining lead impacts to soil. Concentrations of lead in soil exceeding MTCA Method A cleanup levels were reported at SS-5 up to 12 inches bgs and at SS-7 at up to 18 inches bgs; soil samples in these locations were below MTCA Method A cleanup levels at and below 18 and 24 inches (respectively).

In April 2024, additional remedial excavation was completed to remove lead impacted soil in the southeastern excavation areas of SS-5 and SS-7 to a maximum depth of 24 inches bgs. An additional 79.35 tons of impacted soil was transported off-site for disposal.



Overflow -	Site contamination and cleanup history
No overflow	

17081 South Woods Park 20240717

First SHARP

SHARP rating — Low

SHARP Report — Part 2 of 2

Conceptual site model 07/17/2024



