



Shane C. DeGross
Assistant Director
Environmental Remediation

BNSF Railway Company
605 Puyallup Avenue
Tacoma, WA 98421

Phone: (253) 591-2567
E-mail: Shane.DeGross@bnsf.com

23 July 2024

Sent via email

Mr. Ted Uecker
Site Manager
Washington State Department of Ecology
4601 North Monroe Street
Spokane, Washington 99205

Subject: 2024 Cap Inspection and Repair
Hillyard Lead Soils Site, Spokane, Washington
FSID No: 960924; CSID No. 1371

Mr. Uecker:

Per the restrictive covenant for the site, cap inspections are performed once every two years, the prior formal inspection occurring in August of 2023. In June of 2024 fence repairs were performed at the site. Two locations were identified where the fence had been cut and fence panels stolen. This letter presents a photo log of the damaged portions of the fence and the repairs made. There was no disturbance to the cap or any erosion and the remedy remains protective. The next formal inspection will occur in 2025, however more frequent informal fence line inspections may be conducted while the North Spokane Corridor construction is underway.

If you have any questions, please call me at (253) 591-2567.

Thank you,
Shane DeGross

A handwritten signature in blue ink that reads "Shane C. DeGross".

Assistant Director Environmental Remediation
BNSF Railway Company

BNSF

Fence Repair
Hillyard Lead CAP
Spokane, Washington

SES Project No.:
1480-011

Photo No.
1

Direction Photo Taken:
Easterly

Description:

Northern boundary of the fence line prior to work completed seen from the west.



Photo No.
2

Direction Photo Taken:
Westerly

Description:

Northern boundary of the fence line prior to work completed seen from the east.



BNSF

Fence Repair
Hillyard Lead CAP
Spokane, Washington

SES Project No.:
1480-011
Date: 6/25/2024

Photo No.
3

Direction Photo Taken:
Easterly

Description:

Repaired and reinforced section of fence along north side of lead CAP.



Photo No.
4

Direction Photo Taken:
Westerly

Description:

Repaired and reinforced section of fence along north side of lead CAP.



BNSF

Fence Repair
Hillyard Lead CAP
Spokane, Washington

SES Project No.:
1480-011
Date: 6/25/2024

Photo No.
5

Direction Photo Taken:
Southeasterly

Description:

Hole cut into a section of the east side of the fence repaired with wire.



Photo No.
6

Direction Photo Taken:
Westerly

Description:

Hole cut into a section of the west side of the fence repaired with wire.

