PHASE II

ENVIRONMENTAL

SITE ASSESSMENT

REPORT

MAR 2 2 2006

DEPT OF ECOLOGY

PROPERTY LOCATED 6317 CALIFORNIA AVENUE S.W. SEATTLE, WASHINGTON

Short Stop 1 Site

Prepared By

Paul W. Stemen

Stemen Environmental, Inc.

PHASE II ENVIRONMENTAL SITE ASSESSMENT REPORT

PROPERTY LOCATED 6317 CALIFORNIA AVENUE S.W. SEATTLE, WASHINGTON

Short Stop 1 Site

Prepared By

Paul W. Stemen

Stemen Environmental, Inc.

STEMEN ENVIRONMENTAL, INC.

P.O. BOX 3644 LACEY, WASHINGTON 98509-3644 CONTR. LIC. #STEMEEI081J9

Telephone 360-438-9521 Fax 360-412-1225

January 13, 2002

Mr. Vernon Pontius 7730 Cabrini Dr Port Orchard, WA 98367

Dear Mr. Pontius:

RE: PHASE II ENVIRONMENTAL SITE ASSESSMENT FOR FORMER U.S.T. SITE/COMMERCIAL PROPERTY LOCATED AT 6317 CALIFORNIA AVENUE S.W., SEATTLE, WASHINGTON. ECOLOGY SITE #101565.

SITE CHARACTERISTICS AND BACKGROUND

The subject property, Tax Parcel #762570, consists of 20,378 square feet of developed commercial property. The subject property is located in the northwest quarter of section 26, township 24 range 3 east, and is located within the boundaries of the City of Seattle, King County, Washington.

The subject property is bordered on the north by a residential building/property, on the west by residential properties, on the south by an asphalt surfaced roadway and a former full service vehicle fueling station, and on the east by California Avenue S.W., an asphalt surfaced public roadway.

The property is currently occupied by an approximately 3,400 square foot commercial building. The commercial building is surrounded by asphalt surfaced parking lots of various sizes. An earthen surfaced area is present on the southwestern portion of the property.

Available information indicates that several years ago a full service car wash was operated on this site. It is not known if any or all of the underground components/equipment associated with the car wash were removed at the time of it's closure.

The northern portion of the on-site building is currently and for several years has been occupied by a convenience store, while the southern portion of the building is currently and for several years has been occupied by a dry cleaning business.

In recent years a self service vehicle fueling station was operated in conjunction with the convenience store, on the eastern portion of the subject property. The vehicle fueling station was serviced by three underground gasoline storage tanks and their associated pump island.

In 1991, a "30 Day Notice of Intent to Close/Decommission Tanks" form was filed with the Department of Ecology by O'Sullivan Construction. The document indicated that the two (2) 10,000 gallon, and one (1) 6,000 gallon capacity underground gasoline storage tanks present on this site were to be decommissioned on approximately April 15, 1991.

Available information indicates that the three (3) underground gasoline storage tanks were excavated and removed from this site as planned. During the tank removal project, an unknown quantity of petroleum impacted soils were removed from the tank excavation pit and stockpiled on the earthen surfaced area located on the southwestern portion of the property.

The excavation was then backfilled and the area was resurfaced using asphalt.

Eventually the soils present in the petroleum impacted soils stockpiles were distributed evenly across earthen surfaced portion of the site.

Recently, during a routine historical records search, it was learned that an Underground Storage Tank Removal/Decommissioning Site Assessment Report for this site had not been properly filed with the Department of Ecology and that the tanks were still listed on the Department of Ecology's database as being "in use".

Additionally, the confirmed release of petroleum products (gasoline) to the soils and/or groundwaters beneath this site was not properly reported to the Department of Ecology.

During a recent on-site visit, I observed that most of the concrete pump island drive slabs and a capped abandoned steel pipe were still present in the asphalt surfaced parking lot located just east of the convenience store building. Additionally the outline of the asphalt patch placed over the former tank excavation/removal pit was still clearly visible.

I also observed liquids being discharged (dumped) outside the rear door of the dry cleaner's portion of the on-site building. These liquids flowed across the pavement and then pooled on the earthen surfaced portion of the property. These pooled liquids appeared to have suds on their surface. It should also be noted that the asphalt surface materials present in the discharged waters flow area appeared to be aged/distressed/etched to a greater extent than the asphalt in surrounding areas.

On April 5, 2001 I proceeded to obtain eighteen (18) discreet soil samples and five (5) discreet groundwater samples from sixteen (16) separate selected sampling locations on the subject property.

Investigative soil and groundwater sampling locations were selected based on this consultant's on-site observations, and additional information obtained during on-site conversations with knowledgeable interested parties.

The results of the Phase II Environmental Site Assessment and Site Characterization Study performed on the subject property confirmed the presence of gasoline range Total Petroleum Hydrocarbons (T.P.H.) and/or Specific Halogenated Hydrocarbons at levels that exceed the Department of Ecology's Method "A" Clean Up Levels in the soils and/or groundwaters present beneath selected locations on this site.

The samples with the highest concentrations of the above listed contaminants were confirmed in the soils and groundwaters present beneath a portion of the asphalt surfaced parking lot which is located less than 10 feet east of the northern portion of the eastern exterior wall of the on-site dry cleaner's building.

The results of this on-site investigation also confirmed the presence of Specific Halogenated Hydrocarbons in the surface and shallow subsurface soils present at selected locations on the rear (western) portion of the subject property (site).

Based on the results of these on-site investigations, a confirmed release of gasoline range T.P.H., B.T.E.X.'s, and Specific Halogenated Hydrocarbons to the soils and groundwaters beneath this site was immediately reported to the Department of Ecology's Northwest Regional Office.

Additionally, after having discussions with you and members of the Department of Ecology's Staff, this site was entered into the Department of Ecology's Voluntary Clean Up Program.

In an attempt to identify the sources and/or release points of the substances containing Specific Halogenated Hydrocarbons, and to further characterize the impacts of the releases of Specific Halogenated Hydrocarbons and Petroleum Products to the soils and groundwaters beneath this site, it was determined by all of the interested parties, that additional inquiries and/or on-site investigations should be performed.

It was agreed that these proposed on-site investigations would be primarily focused on the subsurface soils and groundwaters beneath the areas directly adjacent to the northeast corner of the dry cleaner's portion of the on-site building. The subsurface soils and groundwaters will be sampled at various depths and locations on the interior of the building as well as the exterior of the building.

Native soils present on this site from just below the surface to an approximate depth of 20 feet below ground surface (b.g.s.) consisted of brownish colored medium grained sands.

Depth to groundwater beneath this site was approximately 12 to 14 feet b.g.s. on the date of these on-site investigative sampling activities.

A body of surface waters, the Puget Sound, is present approximately one (1) mile west of the subject property.

INVESTIGATIVE SOIL AND GROUNDWATER SAMPLING

The primary objectives of these on-site investigative activities was to characterize the vertical migration of Tetrachloroethene (PERC) and other Specific Halogenated Hydrocarbons in the subsurface soils and groundwaters present beneath selected locations on the subject property. Additionally, as time allows, we will investigate the subsurface soils and/or groundwaters at additional selected locations on the subject for the presence of gasoline range T.P.H., B.T.E.X.'s, and/or Specific Halogenated Hydrocarbons.

On September 25, 2001, I proceeded to obtain seven (7) discreet soil samples and eight (8) discreet groundwater samples from six (6) separate selected sampling locations on the subject property. Two (2) of these selected sampling locations were located on the interior of the dry cleaner's portion of the on-site building, while four (4) of these sampling locations were located on the exterior of the on-site building.

Current soil and groundwater sampling locations were selected based on this consultant's on-site observations, the observations of other interested parties, and the information obtained during previous on-site investigative project.

All soil samples were field screened using a water sheen test.

Selection of various investigative soil and groundwater samples for submission for appropriate laboratory analyses was based on the results of previous on-site investigations and/or this consultants observations.

INTERIOR SAMPLING LOCATIONS

SAMPLING LOCATION IS-1

Soil sampling location IS-1 was located on the interior of the dry cleaner's portion of the on-site building. This sampling location was situated approximately 5 feet west and 10 feet south of the interior northeast corner of the dry cleaner's portion of the on-site building. This sampling location was located directly in front of the front access door/portal for the currently in use dry cleaning equipment present on this site.

A rotohammer equipped with a concrete coring bit was used to create an access port through the buildings concrete floor.

All soil and groundwater samples taken at this interior sampling location were obtained using a Limited Access Direct Push Sampling System.

Investigative soil sample IS-1-0/2 was obtained from subsurface soils present at depth of 2 feet or less b.g.s. (below ground surface), soil sample IS-1-6/8 was obtained from soils present

at depths ranging between 6 to 8 feet b.g.s., soil sample IS-1-8/10 was obtained from soils present at depths ranging between 8 to 10 feet b.g.s., soil sample IS-1-12/14 was obtained from soils present at depths ranging between 12 to 14 feet b.g.s., and soil sample IS-1-14/16 was obtained from soils present at depths ranging between 14 to 16 feet b.g.s.,

Investigative groundwater sample STDR was obtained from waters present at a depth of approximately 12 feet b.g.s. at this sampling location.

Although the Limited Access Direct Push Sampling System is capable of obtaining samples at greater depths if needed, it does require more time than exterior sampling equipment/devices. It was my decision that the vertical extent of the plume would be investigated at a selected exterior sampling location.

All of these soil and groundwater samples were immediately submitted for appropriate laboratory analyses.

SAMPLING LOCATION BRDR

Sampling location BRDR was located in the rear storage room of the Dry Cleaner's portion of the on-site building. Water sample BRDR was obtained from waters that were being deposited/discharged into an open drain from a garden hose which was attached to the rear portions of the in-use/operational on-site dry cleaning equipment.

Currently it is not known where the waters placed in this drain eventually end up.

EXTERIOR SAMPLING LOCATIONS

SAMPLING LOCATION S-13

Sampling location S-13 was located on the exterior of the on-site building. Sampling location S-13 was situated approximately 12 feet east of sampling location IS-1 and directly adjacent to previous investigative sampling location S-5.

Investigative soil sample S-13-14/17 was obtained from subsurface soils/sands present at depths ranging between 14 to 17 feet b.g.s. at this sampling location.

Investigative groundwater sample S-13-20 was obtained from waters present at a depth of 20 feet b.g.s., groundwater sample S-13-28 was obtained from waters present at a depth of 28 feet b.g.s., and groundwater sample S-13-35 was obtained from waters present at a depth of 35 feet b.g.s.

All of these soil and groundwater samples were immediately submitted for appropriate laboratory analyses.

SAMPLING LOCATION S-14

Sampling location S-14 was located approximately 15 feet east and 8 feet south of the southeast corner of the dry cleaner's portion of the on-site building.

Investigative soil sample S-14 was obtained from subsurface soils/sands present at depths ranging between 14 to 17 feet b.g.s.

Investigative groundwater sample S-14-W was obtained from waters present at a depth of approximately 20 feet b.g.s. at this sampling location.

All of these soil and groundwater samples were immediately submitted for appropriate laboratory analyses.

SAMPLING LOCATION S-15

Sampling location S-15 is located approximately 7 feet south and 10 feet west of the southeast corner of the on-site building, and directly adjacent to previous investigative sampling location S-8.

Investigative groundwater sample S-15-W was obtained from waters present at a depth of approximately 20 feet b.g.s. at this sampling location.

This water sample was submitted for appropriate laboratory analyses.

SAMPLING LOCATION DW-1

Sampling location DW-1 was located approximately 5 feet north and 10 feet east of the southeast corner of the on-site building. A stormwater catch basin is present at this sampling location. This catch basin has a steel grate which covers it's surface access port.

Investigative water sample DW-1 was obtained from standing waters which were present in the lower portions of the catch basin. The surface of these pooled waters exhibited a petroleum product type sheen on their surface.

This water sample was submitted for appropriate laboratory analyses.

SOIL SAMPLING AND LABORATORY ANALYSES

All discreet soil samples were obtained using a "Direct Push Sampling System" provided and operated by factory trained technicians from Environmental Services Network Northwest, Lacey, Washington. Continuous soil corings were extended to depths ranging from approximately 1 to 35 feet below ground surface (b.g.s.). Continuous soil coring/samples (split spoon samplers) were laid out in order by depth on the surface to facilitate field screening and observation of the soils obtained from various depths.

All discreet groundwater samples were obtained using a parastaltic pump and the "Direct Push Sampling System". The system's sampling tube was purged of all collected waters and then allowed to recharge prior to the collection of these water samples.

All sampling tools/devices were properly cleaned between individual samples to prevent cross sample contamination. All soil samples were then tightly packed in recommended sample jars with no head space, properly refrigerated and transported with proper chain of custody forms, to Environmental Services Network Northwest Inc. of Lacey, Washington, for appropriate laboratory analyses.

All soil and/or groundwater samples were screened for gasoline range T.P.H. (total petroleum hydrocarbons) using method NWTPH-Gx and Volatile Organic Compounds (V.O.C.'s) using EPA method 8021 B.

Groundwater elevations were measured using an electronic water level indicator. Depth to water was measured from the ground surface over the individual sampling location.

All laboratory analyses methods and quality controls meet or exceed current Department of Ecology recommendations for Site Checks and Site Assessments.

Laboratory analyses results for soil samples IS-1-0/2, IS-1-14/16, IS-1-6/8, IS-1-8/10, IS-1-12/14 and groundwater sample STDR confirmed the presence of Specific Halogenated Hydrocarbons at levels that exceeded the Department of Ecology's Method "A" Clean Up Levels in the sampled soils present the beneath the portion of the on-site buildings concrete slab which is situated directly adjacent to and/or beneath the currently in-use dry cleaning equipment. These impacted soils are present at depths ranging from just below the surface to approximately 16 feet b.g.s.

Laboratory analyses results for soil samples IS-1-0/2, IS-1-14/16, IS-1-6/8, IS-1-8/10, IS-1-12/14, S-14, indicated no detectable presence of gasoline range T.P.H. in their respective sampled soils.

Laboratory analyses results for groundwater samples BRDR indicated no detectable presence of Specific Halogenated Hydrocarbons in the waters being discharged into the rear storage room drain.

Laboratory analyses results for groundwater sample S-14-W-20 indicated no presence of gasoline range T.P.H. and/or Specific Halogenated Hydrocarbons at levels that exceeded the Department of Ecology's Method "A" Clean Up Levels in these sampled waters.

Laboratory analyses results for groundwater samples S-13-W-20 and S-15-W-20 indicated no presence of gasoline range T.P.H. at levels that exceeded the Department of Ecology's Method "A" Clean Up Levels in these sampled waters.

Laboratory analyses results for groundwater samples S-13-W-20, S-13-35, and S-15-W-20 confirmed the presence Specific Halogenated Hydrocarbons at levels that exceeded the Department of Ecology's Method "A" Clean Up Levels in these sampled waters.

Laboratory analyses results for catch basin water sample DW-1 confirmed the presence of Special Halogenated Hydrocarbons at levels that exceeded the Department of Ecology's Method "A" Clean Up Levels in the standing/pooled waters present in the lower portions of this catch basin.

HEALTH AND SAFETY

- 1. All on-site work was performed under the Health and Safety guidelines set forth in sections 29 CRF 1910.120 of the Federal Register and Chapter 296-62 WAC which provide regulations for individuals who are engaged in activities involving hazardous substances, including petroleum, and who perform confined space entry during field activities, also Chapter 296-155 WAC which provides State safety standards for construction work.
 - 2. All on-site workers were 40 hour Hazmat certified.
- 3. A copy of the Site Safety Plan was provided to all on-site employees. The contents of this plan and all potential on-site hazards, were discussed during a personnel on-site safety meeting. Based on the contents of this safety plan all workers were required to wear at least Level D protection. First Aid materials and properly trained personnel were present on-site at all times.
- 4. The immediate perimeter of the work area was secured at all times by orange hazard cones.

FACTS AND CONCLUSIONS

1. The results of this on-site investigation confirm the presence of Specific Halogenated Hydrocarbons, at levels that exceed the Department of Ecology's Method "A" Clean Up Levels, in the subsurface soils and groundwaters directly beneath and directly adjacent to the northeast corner of the portion of the on-site building which is occupied by the Dry Cleaners. The remaining presence of Specific Halogenated Hydrocarbons in the soils present at shallow depths beneath this portion of the on-site buildings concrete slab, and the confirmed significant presence of Specific Halogenated Hydrocarbons in the groundwaters present beneath this portion of the subject property, indicates that the discharge point for liquids/materials containing these chemicals is most likely in this immediate area.

2. The results of this on-site investigation confirmed the presence of Specific Halogenated Hydrocarbons in the standing/pooled waters present in the lower portions of the catch basin located approximately 5 feet north and 10 feet east of the southeast corner of the on-site building.

Although the significant presence of Vinyl Chloride, cis-1,2 Dichloroethene, and trans-1,2-Dichloroethene indicate the breaking down/dissipation/aging of the Specific Halogenated Hydrocarbons, it is still highly possible that these chemicals were discharged/flowed into this containment basin in recent times. The exposure of the Specific Halogenated Hydrocarbons to oxygen significantly accelerates the breakdown of these chemicals.

3. The results of this on-site investigation confirmed the presence of Specific Halogenated Hydrocarbons in the subsurface soils present at depths ranging between 14 to 17 feet b.g.s. at sampling location S-14. This sampling location is in relatively close proximity to the on-site stormwater catch basin which contained waters impacted by Specific Halogenated Hydrocarbons.

It should be noted that the groundwaters sampled at this sampling location indicated no detectable presence of Specific Halogenated Hydrocarbons and/or gasoline range T.P.H.

4. The results of this on-site investigation confirmed the presence of Specific Halogenated Hydrocarbons in the groundwaters present at sampling location S-15. This sampling location is situated approximately 7 feet south and 10 feet west of the southeast corner of the on-site building.

Based on the results of the two on-site investigations of subsurface soils and groundwaters beneath this site that our company has recently performed, I have formed the following opinions:

1. The significant presence of Specific Halogenated Hydrocarbons in the soils and groundwaters in the areas directly beneath and/or directly adjacent to the northeast corner of the on-site Dry Cleaner's portion of the building can most likely be attributed to the placement/discharge of liquids containing these chemicals into a floor drain which transports these liquids to their exterior discharge point. It is likely that this speculated drain pipe is connected to the stormwater catch basin located approximately 5 feet north and 10 feet east of the southeast corner of the on-site building. It is believed that the drainage pipe system is leaking. The remaining presence of Specific Halogenated Hydrocarbons in this active catch basin would indicate that very possibly these impacted liquids have been discharged into/flowed through this speculative drainage system and into this catch basin in recent times.

The relatively significant vertical and horizontal migration of Specific Halogenated Hydrocarbons through the soils and/or groundwaters present on this site would indicate that the releases/discharges of impacted liquids containing these contaminants have taken place over an extended period of time.

2. It is highly possible that soils impacted by Specific Halogenated Hydrocarbons were excavated near the northeast corner of the Dry Cleaner's portion of the on-site building, and temporarily stockpiled on-site during the on-site U.S.T. removal activities. These stockpiled materials were screened, by laboratory analyses, for gasoline range T.P.H. and B.T.E.X.'s and that these elements were not found to be present at above acceptable levels.

These apparently suitable backfill materials were placed in the lower portions of the open excavation pit, at various selected locations, and that these backfill materials came in contact with the groundwaters that were reportedly present in lower portions of the excavation at the time backfilling activities took place. The Specific Halogenated Hydrocarbons were transferred from the impacted backfill materials to the subsurface groundwaters.

The above speculated chain of events would account for the presence of groundwaters impacted by Specific Halogenated Hydrocarbons at reportedly upgradient locations on the subject property (sample locations S-1 and S-3).

3. Available information indicates that the excavation of petroleum impacted soils during the U.S.T. removal project were suspended due to the presence of groundwaters in the lower portions of the on-site excavation. This accounts for the remaining presence of gasoline range T.P.H. and B.T.E.X.'s in the soils and/or groundwaters beneath this site at selected locations.

Additionally it should be noted that an unknown quantity of petroleum impacted soils were stockpiled on the rear (western) portion of this property for remediation purposes.

Additional Comments:

- 1. The Dry Cleaner's Site was recently inspected by staff members of various regulatory agencies. The results of the on-site inspections indicated that the currently operational Dry Cleaning equipment appeared to be operating within the current regulatory guidelines. These were only visual inspections of the on-site equipment.
- 2. The operators of the on-site Dry Cleaners were instructed, by a Metro Staff Member to cease the dumping/discharging of any liquids that could potentially contain Specific Halogenated Hydrocarbons out the rear door of the building.

Recommendations:

1. To assist in the further characterization of the groundwaters beneath this site, I would recommend the installation of a minimum of three (3) groundwater monitoring wells, at selected locations on the subject property, and the quarterly monitoring of the groundwaters beneath this site.

Additionally, I would recommend the installation of at least one (1) 4 to 6 inch recovery well at a selected location in close proximity to the northeast corner of the Dry Cleaner's portion of the on-site building. This well could be placed at current sampling location S-13.

2. I would recommend that dye be placed in all of the known on-site drains, associated with the Dry Cleaner's operations, and then flushed with an adequate quantity of water. All storm drains, monitoring wells, and surfaces waters should be monitored periodically for the presence of these dyed waters.

- 3. I would recommend the treatment of the impacted groundwaters beneath this site using an Air Sparging System. This treatment method will have a positive effect on both the Specific Halogenated Hydrocarbons and the gasoline range T.P.H. which have impacted waters. This method will also eventually have a positive effect on the impacted soils present beneath this site. The Air Sparging System would incorporate the use of the proposed on-site recovery well.
- 4. Additionally I would recommend the injection of air into all of the proposed monitoring wells on a periodic basis to facilitate the prompt remediation of the impacted waters.
- 5. In-situ bioremediation treatment of the impacted waters is also a possibility. Unfortunately the microbes/liquid materials that are typically associated with the treatment of waters impacted by Specific Halogenated Hydrocarbons have not been proven to be effective on waters impacted by petroleum hydrocarbons.

Due to the fact that Specific Halogenated Hydrocarbons seem to be the most prevalent contaminant in these impacted waters, I feel that in-situ bioremediation using a solution suited for Specific Halogenated Hydrocarbons would be an attractive remediation option in combination with the proposed Air Sparging Treatment System.

All opinions, observations, and recommendations set forth in this report are based on current available information and on-site conditions, and cannot predict or report on the impacts of future events and/or regulatory requirements on this site.

If you have any questions or need further information please feel free to contact us at the above phone number.

Sincerely,

Paul W. Stemen

Ecology-Registered Site Assessment Supervisor

ASTM Certified

IFCI #0874201-26

cc: Department of Ecology

File

SOIL SAMPLE ANALYSIS TABLE

	PETROLEUM ARBONS (PPN	M)	-NO! Not	for water
SAMPLE NUMBER	SAMPLE DATE	SAMPLE DEPTH	GASOLINE	
SOIL S-14 IS-1-2/14 S-13-14/17	9-26-01 9-26-01 9-26-01	14'-17' 14' 17'	ND ND ND	-no:240 ppm
WATER S-13-W-20 S-15-W-20 S-14-W-20	9-26-01 9-26-01 9-26-01	20' 20' 20'	520 pyll 870 pyll ND	(1/9

WATER SPECIFIC HALOGENATED HYDROCARBONS MY

SAMPLE-NUMBER	DW-1	STDR	BRDR	S-13-W-20	S-13-W-28	S-13-W-35	S-14-W-20	S-15-W-20
DATE	9-25-01	9-25-01	9-25-01	9-25-01	9-25-01	9-25-01	9-25-01	9-25-01
VINYL CHLORIDE	2800	ND	ND	ND	ND	ND	ND	ND
BENZENE	ND	ND	ND	ND	ND	ND	ND	ND
TOLUENE	3.5	ND	ND	37	1.4	270	ND	13
ETHYLBENZENE	ND	ND	ND	23	1.8	320	ND	31
XYLENES	5.9	ND	ND	110	9.1	2300	ND	190
1,1 DICHLORETHENE	ND	ND	ND	ND	ND	ND	ND	ND
METHYLENE CHLORIDE	ND	ND	ND	ND	ND	ND	ND	ND
FRANS 1,2 DICHLOROETHENE	51	ND	ND	ND	ND	ND	ND	ND
1.1 DICHLOROETHANE	ND	ND	ND	ND	ND	ND	ND	ND
CIS-1,2 DICHLOROETHENE	2900	33	ND	ND	ND	ND	ND	ND .
CHLOROFORM	ND	ND	ND	ND	ND	ND	ND	ND
.1.1 TRICHLOROETHANE (TCA)	ND	ND	ND	ND .	ND	ND	ND	ND
CARBON TETRACHLORIDE	ND	ND	ND	ND	ND	ND	ND	ND
1,2 DICHLOROETHANE	ND	ND	ND	ND	ND	ND	ND	ND
TRICHLOROETHENE (TCE)	ND	180	ND .	9.1	ND	9.1	ND	3.3
1,1,2 TRICHLOROETHANE	ND	ND	ND	ND	ND	ND	ND	ND
ETRACHLOROETHENE (PCE)	5.5	4800	ND	36	3.8	180	ND	9.9
1,1,1,2 TRICHLOROETHANE	ND	ND	ND	ND	ND	ND	ND	ND
1,1,2,2 TRICHLOROETHANE	ND	ND	ND	ND	ND	ND	ND	ND
CHLOROMETHANE	ND	ND	ND	ND	ND	ND	ND	ND
BROMOMETHANE	ND	ND	ND	ND	ND	ND	ND	ND
CHLOROETHANE	ND	ND	ND	ND	ND	ND	ND	ND
1,2 DICHLOROPROPANE	ND	ND	ND	ND	ND	ND	ND	ND
BROMODICHLOROMETHANE	ND	ND	ND	ND	ND	ND	ND	ND
CIS-1,3 DICHLOROPROPENE	ND	ND	ND	ND	ND	ND	ND	ND
RANS-1,3 DICHLOROPROPENE	ND	ND	ND	ND	ND	ND	ND	ND
CHLOROBENZENE	ND	ND	ND	ND	ND	ND	ND	ND
DIBROMOCHLOROMETHANE	ND	ND	ND	ND	ND	ND	ND	ND
BROMOFORM	ND	ND	ND	ND	ND	ND	ND	ND
BROMOBENZENE	ND	ND	ND	ND	ND	ND	ND	ND
1,2,3 TRICHLOROPROPANE	ND	ND	ND	ND	ND	ND	ND	ND
DIBROMOMETHAND	ND	ND	ND	ND	ND	ND	ND	ND
M-DICHLOROBENZENE	ND	ND	ND	ND	ND	ND	ND	ND
P-DICHLOROBENZENE	ND	ND	ND	ND	ND	ND	ND	ND
O-DICHLOROBENZENE	ND	ND	ND	ND	ND	ND	ND	ND

SOIL SPECIFIC HALOGENATED HYDROCARBONS

SAMPLE-NUMBER	S-13-14/17	S-14	IS-1-2/14	
DATE	9-25-01	9-25-01	9-25-01	
VINYL CHLORIDE	ND	ND	ND	
BENZENE	ND	ND	ND	
TOLUENE	11000	330	ND	
ETHYLBENZENE	29000	1100	ND	
XYLENES	180000	6500	120	
1,1 DICHLORETHENE	ND	ND	ND	
METHYLENE CHLORIDE	ND	ND	ND	
TRANS 1,2 DICHLOROETHENE	ND	ND	ND	
1,1 DICHLOROETHANE	ND	ND	ND	
CIS-1,2 DICHLOROETHENE	ND	ND	ND	
CHLOROFORM	ND	ND	ND	
1,1 TRICHLOROETHANE (TCA)		ND	ND	
CARBON TETRACHLORIDE	ND	ND	ND	get 1
1,2 DICHLOROETHANE	ND	ND	ND	
TRICHLOROETHENE (TCE)	ND	ND	ND	
1,1,2 TRICHLOROETHANE	ND	ND	ND	
ETRACHLOROETHENE (PCE)	5100	440	400	
1,1,1,2 TRICHLOROETHANE	ND	ND	ND	
1,1,2,2 TRICHLOROETHANE	ND	ND	ND	
CHLOROMETHANE	ND -	ND	ND	
BROMOMETHANE	ND	ND	ND	
CHLOROETHANE	ND	ND	ND	
1,2 DICHLOROPROPANE	ND	ND .	ND	
BROMODICHLOROMETHANE	ND	ND	ND	
CIS-1,3 DICHLOROPROPENE	ND	ND	ND	
RANS-1,3 DICHLOROPROPENE	ND	ND	ND	
CHLOROBENZENE	ND	ND	ND	
DIBROMOCHLOROMETHANE	ND	ND	ND	
BROMOFORM	ND	ND	ND	
BROMOBENZENE	ND	ND	ND	
1,2,3 TRICHLOROPROPANE	ND	ND	ND	
DIBROMOMETHAND	ND	ND	ND	
M-DICHLOROBENZENE	ND	ND	ND	
P-DICHLOROBENZENE	ND	ND	ND	
O-DICHLOROBENZENE	ND	ND	ND	
750				

SOIL SPECIFIC HALOGENATED HYDROCARBONS (fm)

SAMPLE-NUMBER	IS-1-0/2	IS-1-14/16	IS-1-6/8	IS-1-8/10
DATE	10-01-01	10-01-01	10-01-01	10-01-01
VINYL CHLORIDE BENZENE TOLUENE ETHYLBENZENE TOTAL-XYLENE 1,1 DICHLORETHENE METHYLENE CHLORIDE RANS 1,1 DICHLOROETHENE 1,1 DICHLOROETHENE CHLOROFORM 1,1 TRICHLOROETHANE (TCA) CARBON TETRACHLORIDE 1,2 DICHLOROETHANE TRICHLOROETHANE TRICHLOROETHANE TRICHLOROETHANE ETRACHLOROETHANE ETRACHLOROETHANE TRICHLOROETHENE (PCE) 1,1,2 TRICHLOROETHANE T,1,2,2 TRICHLOROETHANE	ND N	0.06 ND	ND N	0.17 ND

October 5, 2001

Paul Stemen Stemen Environmental 5724 Puget Beach Road NE Olympia, WA 98516

Dear Mr. Stemen:

Please find enclosed the analytical data report for the Short Stop Project in Seattle, Washington. Soil samples were analyzed for Specific Halogenated Hydrocarbons and BTEX by Method 8021B on October 3, 2001.

The results of these analyses are summarized in the attached table. All soil values are reported on a dry weight basis. Applicable detection limits and QA/QC data are included. An invoice for this analytical work is also enclosed.

ESN Northwest appreciates the opportunity to have provided analytical services to Stemen Environmental for this project. If you have any further questions about the data report, please give me a call. It was a pleasure working with you on this project, and we are looking forward to the next opportunity to work together.

Sincerely,

Michael A. Korosec

Michael a Koron

President

ESN NORTHWEST CHEMISTRY LABORATORY

SHORT STOP PROJECT Seattle, Washington Stemen Environmental, Inc.

Specific Halogenated and Aromatic Hydrocarbons (EPA 8021B) in Soil

Sample Description		Method	IS-1-0/2	IS-1-14/16	IS-1-6/8	IS-1-8/10
odinpio Description		Blank				
Date Sampled			10/1/01	10/1/01	10/1/01	10/1/01
Date Analyzed		103/01	10/3/01	10/3/01	10/3/01	10/3/01
,	MDL					(11-1
	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)
	2.25			nd	nd	nd
Vinyl chloride	0.25	nd	nd	0.06	nd	0.17
Benzene	0.02	nd	nd	nd	nd	nd
Toluene	0.05	nd	nd		nd	nd
Ethylbenzene	0.05	nd	nd	nd		nd
Total Xylenes	0.05	nd	nd	nd	nd	
1,1-Dichloroethene	0.05	nd	nd	nd	nd	nd
Methylene chloride	0.01	nd	nd	nd	nd	nd
trans -1,2-Dichloroethene	0.05	nd	nd	nd	nd	nd
1,1-Dichloroethane	0.05	nd	nd	nd	nd	nd
cis -1,2-Dichloroethene	0.05	nd	nd	nd	nd	nd
Chloroform	0.05	$\mathbf{n}\mathbf{d}$	nd	nd	nd	nd
1,1,1-Trichloroethane (TCA)	0.05	nd	nd	nd	nd	nd
Carbon tetrachloride	0.05	nd	nd	nd	nd	$\mathbf{n}\mathbf{d}$
1,2-Dichloroethane	0.05	nd	nd	nd	nd	. nd
Trichloroethene (TCE)	0.02	nd	0.04	nd	nd	0.05
1,1,2-Trichloroethane	0.05	nd	nd	nd	nd	nd
Tetrachloroethene (PCE)	0.02	nd	4.9	0.14	1.17	0.58
1,1,1,2-Tetrachloroethane	0.05	nd	nd	nd	nd	$\mathbf{n}\mathbf{d}$
1,1,2,2-Tetrachloroethane	0.05	nd	nd	nd	nd	nd
Surrogate Recovery (%)		132	97	91	87	81

[&]quot;nd" Indicates not detected at listed detection limit.

ACCEPTABLE RECOVERY LIMITS FOR SURROGATE (Chlorobenzene): 65%- 135%

ANALYSES PERFORMED BY: Marilyn Farmer

[&]quot;int" Indicates that interference prevents determination.



CHAIN-OF-CUSTODY NEC _ ID *

CLIENT: STE	n Er) E	NUM	es ME	TV		T	<u>C</u> _					D.	ATE	:_/	10/	1	0	_			PA	GE	_OF/		
ADDRESS:													P	RO.	JEC	TN	IAM	E: -	5	fe	n		STUP			
PHONE: 3604	138-	552	-	FA	X: _								LOCATION: SEATTLE, LIN													
CLIENT PROJECT	#:	ntoru	STOP	PROJE	CT N	ANA	AGEF	R:/	PAVI	Si	Ch	ر	C	OLI	EC	то	R:_	P) <u> </u>		57	EN	(4)	COLLECTION	4	21
Sample Number	Depth	Time	Sample Type	Container Type	AH V	567/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2			10/2/8/20/20/20/20/20/20/20/20/20/20/20/20/20/	5 9 5 C	1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	× /10	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	a diling	Chor	% /		NOTES		Total Number	of Containers Laboratory Note Number
	0-2		SIL	Jan	X				1																	1
2. #58-1-14/16	-		1		7									3					_	1	4					4
3 15-1-6/8	4/8				لم											_	_	_	4	1	-	_				-
3. 75-1-6/8 4. 75-1-8/10	2/10				6									_	_	_	_	_	4	4	\dashv	>			+	+
5.		•											_	_	_	-	-	\dashv	4	+	4	-			+	+
C													_	_	_	_	\dashv	\dashv	_	+	-	\dashv		-	+	\dashv
7.												- 1		_	_	-	-	_	-	\dashv	\dashv		·		+	+
9. 10.													_	_	_	-	_	_	-	+	\dashv				+	+
9.		-											_	_		_	4	4	+	\dashv		_			+	+
10.						\perp							_	_	-	_		-	+	-	_	_			+	+
11.							$\perp \perp$	_					_	_			-	\dashv	-	-					+	+
12.								_					_	-	-	_		\dashv	\dashv	-	-				+	+
12. 13.							$\perp \perp$				-		_					-	-	\dashv	\dashv				+	+
14.							$\perp \perp$	_					_	_	_	_	-	-	-	-					+	-
15.		· .,				_	$\perp \perp$						_	_	_		-	-	\dashv	\dashv	\dashv				+	-
16.				1	\sqcup		\perp	_		_			_		_	-	-	-	\dashv	-	\dashv				-	-
17.										_			_		_	_	-	-	-	-	\dashv				+	
18.						\perp	$\perp \perp$	\perp			<u></u>									-		_				
RELINQUISHED BY (Signa	iture)	DA	TE/TIME	RECEIV	ED B	Y (Sign	ature)		DATE		-		·		APLE					\dashv		14	ABORATORY NOTI	ES:		
10/1/01 Julary leury 9:10 Am			-	OTAL								-		1												
RELINDUISHED BY (Signa	ture)	DA	TE/TIME	RÉCEIV	ED B	Y (Sign	ature)		DATE	TIME	-	HAIN					ALS	1/N/I	VA	-		1				
V				-	SEALS INTACT? Y/N/NA																					
SAMPLE DISPOSAL INSTRUCTIONS					F	RECE	IVED	GO	OD C	OND	./CO	LD		-		٠,	urn Around Times	24 HD 40	. HP	5 DAV						
☐ ESN DISPOSAL @ \$2.00 each ☐ Return ☐ Pickup					7	NOTES: Turn Around Time: 24 HR 48 HR 5 D				5 DAT																

October 11, 2001

Paul Stemen Stemen Environmental 5724 Puget Beach Road NE Olympia, WA 98516

Dear Mr. Stemen:

Please find enclosed the analytical data report for the Short Stop Project in Seattle, Washington. Direct Push services were conducted on September 25, 2001. Soil and water samples were analyzed for Gasoline by NWTPH-Gx and Specific Halogenated Hydrocarbons and BTEX by Method 8021B on September 26 & 27, 2001.

The results of these analyses are summarized in the attached table. All soil values are reported on a dry weight basis. Applicable detection limits and QA/QC data are included. An invoice for this analytical work is also enclosed.

ESN Northwest appreciates the opportunity to have provided analytical services to Stemen Environmental for this project. If you have any further questions about the data report, please give me a call. It was a pleasure working with you on this project, and we are looking forward to the next opportunity to work together.

Sincerely,

Michael A. Korosec

Michael a Kaine

President

ESN NORTHWEST CHEMISTRY LABORATORY

SHORT STOP PROJECT
Seattle, Washington
Stemen Environmental Incorporated
Client Project #Short Stop

Analyses of Gasoline (NWTPH-Gx) in Soil

Sample	6.2	Date	Surrogate	Gasoline
Number		Analyzed	 Recovery (%)	(mg/kg)
Method Blank		9/26/01	90	nd
S-14		9/26/01	76	nd
IS-1-2/14		9/26/01	71	nd
S-13-14/17		9/26/01	70	240
				10
Method Detection	on Limits			10

[&]quot;nd" Indicates not detected at the listed detection limits.

ACCEPTABLE RECOVERY LIMITS FOR SURROGATE (Chlorobenzene): 65% TO 135%

ANALYSES PERFORMED BY: Dean Phillips

[&]quot;int" Indicates that interference prevents determination.

ESN NORTHWEST CHEMISTRY LABORATORY

SHORT STOP PROJECT Seattle, Washington Stemen Environmental Incorporated Client Project #Short Stop

Analyses of Gasoline (NWTPH-Gx) in Water

g 1	Date	Surrogate	Gasoline
Sample Number	Analyzed	Recovery (%)	(ug/l)
Method Blank	9/26/01	100	nd
S-13-W-20	9/26/01	93	520
S-15-W-20	9/26/01	89	870
S-14-W-20	9/26/01	99	nd
			100
Method Detection L	imits		100

"nd" Indicates not detected at the listed detection limits.

"int" Indicates that interference prevents determination.

ACCEPTABLE RECOVERY LIMITS FOR SURROGATE (Chlorobenzene): 65% TO 135%

ANALYSES PERFORMED BY: Dean Phillips

ESN SEATTLE CHEMISTRY LABORATORY (425) 957-9872, fax (425) 957-9904

ESN Job Number:

S10927-3

Client:

STEMEN ENVIRONMENTAL

Client Job Name:

SHORT STOP

Client Job Number:

SHORT STOP

nalytical Results		DW-1	STDR	BRDR	S-13-W-20	S-13-W-28
1021Β, μg/l Matrix	Water	Water	Water	Water	Water	Wate
Date extracted	Reporting	09/27/01	09/27/01	09/27/01	09/27/01	09/27/01
	Limits	09/27/01	09/27/01	09/27/01	09/27/01	09/27/01
Date analyzed	***************************************	***************************************	***************************************	***************************************		
N. L	5.0	nd	nd	nd	nd	ne
Chloromethane	5.0	nd	nd	nd	nd	n
Bromomethane	5.0	2,800	nd	nd	nd	n
/inyl chloride	5.0	nd	nd	nd	nd	n n
Chloroethane	5.0	2,900	33	nd	nd	n
d. D. L.	5.0	nd	nd	nd	nd	n
,1-Dichloroethene	5.0	nd	nd	nd	nd	r
Methylene Chloride	5.0	51	nd	nd	nd nd	_ r
rans-1,2-Dichloroethene	5.0	nd	nd	nd	nd	r
1,1-Dichloroethane	1.0	nd	nd	nd	nd	r
Chloroform	1.0	nd	nd	nd	nd	1
1,1,1-Trichloroethane	1.0	nd	nd	nd	nd	
Carbontetrachloride		nd	nd	nd	nd	
1,2-Dichloroethane	5.0	nd	180	nd	9.1	
Trichloroethene	1.0		nd	nd	nd	
1,2-Dichloropropane	5.0	nd		nd	nd	
Bromodichloromethane	5.0	nd	nd	nd	nd	
cis-1,3-Dichloropropene	5.0	nd	nd		nd	
rans-1,3-Dichloropropene	5.0	nd	nd	nd	nd	
Chlorobenzene	5.0	nd	nd	nd		
1.1.2-Trichloroethane	1.0	nd	nd.	nd	nd	
Tetrachioroethene	1.0	5.5	4,800	nd	36	
Dibromochloromethane	5.0	nd	nd	nd	nd	
Bromoform	5.0	nd	nd	nd	. nd	
1.1.2.2-Tetrachloroethane	5.0	nd	nd	nd	nd	
1,1,1,2-Tetrachloroethane	5.0	nd	nd	nd	nd	
Bromobenzene	5.0	nd	nd	nd	nd	
1,2,3-Trichloropropane	5.0	nd	nd	nd	nd	
	0.01	nd	nd	nd	nd	
Dibromomethane(*)	1.0	nd	nd	nd	nd	
m-Dichlorobenzene	1.0	nd	nd	nd	nd	
p-Dichlorobenzene	1.0	nd	nd	nd	nd	
o-Dichlorobenzene	1.0	nd	nd	nd	nd	
Benzene	1.0	3.5	nd	nd	37	
Toluene	1.0	nd	nd	nd	23	
Ethylbenzene	1.0	5.9	nd	nd	110	
Xylenes	1.0	5.5	.10			
*-instrument detection limit						
Surrogate recoveries:		106%	100%	100%	99%	
SURR1		118%	115%	114%	108%	11
SURR2			106%	104%	98%	10
SURR3		108%	100%	10770		

Data Qualifiers and Analytical Comments

nd - not detected at listed reporting limits

na - not analyzed

C - coelution with sample peaks

M - matrix interference

J - estimated value

Acceptable Recovery limits: 65% TO 135%

ESN SEATTLE CHEMISTRY LABORATORY (425) 957-9872, fax (425) 957-9904

ESN Job Number:

S10927-3

Client:

STEMEN ENVIRONMENTAL

Client Job Name:

SHORT STOP

Client Job Number:

SHORT STOP

A	lvtica	0	0011	lte
Ana	ivtica	ıĸ	esu	ııs

Analytical Results 8021B, µg/l		S-13-W-35	S-14-W-20	S-15-W-20
Matrix	Water	Water	Water	Water
Date extracted	Reporting	09/27/01	09/27/01	09/27/01
Date analyzed	Limits	09/27/01	09/27/01	09/27/01
***************************************	***************************************			
Chloromethane	5.0	nd	nd	nd
Bromomethane	5.0	nd	nd	nd
Vinyl chloride	5.0	nd	nd	nd
Chloroethane	5.0	nd	nd	nd
cis-1,2-Dichloroethene	5.0	nd	nd	nd
1,1-Dichloroethene	5.0	nd	nd	nd
Methylene Chloride	5.0	nd	nd	nd
trans-1,2-Dichloroethene	5.0	nd	nd	nd
1.1-Dichloroethane	5.0	nd	nd	nd
Chloroform	1.0	nd		nd
1,1,1-Trichloroethane	1.0	nd	nd	nd
Carbontetrachloride	1.0	nd	nd	nd
1.2-Dichloroethane	5.0	nd	nd	nd
Trichloroethene	1.0	9.3	nd	3.3
1,2-Dichloropropane	5.0	nd	l nd	nd
Bromodichloromethane	5.0	no	l nd	nd
cis-1,3-Dichloropropene	5.0	no	ı nd	nd
trans-1,3-Dichloropropene	5.0	no	nd nd	nd
Chlorobenzene	5.0	no		nd
	1.0	no		nd
1,1,2-Trichloroethane	1.0	180		9.9
Tetrachloroethene	5.0	no		nd
Dibromochloromethane	5.0	no		nd
Bromoform	5.0	no		nd
1,1,2,2-Tetrachloroethane	5.0	ne		nd
1,1,1,2-Tetrachloroethane		ne	-	nd
Bromobenzene	5.0			nd
1,2,3-Trichloropropane	5.0	ne	-	nd
Dibromomethane(*)	0.01	ne	-	nd
m-Dichlorobenzene	1.0	n	-	nd
p-Dichlorobenzene	1.0	n	-	nd
o-Dichlorobenzene	1.0	n		nd
Benzene	1.0	n		13
Toluene	1.0	27		31
Ethylbenzene	1.0	32		190
Xylenes	1.0	2,30	0 nd	190
*-instrument detection limit				
Surrogate recoveries:		······	6 100%	99%
SURR1		959		113%
SURR2		1089		101%
SURR3		979	% 103%	101%

Data Qualifiers and Analytical Comments

nd - not detected at listed reporting limits

na - not analyzed

C - coelution with sample peaks

M - matrix interference

J - estimated value

Acceptable Recovery limits: 65% TO 135%

ESN SEATTLE CHEMISTRY LABORATORY (425) 957-9872, fax (425) 957-9904

ESN Job Number:

S10927-3

Client:

STEMEN ENVIRONMENTAL

Client Job Name:

SHORT STOP

Client Job Number:

SHORT STOP

Analytical	Results
	- 11

8021B, µg/kg		MTH BLK	LCS	S-13-14/17	S-14	IS-1-2/14
Matrix	Soil	Soil	Soil	Soil	Soil	Soil
Date extracted	Reporting	09/27/01	09/27/01	09/27/01	09/27/01	09/27/01
Date analyzed	Limits	09/27/01	09/27/01	09/27/01	09/27/01	09/27/01
	250			nd	nd	nd
Chloromethane	250	nd		nd	nd	nd
Bromomethane	250	nd		nd	nd	nd
Vinyl chloride	250	nd		nd	nd	nd
Chloroethane	250 250	nd nd		nd	nd	nd
cis-1,2-Dichloroethene	250	nd		nd	nd	nd
1,1-Dichloroethene	20	nd		nd	nd	nd
Methylene Chloride				nd	nd	nd
trans-1,2-Dichloroethene	250	nd		nd	nd	nd
1,1-Dichloroethane	250	nd		nd	nd	nd
Chloroform	50	nd		nd	nd	nd
1,1,1-Trichloroethane	50	nd			nd	nd
Carbontetrachloride	50	nd		nd	nd	nd
1,2-Dichloroethane	250	nd		nd		nd
Trichloroethene	20	nd		nd	nd	nd
1,2-Dichloropropane	250	nd		nd	nd	
Bromodichloromethane	250	nd		nd	nd	nd
cis-1,3-Dichloropropene	250	nd		nd	nd	nd
trans-1,3-Dichloropropene	250	nd		nd	nd	nd
Chlorobenzene	250	nd		nd	nd	nd
1,1,2-Trichloroethane	50	nd		nd	nd	nd
Tetrachloroethene	50	nd		5,100	440	400
Dibromochloromethane	250	nd		nd	nd	nd
Bromoform	250	nd		nd	nd	nd
1,1,2,2-Tetrachloroethane	250	nd		nd	nd	nd
1,1,1,2-Tetrachloroethane	250	nd		nd	nd	nd
Bromobenzene	250	nd		nd	nd	nd
1,2,3-Trichloropropane	250	nd		nd	nd	nd
Dibromomethane(*)	5.0	nd		nd	, nd	nd
m-Dichlorobenzene	50	nd		-nd	nd	nd
p-Dichlorobenzene	50	nd		nd	nd	no
o-Dichlorobenzene	50	nd		nd	nd	no
Benzene	20	nd		nd	nd	no
Toluene	50	nd		11,000	330	no
Ethylbenzene	50	nd		29,000	1,100	no
Xylenes	50	nd		180,000	6,500	120
*-instrument detection limit				£1		
Surrogate recoveries:		-		1000	0.10	94%
SURR1		0%	0%		94%	
SURR2		0%	09		109%	109%
SURR3		0%	09	6 99%	101%	102%

Data Qualifiers and Analytical Comments

nd - not detected at listed reporting limits

na - not analyzed

C - coelution with sample peaks

M - matrix interference

J - estimated value


Results reported on dry-weight basis

Acceptable Recovery limits: 65% TO 135%




CHAIN-OF-CUSTODY RECORD

1													-														/	
CLIENT: STEM	EN	E	NVIR	WIMEL	M	7	士	~<	-				1										GE					
ADDRESS: 577	4-	N	GIT	Band	12	cas		0.	. 01	711	PA,	u		PRO	JEC	TN	AM	E: .		H	W	Ī	570	₽				
PHONE: 3604	38~	152	1	FA	X: _																		not					
CLIENT PROJECT	#: <u>51</u>	turi	STEP	PROJE	CT N	MAN	AGE	R:_	ANL	Sr	<u>Cu</u>	e)	_	COL	LEC	TOF	R:_	PA	DL		712	m	جي	 ,	CO	E OF	9/2	25
				2		,5	//	10%	1/2	/	ine		/			//	/	/	/,	0/	//		///	//			ber	Per
0		_	Sample	0-11-1	AH V	15 (C)		P/0	\$\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	15 X	8 X X	00 15 0 00 15 0	0			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		rand	No de la	CHO	re/	//		/ /			otal Nun	Laboratory Note Number
	Depth		Туре	Container Type	Y	14	1/8/	<u> </u>	<u> </u>	<u> </u>	4	/RY	4/	8 8	78	<u> </u>	1/2/2	1	/ *	1	\leftarrow	\leftarrow	NOT	ES			°	12
1. 5-14	4/17		SoiL	JAR		_	+-+	\dashv	X	-	+	+	+	-	\vdash	+	+	+	\dashv	+						<u> </u>	+-	1
2. ±5-1-12/14	14'	`	4		اصر	+	+-+	\dashv	X	+	+	\dashv	+		-	+	+	+	-	-							+-	1
1. S-14 2. ±S-1-12/14 3. S-13-14/17	17		1	+	>	-	+-+	\dashv	×	+	+	+	+	-		+	+	\dashv	-	\dashv							+-	1
4.						-	++	\dashv	-	+	+	+	+		-	\dashv	\dashv	-	-	-							+-	+
5.					\vdash		++	-		+	\dashv	-	+		\vdash	+	+	-	-	-							+-	+
6.					\vdash	-	+-+	-		\perp	+	+	+	-	$\vdash \vdash$	\dashv	\dashv		-	-							+	+-
7.					$\vdash \vdash$		+-+	\dashv	4	-	+	+	+	-	$\vdash \vdash$	-	\dashv	-	-	-	\dashv						+-	1
8.		-					+-+	-	4	+	+	-	+		$\mid - \mid$	+	-	-	-	-							+-	+
9. DW-/	0"	-	H20	U.ML	X		1-1	\dashv	4	\perp	\perp	-	+		\vdash	\dashv	4	-		-							+-	+-
9. DW-1 105-13-W-28	28'		4	и	X		++		1	+	+	+	+		-	\dashv	+	-	-	-							+-	+
11.5-13-W-20 12.5-13-W-31	20		4	,	X		11		X	4	\perp	-	+	-	-	\dashv	\dashv	_		\dashv							+-	+-
12.5-13-W-35	31		+	'	X		1			4	+	+	+	-	7	+	-	-		-		_					+-	+-
13. 5-15 - W - W	20		14	4	7		+-	-	×	+	+	-	+			\dashv	-	-		-	-						+	+
14. BROR	0'				اعر		+-		4	+	+	+	+		\vdash	\dashv	-	-	-	-	_	-		•			+-	+-
15. STDR	V EX	-	1	1,	مر		1	4		+	+	+	+		\vdash	-	\dashv	-	-	-	-	_					-	+
13. S-15 - W - 20 14. BRDR 15. STDR 16. S-14 - W - W 17.	20		1	•	129	-	+-	1	X	+	\dashv	-	+		\vdash	-	-	-		-		-					-	+-
17.						-	11		4	+	+	-	+	<u> </u>	\vdash	+	\dashv	_		\dashv							-	+-
18. RELINQUISHED BY ASigna										\bot		丄	بل			\perp				4	ا	4	<u> </u>					
RELINQUISHED BY (Signa	ture)	DA	TE/TIME	RECEIV	ED B	Y (Sign	nature)	0		TE/TII		-			MPLE					-		14	BORATO	RY NO	res:			
1 (AKH	(7:40	9/26/0	of William	My	le	Nu	14	414	4/0	100	-	-	NUMBE						-		-						
RELINQUISHED BY (Signa	ture)	- DA	TE/TIME	RECEIV	ED B	(Sign	nature)		DAT	re/TII	ME	-		OF CUS			ALS Y	Y/N/I	NA_	_		-						
					_	,						SEA	AL\$ I	NTACT	? Y/N	/NA		-				1						
	SA	MPLE	DISPOSA	AL INSTRUCT	TION	'S						REC	CEIV	ED GO	OD C	OND.	/COL	D.										
					_	_	_	_	-	_												1						





Scale - 1" = 201



3/27/03

ppy coles

MONITORING WELL INSTALLATION AND QUARTLY GROUNDWATER MONITORING REPORT

ER_



SHORT STOP SITE 6317 CALIFORNIA AVENUE S.W. SEATTLE, WASHINGTON ECOLOGY SITE #101565

Prepared By

Paul W. Stemen

Stemen Environmental, Inc.

STEMEN ENVIRONMENTAL, INC.

PO BOX 3644 LACEY, WA. 98509-3644 CONTR. LIC. #STEMEEI081J9

Telephone 360-438-9521 Fax 360-412-1225

May 15, 2003

Mr. Vernon Pontius 7730 Cabrini Dr. Port Orchard, WA 98367

Dear Mr. Pontius:

RE: GROUNDWATER MONITORING WELL INSTALLATION AND GROUNDWATER MONITORING FOR SHORT STOP SITE LOCATED AT 6317 CALIFORNIA AVENUE S.W., SEATTLE, WASHINGTON. ECOLOGY SITE # 101565

MONITORING WELL INSTALLATION

On March 5 and 6, 2003, I supervised the proper installation of five (5) groundwater monitoring wells at selected locations on the subject site. The two inch in diameter P.V.C. monitoring wells were installed by Licensed Well Drillers from Holt Drilling Inc., of Puyallup, Washington. The five (5) monitoring wells were extended to depths of approximately 32 feet b.g.s. (below ground surface) and were screened from depths of approximately 10 feet b.g.s. to 30 feet b.g.s. A two (2) foot in length sump was placed on the bottom of the monitoring well.

All excess soils (cuttings) generated during the monitoring well installation process were placed in sealable steel drums for temporary on-site storage.

Measurable quantities of water were found to be present in all of the monitoring wells on the dates of their installation.

It was decided that the newly installed wells should be allowed adequate time to stabilize prior to sampling.

GROUNDWATER ELEVATIONS

Groundwater elevations were measured using an electronic water level indicator and verified with a steel tape coated with water detection paste. Depth to water was measured from the top of the monitoring well monument (ground surface).

GROUND WATER SAMPLING

Prior to sampling, the monitoring wells were properly purged by removing a minimum of three (3) casing volumes of water from the wells using a disposable PVC bailer.

All waters generated during purging activities were placed in appropriate containers for transportation to an appropriate treatment/disposal facility.

The water level in the monitoring wells was stabilized to near original levels, then representative groundwater samples were obtained using a disposable PVC bailer. The sampled waters were transferred directly from the bailer to laboratory supplied containers for temporary storage.

On March 26, 2003, I began the process of sampling the groundwaters beneath the subject site. Water sample MW-1 was obtained from waters present at a depth of 11.38 feet b.g.s. in monitoring well MW-1 water sample MW-2 was obtained from waters present in monitoring well MW-2 at a depth of 11.09 feet b.g.s., water sample MW-3 was obtained from waters present in monitoring well MW-3 at a depth of 14.28 feet b.g.s., water sample MW-4 was obtained from waters present in monitoring well MW-4 at a depth of 11.35 feet b.g.s., and water sample MW-5 was obtained from waters present in monitoring well MW-5 at a depth of 11.43 feet b.g.s. These samples were immediately submitted for appropriate laboratory analyses and screened for gasoline range T.P.H., and V.O.C.'s (Specific Halogenated Hydrocarbons).

Laboratory analyses results for water samples MW-1, MW-2, MW-3, MW-4, and MW-5 indicated no detectable presence of gasoline range T.P.H., and/or Volatile Organic Compounds in these sampled waters.

Ground water sampling was performed by Paul Stemen (myself).

LABORATORY ANALYSES

All sampling devices were properly cleaned between individual samples to prevent cross sample contamination. All samples were then tightly packed in recommended containers with no head space, properly refrigerated and transported with proper chain of custody forms to Environmental Services Network Northwest, Inc., of Lacey, Washington for appropriate laboratory analyses. Groundwater samples were screened for Gasoline Range Total Petroleum Hydrocarbons using methods NWTPH-Gx, and Volatile Organic Compounds using E.P.A. method 8260. These analytical methods meet all current Department of Ecology recommendations for groundwater sample analyses and quality controls.

0327/03

1 :	al	toc	Elevation
Mw-t	11.38	233.01	221.63
MW-2	11.09	230.42	219,33
MW-3	14.28	230.64	216.36
MW-4	11.35	230.94	219.59
MW-5	11.43	228,62	217.19

HEALTH AND SAFETY

- 1. All on-site work was performed under the Health and Safety guidelines set forth in sections 29 CRF 1910.120 of the Federal Register and Chapter 296-62 WAC which provide regulations for individuals who are engaged in activities involving hazardous substances, including petroleum, and who perform confined space entry during field activities, also Chapter 296-155 WAC which provides State safety standards for construction work.
 - 2. All on-site workers were 40 hour Hazmat certified.
- 3. A copy of the Site Safety Plan was provided to all on-site employees. The contents of this plan and all potential on-site hazards, were discussed during a personnel on-site safety meeting. Based on the contents of this safety plan all workers were required to wear at least Level D protection. First Aid materials and properly trained personnel were present on-site at all times.
- 4. The immediate perimeter of the work area was secured at all times by orange hazard cones.

SUMMARY AND CONCLUSIONS

The following summary and conclusions are based on information gathered during on-site investigations described in this report.

- 1. Groundwater was present beneath this site on March 26, 2003, at depths ranging from 11.09 b.g.s. to 14.28 feet b.g.s.
- 2. Laboratory analyses results for groundwater samples obtained during this on-site investigation indicated no detectable presence of gasoline range T.P.H. and / or Volatile Organic Compounds in these sampled waters.

If you have any questions or require further information please feel free to contact us at the above phone number.

Sincerely.

Paul W. Stemen

Ecology-Registered Site Assessment Supervisor

IFCI #0874201-26

ASTM Certified

April 4, 2003

Paul Stemen Stemen Environmental P.O. Box 3644 Lacey, WA 98509

Dear Mr. Stemen:

Please find enclosed the analytical data report for the Short Stop Project site in Seattle, Washington. Water samples were analyzed for Gasoline by NWTPH-Gx and VOC's by Method 8260 on March 31, 2003.

The results of these analyses are summarized in the attached tables. Applicable detection limits and QA/QC data are included. An invoice for this analytical work is also enclosed.

ESN Northwest appreciates the opportunity to have provided analytical services to Stemen Environmental for this project. If you have any further questions about the data report, please give me a call. It was a pleasure working with you on this project, and we are looking forward to the next opportunity to work together.

Sincerely,

Michael A. Korosec

Michael a Korne

President

ESN SEATTLE CHEMISTRY LABORATORY (425) 957-9872, fax (425) 957-9904

ESN Job Number:

S30328-8

Client:

STEMEN ENVIRONMENTAL, INC.

Client Job Name:

SHORT STOP

Client Job Number:

Analytical Results

Analytical Results							
NWTPH-Gx		MTH BLK	MW-1	MW-2	MW-3	MW-4	MW-5
Matrix	Water	Water	Water	Water	Water	Water	Water
Date extracted	Reporting	03/30/03	03/30/03	03/30/03	03/30/03	03/30/03	03/30/03
Date analyzed	Limits	03/31/03	03/31/03	03/31/03	03/31/03	03/31/03	03/31/03
NWTPH-Gx, mg/L							
Mineral spirits/Stoddard solvent	0.10	nd	nd	nd	nd	nd	nd
Gasoline	0.10	nd	nd	nd	nd	nd	nd
jii			17				
Surrogate recoveries:							
Bromofluorobenzene		92%	88%	91%	90%	93%	83%
S. Official Operizerie		92%	88%	91%	90%	93%	

Data Qualifiers and Analytical Comments

nd - not detected at listed reporting limits

na - not analyzed

C - coelution with sample peaks

M - matrix interference

J - estimated value

Acceptable Recovery limits: 65% TO 135%

ESN SEATTLE CHEMISTRY LABORATORY (425) 957-9872, fax (425) 957-9904

ESN Job Number: Client: Client Job Name: Client Job Number:

\$30328-8 STEMEN ENVIRONMENTAL, INC. SHORT STOP

Analytical Results

8260 100								
Matrix	Minha	WIH BLK	LCS	F-WM	MW-2	WW-3	MW-4	MW-5
Date extracted	Reporting	03/31/03	03/20/03	PONDEN	vater	Water	Water	Water
Date analyzed	Limits	03/31/03	03/29/03	03/31/03	03/31/03	03/31/03	03/31/03	03/31/03
Dichlorodiff, promethers			2		.0.1			
Chloromethane	1.0	2 2		2 2	2 2	2 8	2 8	2 3
Vinyl chloride	0.2	Z :		a a	R 2	2 2	2 2	2 2
Bromomethane	1.0	2 8		2 5	2 5	2 2	2 2	2. 2
Chloroethane	1.0	Z		a :	2 8	2 i	2 5	2 2
Trichlorofluoromethane	1.0	Z		2	Z	Z.	Z	2
1,1-Dichloroethene	1.0	2. 3.	94%	2	. Z	Б.	ď	a
trans-1.2-Dichloroethene	1.0	2 2		Z Z	E a	a.	Z	. д
1,1-Dichloroethane	1.0	2 3		a. a	2 3	2 2	2 2	B B
cis-1,2-Dichloroethene	1.0	Z.		Z	<u>a</u> . ;	Z :	a a	2 2
2,2-Dichloropropane	1.0	. a		J.	Z	Z.	æ.	Z
Bromochloromethane	1.0	2 3		2. 2.	2 3	Z Z	z z	L a
1,1,1-Trichloroethane	1.0	2 8		2. 2	2. 2	2 2	2 2	2 3
1,2-Dichloroethane	1.0	콦		3.	a.	2 :	a i	2 :
Carbon tetraphicida	1.0	Z		Z	ъ.	2	Б	æ
Benzene	1.0	2 3	1086	2 3	2 3	2 3	. a	. a.
Trichloroethene	1.0	a	110%	2 ;	2 5	a a	2.8	2 2
Dibromomethane	1.0	2 2		2 2	2 2	2 3	Z Z	1 3
Bromodichloromethane	1.0	Z		2.	a 8	2. 2	a a	2. 2
Cis-1,3-Dichloropropene Toluene	1.0	E Z		Z	. Z	. Z.	Z.	a.
trans-1,3-Dichloropropene	1.0	2 2	102.70	2 2	B. a	2 2	8.8	2 3
1,1,2-Trichloroethane	1.0	. 3.		Z	nd.	Z	a.	<u>a</u>
Dibromochloromethane	1.0	2 2		2 2	2 2	2 2	1 3	1 3
Tetrachloroethene	1.0	2 5		2.2	Z. Z	2.8	Zā	2 2
1,2-Dibromoethane (EDB)(*)	0.01	a.		æ	Z.	М	Z.	æ
1,1,1,2-Tetrachioroethane	1.0	2 2	102%	2 2	2 3	1 3	1 3	1 2
Ethylbenzene	1.0	Z		Z. i	a. a	2.8	2 2	2 2
Xylenes	1.0	. a		2	Б	2	M	pd
Bromoform	1.0	a. a		2 2	2 2	2 2	3 a	3 2
1,1,2,2-Tetrachioroethane	1.0	Z.		Б	2	2	2	2 :
1,2,3-Trichloropropane	1.0	2 2		a a	2 2	2 2	3 3	2 2
Bromobenzene	1.0	nd		2	2 :	ь В 1	2 5	- A
2-Chlorotoluene	1.0	. 3.		1 3	E I	. 2	ı a	Z
4-Chlorotoluene	1.0	2.5		a . a	2 2	2 3	2. 2	2 3
1,3,5-Trimethylbenzene	1.0	2		Z	a.	a.	D.	a.
1,2,4-Trimethylbenzene	1 10	2 2		1 2	13	2 3	1 3	2.2
sec-Butylbenzene	1.0	2.5		a a	2 2	2 5	2. 2	2. 2
1,3-Dichlorobenzene	1.0	Z		æ	nd	a.	Z.	a
Isopropyltoluene	1.0	1 3		1 3	2 2	l a	L Z.	. 3.
1,2-Dichlorobenzene	1.0	2.8		3 3	급 급	a. a	2 3	a. a
n-Bulylbenzene	1.0	2		75	Z	P.	nd	a
1,2,4-Trichlorobenzene	1.0	3.3		2 2	2 2	2 2	2 3	2 2
Naphthalene		2 2		2. 2	a. a	2 2	2 3	2. 3
Hexachioro-1,3-butadiene	1.0	2		m	ы	nd	ы	pu
1,2,3-Irichlorobenzene	1.0	E		PL	pd	Pu	DG.	nd

*-instrument detection limits

ESN SEATTLE CHEMISTRY LABORATORY (425) 957-9872, fax (425) 957-9904

ESN Job Number:

S30328-8

Client:

STEMEN ENVIRONMENTAL, INC.

Client Job Name:

SHORT STOP

Client Job Number:

Analytical Results


8260, µg/L		MTH BLK	LCS	MW-1	MW-2	BAIA! 3	TANAL A	BAIA! F
			LUS	14144-1	19199-2	MW-3	MW-4	MW-5
Matrix	Water	Water		Water	Water	Water	Water	Water
Date extracted	Reporting	03/31/03	03/29/03	03/30/03	03/30/03	03/30/03	03/30/03	03/30/03
Date analyzed	Limits	03/31/03	03/29/03	03/31/03	03/31/03	03/31/03	03/31/03	03/31/03
Surrogate recoveries					3			
Dibromofluoromethane		115%	111%	115%	115%	95%	102%	116%
Toluene-d8		85%	89%	85%	86%	99%	95%	84%
4-Bromofiuorobenzene		98%	98%	98%	97%	109%	99%	102%

Data Qualifiers and Analytical Comments nd - not detected at listed reporting limits Acceptable Recovery limits: 65% TO 135% Acceptable RPD limit: 35%

Ss- 32- 3

CHAIN-OF-CUSTODY RECORD

										<u> </u>						-		-						
CLIENT: ST	mo	es a	ENV	RUNN	E	M	- #							_					GE		OF		_	
ADDRESS:					_			7			P	ROJ	ECT	NAM	E:`	SH	Lorz	I	550	P				_
PHONE: 360 - 4:	38-9	521	, ,	FA	x.(=	360)	1/2	-/:	22	5_	Lo	CAT	rion	:	SI	AT	720	رځ	w	4.				_
CLIENT PROJECT	#:	Hors	TOP	PROJE	CTN	IANAGE	R: DA	VL.	STEEL	no	C	OLLE	СТС)R:	PAU	120	STO	m	E-1		DATE (OF CTION .	3/	26
Sample Number	Depth	Time		Container Type	V /			O O				88 ³ /28 ³ 10		1. 18. 18. 18. 18. 18. 18. 18. 18. 18. 1	ard es	Sept Chic	, , , , , , , , , , , , , , , , , , ,		NOTE	s			Total Number of Containers	Laboratory Note Number
1. MW-/		W ₁	#20	THAL	X		X																	
2. MW-2 3. MW-3 4. MW-4 5. MW-5			,	u	M		X	-	4.4	\bot			_		_	\sqcup	\perp	_		_				Ш
3. mw-3			*	4	7		X						1		4	1	_	_						
4. mw-4			<i>r</i>	,,	×	$\bot \bot$	X	.5	-		\sqcup		1		_	\perp	\dashv	\dashv				- 5		
5. MW-5			11	11	\bowtie	++-	X	\square	4		\vdash	_	+-	-	_	\vdash	_	-	/			•:`		\dashv
6.					$\vdash \vdash$			\vdash	- 1	_	-	-	+	\dashv	+	\vdash	\dashv	-						
7					$\vdash \vdash$	++-		-	*	-		+	+	\dashv	+-	H	\dashv	+				-		
8.						++-		-	+	+	-	+	+	\dashv	+	1-1	\dashv	+			/		-	
9.						+		\vdash	*	+	-		+	-	+	\vdash	+	+						-
10.					\vdash				1		-	+	+	\dashv	+-	\vdash	+	+						
11					-	+	-	H	+	+-	-	+	+	-	+	H	+	+						
12.						++-	-		+	+		+	+	\dashv	+	H	+	+					-	\dashv
13.	-				-	+++-	-		_	+	\dashv	+	+	\dashv	+	\vdash		+		7			-	
14.					-				+	+	\dashv	+	$\dagger \dagger$	\neg	+		\dashv	+						\neg
15. 16.					\top	+++	_	+	7	$\top \top$	-	\top	\Box	+	1		十	\top						\neg
17.		-			100				+	\top	7	\top	T	1	\top	\Box	1	1						
					\top							\top												
18. A L RELINQUISHED BY (Signat	ure)	DA	TE/TIME	RECEIVE	DBY	(Signature)	9/	TE/TI	ME		S	AMPL	E REC	EIPT				LAB	ORATORY	NOTE	S:			
11/11/3/	27/0	3		MAS	MI	nos	3/	271	13	TOTAL	NUME	ER O	F CON	TAINE	RS	_								
RELINQUISHED BY (Signal	ure)	DAT	E/TIME	RECEIVE	D BY	(Signature)	DA	TET	ME	CHAIN	OF C	JSTOE	Y SE	LS YA	I/NA	_								
V										SEALS	INTAC	T? Y/	N/NA			_								
	SA	MPLE I	DISPOSA	L INSTRUCT	IONS					RECE	VED G	000	COND.	/COLD		_								
	SŃ DIS	POSAL	@ \$2.00	each 🛭 Reti	um 🛮	Pickup				NOTES	:					\perp		Turr	Around Ti	me:	24 HR	48 HR	5 D	AY



SHORT SHOP SITE SENTLE, NSA.

Project Name Shortstop Clean	ers Date	3-5-03
Well Identification # 1 (TAG#		King NE 1/4 NW 1/4
Drilling Method 4"HSA	Section	26 T. 25N R. 3E
Driller Michael Reynolds		Address 6317 California Ave. Sw/w. Seattle
License # 26367		ard_R61532
		ting Firm Stemen Environm
AS-BUILT	WELL DATA	FORMATION DESCRIPTION
	•	
	MONUMENT TYPE: Flush CONCRETE SURFACE SEAL 1.5 ft. PVC BLANK 2 "x 9-8" BACKFILL 6.5 ft. TYPE: Bentanite PVC SCREEN 2 "x 20" SLOT SIZE: OZO TYPE: PVC GRAVEL PACK 22 ft. MATERIAL: D/20 Silica Sump 2 "x 2" AVC WELL DEPTH 32 , 0 "	Asphalt 12-14 ft. 6ravel Base 14-32 ft. Brn Fine-Med. Sand V Trace Silts ft. REMARKS

Project Name Shortstop Cle	an ers	Date 3-5-03	3
Well Identification # 2 (TAG	# AKP297)	County King	. NE 1/4 FNW 1/4
Drilling Method 4" HSA			T. 25N R. 3E
Driller Michael Reynold	\$		7 California Ave. SW/W. Seat
License # 2636 T		Start Card R615	
	•	Consulting Firm_St	
AS-BUILT	WELL DATA		ORMATION DESCRIPTION
	MONUMENT TYPE: Flush CONCRETE SURFACE S 1-5 ft. PVC BLANK 2 "X BACKFILL 6.5 TYPE: Benton; ft SLOT SIZE: 1020 TYPE: PVC GRAVEL PACK 23 MATERIAL: 10/20 S WELL DEPTH 32	SEAL ASP. 9-8: 12 15 16 17 16 17 18 15 15 15 15 15 15 15 15 15	

Project Name Shortstop Clea	mers	Date 5-3-03	
Well Identification # 3 (TA6#)			NE 1/4 NW 1/4
Drilling Method 4"HSA			25N R. 3E
Driller Michael Reynolds			California Am. SW/w-Seatt
License # 26367		Start Card R61532	
	•	Consulting Firm Stem	
AS-BUILT	WELL DATA	7	MATION DESCRIPTION
	MONUMENT TYPE: Flush CONCRETE SURFACE: 1.5 ft. PVC BLANK 2 "X BACKFILL 6-5 TYPE: Bentin; t PVC SCREEN 2 "X SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 MATERIAL: 19/20 5 WELL DEPTH 32	9-8 Grand 1 11. C 13 Brn 2. 15. Gry Fr. Clica 20 Brn Fin Silt REMARKS	-15 ft. Fine-Med Sand -20 ft. ne-Med Sand -32 ft. ne-Med Sand Witrace
		Signature Muhau	Burnold

Resource Protection Well Report

Well Identification # 4 (The # AKP29) 9 Drilling Method 4" / 15A Driller Michael Reynolds License # 2636 T Street Address \$317 (al/thma Anc. SW/N. Sect. Start Card R6/532 Consulting Firm Stemen Env. AS-BUILT MONUMENT TYPE: FINST CONCRETE SURFACE SEAL 1.5 ft. PVC BLANK 2 'x 9.8' BACKFILL 6.5 ft. TYPE: Bestanitz Backfill 6.5 ft. TYPE: Bestanitz Brown Fine Med. Sand PVC SCREEN 2 'x 20' SLOT SIZE: 1020 TYPE: PVC GRAVEL PACK 22 ft. MATERIAL: 10/20 WELL DEPTH 32. I. WELL DEPTH 32. II. REMARKS	Project Name Shortstop Cleane	Date	5-6-03
Driller Method 7/34 Section 16 T. 25N R. 3E Street Address 63/7 (2d/Horiza Arv. SW/N. Sect. Start Card R6/537 Consulting Firm Stemen Env. AS-BUILT MONUMENT TYPE: Flush CONCRETE SURFACE SEAL 1.5 ft. FVC BLANK 2 'x9.8' BACKFILL 6.5 ft. TYPE: Bentanjtc SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 ft. MATERIAL: 10/20 SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 ft. MATERIAL: 10/20 SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 ft. MATERIAL: 10/20 SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 ft. Brin Fine-Med. Sand Without R. 3E T. 25N R. 3E REMARKS REMARKS REMARKS	Well Identification # 4 (TAC # AK	P2999 County	King NE 1/2 NW 1/4
Driller Michael Reynolds License # 2636 T Start Card R6/532 Consulting Firm Stemen Env. AS-BUILT MONUMENT TYPE: Flush CONCRETE SURFACE SEAL 1/5 ft. PVC BLANK 2 'x 9.8' BACKFILL 6.5 ft. TYPE: Bentanjte BACKFILL 6.5 ft. BYC SCREEN 2 'x 20' SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 ft. MATERIAL: 10/20 Sump 2" x 21' PUC Start Card R6/532 Consulting Firm Am. Sw/w. Sw/w. Seat. AS-PMATION DESCRIPTION FORMATION DESCRIPTION AS-BUILT FORMATION DESCRIPTION FORMATION DESCRIPTION AS-BUILT FORMATION DESCRIPTION FORMATION DESCRIPTION FORMATION DESCRIPTION AS-BUILT AS-PULL AS-PULL BACKFILL 6.5 ft. Brin Fine Med. Sand FORMATION DESCRIPTION AS-BUILT AS-PULL BACKFILL 6.5 ft. Brin Fine Med. Sand FORMATION DESCRIPTION AS-BUILT AS-PULL BACKFILL 6.5 ft. Brin Fine Med. Sand FORMATION DESCRIPTION AS-PULL BACKFILL 6.5 ft. BRIN Fine Med. Sand FORMATION DESCRIPTION AS-PULL BACKFILL 6.5 ft. BRIN Fine Med. Sand FORMATION DESCRIPTION AS-PULL BACKFILL 6.5 ft. BRIN Fine Med. Sand FORMATION DESCRIPTION AS-PULL BACKFILL 6.5 ft. BRIN Fine Med. Sand FORMATION DESCRIPTION AS-PULL BACKFILL 6.5 ft. BRIN Fine Med. Sand FORMATION DESCRIPTION AS-PULL BACKFILL 6.5 ft. BRIN Fine Med. Sand FORMATION DESCRIPTION AS-PULL BACKFILL 6.5 ft. BRIN Fine Med. Sand FORMATION DESCRIPTION BRIN Fine Med. Sand BRIN Fine Med. Sand BRIN Fine Med. Sand FORMATION DESCRIPTION BRIN FINE Med. Sand BRIN Fine Med. Sand FORMATION DESCRIPTION BRIN FINE Med. Sand BRIN Fine Med. San	Drilling Method 4" HSA	Section	26 T 25N B 3E
Start Card A6/532 Consulting Firm Stemen Env. AS-BUILT WELL DATA FORMATION DESCRIPTION MONUMENT TYPE: Flush CONGRETE SURFACE SEAL 1.5 ft. PVC BLANK 2 'x 9.8' BACKFILL 6.5 ft. TYPE: Bentenjtc SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 ft. MATERIAL: 10/20 SLOT SIZE: 10/20 20 . 32 ft. Brin Fine Med. Sand Without Stand Sump 2" x 21 PUC	Driller Michael Reynolds		
CONSULTING FIRM Stemen Env. WELL DATA WELL DATA FORMATION DESCRIPTION MONUMENT TYPE: Flush CONCRETE SURFACE SEAL 1.5 ft. PVC BLANK 2 'x 9.8' BACKFILL 6.5 ft. TYPE: Bentonite Sun Fine Med. Sand PVC SCREEN 2 'x 20 SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 ft. MATERIAL: 14/20 Sun Fine Med. Sand 20 32 ft. Brin Fine Med. Sand 70 32 ft. Brin Fine Med. Sand REMARKS REMARKS		Start Ca	ard R6/532
MONUMENT TYPE: Flush CONCRETE SURFACE SEAL 1.5 ft. PVC BLANK 2 'x 9.8' BACKFILL B.5 ft. TYPE: Bentanite SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 ft. MATERIAL. 16/20 SLOT SIZE: 5/175 REMARKS FORMATION DESCRIPTION FORMATION DESCRIPTION 0 - 12 ft. Asphabt 12 , 4 ft. Growl Base 14 - 15 ft. Brin Fine Med. Sand Type: PUC 15 - 20 ft. Gry Fine-Med. Sand Type: Simp 1 ft. Brin Fine Med. Sand Trace 15 / Trace 16 / Trace 17 / Trace 17 / Trace		- Consult	ting Firm Stemen Env.
Flush CONCRETE SURFACE SEAL 1.5 ft. PVC BLANK 2 'x 9.8' BACKFILL 6.5 ft. TYPE: Bentanite PVC SCREEN 2 "x 20" SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 ft. MATERIAL: 16/20 Sump 2" x 2' PUC D - 12 ft. Asphalt 12 . 4 ft. Froul Base 14 - 15 ft. Brn Fine Med. Sand 15 - 20 ft. Gry Fine-Med. Sand Trace Stifts REMARKS	AS-BUILT		
		Flush CONCRETE SURFACE SEAL 1.5 ft. PVC BLANK 2 "x 9.8" BACKFILL 6.5 ft. TYPE: Bentan; 7c PVC SCREEN 2 "x 20" SLOT SIZE: 1020 TYPE: PUC GRAVEL PACK 22 ft. MATERIAL: 10/20	15 - 20 ft. Bry Fine-Med. Sand 15 - 20 ft. Bry Fine-Med. Sand 20 - 32 ft. Brn. Fine-Med. Sand W. Trace 55175

AV039.CD

Project Name Shortstop Cleaners	Date 5-6-03
Well Identification # 5 (TAK # AK #300)	County King NE 1/4 NW 1/4
Drilling Method_4" HSA	Section 26 T. 25 N R. 3E
Driller Mrchael Reynolds	Street Address 6317 Colifonia Ave. SWW. Seattle
License #_ 2636T	Start Card R6/532
	Consulting Firm Stemen Env.
AS-BUILT WELL DATA	FORMATION DESCRIPTION
MONUMENT TYPE: Flush CONCRETE SURFACE /-5 ft. PVC BLANK 2 ", BACKFILL 6.5 TYPE: Benton; PVC SCREEN 2 " SLOT SIZE: OZ TYPE: PVC GRAVEL PACK 2 MATERIAL: 10/20 Sump 2"×2" WELL DEPTH 32	SEAL Asphabl 1 - 12 ft. Ground Base 12 - 15 ft. Brn Fine-Med Sund 15 - 32 ft. Gry-Brn Fine-Med Sund 22 ft. Silica PVC REMARKS

GROUNDWATER MONITORING REPORT



SHORT STOP SITE 6317 CALIFORNIA AVENUE S.W. SEATTLE, WASHINGTON

Prepared By

Paul W. Stemen

Stemen Environmental, Inc.

STEMEN ENVIRONMENTAL, INC.

PO BOX 3644 LACEY, WA. 98509-3644 CONTR. LIC. #STEMEEI081J9

Telephone 360-438-9521 Fax 360-412-1225

July 25, 2003

Mr. Vernon Pontius 7730 Cabrini Dr. Port Orchard, WA 98367

Dear Mr. Pontius:

RE: GROUNDWATER MONITORING FOR SHORT STOP SITE LOCATED AT 6317 CALIFORNIA AVENUE S.W., SEATTLE, WASHINGTON. ECOLOGY SITE #101565.

MONITORING WELL INSTALLATION

On March 5 and 6, 2003, I supervised the proper installation of five (5) groundwater monitoring wells at selected locations on the subject site. The two inch in diameter P.V.C. monitoring wells were installed by Licensed Well Drillers from Holt Drilling Inc., of Puyallup, Washington. The five (5) monitoring wells were extended to depths of approximately 32 feet b.g.s. (below ground surface) and were screened from depths of approximately 10 feet b.g.s. to 30 feet b.g.s. A two (2) foot in length sump was placed on the bottom of the monitoring well.

All excess soils (cuttings) generated during the monitoring well installation process were placed in sealable steel drums for temporary on-site storage.

Measurable quantities of water were found to be present in all of the monitoring wells on the dates of their installation.

GROUNDWATER ELEVATIONS

Groundwater elevations were measured using an electronic water level indicator and verified with a steel tape coated with water detection paste. Depth to water was measured from the top of the monitoring well monument (ground surface).

The elevations of the tops of the on-site monitoring wells were determined by C&C Surveying of Mountlake Terrace, WA.

GROUND WATER SAMPLING

Prior to sampling, the monitoring wells were properly purged by removing a minimum of three (3) casing volumes of water from the wells using a disposable PVC bailer.

All waters generated during purging activities were placed in appropriate containers for transportation to an appropriate treatment/disposal facility.

The water level in the monitoring wells was stabilized to near original levels, then representative groundwater samples were obtained using a disposable PVC bailer. The sampled waters were transferred directly from the bailer to laboratory supplied containers for temporary storage.

On July 23, 2003, I began the process of sampling the groundwaters beneath the subject site. Water sample MW-1 was obtained from waters present at a depth of 12.04 feet b.g.s. in monitoring well MW-1, water sample MW-2 was obtained from waters present in monitoring well MW-2 at a depth of 11.82 feet b.g.s., water sample MW-3 was obtained from waters present in monitoring well MW-3 at a depth of 14.86 feet b.g.s., water sample MW-4 was obtained from waters present in monitoring well MW-4 at a depth of 11.88 feet b.g.s., and water sample MW-5 was obtained from waters present in monitoring well MW-5 at a depth of 12.20 feet b.g.s. These samples were immediately submitted for appropriate laboratory analyses and screened for gasoline range T.P.H., and Specific Halogenated Hydrocarbons.

Ground water sampling was performed by Paul Stemen (myself).

LABORATORY ANALYSES

Laboratory analyses results for water samples MW-1, MW-2, MW-3, MW-4, and MW-5 indicated no detectable presence of gasoline range T.P.H. in these sampled waters.

Laboratory analyses results for water sample MW-1 indicated no detectable presence of Specific Halogenated Hydrocarbons in these sampled waters.

Laboratory analyses results for water sample MW-1, MW-3, and MW-5 confirm the detectable presence of Tetrachloroethene(PCE) at levels that do not exceed Ecology's Method "A" Clean Up Levels.

Laboratory analyses results for water sample MW-2 confirm the presence of Tetrachloroethene (PCE) and Trichloroethene (TCE) at levels that exceed Ecology's Method "A" Clean Up Levels.

Laboratory analyses results for water sample MW-4 confirm the detectable presence of Tetrachloroethene (PCE) at levels that do not exceed Ecology's Method "A"

All sampling devices were properly cleaned between prevent cross sample contamination.

recommended containers with no head space, properly refrigerated and transported with proper chain of custody forms to Environmental Services Network Northwest, Inc., of Lacey, Washington for appropriate laboratory analyses. Groundwater samples were screened for Gasoline Range Total Petroleum Hydrocarbons using methods NWTPH-Gx, and Volatile Organic Compounds using E.P.A. method 8021B. These analytical methods meet all current Department of Ecology recommendations for groundwater sample analyses and quality controls.

HEALTH AND SAFETY

- 1. All on-site work was performed under the Health and Safety guidelines set forth in sections 29 CRF 1910.120 of the Federal Register and Chapter 296-62 WAC which provide regulations for individuals who are engaged in activities involving hazardous substances, including petroleum, and who perform confined space entry during field activities, also Chapter 296-155 WAC which provides State safety standards for construction work.
 - 2. All on-site workers were 40 hour Hazmat certified.
- 3. A copy of the Site Safety Plan was provided to all on-site employees. The contents of this plan and all potential on-site hazards, were discussed during a personnel on-site safety meeting. Based on the contents of this safety plan all workers were required to wear at least Level D protection. First Aid materials and properly trained personnel were present on-site at all times.
- 4. The immediate perimeter of the work area was secured at all times by orange hazard cones.

SUMMARY AND CONCLUSIONS

The following summary and conclusions are based on information gathered during on-site investigations described in this report.

- 1. Groundwater was present beneath this site on July 24, 2003, at depths ranging from 11.82 b.g.s. to 14.86 feet b.g.s.
- 2. Laboratory analyses results for groundwater samples MW-2, and MW-4 confirmed the presence of Specific Halogenated Hydrocarbons at levels that exceed Ecology's Method "A" Clean Up Levels in the waters present in their respective monitoring wells.

If you have any questions or require further information please feel free to contact us at the above phone number.

Sincerely,

Paul W. Stemen

Ecology-Registered Site Assessment Supervisor

IFCI #0874201-26

ASTM Certified

MICH FOR SPINO PUE APP

6W Flevation CONCRETE WALL PROPERTY LINE 220.97 MW-1 FRONT BOOK **CONVENIENCE STORE** 5 216.42 MW-5 REAR DOOR DRA CLEAMERS 218,60 FRONT DOOR MW-2 A 74 SIGN POST REAR DOOR 219.04 AMW-215.78 MW-3 216 5.3



SHORT STOP 6317 CALIFORNIA AVE. SW SEATTLE, WA.

CALIFORNIA AVE.

SUMMARY OF GROUNDWATER DEPTH AND ELEVATION DATA 7/23/03

WELL NUMBER	TOP OF MONUMENT ELEVATION	DEPTH TO GROUNDWATER	GROUNDWATER ELEVATION
MW-1 MW-2 MW-3 MW-4 MW-5	233.01 230.42 230.64 230.94 228.62	12.04 11.82 14.86 11.88 12.20	220.97 218.60 215.78 219.06 216.42

ALL MEASUREMENTS ARE IN FEET

		1		4	
	WATER LA	BORATOR	Y ANALYSE	S CHARTS	
7				.7"	
		0.6	TOTAL PET	ROLEUM	- 2
		F	YDROCARI	BONS (PPE	3)
200					
SAMPLE	SAMPLE	SAMPLE		14	
NUMBER	DATE	DEPTH	GASOLINE		
MW-1	7-23-03	4	ND		
MW-2	7-23-03		ND		7
MW-3	7-23-03		ND		
MW-4	7-23-03		ND		
MW-5	7-23-03	-	ND		

SPECIFIC HALOGENATE	D HYDRO	CARBONS	WATERS (PPB)	
SAMPLE-NUMBER	MW-1	MW-2	MW-3	MW-4	MW-5
	-				7.7
DATE	7-23-03	7-23-03	7-23-03	7-23-03	7-23-03
DEPTHS	T			, h	
	200				
VINYL CHLORIDE	ND	ND	ND	ND	ND
BENZENE	ND	ND	ND	ND	ND
TOLUENE	ND	ND	1.1	ND	ND
ETHYLBENZENE	ND	ND	ND	ND	ND
TOTAL XYLENES	ND	ND	ND	ND	ND
1,1 DICHLOROETHENE	ND	ND	ND	ND	ND
METHYLENE CHLORIDE	ND	ND	ND	ND	ND
TRANS-1,2-DICHLOROETHENE	ND	ND	ND	ND	ND
1,1 DICHLOROETHENE	ND	ND	ND	ND	ND
CIS-1,2 DICHLOROETHENE	ND	1.9	ND	ND	ND
CHLOROFORM	ND	ND	ND	ND	ND
1,1,1- TRICHLOROETHANE	ND	ND	ND	ND	ND
CARBON TETRACHLORIDE	ND	ND	ND	ND	ND
1,2 DICHLOROETHANE	ND	- ND	ND	ND	ND
TRICHLOROETHENE	ND	6.7	ND	1	ND
1,1,2,-TRICHLOROETHANE	ND		ND	ND	ND
TETRACHLOROETHENE	1.7	74	5	17	5
1,1,1,2-TETRACHLOROETHANE	ND	ND	ND	ND	ND
1,1,2,2-TETRACHLOROETHANE	ND	ND	ND	ND	ND

July 25, 2003

Paul Stemen Stemen Environmental P.O. Box 3644 Lacey, WA 98509

Dear Mr. Stemen:

Please find enclosed the analytical data report for the Short Stop Project site in Seattle, Washington. Water samples were analyzed for Gasoline by NWTPH-Gx and Specific Halogenated Hydrocarbons and BTEX by Method 8021B on July 24, 2003.

The results of these analyses are summarized in the attached tables. Applicable detection limits and QA/QC data are included. An invoice for this analytical work is also enclosed.

ESN Northwest appreciates the opportunity to have provided analytical services to Stemen Environmental for this project. If you have any further questions about the data report, please give me a call. It was a pleasure working with you on this project, and we are looking forward to the next opportunity to work together.

Sincerely,

Multipo Jaimes

Michael A. Korosec

President

SHORT STOP PROJECT Seattle, Washington Stemen Environmental, Incorporated

Analyses of Gasoline (NWTPH-Gx) in Water

Sample Number	Date Analyzed		a 5	Surrogate Recovery (%)	Gasoline (ug/l)
Method Blank	7/24/03			112	nd
MW-1	7/24/03			78	nd
MW-1 Dup	7/24/03	•		77	nd
MW-2	7/24/03			93	nd
MW-3	7/24/03			115	nd
MW-4	7/24/03			107	nd
MW-5	7/24/03			109	nd
Method Detection Limit	ts.				100

[&]quot;nd" Indicates not detected at the listed detection limits.

ACCEPTABLE RECOVERY LIMITS FOR SURROGATE (Chlorobenzene): 65% TO 135%

ANALYSES PERFORMED BY: Dean Phillips

[&]quot;int" Indicates that interference prevents determination.

SHORT STOP PROJECT Seattle, Washington Stemen Environmental, Inc.

Specific Halogenated and Aromatic Hydrocarbons (EPA 8021B) in Water

Sample Description		Method Blank	MW-1	MW-2	MW-3	MW-4	MW-5
Date Sampled			7/23/03	7/23/03	7/23/03	7/23/03	7/23/03
Date Analyzed		7/24/03	7/24/03	7/24/03	7/24/03	7/24/03	
	MDL				1124103	1124/03	7/24/03
	(ug/l)	(ug/l)	(ug/l)	(ug/l)	(ug/l)	(ug/l)	(ug/l)
Vinyl chloride	5.0						(48.)
Benzene	5.0	nd	nd	nd	nd ·	nd	nd
oluene	1.0	nd	nd	nd	nd	nd	nd
thylbenzene	1.0	nd	nd	nd	1.1	nd	nd
otal Xylenes	1.0	nd	nd	nd	nd	nd	nd
,l-Dichloroethene	1.0	nd	nd	nd	nd	nd	nd
Methylene chloride	1.0	nd	nd	nd	nd	nd	nd
cans -1,2-Dichloroethene	1.0	nd	nd	nd	nd	nd	nd
,1-Dichloroethane	1.0	nd	nd	nd	nd	nd	nd
is 1.2 Dioblement	1.0	nd	nd	nd	nd	nd	nd
is -1,2-Dichloroethene	1.0	\mathbf{nd}	nd	1.9	nd	nd	nd
	1.0	nd	nd	nd	nd	nd	nd
1,1-Trichloroethane (TCA) arbon tetrachloride	1.0	nd	nd	nd	nd	nd	nd
	1.0	nd	nd	nd	nd	nd	nd
2-Dichloroethane	1.0	nd	nd	nd	nd	nd	nd
richloroethene (TCE)	1.0	nd	nd	6.7	nd	1.0	nd
I,2-Trichloroethane	1.0	nd	nd	nd	nd	nd	nd
etrachloroethene (PCE)	1.0	nd	1.7	74	5.0	17	5.0
1,1,2-Tetrachloroethane	1.0	nd	nd	nd	nd	nd	nd
1,2,2-Tetrachloroethane	1.0	nd	nd	nd	nd	nd	nd
urrogate Recovery (%)		104	02				
(70)		104	93	int.	90	101	108

[&]quot;nd" Indicates not detected at listed detection limit.
"int" Indicates that interference prevents determination.

ACCEPTABLE RECOVERY LIMITS FOR SURROGATE (Chlorobenzene): 65%- 135%

ANALYSES PERFORMED BY: Marilyn Farmer

SHORT STOP PROJECT Seattle, Washington Stemen Environmental, Inc.

QA/QC Data - EPA 8021B Analyses

		Sample Matrix Spik	Description:	CM
	Spiked Conc. (ug/l)	Measured Conc. (ug/l)	Spike Recovery (%)	
Benzene	5.0	4.67	93	
Toluene	5.0	4.67	93	
1,1-Dichloroethene	5.0	4.44	89	
Trichloroethene (TCE)	5.0	4.67	93	
Surrogate Spike			120	

	Labo	ratory Control	Sample
	Spiked Conc. (ug/l)	Measured Conc. (ug/l)	Spike Recovery (%)
Benzene	5.0	5.36	107
Toluene	5.0	5.45	109
1,1-Dichloroethene	5.0	5.35	107
Trichloroethene (TCE)	5.0	5.65	113
Surrogate Spike			99

ACCEPTABLE RECOVERY LIMITS FOR MATRIX SPIKES: 65%-135% ACCEPTABLE RPD IS 35%

ANALYSES PERFORMED BY: Marilyn Farmer

NORTHWEST Environmental
Services Network

CHAIN-OF-CUSTODY RECORD

CLIENT: ADDRESS: PHONE: 36 CLIENT PROJ	St	25	ME	-	EN	'w	RUL	Im	EI	JIM	7	-7	Tal	D	ATE		7/2	- 3,	10	3		ΡΔ	GE /				
ADDRESS:							. 7							PE	20	IECT	T NIA	ME		5	H	in	* 5	Trut	2		-
PHONE: 36	0-4	3	8-9	52	1	EAV	<i>/</i> .	· ·									INA	IVIC.	<u></u>		110		1				-
CLIENT PROJ	ECT #	, 57	517	P	PRO		T MAA	NACI	-D.	Pari	C			LC	OCA	TIO	N:		22	4	0	1	- hor		TE 0E	7/	
				<u> </u>		7320	1 1017	INAGE	-K.	17/	7	16	wo	100	JLL	ECT	OR:	4	AH		116	in	<u>ک</u>	co	LLECTION	4	-3
			y 1			.	.6	5/	(d)	//	/ /	/ 2					/ ,	//	//	/ &/	//	//				2 6	Ē
	* 1			Sample			MALY		10 X		18 18 18 18 18 18 18 18 18 18 18 18 18 1	500	50%	10	882 1		\$/ _/	//	delan	" /.	ne/	//				Lunt	atory
Sample Numbe	er C	epth	Time		Container		10°/3		eth A	(* / (*)	(5.0°) X	30	14. S				(8 ² /,	Meltar	y 0/3	\$ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		/	NOTES			Total P	abor
1. MW-1					TIA	4	X			X					Ì	Ĭ		Ï				1	NOTES	5		FÖ	72
2. MW-2	-				u	- 6	XI		<u> </u>	X		_		_													\sqcap
3. mw-3	-				U			-	-	120	-	_			1			_			_						
4. mw-4 5. mw-5	-	-			4			-	-	-	-	-	H		+	\dashv	-	_		\dashv	_	4					
6.						-	2	_	-	-	+-	-		\dashv	+		+-	-		-		+					
7.						1	11	_			+	-		+	+	+	+	-		-	+	\dashv					_
8.							11	1			+		H	+	+	+	+	-		-	\dashv	+				-	-
9.		_			·									1	\top	1				\neg	+	+				-	
10.															T					1	\top	-				-	\dashv
11. 12.	-	+				_	+								I												
13.							+	-			+	- 77		1	1	4	<u></u>										\neg
14.	-	-				\dashv	++	-	\dashv		+	-	-	-	+	_	-		_	_	_	1					
5.						\dashv	++	-	-		+	\dashv	-	- -	+	+	-	-	-	\dashv	-	_					
6.				.			11	11		+	11	-	7	_	+	+	\vdash	-	\dashv	+	+	+				-	_
7.						1	11	1		1 7	1	1	+	-	+	+-	H	-	+	+	-	+					
8.	h				1						\Box		1	-	+	+-	\vdash	\dashv	+	+	+	+		-		-	
ELINQUISHED BY S	ignáture	-		E/TIME	REC	FIVED	BY (Sig	nature)		DATE/	TIME	I		SA	AMP	LE RE	CEIP	T		1	1	LABO	DRATORY N	OTES:			\dashv
166	11	- 7/		63						23- 4	53	TO	DTAL I	NUMBI	ER C	F CO	NTAIN	IERS									
ELINQUISHED BY	gnature)	DATI	E/TIME	REC	NED	BY (SIG	nature)		DATE/	TIME	CH	HAIN (OF CU	STO	DY SE	ALS	Y/N/N	IA			ر	TEM E	5			
	SEALS INTACT? Y/N/NA														(
	<u> </u>			SPOSAL								RE	CEIV	ED GC	OOD	CON)./COL	.D							1		1
	LIESN	DISP	USAL	@ \$2.00 e	nach []	Return	LJ Pi	ckup			,	NC	OTES:	-						\perp	\perp	Turn	Around Time	e: 24 HR	48 HR	5 D/	AY

GROUNDWATER MONITORING REPORT



SHORT STOP SITE 6317 CALIFORNIA AVENUE S.W. SEATTLE, WASHINGTON

Prepared By

Paul W. Stemen

Stemen Environmental, Inc.

STEMEN ENVIRONMENTAL, INC.

PO BOX 3644 LACEY, WA. 98509-3644 CONTR. LIC. #STEMEEI081J9

Telephone 360-438-9521 Fax 360-412-1225

December 15, 2003

Mr. Vernon Pontius 7730 Cabrini Dr. Port Orchard, WA 98367

Dear Mr. Pontius:

RE: GROUNDWATER MONITORING FOR SHORT STOP SITE LOCATED AT 6317 CALIFORNIA AVENUE S.W., SEATTLE, WASHINGTON. ECOLOGY SITE # 101565

MONITORING WELL INSTALLATION

On March 5 and 6, 2003, I supervised the proper installation of five (5) groundwater monitoring wells at selected locations on the subject site. The two inch in diameter P.V.C. monitoring wells were installed by Licensed Well Drillers from Holt Drilling Inc., of Puyallup, Washington. The five (5) monitoring wells were extended to depths of approximately 32 feet b.g.s. (below ground surface) and were screened from depths of approximately 10 feet b.g.s. to 30 feet b.g.s. A two (2) foot in length sump was placed on the bottom of the monitoring well.

All excess soils (cuttings) generated during the monitoring well installation process were placed in sealable steel drums for temporary on-site storage.

Measurable quantities of water were found to be present in all of the monitoring wells on the dates of their installation.

GROUNDWATER ELEVATIONS

Groundwater elevations were measured using an electronic water level indicator and verified with a steel tape coated with water detection paste. Depth to water was measured from the top of the monitoring well monument (ground surface).

The elevations of the tops of the on-site monitoring wells were determined by C&C Surveying of Mountlake Terrace, WA.

GROUND WATER SAMPLING

Prior to sampling, the monitoring wells were properly purged by removing a minimum of three (3) casing volumes of water from the wells using a disposable PVC bailer.

All waters generated during purging activities were placed in appropriate containers for transportation to an appropriate treatment/disposal facility.

The water level in the monitoring wells was stabilized to near original levels, then representative groundwater samples were obtained using a disposable PVC bailer. The sampled waters were transferred directly from the bailer to laboratory supplied containers for temporary storage.

On December 7, 2003, I began the process of sampling the groundwaters beneath the subject site. Water sample MW-1 was obtained from waters present at a depth of 11.75 feet b.g.s. in monitoring well MW-1, water sample MW-2 was obtained from waters present in monitoring well MW-2 at a depth of 11.55 feet b.g.s., water sample MW-3 was obtained from waters present in monitoring well MW-3 at a depth of 14.43 feet b.g.s., water sample MW-4 was obtained from waters present in monitoring well MW-4 at a depth of 11.70 feet b.g.s., and water sample MW-5 was obtained from waters present in monitoring well MW-5 at a depth of 11.60 feet b.g.s. These samples were immediately submitted for appropriate laboratory analyses and screened for gasoline range T.P.H., and V.O.C.'s (Specific Halogenated Hydrocarbons).

Laboratory analyses results for water samples MW-1, MW-2, MW-3, MW-4, and MW-5 indicated no detectable presence of gasoline range T.P.H. in these sampled waters.

<u>Laboratory analyses results for water sample MW-1 indicated no detectable presence of Specific Halogenated Hydrocarbons in these sampled waters.</u>

<u>Laboratory analyses results for water sample MW-4 confirm the detectable</u> <u>presence of Tetrachloroethene (PCE) at levels that do not exceed Ecology's Method "A" Clean Up Levels.</u>

Laboratory analyses results for water samples MW-2, MW-3, and MW-5 confirm the presence of Tetrachloroethene (PCE) at levels that exceed Ecology's Method "A" Clean Up Levels.

Ground water sampling was performed by Paul Stemen (myself).

LABORATORY ANALYSES

All sampling devices were properly cleaned between individual samples to prevent cross sample contamination. All samples were then tightly packed in recommended containers with no head space, properly refrigerated and transported with proper chain of custody forms to Environmental Services Network Northwest, Inc., of Lacey, Washington for appropriate laboratory analyses. Groundwater samples were screened for Gasoline Range Total Petroleum Hydrocarbons using methods NWTPH-Gx, and Specific Halogenated Hydrocarbons using E.P.A. method 8021B. These analytical methods meet all current Department of Ecology recommendations for groundwater sample analyses and quality controls.

HEALTH AND SAFETY

- 1. All on-site work was performed under the Health and Safety guidelines set forth in sections 29 CRF 1910.120 of the Federal Register and Chapter 296-62 WAC which provide regulations for individuals who are engaged in activities involving hazardous substances, including petroleum, and who perform confined space entry during field activities, also Chapter 296-155 WAC which provides State safety standards for construction work.
 - 2. All on-site workers were 40 hour Hazmat certified.
- 3. A copy of the Site Safety Plan was provided to all on-site employees. The contents of this plan and all potential on-site hazards, were discussed during a personnel on-site safety meeting. Based on the contents of this safety plan all workers were required to wear at least Level D protection. First Aid materials and properly trained personnel were present on-site at all times.
- 4. The immediate perimeter of the work area was secured at all times by orange hazard cones.

SUMMARY AND CONCLUSIONS

The following summary and conclusions are based on information gathered during on-site investigations described in this report.


- 1. Groundwater was present beneath this site on December 7, 2003, at depths ranging from 11.60 b.g.s. to 14.43 feet b.g.s.
- 2. Laboratory analyses results for groundwater samples obtained during this onsite investigation confirmed the presence of Tetrachloroethene (PCE) in the waters present in monitoring wells MW-2, MW-3, and MW-5 at levels that exceed Ecology's Method "A" Clean Up Levels.

If you have any questions or require further information please feel free to contact us at the above phone number.

Sincerely,

Ecology-Registered Site Assessment Supervisor IFCI #0874201-26

ASTM Certified



SHORT STOP 6317 CALIFORNIA AVE. SW SEATTLE, WA.

SUMMARY OF GROUNDWATER DEPTH AND ELEVATION DATA 12/7/03

WELL	TOP OF MONUMENT ELEVATION	DEPTH TO	GROUNDWATER
NUMBER		GROUNDWATER	ELEVATION
MW-1	233.01	11.75	221.51
MW-2	230.42	11.55	218.87
MW-3	230.64	14.43	216.21
MW-4	230.94	11.70	219.24
MW-5	228.62	11.60	217.02

ALL MEASUREMENTS ARE IN FEET

			T		T
	WATER LA	BORATOR	RY ANALYSE	S CHARTS	
			TOTAL PET		
		1	YDROCAR	BONS (PP	3)
SAMPLE	SAMPLE	SAMPLE			
NUMBER	DATE	DEPTH	GASOLINE		
MW-1	12-7-03		ND.		
MW-2	12-7-03		ND ND		
MW-3	12-7-03		ND		
MW-4~	12-7-03	7 7 7 7	ND		
MW-5	12-7-03		ND		

SPECIFIC HALOGENATE	DHIDRO	CARBONS	WATERS (PPB)	
SAMPLE-NUMBER	MW-1	MW-2	MW-3	MW-4	MW-5
DATE	12-7-03	12-7-03	12-7-03	12-7-03	12-7-03
DEPTHS	4			12 7 00	12-7-03
VINYL CHLORIDE	ND	ND	· ND	ND	
BENZENE	ND	ND	ND	ND	ND_
TOLUENE	ND	ND	ND	ND	ND
ETHYLBENZENE	ND	ND	ND	ND ND	ND
TOTAL XYLENES	ND	ND	ND	ND	ND
1,1 DICHLOROETHENE	ND	ND	ND		ND
METHYLENE CHLORIDE	ND	ND	ND	ND	ND
TRANS-1,2-DICHLOROETHENE	ND	ND	ND	ND	ND
1,1 DICHLOROETHENE	ND	ND	ND	ND	ND
CIS-1,2 DICHLOROETHENE	ND	ND	ND	ND	2.7
CHLOROFORM	ND	ND	ND	ND	ND
1,1,1-TRICHLOROETHANE	ND	ND	ND	ND	ND
CARBON TETRACHLORIDE	ND	ND	ND	ND	ND
1,2 DICHLOROETHANE	ND	ND	ND	ND	ND
TRICHLOROETHENE	ND	ND	1.1	ND	ND
1,1,2,-TRICHLOROETHANE	ND	ND	ND	ND	2
TETRACHLOROETHENE	ND	10	11	ND	ND
,1,1,2-TETRACHLOROETHANE	ND	ND	ND	4.8	39
,1,2,2-TETRACHLOROETHANE	ND	ND	ND	ND ND	ND ND

December 15, 2003

Paul Stemen Stemen Environmental P.O. Box 3644 Lacey, WA 98509

Dear Mr. Stemen:

Please find enclosed the analytical data report for the Short Stop Project site in Seattle, Washington. Water samples were analyzed for Gasoline by NWTPH-Gx and Specific Halogenated Hydrocarbons by Method 8021B on December 10, 2003.

The results of these analyses are summarized in the attached tables. Applicable detection limits and QA/QC data are included. An invoice for this analytical work is also enclosed.

ESN Northwest appreciates the opportunity to have provided analytical services to Stemen Environmental for this project. If you have any further questions about the data report, please give me a call. It was a pleasure working with you on this project, and we are looking forward to the next opportunity to work together.

Sincerely,

Michael A. Korosec

Michael a Konne

President

SHORT STOP PROJECT Seattle, Washington Stemen Environmental, Inc.

Analyses of Gasoline (NWTPH-Gx) in Water

Sample Number	Date Analyzed		Surrogate Recovery (%)	Gasoline (ug/l)
Method Blank	12/10/03	t do la	93	nd
MW-1	12/10/03		108	nd
MW-2	12/10/03		94	nd
MW-3	12/10/03		96	nd
MW-4	12/10/03		102	nd
MW-5	12/10/03		97	nd
Method Detection Li	mits			100

[&]quot;nd" Indicates not detected at the listed detection limits.

ACCEPTABLE RECOVERY LIMITS FOR SURROGATE (Chlorobenzene): 65% TO 135%

ANALYSES PERFORMED BY: Dean Phillips

[&]quot;int" Indicates that interference prevents determination.

SHORT STOP PROJECT Seattle, Washington Stemen Environmental, Inc.

Specific Halogenated and Aromatic Hydrocarbons (EPA 8021B) in Water

Sample Description		Method	MW-1	MW-2	MW-3	MW-4	MW-5
Date Sampled		Blank	12/9/03	12/0/02	10/0/02		
Date Analyzed		12/10/03	12/10/03	12/9/03	12/9/03	12/9/03	12/9/03
	MDL	12/10/03	12/10/03	12/10/03	12/10/03	12/10/03	12/10/03
	(ug/l)	(ug/l)	(ug/l)	(ug/l)	(ug/l)	(ug/l)	(ug/l)
Vinyl chloride	5.0	nd	_1				(48.1)
Benzene	1.0	nd	nd	nd	nd	nd	nd
Toluene	1.0	nd	nd	nd	nd	nd	nd
Ethylbenzene			nd	nd	nd	nd	nd
otal Xylenes	1.0 1.0	nd	nd	nd	nd	nd	nd
,1-Dichloroethene	1.0	nd	nd	nd	nd	nd	nd
fethylene chloride		nd	nd	nd	nd	nd	nd
rans -1,2-Dichloroethene	1.0	nd	nd	nd	nd	nd	nd
,1-Dichloroethane	1.0	nd	nd	nd	nd	nd	nd
is -1,2-Dichloroethene	1.0	nd	nd	nd	nd	nd	nd
hloroform	1.0	nd	nd	nd	nd	nd	2.7
	1.0	nd	nd	nd	nd	nd	nd
1,1-Trichloroethane (TCA)	1.0	nd	nd	nd	nd	nd	nd
	1.0	nd	nd	nd	nd	nd	nd
2-Dichloroethane richloroethene (TCE)	1.0	nd	nd	nd	nd	nd	nd
1.2 Triphlamostham	1.0	nd	nd	nd	1.1	nd	2.0
,1,2-Trichloroethane	1.0	nd	nd	nd	nd	nd	nd
etrachloroethene (PCE)	1.0	nd	nd	10	11	4.8	39
1,1,2-Tetrachloroethane	1.0	nd	nd	nd	nd	nd	nd
1,2,2-Tetrachloroethane	1.0	nd	nd	nd	nd	nd	nd
urrogate Recovery (%)		71	107	88	93	100	96

ACCEPTABLE RECOVERY LIMITS FOR SURROGATE (Chlorobenzene): 65%-135%

ANALYSES PERFORMED BY: Marilyn Farmer & Dean Phillips

[&]quot;nd" Indicates not detected at listed detection limit.
"int" Indicates that interference prevents determination.

SHORT STOP PROJECT Seattle, Washington Stemen Environmental, Inc.

QA/QC Data - EPA 8021B Analyses

		Sample Matrix Spike	Description:	_BPPW-1
	Spiked Conc. (ug/l)	Measured Conc. (ug/l)	Spike Recovery (%)	
Benzene	5.00	5.56	111	
Toluene	5.00	6.32	126	
1,1-Dichloroethene	5.00	5.85	117	
Trichloroethene (TCE)	5.00	3.54	71	
Surrogate Spike			98	

	Labo	ratory Control	Sample
	Spiked Conc. (ug/l)	Measured Conc. (ug/l)	Spike Recovery (%)
Benzene	5.00	4.63	93
Toluene	5.00	5.42	108
1,1-Dichloroethene	5.00	4.96	99
Trichloroethene (TCE)	5.00	4.61	92
Surrogate Spike			74

ACCEPTABLE RECOVERY LIMITS FOR MATRIX SPIKES: 65%-135%

ANALYSES PERFORMED BY: Marilyn Farmer & Dean Phillips

NORTHWEST V

En nen
Services Network

CHAIN-OF-CUSTODY RECORD

CLIENT:	mo		ENV	rrer	In.	LE 27	WZ		1				100	TF.	12/	9/1	1				GE		—		
ADDRESS:																						_OF		7	
DUONE TOUR	38.	90	1										PR								STOP		-		
PHONE: 340 T	70	750	/		FAX	(:					_	LOCATION:SEA							TL	E	alt				
PHONE: Su-4 CLIENT PROJECT	#:	thon	~ Sn	PRO	DJEC	AM T	NAGI	ER:	VAI	L ST	72	رر	co	LLE	СТС	R:_	PAU	16,	500	n	2	DATE OF COLLECTION 12/2			
					T		/		12	7	7	7	77	7	7	7	77	7	7	7	7777	COLLECTION			
					-	J56		80	870	1000	Sirre		//	//	(8°)	/,	//	rine	/	/,			ners	مِّح	
Sample Number	Depth	Time	Sample Type	Container	Туре	10 /01 10 /01		in's	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	81,200 80,200 80,200	34,8	4,00 4,00	10 / S	88 / 88 88 / 88	\$ [*] /\$	×/.	To To To	Chi	37.P	//			Contai	Laboratory Note Numb	
1. MUT			me	Try	2	X	7		X	Y		\simeq	787	979		1/1/2	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	×+/	4	4	NOTES		P 5	3 2	
2. mw 2			1	7	1	X	1	1	150	+		+	+	+		+	+	H		\dashv			-	\sqcup	
3. mw-3 4. mw-4 5. mw-)						X	1		12	_		-	+	+		+	+	H	-+	\dashv		1 ".	+-	\vdash	
4. mw-4					5	1			X			+	1	-		+	\dashv	\vdash	-	+			+	\vdash	
5. mw-)						×			N			7	\dashv	1		+		H	\dashv	+			+-	\vdash	
6.			1	. 1												1		\Box	\dashv	\dashv	/		+-		
7.												1				1	1		_	+			+-	H	
8.																\top			\dashv	+			-	H	
9.																1	+		\dashv	+			+	H	
10.																	1		+	+			+		
11.					1	11										+	+		\dashv	\dashv			+ ;	H	
12.						++	1										1			\top			+-	H	
13.						+	\perp									7	1			+		. apro		-	
14. 15.						++	-								e j				-			1	+	$\overline{}$	
16.	-	-			-	++	+	_		1	_													$\overline{}$	
7.				· · · · · ·	-	+	+-	\dashv		+	_	1	1												
8 /		-			+	+-	+-	-		1	\bot	1	1					,	1						
RELINQUISHED BY (Signatu	re)	DAT	E/TIME	RECE	IVED	BY (Sies		4			Ţ													\neg	
111114	2	8/0		M	1,~/	BY (Sign	r /	/	,	,				MPLE				_	_	LABO	DRATORY NOTES:				
EUNQUISHED BY (Signatu) E/TIME	7///	1 Cue	cal a		ru					UMBE					1	_	K	C/ 20-2/	2			
, Longitalio	,	UAIT) TIME	RECE	ייאבט (BY (Sign	ature)		DATE	TIME			F CUS			SYA	I/NA	-	\dashv	/					
	CARA	DI E O	50054	Mero	07/0								TACT					-	_						
□ ES			SPOSAL 3 \$2.00 e				rup					CEIVE	D GOO	DD CO	ND./C	OLD		+	-	Turn Around Time: 24 HR 48 HR 5 DAY					
			д							-								\perp			24	40 MF	(5 D/	AY	