

SHARP Report — Part 1 of 2

Go to site contamination history

• SHARP first SHARP		v2024.04.29	Ecology	Info
 SHARP rating 	High		ERTS	SHARP it
 SHARP date 	07/28/2025		CSID	3115
EJFlagged?	🛇 - No Override		FSID	2566095
 LD confidence level 	low		VCP	SHARP it
 Cleanup milestone 	remedial investigation		UST ID	SHARP it
• SHARPster	Sam Meng		LUST ID	SHARP it

This section is	blank if	this is the	first SHARP
-----------------	----------	-------------	-------------

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	high	multiple chemical types	~
Groundwater	C3	high	risk to off-site people	✓
Surface water	В3	high	climate change impacts	✓
Sediment	A2	high	plant/animal tissue data	\otimes
Soil	A1	high		

Location and land use info

9721 Burnham Dr NW, Gig Harbor, Pierce County, 98332

Primary parcel 0222313073
Land use residential
Responsible unit SWRO

Sources reviewed

- 1. DRAFT REMEDIAL INVESTIGATION REPORT, Farallon, 2022
- 2. Net Enviromental Benefit Analysis, EnviroVector, 2019



Primary census tract	Associated census tracts
53053072505	SHARP it
330330, 2303	Sinut it
Local demographics co	
zero was applied to all EJscr	reen parameters because the EJscreen website was not available at the time of
ating.	
0 /	
Source/source area des	
	HSC Property is lead shot and clay targets from current and historical operation
he shotgun range, and bullet	ts and bullet jackets from current and historical operation of the rifle and pistol
ange.	
Soil comments	
o comments	
0 1 1	
Groundwater comment	s
Groundwater comment no comments	S
	S
	S
	is a second of the second of t
	ES CONTRACTOR OF THE PROPERTY



Surface water comments
The surface water might be impacted in the drainage ditch that is adjacent to the main source parcel.
Sediment comments
The impacted sediment is present in the drainage ditch that is adjacent to the main source parcel.
Indoor air comments
no comments
Additional factors comments
no comments



Site history Go to top The Site has operated as an outdoor firing range since 1947. The locations of the shotgun range, located in the central portion of the Site, and the rifle and pistol range, located in the northern and eastern portions of the Site. The current configuration of the shotgun range includes seven traps that launch clay targets over an open field. Debris from broken and unbroken clay targets was present on the ground surface primarily in a fan-shaped arc approximately 125 to 225 feet downrange (east) of each trap. The rifle and pistol range has berms on the eastern, western, and northern sides that serve as backstops for bullets fired during target shooting by GHSC patrons. Lead reclamation was completed at the Site in 2011 to remove lead shot from the ground surface of the shotgun range and the wooded area east of the shotgun range.



Overflow - Site contamination and cleanup history More parcels in the site: 0222314016		
More parcels in the site: 0222314016		

3115 Gig Harbor Sportsman Club 20250728

First SHARP

SHARP rating — High

SHARP Report — Part 2 of 2

Conceptual site model 07/28/2025



