

SHARP Report — Part 1 of 2

Go to site contamination history

• SHARP first SHARP		v2024.04.29	Ecology	/ Info
<ul> <li>SHARP rating</li> </ul>	Medium		ERTS	716453
<ul> <li>SHARP date</li> </ul>	08/04/2025		CSID	16656
<ul><li>EJFlagged?</li></ul>	🛇 - No Override		FSID	75334599
<ul> <li>LD confidence level</li> </ul>	low		VCP	NW3347
<ul> <li>Cleanup milestone</li> </ul>	remedial investigation		UST ID	none
• SHARPster	Kim Vik		LUST ID	none

### This section is blank if this is the first SHARP

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	В3	low	multiple chemical types	0
Groundwater	A3	low	risk to off-site people	$\Diamond$
Surface water	D4	low	climate change impacts	$\Diamond$
Sediment	D4	low	plant/animal tissue data	$\Diamond$
Soil	C1	low		

#### Location and land use info

2317 Broadway, Everett, Snohomish County, 98201

Primary parcel 00439149500700 Land use commercial Responsible unit NWRO

_			
SOL	irces	ravia	אסאו

2022 - Excavation and Well Installation Report, 4/8/22

2021 - Limited Site Assessment Report, 11/21/21



Duima a mus a a sassas a tura sa	Associated consustants
Primary census tract	Associated census tracts
53061040400	None
Local demographics co	
ensus Tract obtained from V	/A DOH environmental health disparities map. EPA's EJ Screen tool is not availabl
2	- win kin w
Source/source area de	
Pleases to soil and groundwa	Star from LISTs from the former decoline/service station
siedses to son and groundw	ater from USTs from the former gasoline/service station.
sicuses to son and groundwi	ster from 0313 from the former gasonile/service station.
sicuses to son and groundwi	ater from 0313 from the former gasonile/service station.
reases to som and groundwi	atel from 0313 from the former gasonile/service station.
reases to som and groundwi	ater from 0313 from the former gasonile/service station.
reases to som and groundwi	ater from 0313 from the former gasonile/service station.
	ster from 0313 from the former gasonile/service station.
creases to som and ground.	ster from 0313 from the former gasonile/service station.
reases to som and ground.	ster from 0313 from the former gasonile/service station.
	ster from 0313 from the former gasoline/service station.
	ster from 0313 from the former gasonile/service station.
Soil comments	
Soil comments ne Site has not been fully ch	aracterized. The extent of soil and groundwater contamination across the Site is
Soil comments ne Site has not been fully ch	
Soil comments ne Site has not been fully ch	
<b>Soil comments</b> ne Site has not been fully ch	
<b>Soil comments</b> ne Site has not been fully ch	
Soil comments ne Site has not been fully ch	
<b>Soil comments</b> ne Site has not been fully ch nknown.	aracterized. The extent of soil and groundwater contamination across the Site is
Soil comments ne Site has not been fully ch nknown.  Groundwater comment	aracterized. The extent of soil and groundwater contamination across the Site is
Soil comments ne Site has not been fully ch nknown.  Groundwater comment	aracterized. The extent of soil and groundwater contamination across the Site is
Soil comments ne Site has not been fully ch nknown.  Groundwater comment	aracterized. The extent of soil and groundwater contamination across the Site is
Soil comments The Site has not been fully che of the second secon	aracterized. The extent of soil and groundwater contamination across the Site is



SHARF
Surface water comments
no comments
Sediment comments
no comments
Indoor air comments
Ecology recommended a Tier 1 VI evaluation for the Site building. A VI assessment has not been conducted, so V
for the current building is unknown.
Additional factors comments
no comments



Site history Go to top

A gasoline station operated on the south portion of the Property. The station operations included auto repair and fueling (3 USTs). Waste oil and fuel oil USTs are documented; it is unknown what the 3rd UST contained. Two USTs were removed prior to 2021. There is no information regarding the USTs. The Site was redeveloped into an Alfy's Pizza restaurant (unknown date).

A subsurface investigation was conducted in October 2021. Soil samples were collected: TPH-G (up to 1,400 mg/kg) and TPH-D+O (19,000 mg/kg) were detected. BTEX and cPAHs were also detected in soil above the CULs. A groundwater sample collected from one boring exceeded CULs [TPH-G (2,000 ug/L), TPH-D+O (3,200 ug/L), and cPAHs (TEQ 5.692 ug/L)].

A UST was removed from the SW corner of the Proerty in December 2021. Confirmation soil samples were collected at the limits of the UST excavation: six samples collected at the SW sidewall and the excavation bottom (18 ft bgs) contained TPH-G and benzene above the CULs. Soil was described as saturated and wet; however, there was no mention of groundwater. Approximately 2,000 tons of PCS were removed and disposed off-site.

Six GW monitoring wells were installed and sampled in March 2022. Soil samples collected from MW-1 and MW-2 at 9 ft bgs contained TPH-D+O close to the CUL; all other resuls were below the CULs (both of these wells were located on the northern portion of the Property and were found to be "dry"). Two wells (MW-4 and MW-6) located in the SW portion of the Property contained contaminants (TPH-D, TPH-O, benzene) above the CULs. Groundwater was not sampled for cPAHs. The depth to groundwater is 4 to 6 ft bgs; the flow direction is to the SW. Groundwater may be perched.

Ecology requested further action i	or the Site (opinion letter o	dated 4/11/23). The VCP a	agreement was terminated
on 3/6/24 due to no action.			



Overflow -	- Site contamination and cleanup history
No overflow	

16656 Alfys Pizza Container 20250804

**First SHARP** 

**SHARP** rating — Medium

SHARP Report — Part 2 of 2

Conceptual site model 08/04/2025



SHARP

