

SHARP Report — Part 1 of 2

Go to site contamination history

• SHARP first SHARP	v2024.04.29	Ecology I	Info
 SHARP rating 	Low	ERTS	None
 SHARP date 	09/19/2025	CSID	5798
EJFlagged?	✓ – No Override	FSID	27223439
 LD confidence level 	high	VCP	None
 Cleanup milestone 	post-cleanup controls & monitoring	UST ID	564219
• SHARPster	Rachel Caron	LUST ID	5657

This section	is	blank i	f this	is tl	he first	SHARP
--------------	----	----------------	--------	-------	----------	-------

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	high	multiple chemical types	0
Groundwater	C3	medium	risk to off-site people	\Diamond
Surface water	D4	high	climate change impacts	\Diamond
Sediment	D4	high	plant/animal tissue data	\otimes
Soil	D4	medium		

Location and land use info

1323 Lee Blvd, Richland, Benton County, 99352

Primary parcel 111983020402001

Land use commercial

Responsible unit CRO

Sources reviewed

Second Quarter 2024 Groundwater Monitoring Report, Arcadis, July 2024

Monitoring Well Installation Report, Arcadis, May 2024



Primary census tract	Associated census tracts
5300501600	
Local demographics co	mments
no comments	
Source/source area des	scription
	ite investigations have shown that while soil samples tested for TPHG, TPHD and
	entrations above MTCA Method A cleanup levels, groundwater sampling has
	se contaminants above MTCA Method A cleanup levels. Lead in groundwater has
also exceeded Method A CULs	•
Soil comments	
no comments	
Groundwater comments	3
no comments	



Surface water comments
no comments
Sediment comments
no comments
Indoor air comments
no comments
A J.P.P. and Continue and a second se
Additional factors comments
no comments



Site history Go to top The Site was operated as a Chevron gasoline service station from approximately 1960 until 1976. All station features were subsequently demolished, and the Site remained vacant through at least 2000 (CRA 2007). The Site was redeveloped in 2003 with a commercial structure and associated parkingareas. Currently, the Site is occupied by a Subway® restaurant and associated parking area. Geology at the Site consists of silt and sandy gravels to 20 feet below ground surface (bgs). The depth to groundwater ranged from approximately 12 to 15 feet bgs during groundwater monitoring events conducted from 2018 through 2021. The general direction of groundwater flow beneath the Site is toward the south-southeast.



Overflow - Site contamination and cleanup history
No overflow

5798 Chevron Station 98944 20250919

First SHARP

SHARP rating — Low

SHARP Report — Part 2 of 2

Conceptual site model 09/19/2025



