

2025-05-13 X:\USWACircleKJan2025_MoRmdProgEvalCircleK 4_Graph_Vapor_ERRG hremis




Figure 4. GRO and Benzene Concentrations in System Vapor Influent and Effluent
Second Quarter 2025 Remedial Progress Evaluation Report for Former Circle K 1461
Seattle, WA

2025-10-07 \\EgnyteDrive\GIS\USWA\CircleK\Jan2025_MoRmdProgEval\CircleK_2025may.aprx_6_GW_Elev_ERRG_hrenis




Figure 6. Groundwater Elevation Contours, May 2025
Second Quarter 2025 Remedial Progress Evaluation Report for Former Circle K 1461
Seattle, WA

2025-10-07 I:\EgnyteDrive\GIS\USWA\CircleKJan2025_MoRmdProgEval\CircleK_2025may.aprx_7_GasRO_ERRG_hemis




Figure 7. Groundwater Gasoline-Range Organics Contours, May 2025
Second Quarter 2025 Remedial Progress Evaluation Report for Former Circle K 1461
Seattle, WA

2025-10-07 I:\EgnyteDrive\GIS\USWA\CircleK\Jan2025_MoRmdProgEval\CircleK_2025may.aprx_8_Benzene ERRG hremis




Figure 8. Groundwater Benzene Concentration Contours, May 2025
Second Quarter 2025 Remedial Progress Evaluation Report for Former Circle K 1461
Seattle, WA