



GREYLOCK CONSULTING LLC

Water Resources & Environmental Services

March 4, 2009

Mr. Russ Olson
VCP Unit Manager
Department of Ecology
3190 160th Avenue SE
Bellevue, WA 98008-5452

Re: **Northwest Industrial Repair Site
21850 88th Place South
Limited Phase 2 Site Assessment**

Dear Mr. Olson:


This letter is to inform you that Volatile Organic Compound (VOCs) have been detected in groundwater at the Northwest Industrial Repair Site, located at 21850 88th Place South, in Kent, Washington. VOCs were detected in an upgradient well at the site. VOCs were not detected in downgradient wells. Because of this, we believe the VOCs in groundwater originated from an upgradient, offsite source.

Attached is a report which summarizes the findings of our Limited Phase 2 Site Assessment.

If you have questions on this report, please call me at 253-941-0654.

Sincerely,
GREYLOCK CONSULTING LLC

Suzanne Dudziak, Principal Hydrogeologist
greylockllc@comcast.net
Attachment



cc: Mr. Leo Brutche, The Brutsche Family  Revocable Trust