



- T-91 site boundary
- Tank Farm Affected Area
- Pier head line
- Adjacent property



Prepared by craig, 130/2017, W:\\Projects\\Port of Seattle - T-91 Sediment Investigation\\GIS\\Maps and Analyses\\Historical Data Review Map 1 6352 T-91 Site Map.mxd

Aerial photo credit: Port of Seattle 2016, photo date unknown


**Windward**  
environmental LLC




0 125 250  
Yards  
0 100 200  
Meters


Map 1. T-91 site and vicinity

DRAFT










Aerial photo credit: Port of Seattle 2016, photo date unknown

**Windward**  
environmental LLC

Prepared by craig, 130/2017, W:\\Projects\\Port of Seattle - T91 Sediment Investigation\\GIS\\Maps and Analyses\\Historical Data Review Map 5 6524 T-91 Current conditions.mxd

Map 5. T-91 sediment sample locations that represent existing conditions


DRAFT





0 50 100 150  
Yards  
0 50 100 150  
Meters

**Map 6. Exceedances of SMS standards for metals in surface sediment samples**

**DRAFT**







Aerial photo credit: Port of Seattle 2016, photo date unknown

**Windward**  
environmental LLC



0 50 100 150  
Yards  
0 50 100 150  
Meters

**Map 9. Dioxin/furan TEQs in surface sediment samples**

**DRAFT**