



HAZARDOUS
SITE CONTROL
DIVISION

**Remedial
Planning/
Field
Investigation
Team
(REM/FIT)**

ZONE II

CONTRACT NO.
68-01-6692

CH₂M HILL
Ecology &
Environment

Ponder's Corner

PUBLIC COMMENT

REMEDIAL INVESTIGATION REPORT

PONDER'S CORNER, WASHINGTON

EPA 112-OL22

June 13, 1985





Figure 1.3. Site Map of Plaza Cleaners







Figure 4. Extent of PERC Contamination in the Soil Under Plaza Cleaners at a Depth of 8.0 to 11.5 ft







Figure 3.4. Concentration Distribution of PERC in the 0.0 to 5.0-ft Depth Interval on Plaza Cleaners' Property






Figure 3.6. Concentration Distribution of PERC in the 7.0 to 8.5-ft Depth Interval on Plaza Cleaners' Property




Figure 3.7. Concentration Distribution of PERC in the 8.5 to 11.5-ft Depth Interval on Plaza Cleaners' Property




Figure 3.8. Concentration Distribution of PERC in the 11.5 to 12.5-ft Depth Interval on Plaza Cleaners' Property