



# 2020 ANNUAL CAP INSPECTION REPORT

**BNSF Northport Site** 

December 16, 2020

## 2020 ANNUAL CAP INSPECTION REPORT

**BNSF Northport Site** 

Joel Orchard

Myle SM

Joel Orchard Geologist II

Kyle Haslam Project Manager Prepared for:

Washington State Department of Ecology

East Regional Office 4601 North Monroe, Suite 202 Spokane, Washington 99205

Prepared by:

Arcadis U.S., Inc.

1100 Olive Way

Suite 800

Seattle

Washington 98101

Tel 206 325 5254

Fax 206 325 8218

Our Ref:

30066062

Date:

December 16, 2020

## **CONTENTS**

| Acro | onyms and Abbreviations          | ii |
|------|----------------------------------|----|
| 1    | Introduction                     | 1  |
| 2    | Cap Monitoring and Documentation | 1  |
| 3    | Site conditions                  | 1  |
| 4    | Schedule                         | 1  |

#### **APPENDICES**

Appendix A Photographic Log

#### **ACRONYMS AND ABBREVIATIONS**

Arcadis U.S., Inc.

BNSF Railway Company

Ecology Washington State Department of Ecology

site Northport City Park Cleanup Site in Northport, Washington

#### 1 INTRODUCTION

On behalf of BNSF Railway Company (BNSF), Arcadis U.S., Inc. (Arcadis) prepared this 2020 Annual Cap Inspection Report to document the integrity of the protective cap at the BNSF Northport site in Northport, Washington (the site) for the January 1, 2020 through December 31, 2020 reporting period. The site is located at latitude 47° 34' 39" N and longitude 122° 19' 58" W.

The site is located adjacent to the former LeRoi Smelter site, which refined copper, lead, and silver ores. Prior operations at the former smelter plant contaminated adjacent properties, including the Northport City Park. The Northport City Park property is currently owned by BNSF and leased to the City of Northport.

In 2004, remedial activities were conducted at the site, including the excavation and capping of metal-contaminated soil. As part of the Environmental Covenant for the site, the Washington State Department of Ecology (Ecology) requires annual cap monitoring to ensure the condition of the cap is acceptable and continues to be protective of human health and the environment.

#### 2 CAP MONITORING AND DOCUMENTATION

The cap monitoring activities completed in 2020 include:

- Performed annual cap inspection in November 2020.
- Documented cap integrity.
- Evaluated site to determine if cap repairs were required.
- Submitted an annual report to Ecology to communicate the findings of the cap inspection.

During the cap inspection the following site conditions were evaluated:

- Quality of the sod located within the Northport City Park.
- · Condition of trees near the remedial area.
- Presence or absence of noxious weeds in the remedial area.
- Presence or absence of burrowed animal activity.
- Stability and integrity of the cap.
- Integrity of the barrier fence between the park and railroad tracks.

#### 3 SITE CONDITIONS

Arcadis completed the cap inspection on November 19, 2020. The integrity of the cap was confirmed to be intact and no deficiencies in the cap or vegetation were identified during the inspection. A photographic log documenting site conditions is presented as Appendix A.

#### 4 SCHEDULE


There were no items identified that would require maintenance to be performed. The next cap inspection will occur during the fourth quarter of 2021.

## **APPENDIX A**

Photographic Log



2020 Annual Cap Inspection Report BNSF Northport Site



Photograph: 1

**Description:** 

Gravel cap, looking

east

Location:

Northport, WA

Photograph taken by:

Joel Orchard

Date: 11/19/2020



Photograph: 2

Description:

Access point in fence on west side of cap, looking southeast

Location:

Northport, WA

Photograph taken by:

Joel Orchard

Date: 11/19/2020



2020 Annual Cap Inspection Report BNSF Northport Site



Photograph: 3

Description:

Fence between park and tracks, looking east

Location:

Northport, WA

Photograph taken by:

Joel Orchard

Date: 11/19/2020



Photograph: 4

**Description:** 

Fence between parking lot of park and tracks, looking east

Location:

Northport, WA

Photograph taken by:

Joel Orchard

Date: 11/19/2020



2020 Annual Cap Inspection Report BNSF Northport Site



Photograph: 5

Description:

Park grass and trees, looking west

**Location:** Northport, WA

Photograph taken by: Joel Orchard

Date: 11/19/2020



Photograph: 6

Description:

Identified low spot on east side of cap

Location:

Northport, WA

Photograph taken by:

Joel Orchard

Date: 11/19/2020



2020 Annual Cap Inspection Report BNSF Northport Site



Photograph: 7

Description:

Identified low spot in the middle of fence line

Location:

Northport, WA

Photograph taken by:

Joel Orchard

Date: 11/19/2020



Photograph: 8

Description:

Fence between park and boat launch, looking east

Location:

Northport, WA

Photograph taken by:

Joel Orchard

Date: 11/19/2020



2020 Annual Cap Inspection Report BNSF Northport Site



Photograph: 9

#### **Description:**

Area between park and boat launch, looking east

**Location:**Northport, WA

Photograph taken by: Joel Orchard

Date: 11/19/2020



Photograph: 10

#### **Description:**

South fenceline of gravel cap area, looking south east

**Location:**Northport, WA

### Photograph taken by:

Joel Orchard

Date: 11/19/2020



2020 Annual Cap Inspection Report BNSF Northport Site



Photograph: 11

**Description:** 

Tracks south of park, looking northeast

Location:

Northport, WA

Photograph taken by:

Joel Orchard

Date: 11/19/2020



Photograph: 12

Description:

Entrance to parking lot, looking east

Location:

Northport, WA


Photograph taken by:

Joel Orchard

Date: 11/19/2020



2020 Annual Cap Inspection Report BNSF Northport Site



Photograph: 13

**Description:** 

Parking lot, looking east

Location:

Northport, WA

Photograph taken by:

Joel Orchard

Date: 11/19/2020



#### Arcadis U.S., Inc.

1100 Olive Way

Suite 800

Seattle, Washington 98101

Tel 206 325 5254

Fax 206 325 8218