



## INDUSTRIAL STORMWATER GENERAL PERMIT INSPECTION REPORT

State of Washington Department of Ecology

### Section A: General Data

Ecology Inspector(s): Shannon Adams	On-Site Representative Name: Title: Phone: Email:	Inspection Date: March 31, 2021 Entry/Exit Time: 10:25/10:30	Inspection Type: Termination
		Receiving waters: Esquatzel Coulee Watershed	Permit webpage: <a href="#">Facility Details</a>

### Section B: Background

Tommys Scrap & Salvage Pasco is covered under the State of Washington's Industrial Stormwater General Permit (ISGP). The ISGP is a National Pollutant Discharge Elimination System (NPDES) and a State Waste Discharge permit for discharge of industrial stormwater. The purpose of this inspection was to conduct a termination inspection as the permittee has sold the property. According to the Franklin County Assessors website, the property was sold on December 18, 2020.

### Section C: Observations

Tommys Scrap & Salvage Pasco is permitted for 7 acres of coverage under the Industrial Stormwater General Permit.

I arrived onsite and saw that the site has been cleared and buildings demolished. As mentioned above, the property has been sold and the business no longer exists.

Ecology is initiating a termination for WAR002320 Tommys Scrap & Salvage Pasco as the site is cleaned and property sold.

Ecology Inspector (signature): *Shannon Adams*

Date: April 9, 2021

Ecology Inspector (print name): Shannon Adams

**Department of Ecology**  
**Eastern Regional Field Office**  
**4601 N Monroe Street**  
**Spokane, WA 99205**  
**(509) 570-8783**

All photos taken by Shannon Adams

**Photo 1**

Photo Description: Site from a distance.



Date:2021/03/31 Time:10:28:04 Lat:46.22389 Long:-119.0763 Direction degrees:91.48891

**Photo 2**

Photo Description: Building demolished.



Date:2021/03/31 Time:10:26:10 Lat:46.22531 Long:-119.07646 Direction degrees:272.14093

**Photo 3**

Photo Description: Building demolished. Site cleaned.



Date:2021/03/31 Time:10:26:05 Lat:46.22532 Long:-119.07645 Direction degrees:225.52795

**Photo 4**

Photo Description: Site is cleaned.



Date:2021/03/31 Time:10:26:01 Lat:46.22534 Long:-119.07645 Direction degrees:175.69409