


PHOTO ADDENDUM – CSR MARINE SOUTH



001

Description: Photo showing double walled waste oil container and Stormwater Rx units



002

Description: Photo showing wash pad with vessel on lift recently washed and waiting to be moved.

PHOTO ADDENDUM – CSR MARINE SOUTH



003

Description: Photo showing north side of facility with vessels on blocking and tarps under vessels where work is being conducted.



004

Description: Photo showing north side of facility main building.

PHOTO ADDENDUM – CSR MARINE SOUTH



005
Description: Photo showing Stormwater-Rx current sample location which does not collect overflows.




006
Description: Photo showing Stormwater-Rx piping after overflow connection where new sample port needs to be installed for permit compliant sampling.

PHOTO ADDENDUM – CSR MARINE SOUTH



007
Description: Photo showing above ground wash water tanks.



008
Description: Photo showing vessel being painted via roller with tarp underneath.

PHOTO ADDENDUM – CSR MARINE SOUTH



009

Description: Photo showing secondary containment inside the shop building.



010

Description: Photo showing storage shed to the north with liquid chemicals stored without secondary containment.

PHOTO ADDENDUM – CSR MARINE SOUTH



011
Description: Photo showing sanding dust on ground inside temporary tent structure due to not using tarping during vessel maintenance activities involving sanding of the exterior.



012
Description: Photo showing catch basin with insert. Large amounts of fine debris around this catch basin that is on the east side of the main building.



013
Description: Photo showing close up of catch basin in photo 012



014
Description: Photo showing zinc and aluminum storage containers that are inside a metal storage building.

PHOTO ADDENDUM – CSR MARINE SOUTH



015


Description: Photo showing sanding dust from exterior maintenance of vessels on the ground inside a temporary tent structure due to not using tarps.



016

Description: Photo showing sanding dust from exterior maintenance of vessels on the ground inside a temporary tent structure due to not using tarps.

PHOTO ADDENDUM – CSR MARINE SOUTH



INTENTIONALLY LEFT BLANK

017
Description: Photo showing Stormwater Pollution Prevention Plan Certification page unsigned.

INTENTIONALLY LEFT BLANK

INTENTIONALLY LEFT BLANK