INITIAL INVESTIGATION FIELD REPORT

LUST ID: 2756 **FS ID:** 85982563 **Site ID:** 200042

SITE NAME Uneeda Auto & Boat Rebuild

SITE LOCATION INFORMATION

Contact Person Name	*Title*	*Phone Number*

Mailing Address	*City*	*Zip + 4*
4302 Fremont Ave N	Seattle	98103

Site Location	*Closest City*	*County*
4302 Fremont Ave N	Seattle	

Quarter-Quarter	*Section*	*Township*	*Range*
Latitude:	*Degree*	*Minute*	*Second*
Longitude:	*Degree*	*Minute*	*Second*

INSPECTION INFORMATION

Inspection Date *Inspection Time* *Type of Entry Notice*

Photographs *Yes* *No* *Weather:* *Clear* *Partly Cloudy* *Overcast*

Videotape *Yes* *No* *Precipitation* *Temperature*

Samples *Yes* *No* *Wind Direction* *Wind Speed*

RECOMMENDATION

No Further Action:

No. Residual soil impacts remain near sidewalks and under pump island.

Release or threatened release does not pose a threat

No release or threatened release

Educational Mailing

Refer to another program/agency

Site Hazard Assessment

Interim Action

Emergency Action Plan

Independent Cleanup Action

In Progress *Completed*

CONTAMINANT(S) (See Page 3 for details)

Soil Yes

Groundwater No

Gas, BTEX.

DEPARTMENT REVIEW

Investigator *Date*

Approved by

Unit Supervisor NEC *Date* 4/15/11

Section Manager *Date*

COMMENTS

Two gas USTS were removed from this former gas station in 1993. During removal, water and product from tank rinsing spilled into excavation. Identified PCS (220 tons) was overexcavated and disposed off-site. Confirmation soil samples indicated soil was excavated to below MTCA levels with the exception of two areas: SW corner of the excavation next to the intersection sidewalks at 200 to 500 ppm TPH, and beneath the former pump island at 43 to 3,500 ppm TPH (this location due to financial concerns from the owner). No GW was encountered. No additional info in file.

HCID: 691

WASHINGTON STATE DEPARTMENT OF ECOLOGY

INITIAL INVESTIGATION FIELD REPORT

LUST ID: 2756 **FS ID:** 85982563 **Site ID:** 200042

SITE NAME Uneeda Auto & Boat Rebuild