From:	Warfel, Michael (ECY)
To:	Elisabeth Silver
Cc:	Bonafede, Audrey A
Subject:	RE: Request to Decommission GW-14V -Phillips 66 Burien WA Facility No. 2701476 AOC #2063 (VCP #2718)
Date:	Thursday, March 9, 2023 11:15:09 AM
Attachments:	image001.png image002.png image003.png

Hi Elisabeth:

Thank you for the updated groundwater sampling data for monitoring well GW-14V. Ecology concurs with your plan to decommission this monitoring well. Please forward documentation of the decommissioning at your convenience.

Mike

Michael R. (Mike) Warfel, LG, LHG, RG
Site Manager, Voluntary Cleanup Program
Department of Ecology Northwest Region Office (NWRO)
Physical Address: 15700 Dayton Ave N, Shoreline, WA 98133
Mailing Address: PO Box 330316, Shoreline, WA 98133-9716
Reception (24 hour) number: (206) 594-0000
Direct (Cell): (425) 324-1892
Fax: (206) 366-7810
Email: michael.warfel@ecy.wa.gov
Ecology web site: https://ecology.wa.gov/

From: Elisabeth Silver <Elisabeth.Silver@oneatlas.com>
Sent: Tuesday, March 7, 2023 1:16 PM
To: Warfel, Michael (ECY) <MWAR461@ECY.WA.GOV>
Cc: Bonafede, Audrey A <Audrey.A.Bonafede@p66.com>
Subject: Request to Decommission GW-14V -Phillips 66 Burien WA Facility No. 2701476 AOC #2063 (VCP #2718)

Hi Mike – I wanted to share with you the 4th Qtr. 2022 sampling results for deep well GW-14V located at the Phillips 66 Burien WA Facility No. 2701476 (VCP #2718). As previously discussed, Atlas sampled the deep well GW-14V in the 4th Qtr. 2022, to confirm the observed trends in this well. As concentrations remain below cleanup levels, and do not show a significant increasing trend, we are requesting your concurrence to decommission well GW-14V.

A portion of the summary results table, relevant field notes, and lab report are attached.
Please let me know if you'd like to discuss or have any questions.
Thank you -

Elisabeth Silver
Senior Project Manager

C: 206.491.9754

From: Warfel, Michael (ECY) <MWAR461@ECY.WA.GOV>
Sent: Wednesday, November 23, 2022 2:46 PM
To: Elisabeth Silver <Elisabeth.Silver@oneatlas.com>
Cc: Bonafede, Audrey A <Audrey.A.Bonafede@p66.com>; 'Gurian, Eli A' <Eli.A.Gurian@p66.com>
Subject: [EXTERNAL] RE: GWM Report 2Q2022 Phillips 66 Burien WA Facility No. 2701476 AOC #2063 (VCP #2718)

[External Email] This email originated from outside of the Atlas mail system. Please use caution when opening attachments.

Hi Elisabeth:

Ecology concurs with this approach. Thanks for collaborating on the evaluation of data from monitoring well MW-14V.

Mike

Michael R. (Mike) Warfel, LG, LHG, RG
Site Manager, Voluntary Cleanup Program
Department of Ecology Northwest Region Office (NWRO)
Physical Address: 15700 Dayton Ave N, Shoreline, WA 98133
Mailing Address: PO Box 330316, Shoreline, WA 98133-9716
Reception (24 hour) number: (206) 594-0000
Direct (Cell): (425) 324-1892
Fax: (206) 366-7810
Email: michael.warfel@ecy.wa.gov
Ecology web site: https://ecology.wa.gov/

From: Elisabeth Silver <Elisabeth.Silver@oneatlas.com>
Sent: Wednesday, November 23, 2022 2:44 PM
To: Warfel, Michael (ECY) <MWAR461@ECY.WA.GOV>
Cc: Bonafede, Audrey A <Audrey.A.Bonafede@p66.com>; 'Gurian, Eli A' <Eli.A.Gurian@p66.com>
Subject: RE: GWM Report 2Q2022 Phillips 66 Burien WA Facility No. 2701476 AOC #2063 (VCP #2718)

Mike – thanks for calling – its always nice to catch-up! Per our conversation, we will sample the deep well GW-14V another time, in the 4th Qtr. 2022, to confirm the observed trends in this well. If

concentrations remain below cleanup levels, and do not show a significant increasing trend, we will reach back out to see if its ok to decommission the well.

Thanks again - Elisabeth

Elisabeth Silver
Senior Project Manager

C: 206.491.9754

From: Elisabeth Silver
Sent: Wednesday, November 23, 2022 12:42 PM
To: Warfel, Michael (ECY) <MWAR461@ECY.WA.GOV>
Cc: Bonafede, Audrey A <Audrey.A.Bonafede@p66.com>; 'Gurian, Eli A' <Eli.A.Gurian@p66.com>
Subject: RE: GWM Report 2Q2022 Phillips 66 Burien WA Facility No. 2701476 AOC #2063 (VCP #2718)

Hi Mike – I was wondering, since we were able to confirm in 2 successive events there is vertical delineation of groundwater, would it be ok if we decommission the deep well GW-14V? Its constructed using triple casing, but I would still like to avoid ant conduits to the regional aquifer, if possible.

Thank you – and I hope you have a wonderful thanksgiving weekend!

Elisabeth Silver
Senior Project Manager

C: 206.491.9754

From: Elisabeth Silver
Sent: Monday, September 26, 2022 2:06 PM
To: Warfel, Michael (ECY) <MWAR461@ECY.WA.GOV>
Cc: Bonafede, Audrey A <Audrey.A.Bonafede@p66.com>; 'Gurian, Eli A' <Eli.A.Gurian@p66.com>
Subject: GWM Report 2Q2022 Phillips 66 Burien WA Facility No. 2701476 AOC #2063 (VCP #2718)

Hi Mike - Please see the attached 2Q2022 GWM report for the Burien, WA site, for your files.

Please let us know if you have any questions.

Thank you - Elisabeth

Elisabeth Silver
Senior Project Manager

6347 Seaview Ave NW, Seattle, WA 98107
O: 206.781.1449 | **C:** 206.491.9754
OneAtlas.com **I** LinkedIn **I** Facebook **I** Twitter

Think Safe | Work Safe | Live Safe

ENR #13 Top Construction Management Firm
ENR #8 Top Environmental Management Firm
ENR #44 Top Program Management Firm

This message and any attachments are intended only for the use of the addressee and may contain information that is privileged and/or confidential. If the reader of the message is not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any use and/or dissemination of any of this communication is strictly prohibited. If you have received this communication in error, notify the sender immediately by return email and delete the message and any attachments from your system.
This message and any attachments are intended only for the use of the addressee and may contain information that is privileged and/or confidential. If the reader of the message is not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any use and/or dissemination of any of this communication is strictly prohibited. If you have received this communication in error, notify the sender immediately by return email and delete the message and any attachments from your system.