


LEGEND


- PROPERTY BOUNDARY
- - - PARCEL BOUNDARY
- - - REDEVELOPMENT EXCAVATION AREA
- ◆ MW20 MONITORING WELL
- ◆ MW45 MONITORING WELL (ENVIRONMENTAL PARTNERS INC)
- IW91 INJECTION WELL CONVERTED TO MONITORING WELL
- IW61 INJECTION WELL (SAMPLED)
- ◆ DECOMMISSIONED/DESTROYED MONITORING WELL
- INJECTION WELL
- ANGLED INJECTION WELL
- MONUMENT AND HORIZONTAL PIPING FOR INJECTION WELL SCREEN ACCESS
- - - 1.00-FOOT INTERVAL GROUNDWATER CONTOUR (DASHED WHERE INFERRED)
- GROUNDWATER ELEVATION
- ➔ GROUNDWATER FLOW DIRECTION (DECEMBER 9, 2020)

SoundEarth Strategies
 WWW.SOUNDEARTHINC.COM

TROY LAUNDRY SEATTLE SITE
 389 FAIRVIEW AVENUE NORTH
 SEATTLE, WASHINGTON
 SOUNDEARTH PROJECT #0731-004

FIGURE 3
 GROUNDWATER CONTOUR MAP
 (DECEMBER 9, 2020)





LEGEND

- PROPERTY BOUNDARY
- - - PARCEL BOUNDARY
- - - REDEVELOPMENT EXCAVATION AREA
- ➔ MW20
- ➔ MW-5
- MW-1
- MW-6
- ➔ DECOMMISSIONED/ DESTROYED MONITORING WELL
- INJECTION WELL
- ANGLED INJECTION WELL
- ⊘ MONUMENT AND HORIZONTAL PIPING FOR INJECTION WELL SCREEN ACCESS
- DCE
- PCE
- TCE
- MTCA

NOT DETECTED AT A CONCENTRATION EXCEEDING LABORATORY REPORTING LIMIT


RED DENOTES CONCENTRATIONS EXCEEDING THE MTCA METHOD CLEANUP LEVEL FOR GROUNDWATER


Analytical Results (micrograms per liter)	ds-1-2			trans-1-2			Vinyl Chloride
	PCE	TCE	DCE	DCE	DCE	Chloride	
MTCA Method A	5	5	5	16	160	160	0.2

SoundEarth Strategies
WWW.SOUNDEARTHINC.COM

TROY LAUNDRY SEATTLE SITE
389 PARKVIEW AVENUE NORTH
SEATTLE, WASHINGTON
SOUND EARTH PROJECT #0731-004

FIGURE 4
GROUNDWATER ANALYTICAL RESULTS FOR MONITORING POINTS AT TROY LAUNDRY SEATTLE SITE






LEGEND

- PROPERTY BOUNDARY
- - - PARCEL BOUNDARY
- - - REDEVELOPMENT EXCAVATION AREA
- ◆ MW20 MONITORING WELL
- ◆ MW45 MONITORING WELL (ENVIRONMENTAL PARTNERS INC)
- IW91 INJECTION WELL CONVERTED TO MONITORING WELL
- IW61 INJECTION WELL (SAMPLED)
- ◆ DECOMMISSIONED/DESTROYED MONITORING WELL
- APPROXIMATE EXTENTS OF POST-TREATMENT PCE AND TCE CONCENTRATIONS ABOVE MTCA CLEANUP LEVEL ORIGINATING FROM THE TROY PROPERTY
- DENOTES PCE CONCENTRATION EXCEEDS APPLICABLE MTCA CLEANUP LEVEL
- DENOTES TCE CONCENTRATION EXCEEDS APPLICABLE MTCA CLEANUP LEVEL
- CHLORINATED VOLATILE ORGANIC COMPOUND
- TETRACHLOROETHENE
- TRICHLOROETHENE
- WASHINGTON STATE MODEL TOXICS CONTROL ACT

SoundEarth
Strategies
WWW.SOUNDEARTHINC.COM

TROY LAUNDRY SEATTLE SITE
3800 FAIRVIEW AVENUE, SUITE 100
SEATTLE, WASHINGTON
SOUNDEARTH PROJECT #073-1-004

FIGURE 5
EXTENT OF TROY PROPERTY PCE AND TCE CONCENTRATIONS IN GROUNDWATER PCE-INTERIM REMEDIAL ACTION (04-2020)



P:\0731 TOUCHSTONE\0731-004 TROY LAUNDRY\TECHNICAL\CAD\2020\2020 GW REPORT\0731-004_2020 FIG6 GW VC-POST.DWG 1/26/2021