



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 1951

FS ID: 26239456

Site ID: 6164

SITE NAME Burlington Environmental Kent Facility

SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number	
<i>(Empty)</i>			
Mailing Address	City	Zip + 4	
20245 76th Ave S/20245 77th Ave S	Kent	98032	
Site Location	Closest City	County	
20245 76th Ave S/20245 77th Ave S	Kent		
Quarter-Quarter	Section	Township	Range
Latitude:	Degree	Minute	Second
Longitude:	Degree	Minute	Second

INSPECTION INFORMATION

Inspection Date			Inspection Time	Type of Entry Notice	
Photographs	Yes	No	Weather: Clear	Partly Cloudy	Overcast
Videotape	Yes	No	Precipitation	Temperature	
Samples	Yes	No	Wind Direction	Wind Speed	

RECOMMENDATION

No Further Action:

Yes, but results of landfarmed PCS were not submitted.

- | | |
|--|---|
| <ul style="list-style-type: none"> <i>Release or threatened release does not pose a threat</i> <i>No release or threatened release</i> <i>Educational Mailing</i> <i>Refer to another program/agency</i> | <ul style="list-style-type: none"> <i>Site Hazard Assessment</i> <i>Interim Action</i> <i>Emergency Action Plan</i> <i>Independent Cleanup Action</i> |
|--|---|

In Progress *Completed*

CONTAMINANT(S) (See Page 3 for details)

Soil	Yes	
Groundwater	Yes	Gas, BTEX, diesel

DEPARTMENT REVIEW

Investigator	Date
Approved by	
Unit Supervisor <i>Murrell CA</i>	Date <i>2/17/11</i>
Section Manager	Date

COMMENTS

Three USTs (gas, diesel) were removed from a single excavation at this property in 1991. Approx. 700 cy of PCS were overexcavated and landfarmed on-site. Impacts were noted on GW after removal of the first tank. Confirmation soil samples collected from the excavation after PCS removal indicated that remaining soils were below MTCA for TPH. Several monitoring wells existed at the site and two of them were abandoned b/c they were within the excavation. GW pumped from the excavation was reportedly treated at the facility's treatment system. Although the report indicated the excavated soil was



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 1951

FS ID: 26239456

Site ID: 6164

SITE NAME Burlington Environmental Kent Facility

landfarmed on-site, no report and no lab results exist. In 2003, Ecology sent a letter to Phillips Environmental (now owners) stating concerns on the remediation status and final location of the PCS excavated at the site. No response to the letter was observed in file. No additional info in file.
