

Round The Clock Deli
722 S. Lincoln Street
Port Angeles, Wa 99362

RECEIVED

'94 JAN 27 P2:17

January 25, 1994

DEPARTMENT OF
ECOLOGY

CERTIFIED LETTER

Lynn Gooding
State of Washington
Department of Ecology
Southwest Regional Office
PO Box 47775
Olympia, Wa 98504-7775


Dear Ms. Gooding:

Reference your letter dated January 19, 1994 listing deficiencies contained in the site assessment submitted by Larry Morris of Petroleum Construction & Environmental, Inc.

It seems to me that when hiring a company/person registered and licensed with the State to perform certain specialized functions that a business/person should be able to expect no less than the minimum objectives required by the State. Larry Morris of the above mentioned firm was hired and paid to perform "Permanent Closure" and "Site Assessment" for the business at this address. I understand that with all the varied regulations, etc. omissions and oversights occur. It is my position that by sending Larry Morris copies of the attached three (3) "maps" he should be able to furnish the rest of the required data.

Please call me at (206) 452-1777 if I appear to fail to understand my responsibilities in this matter. I have never, and do not wish to begin, shirking my responsibilities.

Sincerely,


David L. Cotton

Enclosures

cc: Larry Morris, Petroleum Construction & Environmental, Inc.

Round The Clock Deli
722 S. Lincoln Street
Port Angeles, Wa 98362

January 25, 1994

CERTIFIED LETTER

Larry Morris
c/o Bob Rottle
1850 Yantis St. N.W.
Olympia, Wa 98502

Dear Mr. Morris:

I am enclosing a copy of my letter to Lynn Gooding of the Department of Ecology, State of Washington, regarding their definition of "deficiencies" in the Site Assessment done by you at my place of business. I understand she sent you a copy of the Certified Letter that was sent to me regarding this subject.

I am sending you copies of site maps of my property so you can finalize the report required by the State. If you need any additional information please let me know so we can get this situation resolved and get on with business.

Sincerely,


David L. Cotton

Enclosures




Figure 1: Site Map




Figure 2: Lincoln Apartments - Soil Gas, Soil, and Sump Sample Locations

