



## INITIAL INVESTIGATION FIELD REPORT

LUST ID: 4077

FS ID: 74384282

Site ID: 12302

SITE NAME General Telephone Co of NW

### SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number	
<hr/>			
Mailing Address	City	Zip + 4	
426 Casino Rd	Everett	98204	
<hr/>			
Site Location	Closest City	County	
426 Casino Rd	Everett		
<hr/>			
Quarter-Quarter	Section	Township	Range
Latitude:	Degree	Minute	Second
Longitude:	Degree	Minute	Second

### INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No	Weather: Clear	Partly Cloudy Overcast
Videotape Yes No	Precipitation	Temperature
Samples Yes No	Wind Direction	Wind Speed

### RECOMMENDATION

No Further Action:

No. PCS remains on site. Fate of overexcavated PCS is unknown.

Release or threatened release does not pose a threat

Site Hazard Assessment

No release or threatened release

Interim Action

Educational Mailing

Emergency Action Plan

Refer to another program/agency

Independent Cleanup Action

In Progress

Completed

### CONTAMINANT(S) (See Page 3 for details)

Soil	Yes	
Groundwater	No	Diesel

### DEPARTMENT REVIEW

Investigator	Date
Approved by	
Unit Supervisor REC	Date 5/23/11
Section Manager	Date

### COMMENTS

One UST (diesel) & its assoc piping were removed from this site in 1992. The tank excavation was clean; no PCS found. PCS was found in conjunction with the old fuel line penetration at the building. Overexcavation was terminated due to the proximity of the building. It appears the TPH @ 8,300 ppm remains at this location. GW was not encountered. Discussions with Ecology it appears that GTE was not required to remove or treat this PCS. A 'limited cleanup' was granted. The fate of the overexcavated PCS is unknown.

HCID: 1122



## INITIAL INVESTIGATION FIELD REPORT

---

LUST ID: 4077

FS ID: 74384282

Site ID: 12302

SITE NAME General Telephone Co of NW

---