



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Eastern Region Office

4601 North Monroe St., Spokane, WA 99205-1295 • 509-329-3400

August 11, 2022

Doug Pennington
PAPE Machinery
731 F Street SE
Quincy, WA 98848

Re: No Further Action at the following Site:

- **Site Name:** PAPE Machinery
- **Site Address:** 731 F Street SE, Quincy
- **Facility Site ID number:** 82269249
- **Cleanup Site ID number:** 16660

Dear Doug Pennington:

Washington Department of Ecology's (Ecology) Toxics Cleanup Program has reviewed the following information regarding the above-described facility/property:

US Ecology. Incident Report for PAPE Machinery. August 2, 2022.

Based upon the above-listed information, Ecology has determined that the release(s) of *diesel and heavy oil in soil* does not pose a substantial threat to human health or the environment. Therefore, Ecology is issuing a No Further Action (NFA) determination under the Model Toxics Control Act (MTCA)¹.

This NFA determination is made only for releases identified in the independent remedial action report(s) listed above and applies only to the area(s) of the property affected by those releases. The NFA does not apply to any other release or potential release at the property, any other areas on the property, nor any other properties owned or operated by PAPE Machinery.

¹ RCW 70.105D RCW.

Doug Pennington

August 11, 2022

Page 2 of 2

Because your actions were not conducted under a consent decree this letter is offered as informal assistance and advice² and does not constitute a MTCA settlement³, therefore this NFA determination is not binding on Ecology. Should additional information indicate that further action under MTCA is necessary, Ecology may re-evaluate the site.

Should you have any questions regarding this decision, please contact me at 509-319-0047.

Sincerely,

A handwritten signature in dark ink that reads "Sara Fulton". The signature is written in a cursive, flowing style.

Sara Fulton

Initial Investigator

ERO Toxics Cleanup Program

sf:hg

cc: Kathleen Falconer, ERO TCP Section Manager ^{KLF}

² RCW 70.105D.030(1)(i)

³ RCW 70.105D.040(4)