



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 1585

FS ID: 71883959

Site ID: 11470

SITE NAME Eugene Landry

SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number	
<hr/>			
<i>Mailing Address</i>	<i>City</i>	<i>Zip + 4</i>	
9212 45th SW	Seattle	98136	
<hr/>			
<i>Site Location</i>	<i>Closest City</i>	<i>County</i>	
9212 45th SW	Seattle		
<hr/>			
<i>Quarter-Quarter</i>	<i>Section</i>	<i>Township</i>	<i>Range</i>
Latitude:	Degree	Minute	Second
Longitude:	Degree	Minute	Second

INSPECTION INFORMATION

<i>Inspection Date</i>			<i>Inspection Time</i>	<i>Type of Entry Notice</i>	
<i>Photographs</i>	Yes	No	<i>Weather:</i>	Clear	Partly Cloudy Overcast
<i>Videotape</i>	Yes	No	<i>Precipitation</i>	Temperature	
<i>Samples</i>	Yes	No	<i>Wind Direction</i>	Wind Speed	

RECOMMENDATION

No Further Action:

Yes. No info on final disposition of PCS.

Release or threatened release does not pose a threat

Site Hazard Assessment

No release or threatened release

Interim Action

Educational Mailing

Emergency Action Plan

Refer to another program/agency

Independent Cleanup Action

In Progress

Completed

CONTAMINANT(S) (See Page 3 for details)

<i>Soil</i>	Yes	Gas, BTEX, oil
<i>Groundwater</i>	No	

DEPARTMENT REVIEW

<i>Investigator</i>	<i>Date</i>
<i>Approved by</i>	
Unit Supervisor <i>REC</i>	Date <i>4/5/11</i>
Section Manager	Date

COMMENTS

Six USTs (gas, oil) were removed from this property in 1989. Apparently the site was under construction and DCLU stopped all work thinking the contaminated soil associated with the tanks was not being cleaned up. A small letter report provided all results for the cleanup. All soils were below MTCA after overexcavation. No information was provided on the amount of PCS overexcavated or disposal actions. No GW was encountered during excavation. No additional information in file.