



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 5147

FS ID: 84242359

Site ID:

SITE NAME Bellingham Area 1 Maintenance HDQ

SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number	
<hr/>			
Mailing Address	City	Zip + 4	
512 E Sunset Dr	Bellingham	98225	
Site Location	Closest City	County	
512 E Sunset Dr	Bellingham		
Quarter-Quarter	Section	Township	Range
Latitude:	Degree	Minute	Second
Longitude:	Degree	Minute	Second

INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No	Weather: Clear	Partly Cloudy Overcast
Videotape Yes No	Precipitation	Temperature
Samples Yes No	Wind Direction	Wind Speed

RECOMMENDATION

No Further Action:

No: Sampling location map not available.

Release or threatened release does not pose a threat

Site Hazard Assessment

No release or threatened release

Interim Action

Educational Mailing

Emergency Action Plan

Refer to another program/agency

Independent Cleanup Action

In Progress

Completed

CONTAMINANT(S) (See Page 3 for details)

Soil	Yes	
Groundwater	No	Heating oil

DEPARTMENT REVIEW

Investigator	Date
Approved by	
Unit Supervisor <i>REO</i>	Date <i>6/1/14</i>
Section Manager	Date

COMMENTS

One UST (heating oil) was removed from this site in 1994. Approx 210 cy of overexcavated PCS was disposed off-site. Confirmation samples were clean. GW was not encountered. Although confirmation samples appear to be clean, a proper map showing sample locations was not included in the report. This site is not cleaned up.

HCID: