



## INITIAL INVESTIGATION FIELD REPORT

LUST ID: 394428

FS ID: 92325969

Site ID: 375422

SITE NAME US National Bank of WA Bear Creek

### SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number	
<hr/>			
Mailing Address	City	Zip + 4	
17000 Avondale Way NE	Redmond	98052	
<hr/>			
Site Location	Closest City	County	
17000 Avondale Way NE	Redmond		
<hr/>			
Quarter-Quarter	Section	Township	Range
Latitude:	Degree	Minute	Second
Longitude:	Degree	Minute	Second

### INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No	Weather: Clear	Partly Cloudy Overcast
Videotape Yes No	Precipitation	Temperature
Samples Yes No	Wind Direction	Wind Speed

### RECOMMENDATION

No Further Action:

No, GW still impacted

Release or threatened release does not pose a threat

Site Hazard Assessment

No release or threatened release

Interim Action

Educational Mailing

Emergency Action Plan

Refer to another program/agency

Independent Cleanup Action

In Progress

Completed

### CONTAMINANT(S) (See Page 3 for details)

Soil	Yes	Gas, BTEX, HO
Groundwater	Yes	

### DEPARTMENT REVIEW

Investigator	Date
Approved by	
Unit Supervisor <i>REC</i>	Date <i>4/29/11</i>
Section Manager	Date

### COMMENTS

A Phase II was performed to locate 3 USTs (2 gas, 1 oil). GPS was conducted to determine location of USTs. One possible UST and 2 anomalies were located at the site. Seven borings were advanced near the former service station area and near the possible UST and anomalies. Soil sample analytical results were not detected for TPH. GW samples were collected in 3 of the borings and all analytical results were above MTCA for TPH-D/-O.