



INITIAL INVESTIGATION FIELD REPORT

LUST ID: 1553

FS ID: 92645942

Site ID: 100125

SITE NAME Bakkers Fine Dry Cleaning Inc

removal but a tile drain pipe had been crushed during removal and had iridescent sheen on the water. Since the facility had not notified Ecology of the removal and a complaint to the office reported a leaking Stoddard solvent tank, an Ecology rep appeared on site and witnessed the leak. The Ecology rep indicated that the sand surrounding the USTs had absorbed the product and that the excavation was dense till so he thought there was no impact to soil or GW. This is supported by the final excavation samples. No additional info in file.
