



## INITIAL INVESTIGATION FIELD REPORT

LUST ID: 2450

FS ID: 35962717

Site ID: 566

SITE NAME Firestone 31K7

### SITE LOCATION INFORMATION

Contact Person Name	Title	Phone Number	
<hr/>			
Mailing Address	City	Zip + 4	
1012 164th SE	Mill Creek	98012	
<hr/>			
Site Location	Closest City	County	
1012 164th SE	Mill Creek		
<hr/>			
Quarter-Quarter	Section	Township	Range
Latitude:	Degree	Minute	Second
Longitude:	Degree	Minute	Second

### INSPECTION INFORMATION

Inspection Date	Inspection Time	Type of Entry Notice
Photographs Yes No	Weather: Clear	Partly Cloudy Overcast
Videotape Yes No	Precipitation	Temperature
Samples Yes No	Wind Direction	Wind Speed

### RECOMMENDATION

No Further Action:

Yes

Release or threatened release does not pose a threat

No release or threatened release

Educational Mailing

Refer to another program/agency

Site Hazard Assessment

Interim Action

Emergency Action Plan

Independent Cleanup Action

In Progress

Completed

### CONTAMINANT(S) (See Page 3 for details)

Soil Yes WO

Groundwater No

### DEPARTMENT REVIEW

Investigator \_\_\_\_\_ Date \_\_\_\_\_

Approved by \_\_\_\_\_

Unit Supervisor *AN* Date *5/14/11*

Section Manager \_\_\_\_\_ Date \_\_\_\_\_

### COMMENTS

A WO UST was removed from this property in 1991. Approx. 30 tons of PCS were overexcavated over two cleanup phases and disposed off-site. Final confirmation soil samples collected from the excavation indicated that remaining soils were below ND for TPH, PCBs, HVOCS, SVOCs, and TCLP metals. The report mentioned that the excavation was wet but did not indicate the presence of GW. No additional info in file.