

U0007474

3.

(12239

NW

2/2

WASHINGTON STATE  
DEPARTMENT OF TRANSPORTATION  
P.O. Box 1709  
4200 Main Street  
Vancouver, WA 98663  
(206) 696-6518


*Cleanup Action  
for the WSDOT Property at*

BELLINGHAM

512 Sunset Drive  
Bellingham, Washington

Report sent to  
the Northwest  
Regional office

Joyce



Fuel Tank Replacement  
Phase 1, 1990  
February 15, 1991

Bellingham DOT Facility  
512 Sunset Drive  
Bellingham, Washington

SITE # 012239  
TANK # 66A01003

On December 5, 1990, Washington State Department of Transportation (DOT) and its contractor, Stokes Construction, Inc. of Seattle, WA, began removal of a 2,500 gallon diesel tank at the Bellingham Facility. The tank was removed and excavation and stockpiling of contaminated soil began right away.

Approximately 100 C.Y. were removed and stockpiled on site. On December 6, 1990, three soil samples were taken from the contaminated stockpile. Although one sample had less than 10 ppm, the other samples had 656 and 1,038 ppm as diesel.

On December 13, 1990, five soil samples were taken from the hole where the diesel tank had been. Three of these had results of less than 10 ppm, one at 64 ppm, and one at 252 ppm as diesel. The high reading was on the south side of the hole in a small area of sand. The excavation equipment can only access the hole from the north side and could not reach any further to the south.

This sand pocket was cleaned out when the hole was backfilled. The DOT backfilled the hole January 22, 1991. At the same time, the stockpile of contaminated material was hauled and stockpiled at DOT pit number D-245 about one mile north of Arlington.

Mr. Jim Gunderson, DOT Facilities Engineer for District 1 is preparing a report on the soil remediation program at this location.

## APPENDIX

---

# SOUND ANALYTICAL SERVICES, INC.

SPECIALIZING IN INDUSTRIAL &amp; TOXIC WASTE ANALYSIS

4630 PACIFIC HIGHWAY EAST, SUITE B-14, TACOMA, WASHINGTON 98424 - TELEPHONE (206)922-2310 - FAX (206)922-5047

Report To: WA State Dept. of  
Transportation

Date: December 10, 1990

Report On: Analysis of Soil

Lab No.: 14941

IDENTIFICATION:


Samples Received on 12-07-90

Project: Bellingham  
-----ANALYSIS:

<u>Lab Sample No.</u>	<u>Client ID</u>	<u>*Total Petroleum Fuel Hydrocarbons, ppm</u>
1	#1	656 Diesel
2	#2	1,038 Diesel
3	#3	< 10

\*TPH by EPA SW-846 Modified Method 8015

SOUND ANALYTICAL SERVICES

  
C. LARRY ZURAW

# SOUND ANALYTICAL SERVICES, INC.

SPECIALIZING IN INDUSTRIAL &amp; TOXIC WASTE ANALYSIS

4630 PACIFIC HIGHWAY EAST, SUITE B-14, TACOMA, WASHINGTON 98424 - TELEPHONE (206)922-2310 - FAX (206)922-5047

Report To: WA St. Dept. of  
Transportation

Date: December 17, 1990

Report On: Analysis of Soil

Lab No.: 15139

IDENTIFICATION:


Samples Received on 12-14-90

Project: Bellingham  
-----ANALYSIS:

<u>Lab Sample No.</u>	<u>Client ID</u>	<u>*Total Petroleum Fuel Hydrocarbons, ppm</u>
RUSH 1	D-1 NORTH SIDE	64 Diesel
RUSH 2	D-2 EAST SIDE	< 10
RUSH 3	D-3 SOUTH SIDE	252 Diesel
RUSH 4	D-4 WEST SIDE	< 10
RUSH 5	D-5 BOTTOM	< 10

\*TPH by EPA SW-846 Modified Method 8015

SOUND ANALYTICAL SERVICES

  
C. LARRY ZURAW

