



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

P.O. Box 47600 • Olympia, Washington 98504-7600
(360) 407-6000 • TDD Only (Hearing Impaired) (360) 407-6006

RECEIVED
FEB 07 2008
DEPT. OF ECOLOGY
TCP-NWRO

February 4, 2008

MR GREG HELLAND
SCS ENGINEERS
2405 140TH AVE NE STE 107
BELLEVUE WA 98005

**Re: Further Action Determination under WAC 173-340-515(5) for the following
Hazardous Waste Site:**

- Site Name: MEEKER CLEANERS
- Site Address: 1317 W MEEKER ST KENT WA
- Facility/Site No.: 87719977
- VCP No.: NW0879
-

Dear MR HELLEND:

Thank you for submitting your independent remedial action report for the TEXACO 632320307 facility (Site) for review by the State of Washington Department of Ecology (Ecology) under the Voluntary Cleanup Program (VCP). Ecology appreciates your initiative in pursuing this administrative option for cleaning up hazardous waste sites under the Model Toxics Control Act (MTCA), Chapter 70.105D RCW.

This letter constitutes an advisory opinion regarding whether further remedial action is necessary at the Site to meet the substantive requirements of MTCA and its implementing regulations, Chapter 70.105D RCW and Chapter 173-340 WAC. Ecology is providing this advisory opinion under the specific authority of RCW 70.105D.030(1)(i) and WAC 173-340-515(5).

This opinion does not resolve a person's liability to the state under MTCA or protect a person from contribution claims by third parties for matters addressed by the opinion. The state does not have the authority to settle with any person potentially liable under MTCA except in accordance with RCW 70.105D.040(4). The opinion is advisory only and not binding on Ecology.

Ecology's Toxics Cleanup Program has reviewed the following information regarding the Site:

1. Ecology's Pending Inactive Determination Letter of June 22, 2007
2. Ecology's Termination from the VCP of February 4, 2008
3. SOIL REMEDIATION REPORT BY SCS ENGINEERS SEPT 2002
4. GROUNDWATER MONITORING REPORTS BY SCS ENGINEERS: March 2005, March 2004, Dec 2003, Sept 2003, June 2003, March 2003, Dec 2002 and Sept 2002.

The documents listed above will be kept in the Central Files of the Northwest Regional Office of Ecology (NWRO) for review by appointment only. Appointments can be made by calling the

Further Action Determination
Inactive VCP Site NW0879
February 4, 2008

NWRO resource contact at (425) 649-7190.

The Site is defined by the extent of contamination caused by the following release(s):

- PCE and its daughter by products in the soil and groundwater

The Site is more particularly described in Enclosure A to this letter, which includes a detailed Site diagram. The description of the Site is based solely on the information contained in the documents listed above.

Based on a review of the independent remedial action report and supporting documentation listed above, **Ecology has determined that the independent remedial action(s) performed at the Site are not sufficient to meet the substantive requirements contained in MTCA and its implementing regulations, Chapter 70.105D RCW and Chapter 173-340 WAC, for characterizing and addressing any of the contamination at the Site.** Therefore, pursuant to WAC 173-340-515(5), Ecology is issuing this opinion that **further remedial action is necessary** at the Site under MTCA.

Further Action is required at this site for the following reasons

- PCE and its daughter by products remain in the soil above the MTCA cleanup levels (Method A) at the eastern portion of the site: between 5.5 to 6 ft below the ground surface.
- PCE's daughter by products remains in the groundwater above the MTCA cleanup levels (Method A) at the eastern portion of the site (MW-3).
- Ecology is concerned about the ongoing plume migration and off property impacts (between MW1 and MW-2).



Please note that this opinion is based solely on the information contained in the documents listed above. Therefore, if any of the information contained in those documents is materially false or misleading, then this opinion will automatically be rendered null and void.

The state, Ecology, and its officers and employees make no guarantees or assurances by providing this opinion, and no cause of action against the state, Ecology, its officers or employees may arise from any act or omission in providing this opinion.

Again, Ecology appreciates your initiative in conducting independent remedial action and requesting technical consultation under the VCP. As the cleanup of the Site progresses, you may request additional consultative services under the VCP, including assistance in identifying applicable regulatory requirements and opinions regarding whether remedial actions proposed for or performed at the Site meet those requirements. If you have any questions you may reach me at 360-407-7244.

Sincerely

Further Action Determination
Inactive VCP Site NW0879
February 4, 2008




Nnamdi Madakor, VCP Coordinator
HQ - Toxic Cleanup Program

cc: Russ Olsen, NWRO VCP Unit Manager.
Sara Maser, NWRO Data Coordinator
Delores Mitchell, Ecology (NW0879)

NM:nm

Enclosure



SCS ENGINEERS
 STEARNS, CONRAD AND SCHMIDT
 CONSULTING ENGINEERS
 2405 140TH AVE NE, SUITE 107, BELLEVUE, WA 98005 (425) 746-4600

PROJECT NO.	04202001.00	DES BY	B.D.
SCALE	AS SHOWN	CHK BY	B.D.
CAD FILE	FIGURE 1	APP BY	G.H.

SITE PLAN
 FORMER MEEKER CLEANERS
 MEEKER SQUARE, KENT, WASHINGTON

DATE	MAY 2003
FIGURE	1

